

TPAIG.  
Khenchnag.

SLX7155Y.

Toyota Harrier 1986cc

ZSU600070143

|                                      |                                   |
|--------------------------------------|-----------------------------------|
| Rear Bumper Deformed                 | 1343 ✓                            |
| Rear Bumper Lips. New                | 30 ✓                              |
| Rear Bumper Side Holder x 02 New     | $65 \times 2 = 130$ ✓             |
| Rear Bumper Lower Garnish. Deformed  | 489. ✓                            |
| Rear Bumper Reflector x 02 RH could  | $88 \times 2 = 176$ <sup>88</sup> |
| Rear Bumper Sponge could.            | 182 ✓                             |
| Reverse Sensor Dented                | <del>480(SN)</del> 380(SN)        |
| Rear End Panel Dented.               | 715 ✓                             |
| Rear End Panel Top Garnish. Deformed | 367 ✓                             |
| Rear End Panel Sealant New           | 60(SN) ✓                          |
| Taillamp x 02 RH could               | $481 \times 2 = 962$ 481          |
| Taillamp Lower Bracket x 02 RH could | $65 \times 2 = 130$ 65.           |
| Tailgate Rep's                       | 1712 +                            |
| Tailgate Lock. Dented                | 418 ✓                             |
| Tailgate Weatherstripe. cut          | 353 ✓                             |
| Harrier Wordings New                 | 74 ✓                              |
| Tailgate Glass Moulding. Green       | 210 +                             |
| Tailgate Glass Sealant.              | 60(SN) +                          |
| Tailgate Lock Sensor could           | 186 ✓                             |

SLX7155Y

Panel Bending  
Spray Painting.

Wiring.

To undersoil

To remove reverse sensor

To remove upholstery.

To remove tailgate fittings.

To remove tailgate g/ings

1200 900

~~1000~~ 900

~~50~~ 30

~~150~~ 60

~~100~~ 60

~~150~~ 80

~~150~~ 80

180 x

list: 4921

less 25%: 3690.75

S.N: 440.

Labour 2110.

total: 6240.75

4/5: 5K

06 Days

5k.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: