

A.S.S. REC. BY:

REF:

CC 31 MSG 1901914149F3N2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond:

Steering:

Brake:

Modi:

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Des. of Damages:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Coc 3-1-2022 Byg Inta. L79 1100g

3/10/19 @ 1.20pm Email GIA report to MISC.

Remarks that Not claim yet 5000

5/10/19 2/5 = 5000 confirm with ALM. (Red 11844.84, 70%)

06/11/19 @ 9.52am revised to Pauline Thom via MISC.

RECEIVED 06 NOV 2019

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

11/06/11 MISC

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

21

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invt (\$

☐

Weekend (%)

Survey Fee:

Transportation:

3 + RS. \$

Photos

Notes

MISC

200

11

211

Report Form:

Lump Sum / U.C.:

MISC

5000

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 06 Nov 2019

Preliminary Advice

Insured Vehicle No	: SLE6926X	Accident Date	: 29/10/2019
TP Vehicle No	: SGQ802E	Assignment Date	: 01/11/2019
Make	: MAZDA MAZDA5	Est. Duration of Repair	: 6.00
Date of Inspection	: 30/10/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,844.84
Revised Amount	:S\$	6,834.36
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,834.36
Lump Sum Repair	:S\$	5,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 31 October 2019 1:20 PM
To: motorsurvey@sg.msig-asia.com
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 29/10/2019, SGQ 802E (TP VEHICLE), SLE 6926X (OI VEHICLE)
Attachments: SGQ802E_GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SGQ 802E at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

HOTTEST NEW CAR
PROMOTIONS

Toyota Sienta Hybrid

Ready stock available with immediate COE registration. Call us now!!

DON

MAZDA 3

Price Range ▼

Depreciation ▼

> 10 year(▼

Vehicle Type ▼



Home » Used Cars » Hua Heng Motor Trading » Mazda 3 1.6A (COE till 01/2022)

Mazda 3 1.6A (COE till 01/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$15,800

Depreciation ⓘ \$7,050 /yr

Reg Date 01-Feb-2007
(2yrs 2mths 26days COE left)

Mileage N.A.

Manufactured ⓘ 2006

Road Tax ⓘ \$890 /yr

Transmission Auto

Dereg Value ⓘ \$11,350 as of today (change)

OMV ⓘ \$15,079

COE ⓘ \$25,323

ARF ⓘ \$16,587

Engine Cap 1,598 cc

Power 79.0 kW (105 bhp)

Curb Weight ⓘ 1,235 kg

No. of Owners ⓘ 3

Type of Vehicle Mid-Sized Sedan

Features

View specs of the Mazda 3 Sedan (2004-2009)

Description

High Loan Available. New Paint. No Repair Needed. Original Cushion Seats. View To Believe It. Comes With Sport Rims.

Category

COE Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



- Free

Get market value of your existing car for free. Get started

https://www.sgcarmart.com/used_cars/info.php?ID=859494&DL=1243



Location Map

Shortlist

Compare

Report Error

More Action

Seller Information

Company

Hua Heng Mo

» dealer's price

» 2 vehs sold | 3

Address

210 Turf Club Rd

ZB/Z9

Search cars near

Location

Car Mall @ The

mazda 3 Price Range Depreciation > 10 year Vehicle Type Submit

Advanced Search

Home > Used Cars > Boeki Auto Pte Ltd > Mazda 3 1.6A SP (COE till 04/2022)

Mazda 3 1.6A SP (COE till 04/2022)

Overview Financial Insurance Accessories Similar Research Photos Map



BOEKI AUTO PTE LTD



Price	\$16,800		
Depreciation	\$6,720 /yr	Reg Date	03-May-2007 (2yrs 6mths COE left)
Mileage	145,700 km (11.7k /yr)	Manufactured	2007
Road Tax	\$890 /yr	Transmission	Auto
Dereg Value	\$12,564 as of today (change)	OMV	\$14,514
COE	\$25,115	ARF	\$15,966
Engine Cap	1,598 cc	Power	79.0 kW (105 bhp)
Curb Weight	1,235 kg	No. of Owners	3
Type of Vehicle	Mid-Sized Sedan		

Features

View specs of the Mazda 3 Sedan (2004-2009)

Description

Trade-In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company	Boeki Auto Pte Ltd
	* dealer's pricelist
	* 62 vehs sold 40 vehs available
Address	49 Sungei Kadut Loop
	Search cars nearby this location
Office No	67555005
Contact Person(s)	Boeki 82180500

used cars
company profile

Posted on: 17-Oct-2019 | Last Updated on: 25-Oct-2019

Upfront Payment
Compare

> more Financial info

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 506D

Vehicle Details

Vehicle No.: SGQ802E
Vehicle to be Exported: No
Intended Deregistration Date: 01 Nov 2019
Vehicle Make: MAZDA
Vehicle Model: MAZDA3SP LUX
Primary Colour: Red
Manufacturing Year: 2006
Engine No.: Z6502418
Chassis No.: JM6BK106270320272
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$15,955.00
Original Registration Date: 04 Jan 2007
First Registration Date: 04 Jan 2007
Transfer Count: 0
Actual ARF Paid: \$15,159.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 03 Jan 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$25,323.00
COE Rebate Amount: \$11,000.00
Total Rebate Amount: \$11,000.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Oct 2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2019 11:47
Date Of Accident	29/10/2019 16:50
Exact Location Of Accident	JLN AHMAD IBRAHIM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGQ802E
Insured/Policyholder	
Name Of Registered Owner	YIM KIM HOO(YAN JIANHAO)
NRIC No	S6924506D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97832443
Alternative Phone No	OTHERS-97832443

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3SP LUX
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5052465036-07
Cover Note Number	

Driver

Name of Driver	YIM KIM HOO(YAN JIANHAO)
NRIC No	S6924506D
Date Of Birth	08/07/1969
Occupation	INDOOR
Date Of Driving Pass	19/08/2002
Driving Experience	17 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97832443
Fax Number	
Contact Number	OTHERS-97832443
EMail Address	NOEMAIL

Address	BLK 283 #03-406 CHOA CHU KANG AVENUE 3
Postcode	680283
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED; LOCATION; JLN AHMAD IBRAHIM TOWARDS MCE AFTER JALAN BOON LAY

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE6926X
Vehicle Make/Model/Colour	VOLVO / S80 T5 2.0 A/T ABS D/AIRBAG 2WD
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLF5240S
-----------------------------	----------

Vehicle Make/Model/Colour	TOYOTA / LEXUS ES250 A/T S/R
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SHD267G
Vehicle Make/Model/Colour	RENAULT / LATITUDE 2.0L DCI AUTO D/AB 4DR
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SKS8969Y
Vehicle Make/Model/Colour	MERCEDES BENZ / E250 SEDAN (R18)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	YIM KIM HOO(YAN JIANHAO)
Approximate Age	
Injuries Sustain	NECK & BACK PAIN
Injured person in which vehicle?	SGQ802E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 283 #03-406 CHOA CHU KANG AVENUE 3
Postcode	680283

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available insofar.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Admiralty Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, law or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yackb@vicom.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/TFN No.:

Accident Sketch Plan

SKETCH PLAN

	A : SGH 802E
	B : SLE 8926X
	C : SLF 5240S
	D : SHD 267G
	E : SKS 8969Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29.10.2019 at about 4.50pm. I was travelling along Jalan Ahmad Ibrahim towards MCE after Jalan Koon Lay. I stopped due to a front vehicle stopped. Suddenly I felt an impact from my rear and my car moved forward and hit the front vehicle. I was involved in a 5 vehicles chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67418697 Fax: 67492305
Email: vac@idac.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #25-00 Singapore 048000
Tel (65) 6724 0033 Fax (65) 6724 0038
Operating Hours: Monday to Friday, 0900 - 1700
URL: www.gias.org.sg / 201 Reg. No. 19400067705

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No.: MYA 319143540 / VAC Vehicle Registration No.: 36A 802E
Name (as shown in NRIC): Yim Kim Hoo (Yan Jau Hoo) NRIC/FIN/Passport No.: 369245060
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: 81E 283 Choa Chu Kang Avenue 3 #03-406 Singapore (670283)
Contact (Tel): - Mobile No.: 97832443
Email Address: -
Date of Accident: 19.10.2019 Time of Accident: 16.30
Place of Accident: Jln Ahmad Ibrahim Towards MCE After Jalan Boon Lay
Insurance Company: NTUC Income Insurance Co-operative Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

- Amendment Place of Accident

Along Jalan Ahmad Ibrahim Towards MCE After Jalan Boon Lay

Policyholder / Driver's Signature
Date:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416647 Fax: 67492305
Reporting Centre Personnel's Signature
Name: Email: vackb@vicom.com.sg
NRIC/FIN No.:
Date:

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

MAKE/MODEL : MAZDA 3

Not Authorized
Mark
4/5 \$5000/
6dy.
30/10/19

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE SG0802E

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ 11 68.90 X
1	Rear boot lid	\$ 12 972.00 X
1	Rear boot inner lock	\$ Tui/Shade 221.80
1	Rear boot rubber	\$ Tui 118.80
2	Rear boot hinges	\$ 11 280.80 X
1	Rear boot "3" emblem	\$ 11 29.60
1	Rear boot "MAZDA" emblem	\$ 11 25.20
1	Rear boot logo	\$ 11 62.60
2	Rear boot lamps	\$ 11 523.00
1 set	Rear number plate lamps 234.00	\$ 11 417.60
2	Rear taillamps 951x220 1902	\$ 11 2,076.80
2	Rear taillamp panels	\$ 11 204.00 X
1	Rear end panel	\$ 11 357.00
1	Rear end panel inner garnish	\$ 11 212.50
1	Rear bumper 988.20	\$ 11 1,026.70
1	Rear bumper reinforcement	\$ 11 547.00
2	Rear bumper side retainers	\$ 11 77.20
2	Rear bumper reflectors	\$ 11 124.00 X
1 set	Rear bumper lower skirting 365.00	\$ 11 411.20
1	Rear floor panel	\$ 11 2,221.00 X
1	Rear exhaust silencer	\$ 11 953.80 X
2	Rear exhaust mountings	\$ 11 91.00 X
1	Rear fender -LH	\$ 11 1,091.00 X
1	Rear fender air gate	\$ 11 41.50 X
2	Rear fender inner trims	\$ 11 385.30
2	Rear fender inner shields	\$ 11 97.00 X
		\$ 12,637.30
	Less 20%	\$ 2,527.46
		\$ 10,109.84

6049.20
4839.36

c/t: \$ 10,109.84

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$ 11	80.00	X
1	Rear bumper clip (1 set)	\$ see	45.00	✓
1	Rear number plate	\$ 3 set	50.00	40
1	Rear reverse sensor (1 set)	\$ 3 holes	350.00	200
		\$	525.00	


S/N	LABOUR CHARGES
-----	----------------

1	To check wiring and reset headlamps focusing.	\$	80.00	} 30
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	
3	To remove and refit inner garnishes.	\$	150.00	80
4	To remove and refit rear reverse sensor.	\$	120.00	50
5	To transfer rear boot lid mechanism and wiring assembly.	\$	120.00	X
6	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	180.00	X
7	To remove and refit rear windscreen glass.	\$	180.00	X
8	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	X
9	To apply undercoating.	\$	250.00	50
10	Panel beating.	\$	2,500.00	600
11	To re-spray painting on the affected areas.	\$	2,400.00	900
		\$	6,210.00	

GRAND TOTAL:

\$ 16,844.84

6834.36
6.467.48



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19019174/UQF3N2

Date: 07/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001061309
Claimant Vehicle No :	SGQ802E	Insured Vehicle No :	SLE6926X
Date of Loss:	29/10/2019	Nature of Claim:	TP
		Claim No:	232745

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGQ802E		
Make & Model:	MAZDA MAZDA5, 2.0 5-DOOR WAGON 2.0L SP.6EAT SUNR (A)	Engine No:	Z6502418
Reg. Date:	04/01/2007 (Man. Year: 2006)	Chassis No:	JM6BK106270320272
Colour:	Red	Odometer:	192311 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,634.84	5,124.36	5,510.48	51.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,210.00	1,710.00	4,500.00	72.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,844.84	6,834.36	10,010.48	59.43
Approved Total (Overridden) (\$\$)		5,000.00		
(\$\$)	16,844.84	5,000.00	11,844.84	70.32
+ GST 7.00/7.00% (\$\$)	1,179.14	350.00	829.14	70.32
Nett Amount (\$\$)	18,023.98	5,350.00	12,673.98	70.32

INSPECTION

Date of Assignment:	01/11/2019	
Date Inspected:	30/10/2019	Inspected At:
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Nov 2019)
Parts:	M1-SUV	MAZDA MAZDA5 2.0 5-DOOR WAGON 2.0L SP.6EAT SUNR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGQ802E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	68.90 FL	*- FL
2	1		*REAR BOOT LID	Repair	972.00 FL	*- FL
3	1		*REAR BOOT INNER LOCK	Twisted/Shorted	221.80 FL	*221.80 FL
4	1		*REAR BOOT RUBBER	Twisted	118.80 FL	*118.80 FL
5	2		*REAR BOOT HINGES	Not Necessary	280.80 FL	*- FL
6	1		*REAR BOOT 3 EMBLEM	Necessary	29.60 FL	*29.60 FL
7	1		*REAR BOOT MAZDA EMBLEM	Necessary	25.20 FL	*25.20 FL
8	1		*REAR BOOT LOGO	Necessary	62.60 FL	*62.60 FL
9	2		*REAR BOOT LAMPS	Cracked	523.00 FL	*523.00 FL
10	1		*SET REAR NUMBER PLATE LAMPS	Broken	417.60 FL	*234.00 FL
11	2		*REAR TAILLAMPS	Cracked	2,076.80 FL	*1,902.00 FL
12	2		*REAR TAILLAMP PANELS	Repair	204.00 FL	*- FL
13	1		*REAR END PANEL	Badly Dented	357.00 FL	*357.00 FL
14	1		*REAR END PANEL INNER GARNISH	Twisted	212.50 FL	*212.50 FL
15	1		*REAR BUMPER	Distorted	1,026.70 FL	*988.20 FL
16	1		*REAR BUMPER REINFORCEMENT	Distorted	547.00 FL	*547.00 FL
17	2		*REAR BUMPER SIDE RETAINERS	Bent	77.20 FL	*77.20 FL
18	2		*REAR BUMPER REFLECTORS	Not Necessary	124.00 FL	*- FL
19	1		*SET REAR BUMPER LOWER SKIRTING	Torn	411.20 FL	*365.00 FL
20	1		*REAR FLOOR PANEL	Repair	2,221.00 FL	*- FL
21	1		*REAR EXHAUST SILENCER	Not Necessary	953.80 FL	*- FL
22	2		*REAR EXHAUST MOUNTINGS	Not Necessary	91.00 FL	*- FL
23	1		*REAR FENDER-LH	Repair	1,091.00 FL	*- FL
24	1		*REAR FENDER AIR GATE	Not Necessary	41.50 FL	*- FL
25	2		*REAR FENDER INNER TRIMS	Deformed/Torn	385.30 FL	*385.30 FL
26	2		*REAR FENDER INNER SHIELDS	Not Necessary	97.00 FL	*- FL
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
29	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
30	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,162.30	6,334.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,527.46	1,209.84
Total Parts (\$\$)	10,634.84	5,124.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING)	New	80.00	30.00
2	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING)	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
5	TO TRANSFER REAR BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	0.00
6	TO REMOVE,REPLACE AIR-CON CONDENSER,REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	0.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
8	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
9	TO APPLY UNDERCOATING	New	250.00	50.00
10	PANEL BEATING	New	2,500.00	600.00
11	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,400.00	900.00
Gross Labour Cost (S\$)			6,210.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >