



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

11 November 2019

QUOT201911-000012
HHTPCLAIMS19-202

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET, #04-00 / #05-00
IOB BUILDING
SINGAPORE 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SMA5461K & SHA7555U ON 28/10/2019 ALONG BUONA VISTA DRIVE AT ABOUT 0830 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SMA5461K
Vehicle Make : HONDA
Vehicle Model : FREED HYBRID 1.5G AUTO
Vehicle Chassis No. : GB71066576
Policy No. : 5087272209-03
Date of Accident : 28/10/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper ✓ PD		\$ 1,050.60
2	10	Rear Bumper Clip ✓ Nec	\$ 3.90	\$ 39.00 30
3	1 / 2	Rear Bumper Retainer (LH/RH) ✓ Nec	\$ 24.90	\$ 49.80 24.90
4	2	Rear Bumper Reflector (LH/RH) X SVC	\$ 42.80	\$ 85.60
5	1	Rear Tailgate ✓ PD		\$ 1,100.80
6	1	Rear Tailgate Lock ✓ BR.		\$ 151.80
7	1	Rear Tailgate Logo (FREED) ✓ Nec		\$ 55.00
8	1	Rear Tailgate Logo (HYBRID) ✓ Nec		\$ 75.00
9	1	Rear Tailgate Chrome Garnish X SVC		\$ 320.30
10	1	Rear Emblem ✓ Nec		\$ 27.40
11	1	Rear Tailgate Weather Strip ✓ BR.		\$ 168.00
12	1	Rear Windscreen Moulding ✓ Nec.		\$ 151.30
13	1	Rear End Panel ✓ PD.		\$ 623.70
14	1	Rear End Panel Top Garnish ✓ BR.		\$ 115.00
15	1	Rear Reverse Lamp (LH) X SVC.		\$ 360.70
				\$ 4,374.00
				Less 20% \$ 874.80
				\$ 3,499.20
16	1	Reverse Sensor ✓ Short	NETT	\$ 200.00
17	1	Sealant ✓ Nec.	NETT	\$ 40.00
To dismantle, cut & weld rear end panel, change rear bumper, rear tailgate, rear LH reverse lamp, knocking & pull straight rear tyre floor panel and all area affected by accident				\$ 900.00 700
To perform wire checking				\$ 20.00 / Nec

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

11 November 2019

QUOT201911-000012
HHTPCLAIMS19-202

ACCIDENT INVOLVING SMA5461K & SHA7555U ON 28/10/2019 ALONG BUONA VISTA DRIVE AT ABOUT 0830 HOURS

Estimate Repair List for vehicle SMA5461K - HONDA FREED HYBRID 1.5G AUTO

S/N	Quantity	Description	Unit Price S\$	Amount S\$
		To dismantle & refit rear windscreen		\$ 100.00 <i>NEC</i>
		To dismantle & transfer rear tailgate mechanism and fitting to new tailgate		\$ 60.00 <i>NEC</i>
		To dismantle & refit rear bumper sensor		\$ 60.00 <i>NEC</i>
		To spray rear tailgate, rear bumper, rear panel and rear tyre floor panel		\$ 900.00 <i>600</i>
				\$ 5,779.20
7% GST				\$ 404.54
Total				\$ 6,183.74

Repair days - 5 day

Tp without prejudice

Sun Pin / sunpin@lkkauto.com / 8661 2627

Lump Sum Repair

After spray photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


Authorised by Claims Dept

