



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

11 November 2019

QUOT201911-000012

HHTPCLAIMS19-202

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET, #04-00 / #05-00

IOB BUILDING

SINGAPORE 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SMA5461K & SHA7555U ON 28/10/2019 ALONG BUONA VISTA DRIVE AT ABOUT 0830 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SMA5461K
Vehicle Make : HONDA
Vehicle Model : FREED HYBRID 1.5G AUTO
Vehicle Chassis No. : GB71066576
Policy No. : 5087272209-03
Date of Accident : 28/10/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper ✓ PD		\$ 1,050.60/
2	10	Rear Bumper Clip ✓ Nec	\$ 3.90	\$ 39.00 30
3	1/2	Rear Bumper Retainer (LH/RH) ✓ Nec	\$ 24.90	\$ 49.80 24.90
4	2	Rear Bumper Reflector (LH/RH) X SVC	\$ 42.80	\$ 85.60 X
5	1	Rear Tailgate ✓ PD		\$ 1,100.80 1000
6	1	Rear Tailgate Lock ✓ BR		\$ 151.80/
7	1	Rear Tailgate Logo (FREED) ✓ Nec		\$ 55.00/
8	1	Rear Tailgate Logo (HYBRID) ✓ Nec		\$ 75.00/
9	1	Rear Tailgate Chrome Garnish X SVC		\$ 320.30 X
10	1	Rear Emblem ✓ Nec		\$ 27.40/
11	1	Rear Tailgate Weather Strip ✓ BR		\$ 168.00/
12	1	Rear Windscreen Moulding ✓ Nec		\$ 151.30/
13	1	Rear End Panel ✓ PD		\$ 623.70/
14	1	Rear End Panel Top Garnish ✓ BR		\$ 115.00/
15	1	Rear Reverse Lamp (LH) X SVC		\$ 360.70 X
				\$ 4,374.00 3,573.5
			Less 20%	\$ 874.80 -20%
				\$ 3,499.20 2,858.8
16	1	Reverse Sensor ✓ Short	NETT	\$ 200.00/
17	1	Sealant ✓ Nec	NETT	\$ 40.00/ 240
		To dismantle, cut & weld rear end panel, change rear bumper, rear tailgate, rear LH reverse lamp, knocking & pull straight rear tyre floor panel and all area affected by accident		\$ 900.00 700
		To perform wire checking		\$ 20.00/ Nec

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

11 November 2019

QUOT201911-000012

HHTPCLAIMS19-202

ACCIDENT INVOLVING SMA5461K & SHA7555U ON 28/10/2019 ALONG BUONA VISTA DRIVE AT ABOUT 0830 HOURS

Estimate Repair List for vehicle SMA5461K - HONDA FREED HYBRID 1.5G AUTO

S/N	Quantity	Description	Unit Price S\$	Amount S\$
		To dismantle & refit rear windscreen		\$ 100.00 <i>Nec</i>
		To dismantle & transfer rear tailgate mechanism and fitting to new tailgate		\$ 60.00 <i>Nec</i>
		To dismantle & refit rear bumper sensor		\$ 60.00 <i>Nec</i>
		To spray rear tailgate, rear bumper, rear panel and rear tyre floor panel		\$ 900.00 <i>600</i>
				\$ 5,779.20 <i>1,540</i>
7% GST				\$ 404.54
Total				<u>\$ 6,183.74</u>

Repair days - 6 day

Tp without prejudice

Sun Pin / sunpin@lkkauto.com / 86612627

Lump Sum Repair P/P

*After spray photo
before*

P = 2,858.8

N = 240

L = 1,540

4,638.8

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]



Authorised by Claims Dept

Oi Sun Pin (LKK Auto)

From: James Tan <james@huahong.com.sg>
Sent: Tuesday, 10 March, 2020 10:01 AM
To: Oi Sun Pin (LKK Auto)
Cc: claims@huahong.com.sg
Subject: RE: Finalize Case for SMA 5461 K - DOA: 28/10/2019

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Sun Pin,

COR @ \$4,638.80 b4 GST – Confirm
Thanks.

Regards

James Tan

Claims Department



HUA HONG PRIVATE LIMITED
25D SUNGEI KADUT STREET 1 SINGAPORE 729332
T. 6661 9688 | F. 6661 9699 | W. huahong.com.sg
   

From: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Sent: Friday, 6 March 2020 6:29 pm
To: James Tan <james@huahong.com.sg>
Cc: claims@huahong.com.sg
Subject: RE: Finalize Case for SMA 5461 K - DOA: 28/10/2019

Hi James,

Kindly refer the finalize amount is \$4,638.8. Repair day 6 days. (P/P, before gst).
If agree please update

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: James Tan [<mailto:james@huahong.com.sg>]
Sent: Wednesday, 4 March, 2020 11:32 AM
To: Oi Sun Pin (LKK Auto)
Cc: claims@huahong.com.sg
Subject: RE: Finalize Case for SMA 5461 K - DOA: 28/10/2019

Dear Sun Pin,

Please assist to finalize the case asap.