

INS. CASE OWNER:

lynn

CC 4/AXA1901

9177

23

LKK:
IDAC:

ASSIGNMENT

Surveyor:

Kenneth

DOI:

30/10/19

Date / Time:

30/10/19

Registered in Merimen:

Pre-assign / CCU / FTE

SKK 4032T

57M02522/144274



Insured Vehicle No.:

SKK 4032T

Claim No.:

57M02522/144274

Name of Insured:

Kenneth v/o Kenneth

Policy No.:

57M02522/144274

Insured Tel No.:

HP:

Make / Model:

Toyota

Excess Sec II :S\$

D.O.A.:

27/10/19

Place of Accident:

Wishnu St 13

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKK 6197



INSRS:
WSP:
Tel:
Liability:
RMKS:

Photowork



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List: Handler	Typist
		Notification ltr (if non-pickup)	☒
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
--------------	------------	---------------	-------------

Repair Cost:	S\$ 1600.00	(4 days) Reduction: 3355.56 % 60	Email ☐ Call ☐
--------------	-------------	-----------------------------------	--

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
------------------	------------	---------------	--

Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	24.
------------------	-------	-----------------------------------	-----

Repair Cost:	S\$ 1600.00		
--------------	-------------	--	--

Loss of Rental (LOR):	S\$ -	(days)	
-----------------------	-------	---------	--

Loss of Use (LOU):	S\$ 300.00	(5 x 6 days)	
--------------------	------------	--------------	--

Loss of Income (LOI):	S\$ -	(\$ x days)	
-----------------------	-------	--------------	--

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ (Tick only one)			
---	--	--	--

GLA/LTA Search	S\$ 2.00		
----------------	----------	--	--

Medical:	S\$ -		
----------	-------	--	--

Disbursement:	S\$ -	(e.g. Tow/ Independent)	
---------------	-------	-------------------------	--

Legal Cost	S\$ -		
------------	-------	--	--

Total:	S\$ 1905.00	Global Sum S\$:	
--------	-------------	-----------------	--

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☒ Call ☐
---------------	------------	---------------	---

Payee 1:	S\$ 1902.00	Name 1:	Photowork House
----------	-------------	---------	-----------------

Payee 2: (Strike if N.A.)	S\$ -	Name 2:	
---------------------------	-------	---------	--

Payee 3: (Strike if N.A.)	S\$ -	Name 3:	
---------------------------	-------	---------	--

COPY SENT

X 6197

REF: ASM (ANA)

ASS. REC. BY: *

ASSIGNMENT

From: _____ Date: 30.10.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 619J

at Workshop m/s Supreme Auto

at 176 Sin Ming Drw #02-01

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 862k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKX 619J Yr Regn: 01, 18

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra cc 1591

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 23504 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM110841CMJU 609991

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 27/10/19

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 30/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

45 \$1600- (Red+ \$2358.56 / 60%)

4 repair days + 1 PRS + 1 Sunday = 6 days

Date/Time, File Pass in?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return in?

2)

Rep. Form:

Lump Sum / F.B. / etc

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Meal and (\$

Survey Fee:

Transportation:

3 + RS \$

Photos

Other

TOTAL

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

CHAN YEE PIA
c/o 46 Lenton Plain
Singapore 786548

Not Authorised
L1 Day @ 1600p
Recovery After Paint
4 days

Date: 30/10/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: HYUNDAI ELANTRA / SKX 619 J	
1 pc	rear bumper	376.40
1 pc	rear bumper lower pad	315.10
1 pc	rear bumper sponge	365.60
1 pc	rear bumper reinforcement beam	277.40
2 pcs	rear bumper reinforcement beam bracket	126.80
1 pc	rear bumper reflector (left)	119.30
1 pc	rear boot lid	776.30
1 pc	rear boot lock	197.40
1 pc	rear boot lock catch	76.60
1 pc	rear boot emblem logo	72.10
1 pc	rear boot emblem "ELANTRA"	73.20
1 pc	rear boot emblem "S"	31.40
	sub-total	2,807.60
	less 20%	561.52
	sub-total	2,246.08
1 pc	rear bumper parking sensor	220.00
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	400.00
	To check wiring system.	80.00
	To apply putty & spray painting on affected areas.	640.00
	To install reverse sensors and reverse camera	80.00
	total	3,666.08

AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

CHAN YEE PIA
c/o 46 Lenton Plain
Singapore 786548

Date: 8/11/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
1 pc	<u>RE: SUPPLEMENTARY FOR HYUNDAI ELANTRA / SKX 619 J</u> rear boot lock sensor	365.60 X
	sub-total	365.60
	less 20%	73.12
	Total	292.48

\$3958.56

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

CHAN YEE PIA

c/o 46 Lentor Plain
Singapore 786548

*Not Authorised
L1 Day &?
Recovery After Paint*

Date: 30/10/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: HYUNDAI ELANTRA / SKX 619 J	
1 pc	rear bumper	376.40
1 pc	rear bumper lower pad	315.10
1 pc	rear bumper sponge	365.60
1 pc	rear bumper reinforcement beam	277.40
2 pcs	rear bumper reinforcement beam bracket @ 63.40	126.80
1 pc	rear bumper reflector (left)	119.30
1 pc	rear boot lid	776.30
1 pc	rear boot lock	197.40
1 pc	rear boot lock catch	76.60
1 pc	rear boot emblem logo	72.10
1 pc	rear boot emblem "ELANTRA"	73.20
1 pc	rear boot emblem "S"	31.40
	sub-total	2,807.60
	less 20%	561.52
	sub-total	2,246.08
1 pc	rear bumper parking sensor s.nett	220.00
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	400.00
	To check wiring system.	80.00
	To apply putty & spray painting on affected areas.	640.00
	To install reverse sensors and reverse camera	80.00
	total	3,666.08

Auto Consultants hence notify the Repairer of the following:

- To reserve before start any painting
- To display damaged part(s) during recovery
- Parts price are subject to confirmation
- Third party survey is on a 'Visual Positive' basis
- No legal responsibility is assumed
- Supplemental Agreement as mentioned and is subject to full payment of invoice

<< Service Request Details

Claim

S9M02532

Reference

None

Loss Date

October 27, 2019

Report Date

Oct 29, 2019 3:28:29 PM

Request Date

October 29, 2019

Due Date

November 5, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Chao
T: 504p.m
v: ln
E ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKX619J

Model
ELANTRA AD 1.6 GLS

Service Address

...

Primary Contact/Insured

PONNUSWAMY RANUKA D/O
BLK 186 BISHAN STREET 13, #04-337, 570186, Singapore

P.RANUKA@GMAIL.COM

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions
Autoworx House

Messages Invoices History Documents Assessment Metrics Notes

New Message

Summer Lee (LKK Auto)

From: claim.autoworxhouse@gmail.com
Sent: Tuesday, 29 October, 2019 2:29 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] Request for Single Jointed Expert Inspection for SKX 619 J in an accident involving SKK 4032 T on 27-10-2019
Attachments: GIA MAIN.pdf
Categories: Shekhar

Dear Sirs,

We have been authorised by CHAN YEE PIA, the registered owner of motor vehicle: SKX 619 J at the material time of accident to make a claim against your insured.

Please give us the list of panel of your survey firms for our selection to inspect the above said vehicle or you may assign our choice from either one of the 3 survey firms,

- 1) Premier Appraiser Services
- 2) LKK Auto Consultants Pte Ltd
- 3) AJAX Inspection Services Pte Ltd

Please advise us with your assigned surveyor, name and contact number for this matter.

Kindly contact us at **64528211** before coming to ensure the vehicle is in the workshop.

Thank you.

Best regards,

WK Chew
Autoworx House

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Thursday, 19 December 2019 9:47 AM
To: p.ranuka@gmail.com
Subject: RE: <STANDARD LETTER> OUR REF: CC4/ASM19019177/Kgb3 *** ACCIDENT INVOLVING SKK 4032T & SKX 619J ON 27/10/2019 ***
Attachments: SKX 619J VIDEO FOOTAGE.3gpp

Dear Ranuka,

Kindly refer to attached for the Video Footage send by Third Party,

Liability is down against us, as your vehicle has rear ended Third Party vehicle.

Kindly note that your vehicle NCD will be affected.

We will then proceed to direct settle with Third Party.

Thanks

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 18 December 2019 5:40 PM
To: p.ranuka@gmail.com
Subject: <STANDARD LETTER> OUR REF: CC4/ASM19019177/Kgb3 *** ACCIDENT INVOLVING SKK 4032T & SKX 619J ON 27/10/2019 ***
Importance: High

18 DECEMBER 2019

RANUKA D/O PONNUSWAMY

Dear Sir/ Mdm



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/12/2019

Survey Details:

Date of loss	27-Oct-19
Date of appointment	30-Oct-19
Date of survey	30-Oct-19
Location of survey	AUTOWORX HOUSE

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKX 619J
Make and Model	HYUNDAI ELANTRA 1.6
Date of registration	15/1/2018
Excess	
Market Value	\$62,000
Parf Rebate	\$40,258
Nett Loss	\$21,742

Repair details:

Initial Estimate	\$ 3,666.08
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,220.40
Check items (estimate)	\$ -
Labour	\$ 815.00
Total	\$ 2,035.40
Lump Sum(if applicable)	\$ 1,600.00
Number of days for repair	4



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

04 RECOMMENDED REPAIR DAYS + 1PRS + 1SUNDAY = 6DAYS

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	1,600.00
Loss of use	\$	360.00 6days x \$60
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	2.00
Others	\$	-
Proposed Total	\$	1,962.00



<MANDATE IA> - S9M02532 {ACCIDENT INVOLVING SKK 4032T & SKX 619J ON 27/10/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$1962.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 20/12/2019

Reply

AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420
Registration No. 5296929B

INVOICE 5382

AXA INSURANCE PTE LTD

14/11/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE : SKX 619 J / HYUNDAI ELANTRA</u>	
	Lump sum repair for the above mentioned vehicle.	1,600.00
	Total	1,600.00



**Re:<MANDATE IA> - S9M02532 {ACCIDENT INVOLVING
SKK 4032T & SKX 619J ON 27/10/2019}**

Type

Question

Message

Dear CCL, proceed with mandate. Thanks

Reply

AUTOWORX HOUSE

176 Sin Ming Drive, #02-01 Sin Ming Autocare Singapore 575721

Email: claims.autoworxhouse@gmail.com

•TEL: 6452 8211 •FAX: 6451 7420

Direct Settlement THIRD PARTY CLAIM

Your ref:

Our ref: SKX 619 J

AXA INSURANCE PTE LTD

Attn: Officer In Charge

(Motor Claim Department)

15/11/2019

Dear Sir,

RE : ACCIDENT INVOLVING SKX619J & SKK4032T ON 27/10/2019.

We have been authorized by CHAN YEE PIA, the registered owner of vehicle number SKX619J, which was involved in the above accident and at the material time to make a 3rd party claims against vehicle number SKK4032T.

The accident was clearly caused by your insured's negligence. We, therefore seeking compensation from you for our client financial losses as itemized below: -

Repair cost	S\$	1,600.00
Loss of Use (6days x \$60.00) include 2 PRI days	S\$	360.00
Search Fee	S\$	2.00
Total	S\$	1,962.00

We have enclosed copies of relevant documents to support our claims.

Please settle this matter within 7 days.

Your prompt settlement of our claim would be much appreciated.

Do contact us at 64528211 for any clarification.

Thank you.

Yours faithfully,


Autoworx House

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19019177/Kga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN		Date : 13-03-2020		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKK 4032T	Veh. Inspected	SKX 619J	
Policy No.	VA1/GA368681	Coverage (\$)	0.00	
Claim No.	S9M02532	Excess (\$)	0.00	
Assign From		Assign Date	30/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHD841CMJU609991	Colour	METALLIC SILVER	
Odometer	23504	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEXEN	8 mm	
L/H Front Tyre	195/65 R15	NEXEN	8 mm	
R/H Rear Tyre	195/65 R15	NEXEN	8 mm	
L/H Rear Tyre	195/65 R15	NEXEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/10/2019	Inspection Date	30/10/2019	
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 619J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	MTG CRACKED	376.40	376.40
1	REAR BUMPER LOWER PAD (CONSISTENT)	SERVICEABLE	315.10	-
1	REAR BUMPER SPONGE (CONSISTENT)	SERVICEABLE	365.60	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	277.40	277.40
2	REAR BUMPER REINFORCEMENT BEAM BRACKET @\$63.40 (CONSISTENT)	SERVICEABLE	126.80	-
1	REAR BUMPER REFLECTOR (LEFT) (CONSISTENT)	SERVICEABLE	119.30	-
1	REAR BOOT LID (CONSISTENT)	BENT	776.30	776.30
1	REAR BOOT LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	197.40	-
1	REAR BOOT LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	76.60	-
1	REAR BOOT EMBLEM LOGO (CONSISTENT)	NECESSARY	72.10	32.00
1	REAR BOOT EMBLEM 'ELANTRA' (CONSISTENT)	NECESSARY	73.20	32.00
1	REAR BOOT EMBLEM 'S' (CONSISTENT)	NECESSARY	31.40	31.40
	LESS 20% DISCOUNT		-561.52	-305.10
			2,246.08	1,220.40
SPECIAL NETT ITEMS				
1	REAR BUMPER PARKING SENSOR (SN) (CONSISTENT)	SERVICEABLE	220.00	-
			220.00	-
LABOUR				
	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REAR BOOT LOCK AND REAR BOOT LOCK CATCH .		400.00	350.00
	TO CHECK WIRING SYSTEM.		80.00	15.00
	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		640.00	400.00
	TO INSTALL REVERSE SENSORS AND REVERSE CAMERA.		80.00	50.00
			1,200.00	815.00
GRAND TOTAL			3,666.08	2,035.40

Report Ref No. CC4/ASM19019177/Kga3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	----------

Report Ref No. CC4/ASM19019177/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.

Service Request Details

Claim	59M02532
Reference	CC4/ASH19019177/Nga3u2
Loss Date	27 October 2019
Report Date	29 Oct 2019 3:28:29 PM
Request Date	29 October 2019
Due Date	

Vendor Name	L&K AUTO CONSULTANTS PTE LTD (LTP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add Invoice

Vehicle Information	
Incident Vehicle Registration #	SKK619J
Make	TPVO HYUNDAI
Model	ELANTRA AD 1.6 GLS
Service Address	

...

Primary Contact/Insured	
PONNUSWAMY RANUKA D/O BLK 186 BISHAN STREET 13, #04-337, 570186, Singapore	
PRANUKA@GMAIL.COM	

Claim Handler	
KHONG Lynn 68804B92 lynn.khong@aaa.com.sg	

Additional InstructionsAutoswax House

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 LKKAadjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 GSA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	MOA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2020
 MANDATE IA DO 20122019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 HARB COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LETTER TO INSURED.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKX RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LKX SURVEY PHOTO.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 SKX 619/ VIDEO FOOTAGE (convert-video-online.mpg4)	Evidence	Videos	LKX AUTO CONSULTANTS PTE LTD (TP)	19 December 2019
 TP-JA 619 .pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	31 October 2019
 SKX619/ TP GA.pdf	Reports & Statement	GIA Report	KHONG Lynn	29 October 2019
 Service appointment in Vendor Portal claim 59N02532 for vehicle SKX619.html	{!getDocumentType_Auditm.documentType!}		VISHNU BATHAM Shekhar	29 October 2019
 GAJ68681-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	VISHNU BATHAM Shekhar	29 October 2019
 EMAIL TP PRL.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	29 October 2019
 GAJ68681-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	VISHNU BATHAM Shekhar	29 October 2019
 EMAIL TP PRL.png	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	29 October 2019