

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

CHAN YEE PIA
c/o 46 Lenton Plain
Singapore 786548

Not Notarized
11:00 AM @ 1600
Money After Paint
4 days

Date: 30/10/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: HYUNDAI ELANTRA / SKX 619 J	
1 pc	rear bumper	376.40
1 pc	rear bumper lower pad	315.10
1 pc	rear bumper sponge	365.66
1 pc	rear bumper reinforcement beam	277.40
2 pcs	rear bumper reinforcement beam bracket	126.80
1 pc	rear bumper reflector (left)	119.30
1 pc	rear boot lid	776.30
1 pc	rear boot lock	197.40
1 pc	rear boot lock catch	76.60
1 pc	rear boot emblem logo	72.10
1 pc	rear boot emblem "ELANTRA"	73.20
1 pc	rear boot emblem "S"	31.40
	sub-total	2,807.60
	less 20%	561.52
	sub-total	2,246.08
1 pc	rear bumper parking sensor	220.00
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	400.00
	To check wiring system.	80.00
	To apply putty & spray painting on affected areas.	640.00
	To install reverse sensors and reverse camera	80.00
	total	3,666.08

AUTOWORX HOUSE

C/O.176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64520715 FAX: 64529250

ESTIMATE

CHAN YEE PIA
c/o 46 Lentor Plain
Singapore 786548

Date: 8/11/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
1 pc	<u>RE: SUPPLEMENTARY FOR HYUNDAI ELANTRA / SKX 619 J</u>	
	rear boot lock sensor	<i>Sh</i> 365.60 X
	sub-total	365.60
	less 20%	73.12
	Total	292.48