

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 17392

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1293/2019/NS
Date : 29-Oct-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,

5 days - ok - Jy - 10 Jan 2020

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Ho Geok Eng
Address : 507 Canberra Drive
#05-16
Singapore 768127
Telephone : HP +65 94508357
Type of Claim : Own Damage Claims
Policy No. : 2100459231-03
Vehicle No : **SKG 3673 X**
Model Code : Audi A6 1.8 TFSI S -Tronic
Model / Year : 3/31/2016
Engine No : CYG 009319
Chassis No : WAUZZZ4G2GN075995
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Oct-19
Place of Accident : Kwong Wai Shin Hospital

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKG 3673 X

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	2,800.00	\$ 1,250.00
3	To respray front bumper and lhs front fender.	\$	2,300.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,772.00</u>	<u>\$ 3,022.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 3673 X

S/N	Parts Description		<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remarks</u>
1	FRONT BUMPER		\$ 2,443.00	\$ 1,954.40
2	FRONT BUMPER GRILLE		\$ 598.00	
3	FRONT BUMPER LOCKING CLIP	18	\$ 65.00	
4	FRONT BUMPER CHROME TRIM		\$ 276.00	
5	FRONT BUMPER FIXING PARTS		\$ 45.00	
6	FRONT BUMPER CLOSING ELEMENT		\$ 199.00	
7	FRONT BUMPER SPOILER		\$ 227.00	
8	RADIATOR GRILLE		\$ 1,766.00	\$ 1,412.80
9	RADIATOR GRILLE COVER		\$ 33.00	
10	FRONT PARKING AID SENSOR - LH / RH	2	\$ 122.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 319.00	
12	FRONT BUMPER COVER - LH		\$ 46.00	
13	FRONT WHEEL SPOILER - LH		\$ 242.00	\$ 193.20
14	STONE CHIP GUARD		\$ 66.00	\$ 52.72
15	ADHESIVE TAPE		\$ 50.00	\$ 40.00
16	HEADELIGHT WASHER COVER CAP - LH / RH	2	\$ 104.00	
17	HEADLIGHT HOSE		\$ 413.00	
18	LIFT CYLINDER - LH		\$ 216.00	\$ 172.40
19	FRONT BUMPER FOAM FILLER PIECE		\$ 215.00	
20	FRONT BUMPER SIDE REINFORCEMENT BEAM		\$ 754.00	
SUB - TOTAL SPARE PARTS :			\$ 8,199.00	\$ 3,825.52

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKG 3673 X**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
		<i>c/f</i>	\$ 3,825.52
21	FRONT BUMPER COVER	\$ 112.00	
22	FRONT BUMPER GUIDE PIECE - LH	\$ 34.00	\$ 27.12
23	FRONT BUMPER BRACE - LH	\$ 27.00	
24	CAUTION SIGN STICKER	NEC \$ 13.00	
25	FRONT FENDER - LH	\$ 1,269.00	\$ 1,015.20
26	FRONT FENDER ATTACHMENT PARTS	\$ 92.00	
27	STONE GUARD FILM - LH	\$ 110.00	\$ 88.00
28	FRONT FENDER BRACE - LH	\$ 75.00	
29	FRONT WHEEL HOUSING LINER - LH	\$ 256.00	\$ 204.80
30	FRONT WHEEL HOUSING LINER ATTACHMENT PA	\$ 66.00	
31	FRONT TRIM BRACKET - LH	\$ 15.00	
32	HEADLIGHT MOUNTING - LH	\$ 107.00	
33	LED HEADLIGHT - LH	\$ 8,607.00	\$ 6,885.60
34	FRONT NO PLATE	S/N \$ 40.00	\$ 40.00
35	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		\$ 11,123.00	\$ 12,086.24
TOTAL LABOUR CHARGES		\$ 5,772.00	\$ 3,022.00
GRAND TOTAL		\$ 16,895.00	\$ 15,108.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant