BLOCK 9 SIN MING INDUSTRIAL ESTATI SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileem Business Regn No: 269436/00J

29,Oct 2019

China Taiping Insurance (S) PL 105, Cecil Street \$18-00 The Octagon S 069534

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SJW1642B Accident involving vehicle no:SMG3816C/SJW1642B/Sa

DOA: 24/10/2019 AT Aljunied Road twds Macpherson Road

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SMG3816C

To supply--

Description	
Tailgate	
Tailgate lock	
Tailgate MAZDA logo	
Tailgate skycity emblem	
Tailgate-mazda 3 emblem	
Tailgate reflector	
End panel	
End panel top garnish	
Boot weatherstrip	
Taillamp	
Rear bumper	
Rear bumper retainer	
Rear bumper enforcement	
Rear bumper tow cover	
Rear bumper reflector	
Bumper clip/fender cowling clip	
front bumper	
Front Garnish	

Reverse sensor

To remove damaged parts and attachments - Furt

Cut n weld damaged panel Repair/reshape dented areas Replace/align all parts into position To spray paint

LKK Au

the Rer

To resu

• To disp

· Parts p.

• Third party survey is on a "Without Prejudice" basis

2 457 \$5,790

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

1,006.+ 790+ 670+ 570+ 490 . + 5510+ 168 . + 867.+ 9470+ 380+ 5650+ 180+ 351.8+ 610·7= 5,815·5* 5,815.5x 80 . % 4,652.4* 0 . C

0 . C

2000 * -800°+ 1,6000 * 300 . + 60°+ 0 400 == 00 760° * 00 -60 0 . C 4,652.4+ 2000+ 760 == 20.00

,00.00

7,212.4*

7,212.4x

80 . % 5,769.92*