

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

29, Oct 2019

China Taiping Insurance (S) PL
105, Cecil Street \$18-00
The Octagon S 069534

*Not Authored
11/10/19
Review After Repair
Today*

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SJW1642B

Accident involving vehicle no: SMG3816C/SJW1642B/3AB 2382B

DOA: 24/10/2019 AT Aljunied Road twds Macpherson Road

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SMG3816C

To supply--

Description	Qty	Amount
Tailgate	1	1,006.00 ✓
Tailgate lock	1	187.00 x
Tailgate MAZDA logo	1	79.00 —
Tailgate skycity emblem	1	67.00 —
Tailgate-mazda 3 emblem	1	57.00 —
Tailgate reflector	1	490.00 ?
End panel	1	551.00 ?
End panel top garnish	1	168.00 ?
Boot weatherstrip	1	114.00 x
Taillamp	1	867.00 ?
Rear bumper	1	947.00 ✓
Rear bumper retainer	1	38.00 ✓
Rear bumper enforcement	1	565.00 ✓
Rear bumper tow cover	1	18.00 ✓
Rear bumper reflector	1	53.00 x
Bumper clip/fender cowl clip		42.00 ?
Front bumper	1	1,083.00 ?
Front garnish	1	351.80 ✓
Grille	1	610.70 ✓
<i>208</i>		

Reverse sensor

Shan 220.00 20012

To remove damaged parts and attachments - Frt & Rr

Cut n weld damaged panel

Repair/reshape dented areas

Replace/align all parts into position

To spray paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*950.00 Boot
800.00 ✓*