

Our Job Ref No . 305344839  
Date : 30. Oct. 2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA5963M

Date of Accident: 26. Oct. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA SGP5716T

2. The finalized amount shall be:

(a) Spare Parts after List discount \$155.00

(b) Labour Charges \$920.00

**Total for Part-By-Part Repair Cost** \$1,075.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

**Final Lumpsum Repair cost** \_\_\_\_\_

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 31/10/19

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305344839  
 REGN NO : SHA5963M  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 08.11.2018  
 DATE/TIME IN : 29.10.2019 09:50  
 ACCIDENT DATE : 26.10.2019

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	28-01-0103-0003-A	(I40)FRT DOOR LOGO SONATA	1	75.00 0.00 75.00
0002	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00 0.00 80.00

SUB-TOTAL : 155.00

## JOB NATURE

0000	PB	PANEL BEATING		320.00
0001	23-502	SPRAYPAINT ON AFFECTED AREA		600.00

SUB-TOTAL : 920.00

TOTAL : 1,075.00

\_\_\_\_\_  
 MVA NAME & SIGNATURE  
 DATE :

\_\_\_\_\_  
 SURVEYOR NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO

REPAIR ESTIMATE\*

DATE: 29. Oct. 2019

VEHICLE NO : SHA5963M

MAKE : HYUNDAI

DOA: 26. Oct. 2019

CHINA

MODEL : IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR - LH X Repair			\$1,797.20
1	REAR DOOR - LH X Repair			\$1,789.90
1	REAR WHEEL COVER - LH X <sup>scr</sup>			\$346.60
	Per fender (LH) X repair			
<b>SUB TOTAL</b>				<b>\$3,933.70</b>
<b>LESS 20% DISCOUNTED TOTAL</b>				<b>\$786.74</b>
				<b>\$3,146.96</b>
1	FRONT DOOR COMFORT LOGO			\$75.00 <b>Nett</b>
1	REAR DOOR APP LOGO			\$80.00 <b>Nett</b>
				<b>\$155.00</b>
<b>Labour Charge</b>				
1	Panel Beating			<del>\$960.00</del>
1	Spray Painting Charge			<del>\$750.00</del>
1	Wiring Charge			<del>\$80.00</del>
1	Tuff Kote			<del>\$80.00</del>
2	Transfer of Doors		\$120.00	<del>\$240.00</del>
<b>TOTAL LABOUR</b>				<b>\$2,110.00</b>
<b>ESTIMATE TOTAL</b>				<b>\$5,411.96</b>

To be used for insurance claim only  
 • To be used for insurance claim only  
 • Third party liability insurance  
 • No illegal modification of parts on a "justice" basis  
 • Supplementary to final approval by Insurance Company  
 Acknowledged by Repairer  
 Signature: *Kahin (K)*  
 Date: 29/10/19 15:20h  
 P/P  
 After Repair p photo

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.