

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA5963M

DATE: 29. Oct. 2019

MAKE : HYUNDAI

MODEL : IONIQ

DOA: 26. Oct. 2019

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR - LH <i>x repair</i>			\$1,797.20
1	REAR DOOR - LH <i>x repair</i>			\$1,789.90
1	REAR WHEEL COVER - LH <i>x repair</i> <i>for fender (LH) x repair</i>			\$346.60
SUB TOTAL				\$3,933.70
LESS 20%				\$786.74
DISCOUNTED TOTAL				\$3,146.96
1	FRONT DOOR COMFORT LOGO			\$75.00
1	REAR DOOR APP LOGO			\$80.00
Nett				\$155.00
Labour Charge				
1	Panel Beating			\$960.00
1	Spray Painting Charge			\$750.00
1	Wiring Charge			\$80.00
1	Tuff Kote			\$80.00
2	Transfer of Doors		\$120.00	\$240.00
TOTAL LABOUR				\$2,110.00
ESTIMATE TOTAL				\$5,411.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: *Ka hui (LKK)*
Date: *29/10/19 15:20L*

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.