

22/07/2021

ASS. REC. BY:

REF: CS/SPP/19019/189 / EV f3/2

Special Instructions:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): National Railway of

SPF

Date/Time: 30.10.19 3.50pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SSN 7008R

Insured: Q & 295M

at Workshop m/s Inchcape Centre

Tel: 98476179

of 2 Pandan Crescent / Level 4

Policy No:

Claim No: AEMD / 105 / 009 / 2019 / 106

Sum Insured:

Excess:

Make of Vch:

D.O.A. 21.9.2019

(Client's Record)

31.10.19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 30.10.19 4.07pm

Person Contacted:

Francis chur

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SSN 7008R - NA / NV (100/100) / W / DEP - 29/01/2010

Q & 295M - CS / SPP / 19019 / 189 / EV f3/2

Do Not Finalise

20/11/19

@ 2.44pm Francis said vehicle has not send in for repair, pending liability

13/12/19

@ 2.25pm Francis said vehicle has not send in for repair, pending liability

13/2/20

Final fig \$ 3243.39 (Real 5974.30, 65%, 3 days

13/2/20

Upper range \$ 3000 - \$ 4000

13/2/20

To re-open and submit final report, pls pass to typist. Celine 14/2/2020

14/2

reopen not only, let close date 27/12/19

Inspector *Steve*

REF: CS | SPF 19019189 | Evf

ASSIGNMENT

om: Date: Estimated Cost: 2 / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop n/s

ured

icy No.

ims No.

n Insured:


Excess:

lient's Record)

ce of Veh:

olicy Condition)

mark: The veh had commenced its repair at the time of inspection.



or Market Value:

Accident Report: Consistent? : Yes or No

I PR. Seen: Consistent? : Yes or No

Repairs: days Res.: Yes or No

Sum: % 3 Val.: Yes or No

I REV / REP. / 24 HRS

Vehicle: IN / OUT

Person Contacted:

e / Time Action / Instruction

MR-89K

17/12/19 Submit prelim report

mo, File Pass to?

☒ : Prelim. Report

Days Of Repair: *3*

Resurvey No. of Trip:

Survey Fee:

mo, File Return to?

☐ : Final Report

Transportation:

ort Format :

Sum / I.B.I. (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

) : Prior

) : Others

TOTAL

270

270

Veh No: *SJN 7008R* Yr Regn: *8/4/19*
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Toyota Altis* C.C. *1598*

Colour *Silver* A/C: Insured / Std / NI / NA

Sp.Reading *10734* T/Radio: Insured / Std / NI / NA

Eng/No:

CiNo: *MR 053 REH. 6045 96236*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *205/55R16*

R: *11*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. *5* mm R/Bal. *5* mm

L/Bal. *5* mm L/Bal. *5* mm

D.O.A. *21/9/19* D.O.I. *31/10/19*

Survey held at *Quinn Motors*

Des. of Damages: ☒ Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 17 DEC 2019

17/12 - typist



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188
Customer Detail

Account Detail		Account No		Customer Detail				
THIRD PARTY CLAIM		S1000020 / TPCLAIM		Mr Ng Teck Pin 410D Pasir Panjang Road Singapore 118754 Mobile: 93808802				
		Document No						
		0						
		Document Date						
		23/09/2019						
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
19	GEXGPZ	C2	ZRE171R 08/04/2019	SJN7008R	0	48884	65DS/SJN7008R	
Chassis No		Engine No		Terms	Service Engineer	Vehicle In	Collected On	
MR053REH604596236		1ZROD41640		60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : T/P VEH. : QX295M ACC DATE : 21.09.19 BY :					✓ 30	100.00
2	L	BP-LPO SUPPLY REGN PLATE (PO#) (FRT WITH CASING)					✓	68.00/
3	B	BP-MECH2 RESET AND REPROGRAMME ECU.					✓	180.00/
4	B	BP-MECH2 REMOVE AIR CON COMPONENTS TO REGAS AND REPLACE NEW PARTS.					X ?	360.00
5	B	BP-LAB2 REMOVE AND REFOCUS HEADLAMP.					✓	180.00/
6	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR.					✓ 720	2160.00
7	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED (By & Suppl) PORTION OF CAR.					✓ 875	1770.00
8	1	S52119-02982 COVER, FR BUMPER, L/ X R (To dismount & (N/A))			1.00	531.10	✓	531.10
9	2	S52115-02380 SUPPORT, FR BUMPER S X MW			1.00	68.20		68.20
10	3	S52116-02370 SUPPORT, FR BUMPER S X N/A			1.00	68.20		68.20
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		
		Please acknowledge receipt of vehicle		Parts		Less		
				Labour				
				Materials				
				Lubrication/Fluid				
				Others				
						Amount Due		

PLEASE TEAR ALONG PERFORATED LINE

4044299

TO SECURITY GUARD

4044299

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 23/09/2019
TIME 16:24

VEHICLE NO

SJN7008R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Ng Teck Pin 410D Pasir Panjang Road Singapore 118754 Mobile: 93808802
	Document No	
	0	
	Document Date	
	23/09/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GEXGPZ	C2	2RE171R 08/04/2019	SJN7008R	0	48884	65DS/SJN7008R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

MR053REH604596236 1ZROD41640 60 Francis Cher T S --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	4	T90467-05170 CLIP ✓ <i>MM</i> ✓ <i>MM</i> X <i>MM</i>	2.00	2.50		5.00
12	5	S52131-02190 REINFORCEMENT, FR	1.00	399.50		399.50
13	6	S53112-02300 GRILLE, RADIATOR, LW <i>MM</i> X <i>MM</i>	1.00	169.60		169.60
14	7	S53208-02230 SUPPORT SUB-ASSY, HO ✓ <i>BT</i> ✓	1.00	164.90		164.90
15	8	S88450-02350 A/C CONDENSER ASSY, <i>MM</i> X <i>MM</i>	1.00	1801.70		1801.70
16	9	SPC593-1200F LED FOG LAMP (LWR RY H) ✓ <i>MM</i> ✓	1.00	387.80		387.80
17	0	S53100-02B90 GRILLE ASSY, RADIATO <i>MM</i> X <i>MM</i>	1.00	712.10		712.10

(Fev CLKK)
8322 8813
stevechen@1klads.com

w/L *MM* 31/10/19, 12:30pm
3 days
PIP
Ry OK Spj

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

9217.69

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	
	Please acknowledge receipt of vehicle	Parts	9,126.10	
		Labour	4,308.10	
		Materials	4,750.00	
		Lubrication/Fluid	68.00	
		Others	0.00	
		0.00	GST 7.00%	638.83
			Less	0.00
			Amount Due	9,764.93

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME 23/09/2019
16:24

4044300

4044300

VEHICLE NO

SJN7008R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail				Account No		Customer Detail	
THIRD PARTY CLAIM				S1000020 / TPCLAIM		Mr Ng Teck Pin	
				Document No		410D Pasir Panjang Road	
				Document Date		Singapore 118754	
				0		Mobile: 93808802	
				12/02/2020			
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GEXGPZ C2	ZRE171R	08/04/2019	SJN7008R	0	48884	65DS/SJN7008R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053REH604596236	1ZROD41640	60	Francis Cher T S	10/02/2020	8.00	12/02/2020	18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES T/P INS. : T/P VEH. : QX295M ACC DATE : 21.09.19 BY : LKK-STEVE @ 31.10.2019 03 WORKING DAYS				30.00	
2	L	BP-LPO SUPPLY REGN PLATE (PO# 26025) (FRT WITH CASING)	A000			68.00	
3	B	BP-MECH2 RESET AND REPROGRAMME ECU.	18			180.00	
4	B	BP-LAB2 REMOVE AND REFOCUS HEADLAMP.	29			180.00	
5	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR.	29			720.00	
6	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			885.00	
7	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION PO:26073 (RECOAT FRONT BUMPER) (SUPPLEMENTARY)	A000			91.59	
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.							
For & on behalf of Borneo Motors		Customer's Signature	Change Summary		Total		
		Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others		Less		
					Amount Due		

4134216

PLEASE TEAR ALONG PERFORATED LINE

4134216

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SJN7008R

CUSTOMER

DATE 12/02/2020
TIME 13:57

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Ng Teck Pin
	Document No	410D Pasir Panjang Road
	0	Singapore 118754
	Document Date	Mobile: 93808802
	12/02/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GEXGPZ	C2	ZRE171R 08/04/2019	SJN7008R	0	48884	65DS/SJN7008R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053REH604596236	1ZR0D41640	60	Francis Cher T S	10/02/2020	8.00	12/02/2020	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
8	1	S52119-0Z982 COVER, FR BUMPER	1.00	531.10		531.10
9	2	T90467-05170 CLIP	2.00	2.50		5.00
10	3	S53208-02230 SUPPORT SUB-ASSY, HO	1.00	164.90		164.90
11	4	SPC593-1200F LED FOG LAMP	1.00	387.80		387.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 1,088.80	GST 7.00% 227.04
		Labour 1,995.00	
		Materials 159.59	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
			Amount Due 3,470.43

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

12/02/2020

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/02/2020
TIME 13:57

VEHICLE NO SJN7008R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

4134217

4134217



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Supplementary
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
W/Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail				Account No		Customer Detail	
THIRD PARTY CLAIM				S1000020 / TPCLAIM		Mr Ng Teck Pin	
				Document No 0		410D Pasir Panjang Road	
				Document Date 12/02/2020		Singapore 118754	
						Mobile: 93808802	
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	GEXGPZ	C2	ZRE171R 08/04/2019	SJN7008R	0	48884	65DS/SJN7008R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR053REH604596236	1ZR0D41640	60	Francis Cher T S	10/02/2020	8.00	12/02/2020	18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION PO:26073 (RECOAT FRONT BUMPER) (SUPPLEMENTARY)	A000			91.59	
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.							
For & on behalf of Borneo Motors		Customer's Signature	Change Summary		Total	91.59	
		Please acknowledge receipt of vehicle	Parts	0.00	GST 7.00%	6.41	
			Labour	0.00		0.00	
			Materials	91.59	Less		
			Lubrication/Fluid	0.00			
			Others	0.00			
					Amount Due	98.00	

4134218

PLEASE TEAR ALONG PERFORATED LINE

4134218

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SJN7008R

CUSTOMER

DATE 12/02/2020
TIME 13:57

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

INTERNAL INVOICE

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

New vehicle preparation PDI
***** For use by BMS PDI *****

10100001 /NEWVEHIC

Mr TP Ng
410D Pasir Panjang Road

38036523

Singapore 118754

16/04/2019

19 GEXGP2 C2	ZRE171R	08/04/2019	SJN7008R	1	43706	69INT/SJN7008R
MR053REH604596236	1ZR0D41640	00	Raymond Seah L M	--/--/----	0.00	--/--/---- 0.00

M D1068*-PLATINUM SHINEPRO
1 * PSPRO PDI LABOUR FOR PLATINUM SHINE PDI
D1068D) Platinum Shine Glass Coating
1 * PSPRO MAT PDI PLATINUM SHINE SET

0.00	GST 0.00%	0.00
0.00		0.00
0.00		0.00
0.00		0.00

16/04/2019
09:31

SJN7008R

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 13 February 2020 4:25 PM
To: Thomas Pang PTCBC; Steve Chen (LKK Auto); SUR; Admin A
Subject: RE: Finalize Reort of SJN7008R
Attachments: MARKING.pdf

Dear Thomas,

WITHOUT PREJUDICE

For claims against Singapore Police Force, we have instruction not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>
Sent: Wednesday, 12 February 2020 2:11 PM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Finalize Reort of SJN7008R

Dear Steve,

Attach finalize report and supplementary list for your reference. 03 working days.

Thank you

Regards

thomas



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF19019189/Evf3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333			Date : 27-12-2019	
ATTN : HAFIZUL FARHAN RAHMAT			Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 295M	Veh. Inspected	SJN 7008R	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/106	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN RAHMAT	Assign Date	30/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MR053REH604596236	Colour	SILVER	
Odometer	10734	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	5 mm	
L/H Front Tyre	205/55 R16	DUNLOP	5 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	5 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2019	Inspection Date	31/10/2019	
Survey held at	2 PANDAN CRESCENT / LEVEL 4			
Repairer	BORNEO MOTORS (S) PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 7008R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	COVER, FR BUMPER, L (SN)	BROKEN	531.10	531.10
1	SUPPORT, FR BUMPER S (SN)	NOT NECESSARY	68.20	-
1	SUPPORT, FR BUMPER S (SN)	NOT NECESSARY	68.20	-
2	CLIP (SN)	NECESSARY	5.00	5.00
1	REINFORCEMENT, FR (SN)	NOT NECESSARY	399.50	-
1	GRILLE, RADIATOR, LW (SN)	NOT NECESSARY	169.60	-
1	SUPPORT SUB-ASSY, HO (SN)	BENT	164.90	164.90
1	A/C CONDENSER ASSY, (SN)	NOT NECESSARY	1,801.70	-
1	LED FOG LAMP (SN)	CUT	387.80	387.80
1	GRILLE ASSY, RADIATOR (SN)	NOT NECESSARY	712.10	-
			4,408.10	1,118.80
LABOUR				
	SUPPLY REGN PLATE (PO#) (FRT WITH CASING).		68.00	68.00
	RESET AND REPROGRAMME ECU.		180.00	180.00
	REMOVE AIR CON COMPONENTS TO REGAS AND REPLACE NEW PARTS.	NOT NECESSARY	360.00	-
	REMOVE AND REFOCUS HEADLAMP.		180.00	180.00
	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, FRT SUPPORT PANEL AND AFFECTED PORTION OF CAR.		2,160.00	720.00
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		1,770.00	885.00
	LABOUR FOR PLATINUM SHINEPRO & SHINE. (ADDITIONAL)		91.59	91.59
			-	-
			-	-
			-	-
			4,809.59	2,124.59
GRAND TOTAL			9,217.69	3,243.39

Report Ref No. CS/SPF19019189/Evf3e2



RECOMMENDED COST OF REPAIRS			3,243.39
-----------------------------	--	--	----------

Report Ref No. CS/SPF19019189/Evf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.