

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305344836

Date : 2. Nov. 2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SH 9710M

Date of Accident: 28. Oct. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA PC7990R

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,409.83

(b) Labour Charges \$1,130.00

Total for Part-By-Part Repair Cost \$2,539.83

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____


Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kalvin

Date : 4/11/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 02.11.2019
Time: 13:08:15
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305344836
REGN NO : SH 9710H
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 30.08.2017
DATE/TIME IN : 28.10.2019 19:05
ACCIDENT DATE : 28.10.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0002	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0003	04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10
0004	04-01-0302-2286-G	PRIG4 COVER REAR BUMPER-T	1	82.70	25.00	62.02
0005	09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1	135.70		135.70
0006	04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1	47.00	25.00	35.25
0007	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67
0008	04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67
0009	28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1	30.00		30.00
0010	28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1	40.00		40.00
0011	28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1	30.00		30.00

SUB-TOTAL : 1,409.81

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 02.11.2019

Time: 13:08:15

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305344836
REGN NO : SH 9710H
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 30.08.2017
DATE/TIME IN : 28.10.2019 19:05
ACCIDENT DATE : 28.10.2019

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB	PANEL BEATING			480.00		
0001 23-502	SPRAYPAINT ON AFFECTED AREA			600.00		
0002 17-01	WIRING CHARGE			20.00		
0003 L	REMOVE/REFIX REVERSE SENSOR			30.00		

SUB-TOTAL : 1,130.00

TOTAL : 2,539.81

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

REPAIR ESTIMATE

VEHICLE NO: SH 9710H

29/10/2019 14:02

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER <i>X repair</i>			\$ 1,126.60
REAR TRUNK LID COVER TRIM BOARD <i>X see</i>			\$ 254.40
REAR TRUNK LID GLASS (BLACK COLOR) <i>X see</i>			\$ 733.50
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>X repair</i>			\$ 889.70
REAR TRUNK LID LOGO (PRIUS) <i>- see</i>			\$ 52.90
REAR TRUNK LID LOGO (HYBRID) <i>- see</i>			\$ 52.90
REAR TRUNK LID LOGO (TOYOTA STAR) <i>- see</i>			\$ 47.00
REAR BUMPER <i>- see</i>			\$ 458.60
REAR BUMPER RE-INFORCEMENT <i>✓ Bond</i>			\$ 318.80
REAR BUMPER UNDER COVER <i>- see</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>X see</i>			\$ 112.70
REAR BUMPER TOWING COVER <i>- cut</i>			\$ 82.70
REAR BUMPER CLIPS <i>X see</i>			\$ 22.00
REAR END PANEL <i>X repair</i>			\$ 602.10
REAR END PANEL GARNISH <i>X see</i>			\$ 165.80
REAR WINDSCREEN GLASS WITH MOULDING <i>X</i>	<i>84K</i>		\$ 1,778.30
SUB TOTAL			\$ 7,250.60
LESS 25%			\$ 1,812.65
DISCOUNTED TOTAL			\$ 5,437.95
REAR NO. PLATE WITH TRIM COVER <i>X see</i>			\$ 100.00
REAR TRUNK LID APPS STICKER <i>- see</i>			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>- see</i>			\$ 60.00
REAR BUMPER REVERSE SENSOR <i>- see</i>			\$ 135.70
REAR BUMPER RUBBER MAT <i>X (Metal)</i>			\$ 50.00
REAR WINDSCREEN SEALANT <i>X</i>			\$ 46.00
			\$ 431.70
LABOUR CHARGE			
Panel Beating			\$ 480
Spray Painting Charge			\$ 850.00
Wiring Charge			\$ 750.00
Tuff Kote			\$ 50.00
Remove/Refix Reverse Sensor			\$ 50.00
TOWING FEE			\$ 80.00
TOTAL LABOUR			\$ 60.00
ESTIMATE TOTAL			\$ 1,780.00
			\$ 7,649.65

Larry Ng

• Part
 • Third party
 • No illegal modification
 • Supplementary item(s)
 is subject to final approval from insurance company

Acknowledged by Repairer
 Signature: _____
 Date: 29/10/19

Kohin (11/11)
29/10/19
30/10/19
PIP
Before Post pld.

NETT
 NETT
 NETT
 NETT
 NETT
 NETT

600
 20
 30
 X

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.