

INS. CASE OWNER:

CC 6 / CTI1901

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$

Is driver the owner?

S/N 9257A

MULHAMAD SUHAIMI BIN MOKRYAHDEN

HP:

D.O.A:

22/10/19

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

SWM90W50N

DMPCLSW3D3N50L900

HYUNDAI

PIE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

S/D 2492K

INSRS:
WSP:
Tel:
Liability:
RMKS:lll
broINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	04/11/19 - VIC
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☒
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice	☒
	LTA / GIA:	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒
PRELIMINARY ADVICE	Date/Time: 06/11/19	Sent By: VIC
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: Hs	\$S 3,800.00 (5 days) Reduction: 59 %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 17/10/20	Confirm with: ADDLINE
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.:	Email ☒ Call ☐
Repair Cost: (w/gon)	\$S 4,066.00	If NO or B 28, Ass. Lia:
Loss of Rental (LOR):	\$S - (days)	COI RENE-ENDED TP
Loss of Use (LOU):	\$S 700.00 (\$100 x 7 days)	
Loss of Income (LOI):	\$S - (\$ x days)	
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LO ☐ [Tick only one]	
GIA/LTA Search	\$S 36.45	
Medical:	\$S -	1) Claim status: Normal/Reject/Private Settle
Disbursement:	\$S - (e.g. Tow/ Independent)	2) Report Format:
Legal Cost	\$S -	3) Survey fee: \$400.00
Total:	\$S 4,802.45	Global Sum \$S: -
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$S 4,802.45	Name 1: LBS BROTHERS AUTOMOTIVE PTE LTD
Payee 2: (Strike if N.A.)	\$S -	Name 2: -
Payee 3: (Strike if N.A.)	\$S -	Name 3: -

COPY SENT
17/10/20

ASS. REC. BY:

Ref:

MCIWS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SYD 2492K

Yr Regn:

3 of

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Toyota Camry

C.C.

1998

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

279353

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR 053BK 4107025087

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / TOYO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/10/19

D.O.I.

30/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LYA 15156 car uncl 13-3-2023
L/g d 3,800.00
CRED: 45,675.74 (59%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weld end (\$

Report Form(s):

Lump Sum / L&L:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM19D205025
Our ref: CC6/CTI19019191/Uhb3

Date: 06.11.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJD 2492K

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30.10.2019 at the premises of M/s LEE BROTHERS AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	9,475.74
Revised Estimate Amount	: S\$	4,783.28
"Check" Items Amount	: S\$	-
Market Value	: S\$	24,000.00
LTA Reimbursement Value	: S\$	15,156.00
Nett Value	: S\$	8,844.00

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum



camry

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼



Home » Used Cars » CarQuotz Singapore » Toyota Camry 2.4A (COE till 03/2023)

Toyota Camry 2.4A (COE till 03/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$25,998

Depreciation ⓘ \$7,770 /yr

Reg Date 06-Mar-2008
(3yrs 4mths 2days COE left)

Mileage N.A.

Manufactured ⓘ 2007

Road Tax ⓘ \$1,802 /yr

Transmission Auto

Dereg Value ⓘ \$15,053 as of today (change)

OMV ⓘ \$23,643

COE ⓘ \$22,499

ARF ⓘ \$26,008

Engine Cap 2,362 cc

Power 123.0 kW (164 bhp)

Curb Weight ⓘ 1,500 kg

No. of Owners ⓘ 3

Type of Vehicle Luxury Sedan

Features

Smooth 2.4L 4 Cylinder DOHC VVTI Engine Producing 164Bhp, 224NM Of Torque, 5 Speed Automatic Transmission, ABS, SRS Airbags. View specs of the Toyota Camry (2006-2012)

Accessories

Factory Fitted Audio System, Retractable Side Mirrors With Indicators, Electric Leather Seats, Reverse Sensors, Foot Brakes, Start Stop Button.

Description

Drive With Assurance! 1 Year Warranty On Major Engine & Gearbox Problems! Genuine And Transparent! Bank/In House 100% Full Loan Monthly \$743, All Our Quality Consignment Cars Are Fully Done Up & Selling At The Most Reasonable Price With A Peace Of Mind! 100% Non-Private Hire Car. STA Inspection Welcome! Fully Refurbished! No Repair Needed! View To Believe! Daily 9AM To 9PM, Visit Us Today!

Categor

COI Compare

https://www.sgcarmart.com/used_cars/info.php?ID=857860&DL=3382


Location Map

Shortlist

Compare

Report Error

More Actions

Seller Information

Company	CarQuotz Sin » dealer's priceli » 227 vehs sold
Address	1 Kaki Bukit Roa Search cars near
Location	Enterprise One
Contact Person(s)	Mr Koh Jason Koh Kelvin Tan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 393J

Vehicle Details

Vehicle No.: SJD2492K
Vehicle to be Exported: No
Intended Deregistration Date: 31 Oct 2019
Vehicle Make: TOYOTA
Vehicle Model: CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour: Beige
Manufacturing Year: 2008
Engine No.: 1AZE088031
Chassis No.: MR053BK4107025087
Maximum Power Output: 108.0 kW (144 bhp)
Open Market Value: \$26,830.00
Original Registration Date: 14 Mar 2008
First Registration Date: 14 Mar 2008
Transfer Count: 1
Actual ARF Paid: \$29,513.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 13 Mar 2023
COE Category: E - Open Category
COE Period(Years): 5
PQP Paid: \$22,499.00
COE Rebate Amount: \$15,156.00
Total Rebate Amount: \$15,156.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 31 Oct 2019

OK

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

SJN9257A

Not Attached
Lian

2/5 3800

30/10/19

5 day

Toh photo APC

ESTIMATE

DATE : 30.10.2019
VEHICLE NO : SJD2492K
MAKE/MODEL : TOYOTA CAMRY
ACC DATE : 22.10.2019

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	SS	SS
1	1 REAR BOOT <i>1 X</i>	843.90	843.90 <i>X</i>
2	2 REAR BOOT HINGE RH/LH <i>1 X</i>	154.10	308.20 <i>X</i>
3	1 REAR BOOT RUBBER <i>Two</i>	231.20	231.20 <i>✓</i>
4	1 REAR BOOT LOCK <i>Two</i>	371.40	371.40 <i>✓</i>
5	1 REAR BOOT LOCK CATCH <i>1 X</i>	42.70	42.70 <i>X</i>
6	1 REAR BOOT INNER TRIM <i>1 X</i>	380.40	380.40 <i>X</i>
7	1 REAR BOOT EMBLEM LOGO <i>one</i>	58.50	58.50 <i>✓</i>
8	1 REAR BOOT EMBLEM CAMRY <i>one</i>	54.10	54.10 <i>✓</i>
9	1 REAR BOOT EMBLEM 2.0 <i>one</i>	42.60	42.60 <i>✓</i>
10	1 REAR BOOT NUMBER PLATE GARNISH <i>1 X</i>	109.45	109.45 <i>X</i>
11	2 REAR BOOT REFLECTOR RH/LH <i>1 X</i>	395.10	790.20 <i>X</i>
12	2 REAR TAILLAMP RH/LH <i>missed 1 PC</i>	474.10	948.20 <i>1 PC</i>
13	1 REAR BUMPER <i>205</i>	532.50	532.50 <i>✓</i>
14	2 REAR BUMPER REFLECTOR RH/LH <i>1 X</i>	86.55	173.10 <i>X</i>
15	2 REAR BUMPER HOLDER RH/LH <i>missed 1 PC</i>	65.10	130.20 <i>1 PC</i>
16	1 REAR BUMPER REINFORCEMENT <i>20</i>	407.10	407.10 <i>✓</i>
17	2 REAR BUMPER SIDE HOLDER RH/LH <i>1 X</i>	131.20	262.40 <i>X</i>
18	2 REAR BUMPER SIDE RETAINER RH/LH <i>3rd</i>	141.40	282.80 <i>✓</i>
19	1 REAR END PANEL <i>20</i>	689.60	689.60 <i>✓</i>
20	1 REAR END PANEL INNER MEMBER <i>1 X</i>	315.00	315.00 <i>X</i>
21	1 REAR END PANEL GARNISH <i>Two</i>	395.60	395.60 <i>✓</i>
22	1 REAR SPARE TYRE PANEL <i>1 X</i>	680.60	680.60 <i>X</i>
23	1 REAR SPARE TYRE CARDBOARD <i>Two</i>	333.10	333.10 <i>✓</i>
24	2 REAR FENDER INNER TRIM RH/LH <i>1 X</i>	392.40	784.80 <i>X</i>
			9,167.65
LESS 25%			2,291.91
			6,875.74

SPECIAL NETTS ITEM

1	1 REAR BUMPER CLIPS <i>one 40</i>	45.00	45.00 <i>40 S.N</i>
2	1 REAR INNER TRIM CLIPS <i>1 X</i>	45.00	45.00 <i>X</i>
3	1 REAR REVERSE SENSOR <i>should 200</i>	280.00	280.00 <i>200 S.N</i>
			370.00

9-3937.70

252
P-2983.27
S.N- 240.00
L- 1590.00
478307

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR	UNIT PRICE	AMOUNT
QTY	SS	SS
<u>LABOUR CHARGES :</u>		
1		1,000.00 600
	TO KNOCK OUT DENT, CUT/WELD REAR END PANEL AND REPLACE ACCIDENT PARTS	
2	TO SPRAY PAINTING ON ACCIDENT PORTION	800.00 ✓
3	TO CHECK WIRING	40.00 20
4	TO REMOVE, REFIX REAR CUSHION AND INNER TRIM	180.00 60
5	TO REMOVE, REPLACE REVERSE SENSOR	120.00 50
6	TO TUFF KOTE	90.00 60
TOTAL:		2,230.00
		1590

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 9,475.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price is subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No litigation/claim(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Shu Pei (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 1 November 2019 9:14 AM
To: Jeffrey Tay; Shu Pei (LKKAUTO); Vic (LKKAUTO)
Subject: RE: OUR REF: SNM19D205025-SJN9257A-CBS- Accident Involving SJN9257A (OI : CTI - TBA) and SJD2492K (TP : LKK REF - CC6/CTI19019191/Uhb3) on 22.10.2019
Attachments: insured report.PDF

Dear Sir,

Please find GIA report of insured.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road
#16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Shu Pei (LKKAUTO) [<mailto:shupeil@lkkauto.com>]
Sent: Thursday, October 31, 2019 4:34 PM
To: Claims Dept of CTI
Cc: Alfred Toh; Vic (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SJN9257A (OI : CTI - TBA) and SJD2492K (TP : LKK REF - CC6/CTI19019191/Uhb3) on 22.10.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SJD 2492K at M/s Lee Brothers Automotive Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:
- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2360.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI19019191/Uha3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 18-02-2020	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 9257A	Veh. Inspected	SJD 2492K	
Policy No.	DMPCSN3033501900	Coverage (\$)	0.00	
Claim No.	SNM19D205025	Excess (\$)	0.00	
Assign From		Assign Date	30/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053BK4107025087	Colour	BEIGE	
Odometer	279353	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2019	Inspection Date	30/10/2019	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 2492K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	TO REPAIR SEE LABOUR	843.90	-
2	REAR BOOT HINGE RH/LH @\$154.10	NOT NECESSARY	308.20	-
1	REAR BOOT RUBBER	TWISTED	231.20	231.20
1	REAR BOOT LOCK	TWISTED	371.40	371.40
1	REAR BOOT LOCK CATCH	NOT NECESSARY	42.70	-
1	REAR BOOT INNER TRIM	NOT NECESSARY	380.40	-
1	REAR BOOT EMBLEM LOGO	NECESSARY	58.50	58.50
1	REAR BOOT EMBLEM CAMRY	NECESSARY	54.10	54.10
1	REAR BOOT EMBLEM 2.0	NECESSARY	42.60	42.60
1	REAR BOOT NUMBER PLATE GARNISH	NOT NECESSARY	109.45	-
2	REAR BOOT REFLECTOR RH/LH @\$395.10	NOT NECESSARY	790.20	-
2	REAR TAILLAMP RH/LH @\$474.10	N/S CRACKED	948.20	474.10
1	REAR BUMPER	DISTORTED	532.50	532.50
2	REAR BUMPER REFLECTOR RH/LH @\$86.55	NOT NECESSARY	173.10	-
2	REAR BUMPER HOLDER RH/LH @\$65.10	N/S BENT	130.20	65.10
1	REAR BUMPER REINFORCEMENT	DENTED	407.10	407.10
2	REAR BUMPER SIDE HOLDER RH/LH @\$131.20	NOT NECESSARY	262.40	-
2	REAR BUMPER SIDE RETAINER RH/LH @\$141.40	BENT	282.80	282.80
1	REAR END PANEL	DENTED	689.60	689.60
1	REAR END PANEL INNER MEMBER	TO REPAIR SEE LABOUR	315.00	-
1	REAR END PANEL GARNISH	TWISTED	395.60	395.60
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	680.60	-
1	REAR SPARE TYRE CARDBOARD	TORN	333.10	333.10
2	REAR FENDER INNER TRIM RH/LH @\$392.40	NOT NECESSARY	784.80	-
	LESS 25% DISCOUNT		-2,291.91	-984.43
			6,875.74	2,953.27
SPECIAL NETT ITEMS				
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	40.00

Report Ref No. CC6/CTI19019191/Uha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR INNER TRIM CLIPS (SN)	NOT NECESSARY	45.00	-
1	REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			370.00	240.00
	LABOUR			
	TO KNOCK OUT DENT,CUT/WELD REAR END PANEL AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOT,REAR END PANEL INNER MEMBER AND REAR SPARE TYRE PANEL.		1,000.00	600.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		800.00	800.00
	TO CHECK WIRING.		40.00	20.00
	TO REMOVE,REFIX REAR CUSHION AND INNER TRIM.		180.00	60.00
	TO REMOVE,REPLACE REVERSE SENSOR.		120.00	50.00
	TO TUFF KOTE.		90.00	60.00
			2,230.00	1,590.00
GRAND TOTAL			9,475.74	4,783.27

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00
---	--	--	-----------------

Report Ref No. CC6/CTI19019191/Uha3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.