

21/03/2011

ASS. REC. BY:

REF: (S) MSG1901203 / DS f3 | 112  
Special Instructions:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Crystal Lu of MSG Date/Time: 30.10.19 5.01p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 84934 Insured: SLT 6790

at Workshop no/s: Sun Hock Motor Tel: 65425119

of AME Autopoint #01-05/06

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 30.10.19  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>1/2p</sup> H.O.D. Enforcement:

Date/Time: 30.10.19 5.21p.m Person Contacted: Lynn Vehicle: IN/OUT



## Summer Lee (LKK Auto)

---

**From:** Crystal Lee <crystal\_lee@sg.msig-asia.com>  
**Sent:** Wednesday, 30 October, 2019 5:01 PM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Ong Zi Hui  
**Subject:** Survey Request - Manual Assigned  
**Attachments:** 30102019154350.pdf

### Accident involving veh no: SHC 8493Y & SLT 679U (Grab) on 30.10.19

#### Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,  
Crystal Lee  
Admin Officer, Claims Services (In-House Survey)  
D: +65 6594 2535 | F: +65 6643 1349 | [crystal\\_lee@sg.msig-asia.com](mailto:crystal_lee@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Helene Phua  
**Sent:** Wednesday, 30 October, 2019 4:40 PM  
**To:** Crystal Lee <crystal\_lee@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>  
**Subject:** FW: Accident involving veh no: SHC 8493Y & SLT 679U (Grab) on 30.10.19

*Have a great week ahead!*

Helene Phua  
Admin Assistant, Claims Services  
D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)





A Member of **MS&AD** INSURANCE GROUP

**From:** Helene Phua  
**Sent:** Wednesday, 30 October, 2019 4:39 PM  
**To:** 'Chunni Motor' <[chunnimotor@gmail.com](mailto:chunnimotor@gmail.com)>  
**Cc:** Winnie Chua <[pingping\\_chua@sg.msig-asia.com](mailto:pingping_chua@sg.msig-asia.com)>  
**Subject:** RE: Accident involving veh no: SHC 8493Y & SLT 679U (Grab) on 30.10.19

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

*Have a great week ahead!*

**Helene Phua**  
Admin Assistant, Claims Services  
D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



A Member of **MS&AD** INSURANCE GROUP

**From:** Chunni Motor [<mailto:chunnimotor@gmail.com>]  
**Sent:** Wednesday, 30 October, 2019 4:23 PM  
**To:** Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)>  
**Cc:** Winnie Chua <[pingping\\_chua@sg.msig-asia.com](mailto:pingping_chua@sg.msig-asia.com)>  
**Subject:** Re: Accident involving veh no: SHC 8493Y & SLT 679U (Grab) on 30.10.19

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir,

We appoint LKK Auto Consultants P/L

Thank you

Regards,

Chunni Motor Work P/L

On Wed, Oct 30, 2019 at 4:14 PM Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)> wrote:

Hi,

We refer to your email dated 30/10/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Chow Bo Xiong
2) Kenneth Kong	7) Siew Meng Hui
3) Marcus Chua	8) Daniel Chan
4) Ng You Han	9) Victor Png
5) Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

(a) \*Fast lane settlement is not applicable for cases that liability is in dispute\*

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | [helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Chunn Motor [mailto:[chunnimotor@gmail.com](mailto:chunnimotor@gmail.com)]

**Sent:** Wednesday, 30 October, 2019 4:02 PM

**To:** Motor Survey <[motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)>

**Cc:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>; Helene Phua <[helene\\_phua@sg.msig-asia.com](mailto:helene_phua@sg.msig-asia.com)>

**Subject:** Accident involving veh no: SHC 8493Y & SLT 679U on 30.10.19

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

**Kindly survey at AMK Autopoint, Soon Hock Motor,#01-05/06.**

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

MCD819143644 / ComfortDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 30/10/2019 14:02  
 SUBMITTED BY: Janet Lim Seng Gek

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	30/10/2019 14:02
Date Of Accident	30/10/2019 08:30
Exact Location Of Accident	BOON LAY TWDS CORPORATION RD.
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8493Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

#### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

#### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

#### Driver

Name of Driver	LEE ENG GUAN
NRIC No	S0209819J
Date Of Birth	10/11/1954
Occupation	OUTDOOR
Date Of Driving Pass	02/02/1972
Driving Experience	47 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92733887
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 572 CHOA CHU KANG STREET 52 #09-268
Post Code	680572
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Vehicle	-
Insurance Company of Driver's Own Vehicle	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER ATTACHED \* TYPE OF ACCIDENT :- HEAD TO SIDE

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLT679U
Vehicle Make/Model/Colour	MAZDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KAMARUDIN BIN YAHYA
NRIC/Passport Number	S0028364I
Contact Number	96692941
Address	
Postcode	
Insurance Company Name	

Nature of Damage

FRONT RH

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

*Kymack*  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 30.10.2019  
@ 12:00hrs

*Lisa Diong*  
\_\_\_\_\_  
Reporting Centre Personnet's Signature  
Name:  
NRIC/FIN No.:



**CHUNNI MOTOR WORK PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 8493Y

DATE : 30.10.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

*ml/c*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>disbored / monkey cable</i>			\$ 544.50 ✓
	Front Bumper Sponge <i>new</i>			\$ 99.20 X
	Front Bumper Reinforcement <i>new</i>			\$ 402.10 X
	Front Bumper Grille (LH) <i>new</i>			\$ 41.60 X
	Front Bumper Bracket Top (LH) <i>new</i>			\$ 22.40 X
	Front Bumper Bracket (LH) <i>new</i>			\$ 24.60 X
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40 ✓
	Headlamp (LH) <i>monkey broken</i>			\$ 1,388.00 ✓
	Front Fender (LH) <i>BT</i>			\$ 566.30 ✓
	Front Fender Shield (LH) <i>disbored / torn</i>			\$ 174.90 ✓
	Front Fender Retainer <i>new</i>			\$ 24.60 X
	Front Wheel Rim (LH) <i>disbored</i>			\$ 325.30 ✓
	Front Wheel Hub Cap (LH) <i>new</i>			\$ 107.10 ✓
	Front Wheel Bearing <i>2 done</i>			\$ 540.50 ✓
	Front Shock Absorber (Assy) (LH) <i>disbored</i>			\$ 342.20 ✓
	Front Shock Absorber Mounting (LH) <i>new</i>			\$ 108.80 X
	Front Drive Shaft (LH) <i>new</i>			\$ 1,030.80 X
	Rack & Pinion Assy <i>new</i>			\$ 969.60 X
	STG Tie End <i>disbored</i>			\$ 62.60 ✓
	Stabilizer Bar <i>new</i>			\$ 252.30 X
	Stabilizer Bar Bush (LH) <i>new</i>			\$ 16.40 X
	Stabilizer Bar Link <i>new</i>			\$ 61.10 X
	Stabilizer Bracket <i>new</i>			\$ 24.00 X
	Front Suspension Lower Arm (LH) <i>disbored</i>			\$ 529.30 ✓
	Knuckle Arm (LH) <i>disbored</i>			\$ 552.00 ✓
	<b>SUB TOTAL</b>			\$ 9,117.60
	<b>LESS 20%</b>			\$ 1,823.52
	<b>DISCOUNTED TOTAL</b>			\$ 7,294.08
	Front Tyre (LH) <i>new</i>			\$ 216.00 <b>Nett X</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 1,200.00 <i>500/-</i>
	Spray Painting Charge			\$ 500.00 <i>400/-</i>
	Wiring Charge			\$ 50.00 <i>30/-</i>
	Tuff Kote			\$ 50.00 <i>30/-</i>
	Towing Charge			\$ 50.00 <i>20/-</i>
	Remove/Refix Undercarriage (FRD)			\$ 200.00 <i>150/-</i>
	FRT Wheel Alignment			\$ 120.00 <i>60/-</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00 <i>150/-</i>
	Re-set Frt ABS System			\$ 200.00 <i>150/-</i>
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	<b>TOTAL LABOUR</b>		<i>1320.00</i>	\$ 3,000.00
	<b>ESTIMATE TOTAL</b>			\$ 10,510.08

*6040.10*  
*4832.08*

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_

*31/10/19 @ 09:15 hrs*  
*NA Auctum*  
*2/30/19 6 days*

*LKK Auto*

*11620.48*

**REPAIR ESTIMATE\***

VEHICLE NO : SHC 8493Y (Supplementary)

DATE : 31.10.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (RH) mounting crack			S 1,388.00
	SUB TOTAL			S 1,388.00
	LESS 20%			S 277.60
	DISCOUNTED TOTAL			S 1,110.40

*Man* 31/10/19  
*DKK Auto*



main estimate 6152.08  
 Supp 1110.40  


---

 7262.48  
 L/s 5800/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME  
ADDRESS

Home Tel.:  
VIN:  
Registration: SHC 8493 Y  
Technician:  
Mileage: 707393  
Time Printed 31.10.19 9:51 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°51'		-3°00' 3°00'
4°18'		-0°19' 5°41'
2°07'		-1°30' 1°30'
16°14'		
15°23'		

Front : Right

Actual	BEFORE	Specified Range
-0°36'		-3°00' 3°00'
4°08'		-0°19' 5°41'
0°02'		-1°30' 1°30'
15°43'		
15°07'		

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front

	Actual	BEFORE	Specified Range
Cross Camber	-0°15'		-3°00' 3°00'
Cross Caster	0°10'		-3°00' 3°00'
Cross SAI	0°31'		-3°00' 3°00'
Total Toe	2°09'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-2°34'		-3°30' 2°30'
-0°15'		-1°30' 1°30'

Rear : Right

Actual	BEFORE	Specified Range
-2°38'		-3°30' 2°30'
0°07'		-1°30' 1°30'

Camber  
Toe

Rear

	Actual	BEFORE	Specified Range
Cross Camber	0°03'		-3°00' 3°00'
Total Toe	-0°08'		-3°00' 3°00'
Thrust Angle	-0°11'		-3°00' 3°00'

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19019203/DSF3N2

Date: 27/11/2019

**REFERENCE**

<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	29114756
<b>Claimant Vehicle No :</b>	SHC8493Y	<b>Insured Vehicle No :</b>	SLT679U
<b>Date of Loss:</b>	30/10/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	610137

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	SHC8493Y	<b>Engine No:</b>	D4DFDU564936
<b>Make &amp; Model:</b>	HYUNDAI I40, 1.7 D (A)	<b>Chassis No:</b>	KMHLB41UMGU080697
<b>Reg. Date:</b>	03/12/2015 (Man. Year: 2015)	<b>Odometer:</b>	707392 km
<b>Colour:</b>	Blue		
<b>Engine Capacity:</b>	1685 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
<b>Handbrake (Serviceable):</b>	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	205/60R16	<b>Rear Tyre Size:</b>	205/60R16
<b>Front Left Side:</b>	West Lake 5 mm	<b>Rear Left Side:</b>	West Lake 5 mm
<b>Front Right Side:</b>	West Lake 5 mm	<b>Rear Right Side:</b>	West Lake 5 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,620.48	5,942.48	2,678.00	31.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,320.00	1,680.00	56.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,620.48</b>	<b>7,262.48</b>	<b>4,358.00</b>	<b>37.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,800.00</b>		
	(S\$) 11,620.48	5,800.00	5,820.48	50.09
<b>+ GST 7.00/7.00% (S\$)</b>	813.43	406.00	407.43	50.09
<b>Nett Amount (S\$)</b>	<b>12,433.91</b>	<b>6,206.00</b>	<b>6,227.91</b>	<b>50.09</b>

**INSPECTION**

<b>Date of Assignment:</b>	31/10/2019	
<b>Date Inspected:</b>	31/10/2019	<b>Inspected At:</b>
		CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047

**Estimated Period of Repair:** 6.0 days**Adjuster:** BRYAN TANI**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC8493Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Distorted/Mounting Cracked	544.50 FL	*544.50 FL
2	1		*FRONT BUMPER SPONGE	Not Necessary	99.20 FL	*-FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	402.10 FL	*-FL
4	1		*FRONT BUMPER GRILLE (LH)	Not Necessary	41.60 FL	*-FL
5	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	22.40 FL	*-FL
6	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	24.60 FL	*-FL
7	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
8	1		*HEADLAMP (LH)	Mounting Broken	1,388.00 FL	*1,388.00 FL
9	1		*FRONT FENDER (LH)	Bent	566.30 FL	*566.30 FL
10	1		*FRONT FENDER SHIELD (LH)	Deformed/Torn	174.90 FL	*174.90 FL
11	1		*FRONT FENDER RETAINER	Not Necessary	24.60 FL	*-FL
12	1		*FRONT WHEEL RIM (LH)	Distorted	325.30 FL	*325.30 FL
13	1		*FRONT WHEEL HUB CAP (LH)	Cut	107.10 FL	*107.10 FL
14	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
15	1		*FRONT SHOCK ABSORBER (ASSY)(LH)	Distorted	342.20 FL	*342.20 FL
16	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	108.80 FL	*-FL
17	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,030.80 FL	*-FL
18	1		*RACK & PINION ASSY	Not Necessary	969.60 FL	*-FL
19	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
20	1		*STABILIZER BAR	Not Necessary	252.30 FL	*-FL
21	1		*STABILIZER BAR BUSH (LH)	Not Necessary	16.40 FL	*-FL
22	1		*STABILIZER BAR LINK	Not Necessary	61.10 FL	*-FL
23	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	*-FL
24	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	529.30 FL	*529.30 FL
25	1		*KNUCKLE ARM (LH)	Distorted	552.00 FL	*552.00 FL
26	1		*HEADLAMP (RH)	Mounting Cracked	1,388.00 FL	*1,388.00 FL
27	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>10,721.60</b>	<b>7,428.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>2,101.12</b>	<b>1,485.62</b>
<b>Total Parts (S\$)</b>	<b>8,620.48</b>	<b>5,942.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,200.00	500.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	30.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
10	RE-SET FRT ABS SYSTEM }	New	200.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,000.00</b>	<b>1,320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >