

ASS. REC. BY:

REF:

CS/C7219019204/AVF312

Special Instruction:

SUBJECT:

Adrian

ASSIGNMENT (Office)

From (Person):

Tan Kah Leng

of

C72

Date/Time:

30.10.19 5.01p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 198B

Insured:

SDM 9155 L

at Workshop m/s

Premium

Tel:

67689911

of

55. Ubi road 1

Policy No:

Claim No:

SNM 1912205089

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29.10.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

30.10.19 5.01p.m

Person Contacted:

Kelvin

Vehicle:

IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLR 198B - X

SDM 9155L -

CCA/ASMRCC7316/11/2019 DOA-23/10/2019

31/10/19

Final fig

\$2640

Confirmed by email

(Ref 3037, 5319)

REG. REC. BY:

REF: A19

ASSIGNMENT

From: Date 3.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 198B

at Workshop m/s Premium

of 55 ubi road 1

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: 10a.m owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

typ

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLR198B. Yr Regn: 2019, Jan.

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q2 C.C. 999

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 24842 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZ2G A8KA 001634

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16.

R: 215/60R16.

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. D.O.I. 31/10/19

Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP chng.

RECEIVED 02 JAN 2020

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 3/12 - typist

Prepared By: MERIMEN

Lump Sum / H.P.: 2642.50

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

S + RE. \$

Photos

Other

TOTAL

220

Summer Lee (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 30 October, 2019 5:01 PM
To: Claims; assignments
Cc: Irene Tay
Subject: RE: OUR REF: SNM19D205088-SDM9155L-THP- ACCIDENT BETWEEN SLR 198 B AND YOUR INSURED SDM 9155 L ON 28/10/2019

WITHOUT PREJUDICE

Dear Kelvin,

We refer to your email dated 30.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, October 30, 2019 4:56 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>; claims@premiumauto.com.sg
Subject: RE: OUR REF: SNM19D205088-SDM9155L-THP- ACCIDENT BETWEEN SLR 198 B AND YOUR INSURED SDM 9155 L ON 28/10/2019

Dear Kah Leong,

Noted, We agree LKK for the survey, do let us know who will come for survey.

Best Regards,
Kelvin Khoo
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

D. +65 6768 9911 P. +65 9871 9902

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Tan Kah Leong [<mailto:khleong.Tan@sg.cntaiping.com>]

Sent: Wednesday, 30 October, 2019 10:30 AM

To: Claims <claims@premiumauto.com.sg>

Cc: Irene Tay <irene.tay@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D205088-SDM9155L-THP- ACCIDENT BETWEEN SLR 198 B AND YOUR INSURED SDM 9155 L ON 28/10/2019

Without Prejudice

Dear Syafiq,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards,

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 F: (65) 6222 1033

W: www.sg.chinataiping.com FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Wednesday, October 30, 2019 10:27 AM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Claims <claims@premiumauto.com.sg>

Subject: OUR REF: SNM19D205088-SDM9155L-THP- ACCIDENT BETWEEN SLR 198 B AND YOUR INSURED SDM 9155 L ON 28/10/2019

Dear Kah Leong,

Please assist to conduct PRS for SLR198B.

Note Officer in charge – Irene Tay 6389192.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or distribution of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Tuesday, 29 October, 2019 4:13 PM

To: Claims Dept of CTI <claims_dept@sg.cntaiping.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: ACCIDENT BETWEEN SLR 198 B AND YOUR INSURED SDM 9155 L ON 28/10/2019

Dear all,

Kindly assist in the liability clearance for above mentioned case. We propose for a 100% direct settlement in our client's favour

Please advise who is the officer in-charge we shall liaise with. To avoid dispute during finalisation, we propose for LOU/R at \$60/100 per day.

Attached is the GIA report for your reference and we will send you the estimate once it is ready.

Kindly arrange survey on 31/10/2019, 11AM. Owner waiting.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachments, may be confidential and may also be privileged.
If you have received this email in error, please do not reply, forward, copy, or otherwise use the information contained herein.
Please delete this email and its contents or any attachment to any other person. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

• **Veron Chen (LKKAuto)**

From: Veron Chen (LKKAuto)
Sent: Tuesday, 31 December 2019 12:15 PM
To: jiajee.yap@premiumauto.com.sg; Admin A; CS A Team; SUR
Cc: 'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLR198B - TP CHINA - SURVEYED 31 OCT 19

Dear Jia Yee,

WITHOUT PREJUDICE

Confirm repair cost of \$2642.00 before GST @ 3 days.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiajee.yap@premiumauto.com.sg <jiajee.yap@premiumauto.com.sg>
Sent: Tuesday, 31 December 2019 11:37 AM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLR198B - TP CHINA - SURVEYED 31 OCT 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$2642.00 @ 3 days.

Your early closure is well appreciated.

Thanks & Best Regard

JiaYee Yap

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiajee.yap@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 17291

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1298/2019/NS
Date	:	30-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no. : **SDM 9155 L**

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name	:	Mr Poh Bok Seng
Address	:	Blk 163 Tampines Street 12 #11-253 Singapore 521163
Telephone	:	(HP) + 65 98301903
Type of Claim	:	Third Party Claim
Policy No.	:	1900002533
Vehicle No	:	SLR 198 B
Model Code	:	Audi Q2 1.0 TFSI S TRONIC
Model / Year	:	Jan-19
Engine No	:	CHZ a93127
Chassis No	:	WAUZZZGA8KA001634
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Oct-19
Place of Accident	:	Lor 6 Toa Payoh

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 198 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 800 ✓	
3	To respray rear bumper.	\$ 1,000.00 800 ✓	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,672.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 198 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	REMARKS
1	REAR BUMPER <i>Repair</i>	\$ 1,074.00	+
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 70.00	+
3	REAR BUMPER SPOILER - LH <i>Delivered</i>	\$ 259.00	✓ 259
4	REAR BUMPER TOWING EYE COVER <i>new</i>	\$ 39.00	+
5	REAR LIGHT REFLECTOR - LH/RH <i>new</i>	\$ 54.00	+
6	REAR BUMPER CARRIER	\$ 501.00	+
7	REAR BUMPER HOLDING STRAP - LH/RH	\$ 24.00	+
8	REAR PARKING AID SENSOR - INNER	2 \$ 462.00	+
9	REAR PARKING AID SEAL RING	4 \$ 12.00	+
10	REAR WHEEL COVER - LH / RH <i>new</i>	2 \$ 312.00	✓ 311
11	SUNDRIES <i>new</i>	\$ 200.00	?

TOTAL SPARE PARTS CHARGES

: \$ 3,007.00

TOTAL LABOUR CHARGES

\$ 2,672.00

GRAND TOTAL

\$ 5,679.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 31/10/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 17291

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1298/2019/NS
Date : 30-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no. : **SDM 9155 L**

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Hi Adrian,

3 days - ok - Jy - 31 Dec 2019

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr Poh Bok Seng
Address : Blk 163 Tampines Street 12
#11-253
Singapore 521163
Telephone : (HP) + 65 98301903
Type of Claim : Third Party Claim
Policy No. : 1900002533
Vehicle No : **SLR 198 B**
Model Code : Audi Q2 1.0 TFSI S TRONIC
Model / Year : Jan-19
Engine No : CHZ a93127
Chassis No : WAUZZZGA8KA001634
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Oct-19
Place of Accident : Lor 6 Toa Payoh

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 198 B

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00	\$ 280.00
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$	1,200.00	\$ 800.00
3	To respray rear bumper.	\$	1,000.00	\$ 800.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,672.00</u>	<u>\$ 2,072.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 198 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	REMARKS
1	REAR BUMPER	\$ 1,074.00	
2	REAR BUMPER FIXING PARTS	\$ 70.00	
3	REAR BUMPER SPOILER - LH	\$ 259.00	\$ 259.00
4	REAR BUMPER TOWING EYE COVER	\$ 39.00	
5	REAR LIGHT REFLECTOR - LH/RH	\$ 54.00	
6	REAR BUMPER CARRIER	\$ 501.00	
7	REAR BUMPER HOLDING STRAP - LH/RH	\$ 24.00	
8	REAR PARKING AID SENSOR - INNER	2 \$ 462.00	
9	REAR PARKING AID SEAL RING	4 \$ 12.00	
10	REAR WHEEL COVER - LH / RH	2 \$ 312.00	\$ 311.00
11	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES		\$ 3,007.00	\$ 570.00
TOTAL LABOUR CHARGES		\$ 2,672.00	\$ 2,072.00
GRAND TOTAL		\$ 5,679.00	\$ 2,642.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019204/AVF3N2
Date: 06/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30482719000
Claimant Vehicle No :	SLR198B	Insured Vehicle No :	SDM9155L
Date of Loss:	28/10/2019	Nature of Claim:	TP
		Claim No:	SNM19D205088C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR198B	Engine No:	CHZA93127
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Chassis No:	WAUZZZGA8KA001634
Reg. Date:	10/01/2019 (Man. Year: 2018)	Odometer:	24942 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,007.00	570.00	2,437.00	81.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,672.00	2,072.00	600.00	22.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,679.00	2,642.00	3,037.00	53.48
+ GST 7.00/7.00% (S\$)	397.53	184.94	212.59	53.48
Nett Amount (S\$)	6,076.53	2,826.94	3,249.59	53.48

INSPECTION

Date of Assignment:	30/10/2019		
Date Inspected:	31/10/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Jan 2020)

Parts: N/A AUDI Q2 999cc 1.0 TFSI S TRONIC (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR198B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,074.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	70.00 FS	*- FS
3	1		*REAR BUMPER SPOILER-LH	Deformed	259.00 FS	*259.00 FS
4	1		*REAR BUMPER TOWING EYE COVER	Not Necessary	39.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR-LH/RH	Not Necessary	54.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	501.00 FS	*- FS
7	2		*REAR BUMPER HOLDING STRAP-LH/RH	Not Necessary	24.00 FS	*- FS
8	2		*REAR PARKING AID SENSOR-INNER	Not Necessary	462.00 FS	*- FS
9	4		*REAR PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
10	2		*REAR WHEEL COVER-LH/RH	Necessary	312.00 FS	*311.00 FS
11	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					3,007.00	570.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	800.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	800.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,672.00	2,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >