

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

LI PENG

29/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

T.P. AXA.

Xiao Tony.

MR053BK4107036526.

Accident date: 25/10/2019

Estimated repair cost for vehicle no: SJL8378B TOYOTA CAMRY 2.0 A '08

CHASSIS: MR053BK4107036526

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Buckled</i>		\$980.20 ✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$131.75	\$263.50 ✓
3	1	Rear Boot Lid Emblem Logo ?		\$76.10 ✓
4	1	Rear Boot Lid Camry Logo <i>new</i>		\$74.00 ✓
5	1	Rear Boot Lid 2.0 Logo		\$53.20 ✓
6	1	Rear Boot Lid Centre Chrome Moulding <i>3 new</i>		\$297.20 x
7	4	Rear Boot Lid Centre Chrome Moulding Clip	\$6.50	\$26.00 x
8	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00 x
9	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$83.10	\$166.20 x
10	2	Rear Boot Lid Side Reflector <i>RH cracked</i>	\$387.00	\$774.00 387. ✓
11	1	Rear Boot Lid Inner Lock Assy <i>new</i>		\$429.30 ✓
12	1	Rear Boot Lid Inner Rubber <i>new</i>		\$182.90 ✓
13	1	Rear Boot Lid Inner Trim Board <i>new</i>		\$561.20 x
14	8	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00 x
15	2	Rear Tail Lamp <i>RH cracked</i>	\$474.85	\$949.70 474.85 ✓
16	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 16 ✓
17	2	Rear Tail Lamp Lower Bracket <i>new</i>	\$43.75	\$87.50 x
18	1	Rear R/H Tail Lamp Panel <i>Repair</i>		\$193.20 x
19	1	Rear Bumper <i>Dehine</i>		\$546.20 ✓
20	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 30 ✓
21	2	Rear Bumper Side Retainer <i>new</i>	\$131.35	\$262.70 ✓
22	1	Rear R/H Bumper Side Reflector <i>new</i>		\$83.10 ✓
23	1	Rear Bumper Reinforcement <i>Best</i>		\$531.50 361 ✓
24	1	Rear R/H Bumper Reinforcement Bracket <i>new</i>		\$121.10 x
25	1	Rear R/H Bumper Mud Shield <i>new</i>		\$93.10 x
26	1	Rear Bumper Reverse Sensor <i>new</i>		\$380.00 200/100 ✓
27	1	Rear R/H Fender <i>Buckled Repair</i>		\$981.45 x

28	1	Rear R/H Fender Air Duct		\$112.00	x
29	1	Rear R/H Fender Inner Trim Board	New	\$444.30	x
30	8	Rear R/H Fender Inner Trim Board Clip	\$6.50	\$52.00	x
31	1	Rear End Panel	Dented	\$659.25	✓
32	1	Rear End Panel Top Garnish	Deformed	\$381.40	✓
33	1	Rear Spare Tyre Panel	By Buckard	\$708.10	✓
34	1	Rear Spare Tyre Panel Top Cover	ton	\$281.90	✓
35	1	Rear Spare Tyre Panel Top Foam	New	\$268.20	x
36	1	Rear Spare Tyre Panel & End Panel Sealant	Nec	\$450.00	250/sv
37	1	Rear R/H Spare Tyre Side Panel	By	\$182.30	x
38	1	Rear Exhaust	Best	(\$981.85)	891
39	1	Rear Exhaust Chrome Pipe	New	\$160.00	x
40	2	Rear Exhaust Mounting	New	\$65.90	\$131.80 x
41	1	Rear Center Exhaust	Best	\$1,081.20	989
42	1	Rear Windscreen Moulding	New	\$181.25	x
43	1	Rear Windscreen Seal	Nec	\$95.00	60/sv

7684.30 S.N. 450

5763.22

Subtotal :- \$14,469.90

Labour charges

To remove & refit cushion

~~\$280.00~~ 200

To remove & refit reverse sensor

~~\$100.00~~ 60

To remove & refit rear windscreen

~~\$120.00~~ x

Gum

~~\$50.00~~ x

To remove & refit rear exhaust

~~\$280.00~~ 200

To check wiring

~~\$100.00~~ 30

Towing fee

3150

~~\$100.00~~ 60

Tuff kote

~~\$150.00~~ 100

Panel beating

~~\$1,800.00~~ 1400

Spray painting

~~\$1,800.00~~ 1100

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian King
L/S 29/10/19

11 Days

total 9363.22

L/S 7.5K

Subtotal :- \$4,780.00

Total :- \$19,249.90

7.5K