

ASSIGNMENT

Surveyor: STEVE DOI: 02/12/2019 Date / Time: 30.10.19
 Registered in Merimen: 30.10.19

Pre-assign / CCU / FTE

Insured Vehicle No.: SLW 5261S Claim No.: 3989393155SG
 Name of Insured: SOW CHIANG HWA Policy No.: 1800016302
 Insured Tel No.: _____ HP: +65-97908391 Make / Model: MAZDA6 2.0L
 Excess Sec II : \$\$ D.O.A: 30/10/2019 07:00 Place of Accident: JUNCTION OF CCK AVE 3/CCK CENTRAL
 Is driver the owner? (YES / NO) Nature of Accident: _____
 If NO, Driver Name / Age: _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No.: _____ (V/L: YES / NO) Insured Liability: % Final ? Yes / No

SMD 9802T

INSRS: WSP: Performance INSRS: WSP: _____ INSRS: WSP: _____ INSRS: WSP: _____
 Tel: _____ Tel: _____ Tel: _____ Tel: _____
 Liability: _____ Liability: _____ Liability: _____ Liability: _____
 RMKS: _____ RMKS: _____ RMKS: _____ RMKS: _____

Date/ Time		STAGE	DATE / PIC
02/11/19	- PIR REVIEWED. OI KATH- ENDED TP. - EMAIL CAPSULEY CLERK - OI VIDEO UPLOADED BY AG IN WETWORK	Non-Reporting Itr (1st): Non-Reporting Itr (2nd): Non-Reporting Itr (Final): Notification Itr (if non-pickup): Call OI:	
09/12/19	- SEND LETTER IN BULK TO OI- - MINUTED - TP LOB IN ORIGINAL	After call Itr to OI:	09/12/19-JIC
15/01/2020	- UPLOADED HANDS IN IN WETWORK	Documentation Check List: Handler Typist	
22/01/2020	- AG APPROVED WARRANT - SEND ACCEPTANCE BULK TO TP - ALL DOCS IN ORDER - TO CLERK	Notification Itr (if non-pickup): After call Itr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA: Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: <u>R/P</u>	SS <u>7,015.90</u> (<u>5</u> days) Reduction: <u>48</u> %		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: <u>22/01/20</u>	Confirm with: <u>CAROLINE</u>	Email ☒ Call ☐
Final Liability: % <u>100</u> (Assessed) BOLA S/N No.: <u>27</u>			If NO or B 28, Ass. Lia: <u>(OI KATH- ENDED TP)</u>
Repair Cost: (w/acc) SS <u>7,504.87</u>			
Loss of Rental (LOR): SS <u>400.00</u> (<u>4</u> days) X <u>4100</u>			
Loss of Use (LOU): SS <u>-</u> (<u>5</u> x days)			
Loss of Income (LOI): SS <u>-</u> (<u>5</u> x days)			
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]			
GIA/LTA Search SS <u>2.00</u>			
Medical: SS <u>-</u>			
Disbursement: SS <u>-</u> (e.g. Tow/ Independent)			
Legal Cost SS <u>-</u>			
Total: SS <u>7,906.87</u>		Global Sum SS: <u>-</u>	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: SS <u>7,906.87</u>	Name 1: <u>PERFORMANCE MOTORS LIMITED</u>		
Payee 2: (Strike if N.A.) SS <u>-</u>	Name 2: <u>-</u>		
Payee 3: (Strike if N.A.) SS <u>-</u>	Name 3: <u>-</u>		

BMW Dealer

Performance Motors Limited

A Siam Derby Motors Company
Co. Reg. No. 197402559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2265300)

111, Alexandra Road
Siam Derby Performance Centre
Singapore 119941
Fax: 64747770

280, Kembangan Avenue Road
East Coast Centre
Singapore 438180
Fax: 63449773

111, Alexandra Road
Siam Derby Business Centre
Singapore 119944
Fax: 64786601 (AfterSales)
64786624 (Motors&S)

Change Due
to 25/11 → 25/11/2019
meeting bumper
and repair
rental



GST REG. NO : M2 - 0020081 - X

30 OCT 2019

ESTIMATE

Estimate No. : b1 53261
Date Estimated : 30/10/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Boey Yew Khuan
Blk 130 Choa Chu Kang Avenue 1
#04-36

Singapore 680130

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD9802T	WBA2D920605L53289	14/09/2018	216i GT	0

DESCRIPTION

VALUE

Replace rear boot lid, rear bumper include remove attachment etc include knock on accident damage

1700 2,550.00

Spray painting rear bumper and rear boot lid

1730 1,923.00

To replace rear windscreen glass.

574.00

To conduct water leak tests

75.00

To supply and install rear windscreen solar film.

? 531.00 X

To check electrical wiring systems and lightings at the rear section for proper function

150 177.00

To carry out body cavity preservation (Per panel).

100 118.00

Sundries

80 / ? 150.00

Total Labour 1: 6,098.00

DESCRIPTION

QTY

PRIC

VALUE

BOOTLID

1 1,204.35 1,204.35

RR BUMPER LH SIDE GUIDE X N/A

1 61.35 61.35

RR BUMPER RH SIDE GUIDE X N/A

1 61.35 61.35

REAR BUMPER CARRIER X N/A

1 458.10 458.10

SUPPORT X N/A

1 45.30 45.30

RR BUMPER LH INNER SIDE GUIDE X N/A

1 67.55 67.55

RR BUMPER RH INNER SIDE GUIDE X N/A

1 67.55 67.55

LEFT PROTECT X N/A

1 11.20 11.20

RIGHT PROTECT X N/A

1 11.20 11.20

REAR BUMPER PANEL PRIMED (PDC) DO

1 1,045.45 1,045.45

SET MOUNTS PDC SENSOR REAR X N/A

1 60.35 60.35

REAR BUMPER TOWING FLAP EYE PRIMED X N/A

1 42.85 42.85

STRIKER BOOT LID X N/A

1 59.50 59.50

1212-35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2251248)

117, Alexandra Road
Sime Darby Performance Centre
Singapore 119944
Fax: 64747772

260, Kembangan Avenue Road
East Coast Centre
Singapore 435185
Fax: 63449772

115, Alexandra Road
Sime Darby Business Centre
Singapore 119944
Fax: 64796011 (AfterSales)
64796024 (Motocars)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53261
Date Estimated : 30/10/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD9802T	WBA2D920605L53289	14/09/2018	2161 GT	0

DESCRIPTION	QTY	PRIC	VALUE
LOCK TRUNK LID <i>X NAI</i>	1	193.80	193.80
ACTUATION UNIT <i>X NAI</i>	1	601.30	601.30
SPINDLE DRIVE <i>X NAI</i>	2	353.90	707.80
REAR WINDOW <i>X NAI</i>	1	654.35	654.35
HOOK AND LOOP FASTENER <i>X NAI</i>	4	2.85	11.40
BOOTLID SEALING <i>X NAI</i>	1	143.00	143.00
DECOUPLING RING PDC TORQUE CONVERTER <i>X NAI</i>	4	5.05	20.20
ULTRASONIC SENSOR ATLANTIKGRAU(WC09) <i>X NAI</i>	4	380.65	1,522.60
(DG) CLEANER R1 (100ML) <i>NAI</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>NAI</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>NAI</i>	1	27.85	27.85

Total Parts : 7,367.65

+ SUPP

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 2/12/19, 11:30 am Excess S\$ _____

Surveyor's Name SPR (LKK) Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ P.M. Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend _____

WHL Nipl
P/P
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- No display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

Labour 1	:	6,098.00
Parts	:	7,367.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	942.60
Grand Total	:	14,408.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

13,497.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-000081-1



Supplementary

Estimate No. : **b1 53261**
Date Estimated : **30/10/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Boey Yew Khuan
Blk 130 Choa Chu Kang Avenue 1
#04-36

Singapore 680130

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD9802T	WBA2D920605L53289	14/09/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT / <i>REC</i>	1.00	2.00		2.00
# BUMP STOP / <i>REC</i>	3.75	8.00		30.00

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	32.00
Total Labour & Parts :	32.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-003081-X

VIC



Final Report

Estimate No. : b1 53261
Date Estimated : 30/10/2019
Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -
Boey Yew Khuan
Blk 130 Choa Chu Kang Avenue 1
#04-36

Singapore 680130

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD9802T	WBA2D920605L53289	14/09/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, bootlid including remove attachments to facilitate repairs.	1,700.00		1,700.00 ✓
To respray rear bumper and bootlid.	1,730.00		1,730.00 ✓
To remove and install rear windscreen glass to facilitate repairs.	574.00		574.00 ✓
To conduct water leak tests.	75.00		75.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00 ✓
To carry out body cavity preservation. (Per panel).	100.00		100.00 ✓
Sundries.	80.00		80.00 ✓


DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,210.35	1.00		1,210.35 ✓
# EXPANDING NUT	1.00	2.00		2.00 ✓
REAR BUMPER PANEL PRIMED (PDC)	1,045.45	1.00		1,045.45 ✓
# BUMP STOP	3.75	8.00		30.00 ✓
(DG) CLEANER R1 (100ML)	26.15	1.00		26.15 ✓
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10 ✓
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,409.00
Total Parts :	2,604.90
Total Labour & Parts :	7,013.90 ✓
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,013.90
GST @7%:	490.97
Grand Total :	7,504.87

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD18V10349 /VPC2 /R00										
Form	MX1										
Date of Issue	24-SEP-2018										
1.Index Mark and Registration No. of Vehicle:	SMD9802T										
2.Chassis number of Vehicle:	WBA2D920605L53289										
3.Name of Policyholder:	BOEY YEW KHUAN										
4.Effective date of Commencement of Insurance for the purposes of the Act:	14-SEP-2018 00:00 AM										
5.Date of Expiry of Insurance:	13-SEP-2020 23:59 PM										
6.Persons or Classes of Persons entitled to drive*: A) The Policyholder. B) Any other person who is driving on the Policyholder's order or with his permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.											
7.Limitations as to use*: Use only for social, domestic and pleasure purposes and for the Policyholder's business.											
8.The Policy does not cover: A) Use for hire or reward. B) Use for racing, pace-making, reliability trials or speed-testing. C) Use for the carriage of goods (other than samples) in connection with any trade or business. D) Use for any purpose in connection with the Motor Trade. *Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.											
I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).											
For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers  _____ Authorised Signature											
For Information only: <table style="width: 100%;"> <tr> <td style="width: 30%;">COVERAGE :</td> <td>Comprehensive, Unlimited Windscreen</td> </tr> <tr> <td>SUM INSURED:</td> <td>MARKET VALUE AT THE TIME OF LOSS</td> </tr> <tr> <td>EXCESS:</td> <td>Section I S\$800, Additional Excess For Young & Inexperienced Drivers: S\$2500, Windscreen Excess S\$0</td> </tr> <tr> <td>FINANCE COMPANY:</td> <td>DBS BANK LTD</td> </tr> <tr> <td>PRODUCER NAME:</td> <td>SD CONTEGO SERVICES</td> </tr> </table>		COVERAGE :	Comprehensive, Unlimited Windscreen	SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS	EXCESS:	Section I S\$800, Additional Excess For Young & Inexperienced Drivers: S\$2500, Windscreen Excess S\$0	FINANCE COMPANY:	DBS BANK LTD	PRODUCER NAME:	SD CONTEGO SERVICES
COVERAGE :	Comprehensive, Unlimited Windscreen										
SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS										
EXCESS:	Section I S\$800, Additional Excess For Young & Inexperienced Drivers: S\$2500, Windscreen Excess S\$0										
FINANCE COMPANY:	DBS BANK LTD										
PRODUCER NAME:	SD CONTEGO SERVICES										

PLMJ/PLMJ/10-OCT-18

S1_Cl_T1_T3_OE_Template2-Ver1,

10-OCT-18

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2019 Edit Reg		02 Dec 2019 00:00 Edit Adj Rpt	S\$7,013.90 Edit Estimates	S\$7,013.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	SOW CHIANG HWA, ID: S7304924E		
Main Claimant:	BOEY YEW KHUAN, ID: S8020034Z		
Vehicle Reg. No.:	SMD9802T	Date of Loss:	30/10/2019 07:00 - :59 [13 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3989393155SG	Policy/Cover Note No.:	1800016302 (Comprehensive)
Vehicle Reg. No. (Insured):	SLW5261S	Policy No. (Claimant):	SD18V10349
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 08/11/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
• AIG_SG_EXPRESS (22/01/2020): Alert - Adj Mandate Approved (S\$7906.87) - SMD9802T - Claim Handler: Chan, Kian ...			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SMD9802T (3989393155SG)
[SLW5261S]
TP
BOEY YEW KHUAN
Oct 30 2019 7:00AM
[SOW CHIANG HWA]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Video			1 per page v	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/10/19 11:33	OI VIDEO	Load MP4	
Letters/Correspondences			1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Assessment Reports			1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/01/20 09:32	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/12/19 16:56	General View	Load JPG ☒	
2	02/12/19 16:56	General View	Load JPG ☒	
3	02/12/19 16:56	General View	Load JPG ☒	
4	02/12/19 16:56	General View	Load JPG ☒	
5	02/12/19 16:56	General View	Load JPG ☒	
6	02/12/19 16:56	Odometer Reading	Load JPG ☒	
7	02/12/19 16:56	Chassis Number	Load JPG ☒	
8	02/12/19 16:56	General View	Load JPG ☒	
9	02/12/19 16:56	General View	Load JPG ☒	
10	02/12/19 16:56	General View	Load JPG ☒	
11	02/12/19 16:56	General View	Load JPG ☒	
12	02/12/19 16:56	General View	Load JPG ☒	
13	02/12/19 16:56	General View	Load JPG ☒	
14	02/12/19 16:56	General View	Load JPG ☒	
15	02/12/19 16:56	General View	Load JPG ☒	
16	02/12/19 16:56	General View	Load JPG ☒	
17	02/12/19 16:56	General View	Load JPG ☒	
18	02/12/19 16:56	General View	Load JPG ☒	
19	02/12/19 16:56	General View	Load JPG ☒	
20	02/12/19 16:56	General View	Load JPG ☒	
21	02/12/19 16:56	General View	Load JPG ☒	
22	02/12/19 16:56	General View	Load JPG ☒	
23	02/12/19 16:56	General View	Load JPG ☒	
24	02/12/19 16:56	General View	Load JPG ☒	
25	02/12/19 16:56	General View	Load JPG ☒	
26	02/12/19 16:56	General View	Load JPG ☒	
27	02/12/19 16:56	General View	Load JPG ☒	
28	02/12/19 16:56	General View	Load JPG ☒	
29	27/12/19 09:50	Reinspection Photo	Load JPG ☒	
30	27/12/19 09:50	Reinspection Photo	Load JPG ☒	
31	27/12/19 09:50	Reinspection Photo	Load JPG ☒	
Documentation			1 per page v	☒

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/10/19 18:33	TP ESTIMATE		Load PDF	
2	30/10/19 18:33	TP GIA REPORT		Load PDF	
3	05/12/19 12:18	TP ESTIMATE - MARKED		Load PDF	
4	09/12/19 16:35	EMAIL TO OI		Load PDF	
5	09/12/19 16:35	LETTER TO OI		Load PDF	
6	15/01/20 09:18	TP ESTIMATE - FINALIZED		Load PDF	
7	15/01/20 09:23	TP LOD		Load PDF	
8	22/01/20 11:13	EMAIL TO TP		Load PDF	
9	30/01/20 14:35	WORKSHOP INVOICE		Load PDF	
10	30/01/20 14:35	AUTHORISATION TO ACT FORM		Load PDF	
11	30/01/20 14:35	Release Voucher		Load PDF	
12	30/01/20 14:35	RENTAL RECEIPT		Load PDF	
13	30/01/20 14:35	GIA SEARCH		Load PDF	
14	30/01/20 14:35	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	31/10/19 11:32	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer (Note: Remarks are private unless you show it to other parties.)

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLW5261S (Insd veh)	Model:	BMW 216I 1.5 D GT LED (A)
	SMD9802T (TP veh)		
Date of Accident:	30/10/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	14,442.49
Final Repair Cost	:	\$	7,504.87
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	400.00 4 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,906.87
Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No- BOLA Scenario No:	
		27	
BOLA Liability: _____100____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 7,906.87
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

30 Jan

2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19019209/EHA3Q2

Date: 30/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800016302
Claimant
Vehicle No : SMD9802T **Insured Vehicle No :** SLW5261S
Date of Loss: 30/10/2019 **Nature of Claim:** TP **Claim No:** 3989393155SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD9802T
 Make & Model: BMW 216I, 1.5 D GT LED (A) Engine No: 31535269B38A15A
 Reg. Date: 14/09/2018 (Man. Year: 2018) Chassis No: WBA2D920605L53289
 Colour: Grey Odometer: 27193 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
 Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,549.65	2,684.90	4,864.75	64.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,948.00	4,329.00	1,619.00	27.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,497.65	7,013.90	6,483.75	48.04
+ GST 7.00/7.00% (S\$)	944.84	490.97	453.87	48.04
Nett Amount (S\$)	14,442.49	7,504.87	6,937.62	48.04
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,906.87		

INSPECTION

Date of Assignment: 02/12/2019
 Date Inspected: 02/12/2019 Inspected At: Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*BOOTLID	Dented	1,204.35 FS	*1,210.35 FS
3	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	61.35 FS	*- FS
4	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	61.35 FS	*- FS
5	1		*REAR BUMPER CARRIER	Not Necessary	458.10 FS	*- FS
6	1		*SUPPORT	Not Necessary	45.30 FS	*- FS
7	1		*RR BUMPER LH INNER SIDE GUIDE	Not Necessary	67.55 FS	*- FS
8	1		*RR BUMPER RH INNER SIDE GUIDE	Not Necessary	67.55 FS	*- FS
9	1		*LEFT PROTECT	Not Necessary	11.20 FS	*- FS
10	1		*RIGHT PROTEC	Not Necessary	11.20 FS	*- FS
11	1		*REAR BUMPER PANEL PRIMED (PDC)	Dented	1,045.45 FS	*1,045.45 FS
12	1		*SET MOUNTING PDC SENSOR REAR	Not Necessary	60.35 FS	*- FS
13	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Not Necessary	42.85 FS	*- FS
14	1		*STRIKER BOOTLID	Not Necessary	59.50 FS	*- FS
15	1		*LOCK TRUNK LID	Not Necessary	193.80 FS	*- FS
16	1		*ACTUATION UNIT	Not Necessary	601.30 FS	*- FS
17	1		*SPINDLE DRIVE	Not Necessary	707.80 FS	*- FS
18	1		*REAR WINDOW	Not Necessary	654.35 FS	*- FS
19	4		*HOCK AND LOOP FASTENER	Not Necessary	11.40 FS	*- FS
20	1		*BOOTLID SEALING	Not Necessary	143.00 FS	*- FS
21	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
22	4		*ULTRASONIC SENSOR ATLANTIKGRAU (WC09)	Not Necessary	1,522.60 FS	*- FS
23	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
24	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
25	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
26	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
27	8		*BUMPER STOP	Necessary	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					7,549.65	2,684.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BOOT LID REAR BUMPER INCLUDE REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DAMAGE	New	2,550.00	1,700.00
2	SPRAY PAINTING REAR BUMPER AND REAR BOOT LID	New	1,923.00	1,730.00
3	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
4	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
5	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (\$\$)			5,948.00	4,329.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >