

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



VIC

Final Report

Estimate No. : **b1 53261**
Date Estimated : **30/10/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Boey Yew Khuan
Blk 130 Choa Chu Kang Avenue 1
#04-36

Singapore 680130

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD9802T	WBA2D920605L53289	14/09/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, bootlid including remove attachments to facilitate repairs.	1,700.00		1,700.00 ✓
To respray rear bumper and bootlid.	1,730.00		1,730.00 ✓
To remove and install rear windscreen glass to facilitate repairs.	574.00		574.00 ✓
To conduct water leak tests.	75.00		75.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00 ✓
To carry out body cavity preservation. (Per panel).	100.00		100.00 ✓
Sundries.	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,210.35	1.00		1,210.35 ✓
# EXPANDING NUT	1.00	2.00		2.00 ✓
REAR BUMPER PANEL PRIMED (PDC)	1,045.45	1.00		1,045.45 ✓
# BUMP STOP	3.75	8.00		30.00 ✓
(DG) CLEANER R1 (100ML)	26.15	1.00		26.15 ✓
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10 ✓
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,409.00
Total Parts :	2,604.90
Total Labour & Parts :	7,013.90 ✓
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,013.90
GST @7%:	490.97
Grand Total :	7,504.87

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53261**
Date Estimated : **30/10/2019**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Boey Yew Khuan
Blk 130 Choa Chu Kang Avenue 1
#04-36

Singapore 680130

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD9802T	WBA2D920605L53289	14/09/2018	216i GT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT / <i>MC</i>	1.00	2.00		2.00
# BUMP STOP / <i>MC</i>	3.75	8.00		30.00

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	<u>32.00</u>
Total Labour & Parts :	<u>32.00</u>

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

Change Due
to 25/11 → 25/11/2019
mediary Guyco
and repair
rental



GST REG. NO : M2 - 0020081 - X

30 OCT 2019

E S T I M A T E

Estimate No. : b1 53261
Date Estimated : 30/10/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- **ESTIMATE REPAIR FOR -**
Boey Yew Khuan
Blk 130 Choa Chu Kang Avenue 1
#04-36
Singapore 680130

- **ACCOUNT - 40000**
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD9802T	WBA2D920605L53289	14/09/2018	216i GT	0

DESCRIPTION	VALUE
Replace rear boot lid, rear bumper include remove attachment etc include knock on accident damage	1700 2,550.00
Spray painting rear bumper and rear boot lid	1730 1,923.00
To replace rear windscreen glass.	574.00
To conduct water leak tests.	75.00
To supply and install rear windscreen solar film.	? 531.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries.	80 / ? 150.00

Total Labour 1: **6,098.00**

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,204.35	1,204.35
RR BUMPER LH SIDE GUIDE	1	61.35	61.35
RR BUMPER RH SIDE GUIDE	1	61.35	61.35
REAR BUMPER CARRIER	1	458.10	458.10
SUPPORT	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE	1	67.55	67.55
RR BUMPER RH INNER SIDE GUIDE	1	67.55	67.55
LEFT PROTECT	1	11.20	11.20
RIGHT PROTEC	1	11.20	11.20
REAR BUMPER PANEL PRIMED (PDC)	1	1,045.45	1,045.45
SET MOUNTS PDC SENSOR REAR	1	60.35	60.35
REAR BUMPER TOWING FLAP EYE PRIMED	1	42.85	42.85
STRIKER BOOT LID	1	59.50	59.50

1219.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53261
Date Estimated : 30/10/2019
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD9802T	WBA2D920605L53289	14/09/2018	216i GT	0

DESCRIPTION	QTY	PRIC	VALUE
LOCK TRUNK LID <i>X NAI</i>	1	193.80	193.80
ACTUATION UNIT <i>X NAI</i>	1	601.30	601.30
SPINDLE DRIVE <i>X NAI</i>	2	353.90	707.80
REAR WINDOW <i>X NAI</i>	1	654.35	654.35
HOOK AND LOOP FASTENER <i>X NAI</i>	4	2.85	11.40
BOOTLID SEALING <i>X NAI</i>	1	143.00	143.00
DECOUPLING RING PDC TORQUE CONVERTER <i>X NAI</i>	4	5.05	20.20
ULTRASONIC SENSOR ATLANTIKGRAU(WC09) <i>X NAI</i>	4	380.65	1,522.60
(DG) CLEANER R1 (100ML) <i>AK</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>AK</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>AK</i>	1	27.85	27.85

Total Parts : 7,367.65

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 21/12/19 11:30 am Excess S\$ _____

Surveyor's Name Steve (LKK) Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

W/L NAI
P/P
5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

Labour 1	:	6,098.00
Parts	:	7,367.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	942.60
Grand Total	:	14,408.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **