

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19019215/UPA3Q2

**Date:** 08/09/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
<b>Claimant Vehicle No :</b>	GBF4634P	<b>Insured Vehicle No :</b>	GBJ2633J
Date of Loss:	21/10/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001320

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBF4634P</b>		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30015097N
Reg. Date:	15/11/2016 (Man. Year: 2016)	Chassis No:	JN1SC2F24Z0859244
Colour:	White	Odometer:	70476 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/80 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,230.00	4,120.00	3,110.00	43.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	900.00	850.00	48.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,980.00</b>	<b>5,020.00</b>	<b>3,960.00</b>	<b>44.10</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,000.00</b>		
<b>(\$\$)</b>	8,980.00	4,000.00	4,980.00	55.46
<b>+ GST 7.00/7.00% (\$\$)</b>	628.60	280.00	348.60	55.46
<b>Nett Amount (\$\$)</b>	<b>9,608.60</b>	<b>4,280.00</b>	<b>5,328.60</b>	<b>55.46</b>
<b>+ Car Rental (3.0 x S\$120.00/day) (\$\$)</b>		360.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>4,647.45</b>		

### INSPECTION

Date of Assignment:	29/10/2019	
Date Inspected:	30/10/2019 Inspected At:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Dec 2019)	
<b>Parts:</b>	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF4634P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR POWER GATE	Bent / Cracked	4,500.00 FS	*4,000.00 FS
2	1		*REAR POWER GATE STICKER	Necessary	60.00 FS	*60.00 FS
3	1		*REAR POWER GATE BRACKET -RH	Serviceable	200.00 FS	*- FS
4	1		*REAR HYDRAULIC PUMP	Repair	1,800.00 FS	*- FS
5	4		*LTRS REAR HYDRAULIC PUMP OIL	Necessary	320.00 FS	*60.00 FS
6	1		*REAR DOOR SIDE MIRROR	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **7,230.00**      **4,120.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	650.00	500.00
2	SPRAY PAINTING	New	250.00	200.00
3	TO REMOVE & REPLACE HYDRAULIC PUMP	New	850.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>1,750.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >