

HSIAO TONG

not Authorized
1/5 @ 4000
3 day

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : India International Insurance

Estimate No: EST0001039

Date: 31 Oct 2019

Policy No:

Veh Reg No: **GBF4634P**

Make/Model: NISSAN CABSTAR 3.0

Chassis No: JN1SC2F24ZO859244

Engine No: ZD30015097N

Reg. Date: 15/11/2016

ATTN: Motor Claim Department
Your Ref No: GBF4634P NISSAN CABS
Claim Type: Third Party
Accident Date: 21/10/2019

Estimate Repair Cost to Vehicle No :GBF4634P

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Special Net				
1 Rear Power Gate <i>gentle</i>	4,500.00	1 PCS	4,500.00	4000 <i>s.w</i>
2 Rear Power Gate Sticker <i>new</i>	60.00	1 PCS	60.00	✓
3 Rear Power Gate Bracket - RH <i>new</i>	200.00	1 PCS	200.00	X
4 Rear Hydraulic Pump <i>refer to (a)</i>	1,800.00	1 PCS	1,800.00	X
5 Rear Hydraulic Pump Oil <i>new</i>	80.00	4 LTRS	320.00	60 <i>s.w</i>
6 Rear Door Side Mirror <i>new</i>	350.00	1 PCS	350.00	X
			7,230.00	7,230.00
Labour				
7 Panel Beating	650.00	1 PC	650.00	500
8 Spray Painting	250.00	1 PC	250.00	200
9 To Remove & Replace Hydraulic Pump	850.00	1 PCS	850.00	200
			1,750.00	1,750.00
			Total	S\$ 8,980.00

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND NINE HUNDRED EIGHTY ONLY

For FOCUS AUTO PTE LTD

to do

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE