

AIG INSURANCE

Vehicle number	SJU7276X
Make / Model	MITSUBISHI ATTRAGE
Chassis number	MMBSTA13AKH002775
Accident date	24/10/2019
Reference	1910-36

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER ✓ CRA	814.20 650.30 ✓
1	REAR BUMPER LOWER GARNISH X	437.00
2	REAR BUMPER BRACKET 2/1H only ✓ CRA R/H x (SVC)	201.80 87.30 ✓
2	REAR BUMPER RETAINER ✓ nec	69.00 55 ✓
2	REAR BUMPER LOWER GARNISH CHROME COVER X, SVC R/H 1/1H	276.00
1	END PANEL ✓ BT - photo ✓	807.30 425.50 ✓
1	END PANEL TOP GARNISH ✓ CRA	136.00 99.70 ✓
1	KEYLESS SENSOR ✓ CRA	172.50 114.40 ✓
1	END PANEL KEYLESS SENSOR SPEAKER X SVC	138.00
2	TAILLAMP 1/1H - CRA R/H ✓ CRA	662.40 552.60 ✓
2	TAILLAMP PANEL X CR (R)	192.00
2	TAILLAMP SEALER X SVC	72.00
1	BOOTLID ✓ BT	952.20 728.70 ✓
1	BOOTLID LOCK ✓ JM	247.20 189.80 ✓
1	BOOTLID LOCK STRIKER X SVC	24.00
1	BOOTLID CHROME OUTER GARNISH X SVC	365.70
1	BOOTLID WEATHERSTRIP ✓ CRA	170.20 128.70 ✓
1	BOOTLID EMBLEM - ATTRAGE ✓ nec	25.30 20 ✓
1	BOOTLID EMBLEM - C & C ✓ nec	41.00 28 ✓
1	BOOTLID EMBLEM - MIVEC ✓ nec	39.50 30 ✓
1	BOOTLID - LOGO ✓ nec	47.15 39 ✓
2	BOOTLID HINGE 1/1H - X (SVC) R/H (X SVC)	441.60
1	BOOTLID INNER TRIM X CR NN	172.50
1	SPARE TYRE TOP BOARD ✓ CRA	212.75 182.30 ✓
1	FLOOR PANEL X CR (R)	1041.90
2	REAR FENDER 1/1H - BT ✓ R/H - X (SVC) (R)	1662.90 920.50 ✓
2	REAR FENDER INNER TRIM 1/1H X R/H - X (SVC)	363.40
2	REAR FENDER AIR VENT 1/1H X (SVC) R/H - X (SVC)	187.40
1	REAR WINDSCREEN MOULDING ✓ nec	42.00 42 ✓
1	REAR EXHAUST SILENCER X (SVC)	656.65
1	REAR EXHAUST HEATSHIELD X (SVC)	284.00
2	REAR EXHASUT MOUNTING X (SVC)	67.20
2	MUD FLAP X (SVC)	96.00
1	REAR AIRDUCT W/ CR X SVC	134.40
1	REAR AIRDUCT COVER ✓ CRA	91.20 58.20 ✓
		11344.35
Less 20%		2268.87
Subtotal		9075.48
Balance C/F		9075.48

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	9075.48
1 SET	REAR BUMPER CLIP <i>✓ nec</i>	50.00 25
2 SET	REAR FENDER INNER TRIM CLIP <i>✓ nec</i>	120.00 40
1 SET	BOOTLID INNER TRIM CLIP <i>X NN</i>	60.00 X
1	REAR NUMBER PLATE <i>X (SVC)</i>	80.00 X
1	WINDSCREEN SEALANT <i>✓ nec</i>	50.00 30
1 BOT	BRAKE FULID <i>X NN</i>	60.00 X
1 SET	REVERSE SENSOR <i>✓ short</i>	500.00 200
1	REAR NUMBER PLATE GARNISH <i>X (SVC)</i>	60.00 X
1 SET	END PANEL TOP GARNISH CLIP <i>✓ nec</i>	60.00 27
	Subtotal	1040.00
	Balance C/F	10115.48
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	10115.48
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	120.00 30
4	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200.00 70
5	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30
9	REMOVE AND REFIT FUEL TANK	300.00 30
10	REMOVE AND REFIT REAR WINDSCREEN	150.00 100
11	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 X
12	REMOVE AND RENEW FLOOR INSULATOR	120.00 36
13	REMOVE AND RENEW REAR EXHAUST SILENCER	200.00 X
14	PANEL BEATING ON AFFECTED AREAS <i>6.5</i>	2400.00 1300
15	SPRAY PAINTING ON AFFECTED AREAS <i>6</i>	2400.00 1200
16	APPLY ANTI RUST ON AFFECTED AREAS	150.00 56
	Subtotal	6390.00
	Grand total	16505.48

✓ L/S report / P/LP report?
w/short Pro 2.5hr
8 Aug

H. ANN
8531483
6.35 pm
29/10/19

Resing with paint / Resing body part?
Have Ann @ Klu. Auto. car.

16,647.96

18,297.96#

AIG INSURANCE

Vehicle number	SJU7276X
Make / Model	MITSUBISHI ATTRAGE
Chassis number	MMBSTA13AKH002775
Accident date	24/10/2019
Reference	1910-36

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	REAR BUMPER LOWER GARNISH (AFTER MARKET/our Lip ✓ CR4	1200.00
2	REAR BUMPER LOWER GARINISH CHROME COVER AFTER MARK	450.00 X NN
	Subtotal	1650.00
	Grand total	1650.00

380.00 ✓

Resurvey
30/10/19
11-40 AM
wrong color part
work stop require
to L/S repair
without prejudice.

Parts - 4352.00

parts
less 20% 20%

3481.60

spe nett 695

labour 2840

7016.60

L/S less 20%

5613.28

Total

L/S At

\$5600 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: