

Surveyor: **KENNETH**

DOI: **ASSIGNMENT**
29/10/2019

Date / Time: **29.10.2019**

Registered in Merimen: **31.10.2019**

Pre-assign / CCU / FTE



Insured Vehicle No. : **SMG 4011B**
 Name of Insured : **LEE YANG**
 Insured Tel No. : _____ HP: **+65-81685795**
Excess Sec II :SS _____ D.O.A : **25/10/2019 10:30**
 Is driver the owner? (YES / NO) _____ Nature of Accident : _____

Claim No. : _____
 Policy No. : **1900003699**
 Make / Model : **MAZDA 3-1.5 DELUXE SKYACTIV (A)**
 Place of Accident : **AYE NEAR NUH**

If NO, Driver Name / Age : _____
 Driver Tel No. : _____ (V/L: YES / NO)

OI GIA REPORT: YES / NO : _____ TP GIA REPORT: YES / NO
 Insured Liability : % **Final ? Yes / No**

SME 2210S



INSRS:
WSP: **Massive Trading**
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/ Time	SME 2210S - X	SMG 4011B - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
06.11.19	Final vsp liability case		Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI	08/11/19
26.11.19	Final pass to typist to prepare report.		After call ltr to OI	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	<input type="checkbox"/>
			After call ltr to OI	<input checked="" type="checkbox"/>
			Authorisation To Act	<input checked="" type="checkbox"/>
			Release Voucher	<input checked="" type="checkbox"/>
			Final Repair Bill	<input checked="" type="checkbox"/>
			Car Rental Invoice	<input type="checkbox"/>
			Towing Invoice	<input type="checkbox"/>
			LTA / GIA :	<input type="checkbox"/>
			Medical Bill:	<input type="checkbox"/>
			PIR:	<input type="checkbox"/>
			Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
			LOD	<input checked="" type="checkbox"/>
			Payment Breakdown Form:	<input type="checkbox"/>
			Post-Repair Photos:	<input type="checkbox"/>
			Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: **WSC**

Repair Cost: **45** S\$15,000 (10 days) Reduction: **55** % Email Call

FINAL SETTLEMENT Date/Time: **30.11.20** Confirm with: **AN/MSH** Email Call

Final Liability: **100** (Agreed / Assessed) BOLA S/N No. : **2810** If NO or B 28, Ass. Lia : **100%**

Repair Cost: **SS15,000.00** 4 YRS CL CL 1951

Loss of Rental (LOR): **SS -** (days)
 Loss of Use (LOU): **SS 1,500.00** (500 x 3 days)
 Loss of Income (LOI): **SS -** (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: **SS -**
 Medical: **SS -**
 Disbursement: **SS -** (e.g. Tow/ Independent)
 Legal Cost: **SS -**

Total: **SS 16,500.00** **Global Sum S\$:**
FINAL PAYMENT Date/Time: **30.11.20** Confirm with: **AN/MSH** Email Call

Payee 1: **SS16,500.00** Name 1: **MASSIVE TRADING + AUTO**
 Payee 2: (Strike if N.A.) **SS** Name 2: _____
 Payee 3: (Strike if N.A.) **SS** Name 3: _____

Handwritten signature/initials

ASS. REC. BY:

REF: 1161

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s MARRIVE

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 859k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SME 22105 Yr Regn: 05, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon
Make: Volkswagen Sharan c.c 1984

Colour: Cory A/C: Insured / Std / Nil / NA

Sp. Reading: 159059 T/Radio: Insured / Std / Nil / NA

Eng/No: _____
C/No: WVW ZZZ 7N ZCVO38401

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PRT / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 25/10/11 D.O.I. 29/10/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

OLS M & NLS M

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to
GIA & EM not ready

45: +15,000 (RED: +20,684.42 58%)

Nt.V: +59,000

LTA: +43,858

NET: +15,142

Date/Time, File Pass to?

: Preil. Report

: Final Report

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportation: _____
S - RS. \$

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Fuel

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Massive Trading & Auto

Bik 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Ong Sio Kheong
31B West Coast Park
#06-33 Botannia
Singapore 127726

Not Authorized

Repair After Paint

10 days

Vehicle No : SME 2210 S
Make : Volkwagon Sharan 2.0
Year : 2012

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front bonnet		By \$1,480.70 ✓
1 pc	Front bonnet lock		L \$255.60 X
2 pcs	Front fender		By \$1,500.40 ✓
1 pc	Front o/s fender innershield	\$750.20	CM \$187.10 ✓
2 pcs	Front headlamp assy " LED "	By \$2,250.60	\$4,501.20 ✓
2 pcs	Front headlamp water nozzle motor	\$208.70	Z \$413.40 ✓
2 pcs	Front headlamp water nozzle bracket	\$155.10	O/I \$310.20 ✓
2 pcs	Front headlamp water nozzle outer cover	\$75.10	A/I \$150.20 ✓
2 pcs	Front support top side panel	\$207.10	By \$414.20 ✓
1 pc	Front radiator support panel - fiber		\$550.70 ✓
1 pc	Front radiator support panel garnish		\$215.60 ✓
1 pc	Front bumper		Balance \$1,350.70 ✓
1 pc	Front bumper reinforcement		By \$855.70 ✓
1 pc	Front bumper top beam		O/I \$185.30 ✓
2 pcs	Front bumper side retainer	\$65.10	O/I \$130.20 ✓
1 pc	Front bumper lower grille		Sm \$205.60 X
1 pc	Front bumper under cover		Sm \$167.20 X
1 pc	Front bumper tow cover		Sm \$45.80 X
2 pcs	Front bumper sensor	Shu \$255.70	\$511.40 ✓
1 pc	Front grille		CM \$505.80 ✓
1 pc	Front grille emblem		Mc \$105.60 ✓
1 pc	Air con condenser		Re \$1,850.10 X
1 pc	Turbo cooler		Sm \$1,850.10 X
1 pc	Radiator assy		Sm \$1,255.60 X
1 pc	Radiator fan assy		Sm \$1,050.10 X
1 pc	Rear tail-gate assy		By \$1,955.70 ✓
1 pc	Rear tail-gate inner lock		K \$189.10 X
1 pc	Rear tail-gate emblem " Logo "		Mc \$65.70 ✓
1 pc	Rear tail-gate emblem " sharan "		Mc \$60.10 ✓
1 pc	Rear tail-gate emblem " 2.0 Tsi "		Mc \$40.60 ✓

balance of \$22,359.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SME 2210 S

balance b/f \$22,359.70

- 1 pc Rear end panel ?
- 1 pc Rear bumper ✓
- 1 pc Rear bumper reinforcement ?
- 1 pc Rear bumper lower bumper ?
- 3 pcs Rear bumper sensor ?
- 2 pcs Rear bumper reflector ?
- 2 pcs Rear bumper side retainer ?
- 1 pc Rear windscreen moulding ✓
- 2 pcs Front shock absorber ?
- 2 pcs Front lower arm ?
- 2 pcs Front knuckle arm ?
- 2 pcs Front knuckle bearing ?
- 2 pcs Front hub assy ?

		\$750.10	X
	Bu	\$1,380.10	✓
	Bu	\$865.80	✓
	Bu	\$900.10	X
	Bu	\$255.70	X
	Bu	\$185.10	X
	Bu	\$65.20	X
	Bu	\$75.10	✓
Sm		\$750.10	X
Sm		\$687.20	X
By		\$625.10	✓
By		\$200.10	✓
By		\$660.10	✓
		<u>\$33,443.80</u>	
	Less 10%	\$3,344.38	
		<u>\$30,099.42</u>	

S Nett

- 2 pcs Front tyre rim ✓
- 1 pc Rear windscreen sealant ✓
- 1 pc Front no plate ✓
- 20 pcs Bumper clip ✓

\$600.00	Bu	\$1,200.00	✓
	Bu	\$40.00	✓
	Sm	\$40.00	X
\$3.00	Bu	\$60.00	✓
		<u>\$1,240.00</u>	

Labour Charges

- Remove/renew the above parts including knocking, welding & cutting.
- To putty & spray paint rear accident affected portion.
- Check/reconnect wiring.
- To spray anti rust on accident affected portion.
- Remove/renew front undercarriages
- Check and realign front wheel alignment
- Towing
- Remove/renew air con condenser & to top up gas element
- Remove/refit turbo cooler and to top up turbo oil

\$1,600.00	Pool	
\$1,600.00	1200	
\$45.00	401	
\$180.00	1201	
\$450.00	2001	
\$60.00	✓	
\$50.00	✓	
\$180.00	1001	
	Sm	\$180.00 X
Total		<u>\$35,684.42</u>

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Ong Sio Kheong
31B West Coast Park
#06-33 Botannia
Singapore 127726

Vehicle No : SME 2210 S
Make : Volkwagon Sharan 2.0
Year : 2012

Part - 19,675.98
Snett - 1,300.00
labour - 2,190.00
23,665.98
18,950.00
→ closed at \$15,000/-
Lup Sin

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front bonnet		\$1,480.70
1 pc	Front bonnet lock ?		\$255.60
2 pcs	Front fender		\$1,500.40
1 pc	Front o/s fender innershield ? photo	\$750.20	\$187.10
2 pcs	Front headlamp assy " LED "		\$4,501.20
2 pcs	Front headlamp water nozzle motor ? photo	\$2,250.60	\$413.40
2 pcs	Front headlamp water nozzle bracket ? photo	\$206.70	\$310.20
2 pcs	Front headlamp water nozzle outer cover	\$155.10	\$150.20
2 pcs	Front support top side panel	\$75.10	\$414.20
1 pc	Front radiator support panel - fiber ? photo	\$207.10	\$550.70
1 pc	Front radiator support panel garnish ? photo		\$215.60
1 pc	Front bumper		\$1,350.70
1 pc	Front bumper reinforcement ? photo		\$855.70
1 pc	Front bumper top beam		\$185.30
2 pcs	Front bumper side retainer		\$130.20
1 pc	Front bumper lower grille ? photo	\$65.10	\$205.60
1 pc	Front bumper under cover ? photo		\$167.20
1 pc	Front bumper tow cover		\$45.80
2 pcs	Front bumper sensor ? photo	\$255.70	\$511.40
1 pc	Front grille ? photo		\$505.80
1 pc	Front grille emblem ? photo		\$105.80
1 pc	Air con condenser ? photo		\$1,850.10
1 pc	Turbo cooler ?		\$1,850.10
1 pc	Radiator assy ?		\$1,255.60
1 pc	Radiator fan assy ?		\$1,050.10
1 pc	Rear tail-gate assy		\$1,955.70
1 pc	Rear tail-gate inner lock ?		\$189.10
1 pc	Rear tail-gate emblem " Logo "		\$65.70
1 pc	Rear tail-gate emblem " sharan "		\$60.10
1 pc	Rear tail-gate emblem " 2.0 Tsi "		\$40.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Play damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

balance c/f \$22,359.70 16,803.5

1 pc	Rear end panel ?
1 pc	Rear end panel
1 pc	Rear bumper
1 pc	Rear bumper reinforcement ? photo
1 pc	Rear bumper lower bumper ? photo
3 pcs	Rear bumper sensor ? photo
2 pcs	Rear bumper reflector ?
2 pcs	Rear bumper side retainer ?
1 pc	Rear windscreen moulding
2 pcs	Front shock absorber
2 pcs	Front lower arm ?
2 pcs	Front knuckle arm ? photo
2 pcs	Front knuckle bearing ? photo
2 pcs	Front hub assy ? photo

S Nett

2 pcs	Front tyre rim
1 pc	Rear windscreen sealant
1 pc	Front no plate
20 pcs	Bumper clip

Labour Charges

- Remove/renew the above parts including knocking, welding & cutting.
- To putty & spray paint rear accident affected portion.
- Check/reconnect wiring.
- To spray anti rust on accident affected portion.
- Remove/renew front undercarriages
- Check and realign front wheel alignment
- Towing
- Remove/renew air con condenser & to top up gas element
- Remove/refit turbo cooler and to top up turbo oil

		22,500.00 X
Bus		750.00 X
		1,380.10
		865.00
		900.10
\$255.70		767.10
\$185.10	Sm	370.20 X
\$65.20	Sm	130.40 X
	Sm	75.10
\$750.40		1,500.20 7X
\$667.20		1,374.40 7X
\$625.10		1,250.20 7-
\$200.10		400.20 7-
\$660.10		1,320.20 7-
		<u>\$33,443.80</u> >1,862.20
Less 10 %		<u>\$3,344.38</u> 2,186.20
		\$30,099.42 19,675.98

\$600.00	Ad	\$1,200.00	✓
	Sm	\$40.00	✓
	Sm	\$40.00	X
\$3.00	Sm	\$60.00	✓
		<u>\$1,240.00</u>	1300

		\$1,600.00	Pool
		\$1,600.00	1200
		\$45.00	401
		\$180.00	1201
		\$450.00	7 200
		\$50.00	✓
		\$50.00	✓
		\$180.00	7 120
		\$180.00	7 X
Total		<u>\$35,684.42</u>	>2690.0

IT'S NEVER TOO EARLY TO THINK ABOUT YOUR 2020 DRIVE

VISIT THE LEXUS SHOWCASE @ TAMPINES 1 MALL FROM 8-14 NOV



LEXUS
CELEBRATING
30

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Wish 1.8X CVT, May-2018 54000kms, White, \$75,000



1st Owner, New Tyres, Low Mileage 54000, Leather Seats, No Accident, White Color, Direct Owner StarAd



Browse by Category

Sort by Date Posted

20 results/page

2 vehicles

Volkswagen Sharan

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection:	Volkswagen Sharan	Any	Any	2011	Any	Any	Any	Available
	Volkswagen Sharan 2.0 TSI	\$46,000	\$13,390 /yr	04-Nov-2011	1,984 cc	107,500 km	Sedan	Available
Full Size MPV 100%. Well Maintained And In Pristine Condition, Full Serviced History Available. Auto Sliding Doors For Easy Access Needs, Spacious Leg Room For The 2nd And 3rd Seating Row. One Of The Best MPV.								
Posted: 31-Oct-2019 Tags: 2011 Volkswagen Sharan, 2011 volkswagen sharan, Volkswagen Sharan, volkswagen sharan, Volkswagen, Sharan, sharan, Used Volkswagen								
	Volkswagen Sharan 2.0A TSI	\$48,000	\$13,850 /yr	17-Nov-2011	1,984 cc	-	MPV	Available
Consignment Unit - Comprehensive Maintenance History Provided With Plenty Of Wear And Tear Replaced, Car Interior In Showroom Condition, All Panels And Trims In Excellent State. New Roof Lining, New Intake Manifold, New Injectors And More. Bank/in House Loan...								
Posted: 08-Oct-2019 Tags: 2011 Volkswagen Sharan, 2011 volkswagen sharan, Volkswagen Sharan, volkswagen sharan, Volkswagen, Sharan, sharan, Used Volkswagen								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & DPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Volkswagen Sharan, Volkswagen Sharan Singapore, used Volkswagen Sharan Singapore, used Volkswagen Sharan, used vehicles Singapore or even buy used Volkswagen Sharan Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	678G
Vehicle Details	
Vehicle No.:	SME22105
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Oct 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI AT 7N14H3
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	CCZ239274
Chassis No.:	WVWZZZ7N2CV038468
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$39,574.00
Original Registration Date:	28 May 2012
First Registration Date:	28 May 2012
Transfer Count:	2
Actual ARF Paid:	\$39,574.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 May 2022
PARF Rebate Amount:	\$23,744.00
Intended COE Rebate Details	
COE Expiry Date:	27 May 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$78,189.00
COE Rebate Amount:	\$20,114.00
Total Rebate Amount:	\$43,858.00

The information contained herein is correct as at 30 Oct 2019

OK

Attu: Eddie

0133 6660

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Ong Sio Kheong
31B West Coast Park
#06-33 Botannia
Singapore 127726

Not Authored
Max L/Sng \$10k
Return After Paint
10 days

Vehicle No : SME 2210 S
Make : Volkwagon Sharan 2.0
Year : 2012

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front bonnet ✓	<i>By</i>	\$1,480.70	✓
1 pc	Front bonnet lock ?	<i>L</i>	\$255.60	X
2 pcs	Front fender ✓	\$750.20	\$1,500.40	✓
1 pc	Front o/s fender innershield ?	<i>By</i>	\$187.10	✓
2 pcs	Front headlamp assy "LED" ✓	<i>cm</i>	\$187.10	✓
2 pcs	Front headlamp water nozzle motor ?	<i>Br</i>	\$2,250.60	\$4,501.20
2 pcs	Front headlamp water nozzle bracket ?		\$206.70	\$413.40
2 pcs	Front headlamp water nozzle bracket ?		\$155.10	\$310.20
2 pcs	Front headlamp water nozzle outer cover ✓		\$75.10	\$150.20
2 pcs	Front support top side panel ✓		\$207.10	\$414.20
1 pc	Front radiator support panel - fiber ?			\$550.70
1 pc	Front radiator support panel garnish ?			\$215.60
1 pc	Front bumper ✓	<i>Br/Com</i>	\$1,350.70	✓
1 pc	Front bumper reinforcement ?		\$855.70	?
1 pc	Front bumper top beam ?		\$185.30	?
2 pcs	Front bumper side retainer ✓	\$65.10	\$130.20	✓
1 pc	Front bumper lower grille ?	<i>D/I</i>	\$205.60	X
1 pc	Front bumper under cover ?	<i>Sm</i>	\$167.20	X
1 pc	Front bumper tow cover ✓	<i>Sm</i>	\$45.80	X
2 pcs	Front bumper sensor ?		\$255.70	\$511.40
1 pc	Front grille ?			\$505.80
1 pc	Front grille emblem ?			\$105.60
1 pc	Air con condenser ?	<i>Sm</i>	\$1,850.10	X
1 pc	Turbo cooler ?			\$1,850.10
1 pc	Radiator assy ?			\$1,255.60
1 pc	Radiator fan assy ?			\$1,050.10
1 pc	Rear tail-gate assy ✓	<i>By</i>	\$1,955.70	✓
1 pc	Rear tail-gate inner lock ?	<i>L</i>	\$189.10	X
1 pc	Rear tail-gate emblem "Logo" ✓	<i>Me</i>	\$65.70	✓
1 pc	Rear tail-gate emblem "sharan" ✓	<i>Me</i>	\$60.10	✓
1 pc	Rear tail-gate emblem "2.0 Tsi" ✓	<i>Me</i>	\$40.60	✓

balance c/f \$22,359.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SME 2210 S

1 pc	Rear end panel	?
1 pc	Rear bumper	/
1 pc	Rear bumper reinforcement	?
1 pc	Rear bumper lower bumper	?
3 pcs	Rear bumper sensor	?
2 pcs	Rear bumper reflector	?
2 pcs	Rear bumper side retainer	?
1 pc	Rear windscreen mouldng	/
2 pcs	Front shock absorber	?
2 pcs	Front lower arm	?
2 pcs	Front kunckle arm	?
2 pcs	Front kunckle bearing	?
2 pcs	Front hub assy	?

balance b/f \$22,359.70

		\$750.10	X
	<i>Bu</i>	\$1,380.10	/
		\$865.80	?
		\$900.10	?
\$255.70		\$767.10	?
\$185.10	<i>Sm</i>	\$370.20	X
\$65.20	<i>Sm</i>	\$130.40	X
	<i>Am</i>	\$75.10	/
\$750.10		\$1,500.20	?
\$687.20		\$1,374.40	?
\$625.10		\$1,250.20	?
\$200.10		\$400.20	?
\$660.10		\$1,320.20	?
		<u>\$33,443.80</u>	
Less 10 %		\$3,344.38	
		<u>\$30,099.42</u>	

S Nett

2 pcs	Front tyre rim	/
1 pc	Rear windscreen sealant	/
1 pc	Front no plate	/
20 pcs	Bumper clip	/

\$600.00	<i>Am</i>	\$1,200.00	/
	<i>Am</i>	\$40.00	/
	<i>Sm</i>	\$40.00	X
\$3.00	<i>Am</i>	\$60.00	/
		<u>\$1,240.00</u>	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,600.00	<i>Pool</i>
To putty & spray paint rear accident affected portion.	\$1,600.00	<i>1200</i>
Check/reconnect wiring.	\$45.00	<i>401</i>
To spray anti rust on accident affected portion.	\$180.00	<i>1201</i>
Remove/renew front undercarriages	\$450.00	<i>?</i>
Check and realign front wheel alignment	\$60.00	<i>/</i>
Towing	\$50.00	<i>/</i>
Remove/renew air con condenser & to top up gas element	\$180.00	<i>?</i>
Remove/refit turbo cooler and to top up turbo oil	\$180.00	<i>?</i>
Total	<u>\$35,684.42</u>	

19775 / kpk ke

PRE-REPAIR INSPECTION REQUEST - SME2210S vs SMG4011B (OI) on D.O.A.: 25/10/2019

From: Hor, Yinnul

To: 'assignments@kkauto.com' Admin & (admin-a@kkauto.com)
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Manesa, Azlan, Syazardina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeekaur, Parthiban, Theerthan, Subramaniam, Div
Sent: Tuesday, 29 October 2019 2:19:22 PM
Attachments: [log_in.jpg](#) [lkk.pdf](#) [20191029110845.pdf](#) [20191029110845.pdf](#)

Hi,

Please refer to the enclosed request from Massive Trading & Auto
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Ruf (Viviane)
AIG
FNOL, Regulator
Singapore FNOL, | Claims Operations - Auto

Tel: 90720556 | Ext: 1002208
Email: Hor@aig.com | www.aig.sg

P: Anthony
T: 2:28 p.m
V: Out
E: ✓

From: Anthony Cheong [mailto:cheonganthony@yahoo.com.sg]
Sent: Tuesday, October 29, 2019 1:09 PM
To: Hor, Yinnul
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG4011B AND SME2210S ON 25/10/2019

This message is from an external sender; be cautious with links and attachments.

Without Prejudice

Dear Sir

Our client has agreed to the usage of Mr Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you

On Tuesday, 29 October 2019, 11:55:17 am GMT+8, Hor, Yinnul <yinnul.hor@aig.com> wrote

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息，如要阅读此信息，请开启附件。

இந்த செய்தி மிகவும் பாதுகாக்கப்பட்ட செய்தி ஆகும். அதைப் படிக்க, இதைத் திறக்கவும்.

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부파일을 열어야 합니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-11-05 11:55 +08 to read your message.
After that, open the attachment.

[View more](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. If you have received this email by mistake, please notify the sender immediately by e-mail. Do not disseminate, distribute or copy this e-mail. If you have received this email by mistake, please notify the sender immediately by e-mail. Do not disseminate, distribute or copy this e-mail.

Powered by: [Protopopis Encryption](#). Copyright © 2006-2011 Protopopis, Inc. All rights reserved.

IMPORTANT NOTICE
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul Hor@sig.com
To: cheonganthony@yahoo.com.sg
Cc: Andy-SY Fong@sig.com, Winnie-LW Fan@sig.com, NoorManesa.AbuKassim@sig.com, Syazardina.Azlan@sig.com, yokeeshi.chan@sig.com, ShengYang.Lim@sig.com, Aashweenjeekaur.Mithoosingh@sig.com, Theerthan.Parthiban

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG4011B AND SME2210S ON 25/10/2019
Date: Tue, 29 Oct 2019 03:55:28 +0000

Without Prejudice

Your Reference : SME2210S
 Our Reference : SMG4011B

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hur Yin Rui (Viviane)
 AIG
 FNOC Adjuster I
 Singapore FNOC, 1 Claims Operations – Auto

Tel: 600118558 | Fax: 1002228
YinARui@aig.com | www.aig.sg

From: Anthony Cheong [mailto:cheonganthony@yahoo.com.sg]
Sent: Tuesday, October 29, 2019 11:46 AM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] Accident involving SME2210S & SMG4011B on 25.10.2019

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Your ref : SMG4011B
 Our ref : 27102019

Dear Sir/Mdm

We refer to the above matter.

Our client's vehicle SME2210S was involved in the above accident with your insured's vehicle no SMG4011B on 25 Oct 2019.

Kindly let us have your surveyor list for our attention.

Also, please let us know within 2 working days whether you would like to conduct the pre-repair survey of our client's vehicle.

The survey can be conducted at the following address.

Blk 403B #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541

If we do not hear from you within the next 2 working days excluding Saturday, Sunday or holiday, we will commence repairs thereafter without further reference to you.

Enclosed herewith the GIA report of SME2210S for your kind perusal.

In the meantime, if you have any queries, please do not hesitate to contact me at 91081728 and I'll be most happy to assist you.

Your kind attention to the above is much appreciated.

Best Regards
Anthony Cheung
Claims
Massive Trading & Auto

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 6 November 2019 10:13 AM
To: Anthony Cheong
Subject: RE: SME2210S

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards.

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher@sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

From: Anthony Cheong <cheonganthony@yahoo.com.sg>
Sent: Wednesday, 6 November 2019 9:03 AM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: Re: SME2210S

WITHOUT PREJUDICE

Hi Asher,

Kindly let me know has liability been established

Thanks

Anthony

Sent from Yahoo Mail for iPhone

On Friday, November 1, 2019, 11:05 AM, Asher Sng (LKKAuto) <AsherSng@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Hi Anthony,

We are still pending for insured GIA report.

Shall revert when we received our insured report.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: [6841-6051](tel:6841-6051) | email: ashersng@lkkauto.com | fax: [6741-4108](tel:6741-4108)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anthony Cheong <cheonganthony@yahoo.com.sg>
Sent: Friday, 1 November 2019 10:57 AM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Cc: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: SME2210S

Hi Kenneth,

Attached GIA report and estimate for your necessary action.

Thanks

Anthony

Claim Audit

AUDIT TRAIL				
No.	On	Action	Remarks	By
1	31 Oct 2019 11:22	Cim Dtl Modified	Claimant's Name: -> ONG SIO KHEONG, Claimant's ID: -> S7319678G.	[A] HOW MEI KWAN
2	31 Oct 2019 11:22	Cim Veh Model Changed	(204805) VOLKSWAGEN SHARAN 2.0 TSI AT 7N14H3 (A).	[A] HOW MEI KWAN
3	31 Oct 2019 11:22	Cim Created	Reg No: SME2210S. Acct Date: 2019/10/25. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: Massive Trading & Auto ()	[A] HOW MEI KWAN
4	31 Oct 2019 11:22	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	31 Oct 2019 11:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/11/11	[A] HOW MEI KWAN
6	31 Oct 2019 11:22	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	31 Oct 2019 11:22	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[E] Merimen Administrator
8	31 Oct 2019 11:23	Label Added	(19):Fastlane.	[A] HOW MEI KWAN
9	31 Oct 2019 11:23	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] HOW MEI KWAN
10	04 Nov 2019 15:32	Cim Registration Modified	Init.Est.:8,000 - 9,000->30,000 - 40,000.	[A] HOW MEI KWAN
11	06 Nov 2019 10:11	Video Downloaded	Downloaded OI VIDEO	[A] Asher Sng Rong Yi
12	08 Nov 2019 16:43	Video Downloaded	Downloaded OI VIDEO	[A] Asher Sng Rong Yi
13	23 Dec 2019 11:13	Adj Rpt Initiated		[A] Asher Sng Rong Yi
14	23 Dec 2019 11:13	Insured Phone No Updated	[None] -> [+6581685795]	[A] Asher Sng Rong Yi
15	23 Dec 2019 11:13	Cim Dtl Modified	Claim Conclusion: -> 1.	[A] Asher Sng Rong Yi
16	23 Dec 2019 11:13	Cim Dtl Modified	JPJ Reg. Date: -> 2012/05/28.	[A] Asher Sng Rong Yi
17	23 Dec 2019 11:13	Cim Details Notified		[A] Asher Sng Rong Yi
18	23 Dec 2019 12:48	Adj Mandate Request	Cur.Req:16300.00:LIABILITY: 100% B:28k 4VEH CC OI LAST	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

DR Ref No	DR Date	DR Type	Acc Type	Acc Name	Dr Name (Branch)	Ref 1	Ref 2	Amount
2333938	04 Nov 2019 11:55:43	Video Upload	Motor	AIG Asia Pacific Insurance Pte. Ltd.	AIG Asia Pacific Insurance Pte. Ltd. (SG)	SME2210S	Abu Kassim, Noor Mariesa	xx.xx
2336899	06 Nov 2019 09:48:26	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SME2210S	SMG4011B	11.77
2384573	23 Dec 2019 11:13:25	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SME2210S	SMG4011B	11.77

Print Received Message

This mail is associated with :

***SME2210S (6868158273SG)**
[SMG4011B]
TP
ONG SIO KHEONG
Oct 25 2019 10:00PM
[LEE YANG]
Massive Trading & Auto

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/01/2020 10:12 AM
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16300.00) - SME2210S - Claim Handler: MdNoor, Norsiah

Approved:16300.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Oct 2019 Edit Reg		29 Oct 2019 00:00 Edit Adj Rpt	\$15,000.00 Edit Estimates	\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEE YANG , ID: S9226918C, Tel: +6581685795								
Main Claimant:	ONG SIO KHEONG , ID: S7319678G								
Vehicle Reg. No.:	SME2210S	Date of Loss:	25/10/2019 22:00 - :59 [88 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6868158273SG	Policy/Cover Note No.:	1900003699 (Comprehensive) Coverage: 18/12/2018 - 17/12/2020						
Vehicle Reg. No. (Insured):	SMG4011B	Policy No. (Claimant):	5105379098						
Excess:									
Repairer:	Massive Trading & Auto () Blk 503B #01-405, Ang Mo Kio Industrial Pk 2, 569541 Ang Mo Kio - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/11/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
• AIG_SG_EXPRESS (20/01/2020): Alert - Adj Mandate Approved (\$16300.00) - SME2210S - Claim Handler: MdNoor, No...									
ALL ASSOCIATED TASKS									
				View All	Search Tasks	Create New Task	Complete		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME2210S (6868158273SG)
[SMG4011B]
TP
ONG SIO KHEONG
Oct 25 2019 10:00PM
[LEE YANG]
Massive Trading & Auto

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>	
Video															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print			
1	04/11/19 11:55	OI VIDEO											Load AVI	<input type="checkbox"/>		
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit	<input type="checkbox"/>		
Photos/Images															3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
2	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
3	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
4	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
5	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
6	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
7	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
8	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
9	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
10	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
11	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
12	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
13	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
14	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
15	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
16	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
17	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
18	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
19	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
20	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
21	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
22	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
23	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
24	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
25	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
26	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
27	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
28	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
29	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
30	23/12/19 11:02	General View											Load JPG	<input checked="" type="checkbox"/>		
31	23/12/19 11:02	Odometer Reading											Load JPG	<input checked="" type="checkbox"/>		
32	23/12/19 11:09	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
33	23/12/19 11:09	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
34	23/12/19 11:09	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
35	23/12/19 11:09	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		
36	23/12/19 11:09	Reinspection Photo											Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
37	23/12/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
38	23/12/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
39	23/12/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	23/12/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	23/12/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	23/12/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/19 11:24	TP GIA REPORT		Load PDF
2	31/10/19 11:24	ACKNOWLEDGEMENT EMAIL TO AIG DD 29.10.19		Load PDF
3	31/10/19 11:24	EMAIL FROM AIG DD 29.10.19		Load PDF
4	06/11/19 13:15	TP ESTIMATE - MARKED		Load PDF
5	11/11/19 12:04	LETTER TO OI		Load PDF
6	23/12/19 12:47	LOD		Load PDF
7	23/12/19 12:49	LTA PARF COE Rebate Details		Load PDF
8	31/01/20 09:46	WORKSHOP INVOICE		Load PDF
9	31/01/20 09:46	AUTHORISATION TO ACT FORM		Load PDF
10	31/01/20 09:46	Release Voucher		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/11/19 11:54	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SMG4011B (Insd veh)	Model:	VOLKSWAGEN SHARAN 2.0 TSI AT 7N14H3 (A)
	SME2210S (TP veh)		
Date of Accident:	25/10/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	35,784.42	
Final Repair Cost	:	\$	15,000.00	
Loss of Use	:	\$	1,300.00	13.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	16,300.00	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability ___100___(%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____(%)		Assessed Liability (*): ___100___(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Massive Trading & Auto	:	\$ 16,300.00
2)		:	\$

JOANNE LEE KHANG MIN

31 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019225/KEA3Q2

Date: 31/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900003699
Claimant
Vehicle No : SME2210S **Insured Vehicle No :** SMG4011B
Date of Loss: 25/10/2019 **Nature of Claim:** TP **Claim No:** 6868158273SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME2210S**
 Make & Model: VOLKSWAGEN SHARAN, 2.0 TSI AT 7N14H3 (A) Engine No: CCZ239274
 Reg. Date: 28/05/2012 (Man. Year: 2012) Chassis No: WWWZZZ7NZCV038468
 Colour: Grey Odometer: 159059 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
 Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,439.42	20,979.31	10,460.11	33.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,345.00	2,670.00	1,675.00	38.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,784.42	23,649.31	12,135.11	33.91
Approved Total (Overridden) (S\$)		15,000.00		
Nett Amount (S\$)	35,784.42	15,000.00	20,784.42	58.08
+ Loss of Use (13.0 x S\$100.00/day) (S\$)		1,300.00		
	Nett Liability (S\$)	16,300.00		

INSPECTION

Date of Assignment: 29/10/2019
 Date Inspected: 29/10/2019 Inspected At: Massive Trading & Auto
 Blk 5038 #01-405, Ang Mo Kio
 Industrial Pk 2
 Singapore 569541
 Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$59,000

LTA REBATE: \$43,858

NETT VALUE: \$15,142

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,480.70 FL	*1,480.70 FL
2	1		*FRONT BONNET LOCK	Repair	255.60 FL	*- FL
3	2		*FRONT FENDER	Bent	1,500.40 FL	*1,500.40 FL
4	1		*FRONT O/S FENDER INNERSHIELD	Cracked	187.10 FL	*187.10 FL
5	2		*FRONT HEADLAMP ASSY LED	Broken	4,501.20 FL	*4,501.20 FL
6	2		*FRONT HEADLAMP WATER NOZZLE MOTOR	Jammed	413.40 FL	*413.40 FL
7	2		*FRONT HEADLAMP WATER NOZZLE BRACKET	Distorted	310.20 FL	*310.20 FL
8	2		*FRONT HEADLAMP WATER NOZZLE OUTER COVER	Missing	150.20 FL	*150.20 FL
9	2		*FRONT SUPPORT TOP SIDE PANEL	Bent	414.20 FL	*414.20 FL
10	1		*FRONT RADIATOR SUPPORT PANEL - FIBER	Not Necessary	550.70 FL	*- FL
11	1		*FRONT RADIATOR SUPPORT PANEL GARNISH	Not Necessary	215.60 FL	*- FL
12	1		*FRONT BUMPER	Buckled / Cracked	1,350.70 FL	*1,350.70 FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	855.70 FL	*855.70 FL
14	1		*FRONT BUMPER TOP BEAM	Distorted	185.30 FL	*185.30 FL
15	2		*FRONT BUMPER SIDE RETAINER	Distorted	130.20 FL	*130.20 FL
16	1		*FRONT BUMPER LOWER GRILLE	Serviceable	205.60 FL	*- FL
17	1		*FRONT BUMPER UNDER COVER	Serviceable	167.20 FL	*- FL
18	1		*FRONT BUMPER TOW COVER	Serviceable	45.80 FL	*- FL
19	2		*FRONT BUMPER SENSOR	Shorted	511.40 FL	*511.40 FL
20	1		*FRONT GRILLE	Cracked	505.80 FL	*505.80 FL
21	1		*FRONT GRILLE EMBLEM	Necessary	105.60 FL	*105.60 FL
22	1		*AIR CON CONDENSER	Punctured	1,850.10 FL	*1,850.10 FL
23	1		*TURBO COOLER	Serviceable	1,850.10 FL	*- FL
24	1		*RADIATOR ASSY	Serviceable	1,255.60 FL	*- FL
25	1		*RADIATOR FAN ASSY	Serviceable	1,050.10 FL	*- FL
26	1		*REAR TAIL-GATE ASSY	Bent	1,955.70 FL	*1,955.70 FL
27	1		*REAR TAIL-GATE INNER LOCK	Repair	189.10 FL	*- FL
28	1		*REAR TAIL-GATE EMBLEM LOGO	Necessary	65.70 FL	*65.70 FL
29	1		*REAR TAIL-GATE EMBLEM SHARAN	Necessary	60.10 FL	*60.10 FL
30	1		*REAR TAIL-GATE EMBLEM 2.0 TSI	Necessary	40.60 FL	*40.60 FL
31	1		*REAR END PANEL	Repair	750.10 FL	*- FL
32	1		*REAR BUMPER	Buckled	1,380.10 FL	*1,380.10 FL
33	1		*REAR BUMPER REINFORCEMENT	Bent	865.80 FL	*865.80 FL
34	1		*REAR BUMPER LOWER BUMPER	Serviceable	900.10 FL	*- FL
35	3		*REAR BUMPER SENSOR	Serviceable	767.10 FL	*- FL
36	2		*REAR BUMPER REFLECTOR	Serviceable	370.20 FL	*- FL
37	2		*REAR BUMPER SIDE RETAINER	Serviceable	130.40 FL	*- FL
38	1		*REAR WINDSCREEN MOULDING	Necessary	75.10 FL	*75.10 FL
39	2		*FRONT SHOCK ABSORBER	Serviceable	1,500.20 FL	*- FL
40	2		*FRONT LOWER ARM	Serviceable	1,374.40 FL	*- FL
41	2		*FRONT KUNCKLE ARM	Bent	1,250.20 FL	*1,250.20 FL
42	2		*FRONT KUNCKLE BEARING	Necessary	400.20 FL	*400.20 FL
43	2		*FRONT HUB ASSY	Bent	1,320.20 FL	*1,320.20 FL
44	2		*FRONT TYRE RIM	Damaged	1,200.00 FS	*1,200.00 FS
45	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
46	1		*FRONT NO PLATE	Serviceable	40.00 FS	*- FS
47	20		*BUMPER CLIP	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **34,783.80** **23,165.90**
 - List Item Discount on L Items 10.00/10.00% (\$\$) 3,344.38 2,186.59

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	31,439.42	20,979.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	1,800.00	900.00
2	TO PUTTY & SPRAY PAINT REAR ACCIDENT AFFECTED PORTION	New	1,600.00	1,200.00
3	CHECK/RECONNECT WIRING	New	45.00	40.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	180.00	120.00
5	REMOVE/RENEW FRONT UNDERCARRIAGES	New	450.00	200.00
6	CHECK AND REALIGN FRONT WHEEL ALIGNMENT	New	60.00	60.00
7	TOWING	New	50.00	50.00
8	REMOVE/RENEW AIR CON CONDENSER & TOP UP GAS ELEMENT	New	180.00	100.00
9	REMOVE/REFIT TURBO COOLER AND TO TOP UP TURBO OIL	New	180.00	0.00
Gross Labour Cost (S\$)			4,345.00	2,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >