

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Fax : 64816131

Ong Sio Kheong
31B West Coast Park
#06-33 Botannia
Singapore 127726

Not Authored

Max 1 Day \$10k

Recovery After Paint

Vehicle No : SME 2210 S
Make : Volkwagon Sharan 2.0
Year : 2012

10 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front bonnet ✓		\$1,480.70 ✓
1 pc	Front bonnet lock ?		\$255.60 X
2 pcs	Front fender ✓	\$750.20	\$1,500.40 ✓
1 pc	Front o/s fender innershield ?		\$187.10 ✓
2 pcs	Front headlamp assy " LED " ✓	Brn \$2,250.60	\$4,501.20 ✓
2 pcs	Front headlamp water nozzle motor ?		\$206.70 \$413.40 ?
2 pcs	Front headlamp water nozzle bracket ?		\$155.10 \$310.20 ?
2 pcs	Front headlamp water nozzle outer cover ✓		\$75.10 \$150.20 ✓
2 pcs	Front support top side panel ✓		\$207.10 \$414.20 ✓
1 pc	Front radiator support panel - fiber ?		\$550.70 ?
1 pc	Front radiator support panel garnish ?		\$215.60 ?
1 pc	Front bumper ✓		\$1,350.70 ✓
1 pc	Front bumper reinforcement ?		\$855.70 ?
1 pc	Front bumper top beam ?		\$185.30 ?
2 pcs	Front bumper side retainer ✓	\$65.10	\$130.20 ✓
1 pc	Front bumper lower grille ?		\$205.60 X
1 pc	Front bumper under cover ?		\$167.20 X
1 pc	Front bumper tow cover ✓		\$45.80 X
2 pcs	Front bumper sensor ?	\$255.70	\$511.40 ?
1 pc	Front grille ?		\$505.80 ?
1 pc	Front grille emblem ?		\$105.60 ?
1 pc	Air con condenser ?		\$1,850.10 X
1 pc	Turbo cooler ?		\$1,850.10 ?
1 pc	Radiator assy ?		\$1,255.60 ?
1 pc	Radiator fan assy ?		\$1,050.10 ?
1 pc	Rear tail-gate assy ✓		\$1,955.70 ✓
1 pc	Rear tail-gate inner lock ?		\$189.10 X
1 pc	Rear tail-gate emblem " Logo " ✓		\$65.70 ✓
1 pc	Rear tail-gate emblem " sharan " ✓		\$60.10 ✓
1 pc	Rear tail-gate emblem " 2.0 Tsi " ✓		\$40.60 ✓

balance c/f \$22,359.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SME 2210 S

1 pc	Rear end panel ?
1 pc	Rear bumper ✓
1 pc	Rear bumper reinforcement ?
1 pc	Rear bumper lower bumper ?
3 pcs	Rear bumper sensor ?
2 pcs	Rear bumper reflector ?
2 pcs	Rear bumper side retainer ?
1 pc	Rear windscreen mouldng ✓
2 pcs	Front shock absorber ?
2 pcs	Front lower arm ?
2 pcs	Front kunckle arm ?
2 pcs	Front kunckle bearing ?
2 pcs	Front hub assy ?

balance b/f \$22,359.70

		\$750.10	X
	Bu ^R	\$1,380.10	✓
		\$865.80	?
		\$900.10	?
\$255.70		\$767.10	?
\$185.10	Bu	\$370.20	X
\$65.20	Sm	\$130.40	X
	Am	\$75.10	✓
\$750.10		\$1,500.20	?
\$687.20		\$1,374.40	?
\$625.10		\$1,250.20	?
\$200.10		\$400.20	?
\$660.10		\$1,320.20	?
		<u>\$33,443.80</u>	
Less 10 %		\$3,344.38	
		<u>\$30,099.42</u>	

S Nett

2 pcs	Front tyre rim ✓
1 pc	Rear windscreen sealant ✓
1 pc	Front no plate ✓
20 pcs	Bumper clip ✓

\$600.00	Ad	\$1,200.00	✓
	Am	\$40.00	✓
	Sm	\$40.00	X
\$3.00	Am	\$60.00	✓
		<u>\$1,240.00</u>	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	\$1,600.00	Pod
To putty & spray paint rear accident affected portion.	\$1,600.00	1200
Check/reconnect wiring.	\$45.00	401
To spray anti rust on accident affected portion.	\$180.00	1201
Remove/renew front undercarriages	\$450.00	?
Check and realign front wheel alignment	\$60.00	✓
Towing	\$50.00	✓
Remove/renew air con condenser & to top up gas element	\$180.00	?
Remove/refit turbo cooler and to top up turbo oil	\$180.00	?
Total	<u>\$35,684.42</u>	