



You
today at 10:23



Adjuster Report.pdf - Adobe Acrobat Reader DC

File Edit View Window Help

Home Tools Adjuster Report.pdf x

2 / 3 102% Share

Fill & Sign Tab X ✓ ○ — • Sign Next Close

Print Code: LKK Auto Consultants Pte Ltd/SHAB729D/12/11/2019 08:26

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER X	Crushed	599.68 FL	*599.68 FL
2	1		*REAR BUMPER DIFFUSER X	Cut	228.40 FL	*228.40 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	484.40 FL	*. FL
4	1		*REAR BUMPER REINFORCEMENT SPONGE	Not Necessary	98.99 FL	*. FL
5	1		*REAR BUMPER CLIPS X	Necessary	35.00 FS	*30.00 FS
6	1		*REAR BUMPER ADS STICKER	Necessary	120.00 FS	*80.00 FS
7	1		*REAR BUMPER PROTECTOR PAD	Not Necessary	120.00 FS	*. FS
					Sub Total (\$\$)	1,686.47 938.08
					- List Item Discount on L Items 20.00/20.00% (\$\$)	282.29 165.62
					Total Parts (\$\$)	1,404.18 772.46

LKK Auto Consultants Pte Ltd/SHAB729D/12/11/2019 08:26 Not valid without Reference section.

AXA | Login

you in office? 09:36 ✓

eed your help 09:38 ✓

aya Ubi

X condition

https://web.whatsapp.com

1/1