

ASS. REC. BY:

REF:

CS/40119019240/E+R32

Special Instruction:

de

Manager: Steve

ASSIGNMENT (Office)

From (Person): Jenny Lew

of UOI

Date/Time: 31/10/2009

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8LF5240S

Insured:

at Workshop m/s Borneo Motor

Tel: 9847 6178 Wally

of 2 Pandan Crescent Level 4

Policy No:

Claim No: DHOM110169691900

Sum Insured:

Excess:

\$800

Make of Veh:

D.O.A

(Client's Record)

21/10/2009

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 31/10

Person Contacted:

Wally

Vehicle IN/OUT

Date/Time

Action/Instruction

Vehicle (✓)

8LF5240S-X

11/11-

Revert wa email pending repair from repairer

5/11-

inform by Jenny authorise repair all in \$42

5/11 @ 11:23pm

- inform. Wally authorise excess \$800 all in \$421-

Signature: Steve

REF:

ASSIGNMENT

om.
Estimated Cost:
TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:
Workshop m/s

urod.
Cy No.

ims No.
n Insured:

Client's Record)
e of Velt:

olicy Condition)

mark: The veh had commenced its
repair at the time of inspection.

or Market Value:

Accident Report: Consistent? : Yes or No

PP Seen: Consistent? : Yes or No

Repairs: days Res.: Yes or No

Sum: % 3 Val.: Yes or No

REV / REP. / 24 HRS

Person Contacted: Vehicle: IN / OUT

Veh No: SLFS240S Yr Regn: 30/8/16
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Lexus ES250 c.c 2494

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 34333 T/Radio: Insured / Std / NI / NA

Eng/No:

Ci/No: JTHBJ166X 0299 3658

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

| | | | | | |
|--------|---|----|--------|---|----|
| Front | | | Rear | | |
| R/Bal. | 5 | mm | R/Bal. | 5 | mm |
| L/Bal. | 5 | mm | L/Bal. | 5 | mm |

D.O.A. 29/10/19 D.O.I. 31/10/19

Survey held at Borneo Motors

Des. of Damages: (Frt) / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

| o / Time | Action / Instruction |
|----------|--|
| | MV - 121,000 Offer 42k Global sum repair (really 98476178) |
| | PV - 71,536 |
| | NV - 49,464 Repair Sum \$42,000/- (Red: 1370530; 30%) |

RECEIVED 19 DEC 2019

mo, File Pass to? ☐ : Proil. Report
19/12 Typst ☐ : Final Report

mo, File Return to?

Days Of Repair: 12

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee: 50x25 = 1250
250+1250
Transportation: 60
S + RS - SI
Phone 72
Others
TOTAL 1632

ort Format :
Som / I.B.I: (\$ 42000/-)

Nivitha (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Thursday, 31 October 2019 11:29 AM
To: wally.tan@borneomotors.com.sg; assignments; SUR
Cc: LEE KATIE
Subject: DHOM110169691900 / OD Claim - SLF5240S / DOA: 29.10.2019
Attachments: SAS2694429.zip

Importance: High

Dear Wally,

We will arrange LKK to survey the vehicle.

Dear Shiau Chan,

Please arrange to survey the vehicle at 2 Pandan Crescent level 4.
Excess: S\$800.00

Kindly assist to check the pre-accident market value and salvage value and revert to us soonest.

Password for attachment: uoi123

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #25-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 5 November 2019 1:23 PM
To: Wally Tan PTCBC; Steve Chen (LKK Auto)
Cc: Dion Wang; Ivan Ng PTCBC; Alvin Lee Yee Peng PTCBC
Subject: RE: SLF5240S
Attachments: OD Template.zip

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLF 5240S (Excess \$800/-). All in \$42,000/- inclusive supplementary.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wally Tan PTCBC <wally.tan@borneomotors.com.sg>
Sent: Monday, 4 November 2019 10:58 AM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Cc: Dion Wang <Dion.Wang@inchcape.com.sg>; Ivan Ng PTCBC <Ivan.Ng@inchcape.com.sg>; Alvin Lee Yee Peng PTCBC <Alvin.LeeYP@inchcape.com.sg>
Subject: RE: SLF5240S

Hi Denise,

Please try to expedite asap.

Regards
Wally

From: Denise Tay (LKKAUTO) [<mailto:denisetay@lkkauto.com>]
Sent: Monday, 4 November 2019 8:43 AM
To: Wally Tan PTCBC; Steve Chen (LKK Auto)
Cc: Dion Wang; Ivan Ng PTCBC; Alvin Lee Yee Peng PTCBC
Subject: RE: SLF5240S

Denise Tay (LKKAUTO)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Tuesday, 5 November 2019 1:17 PM
To: Denise Tay (LKKAUTO); Admin-D (LKKAUTO); assignments; SUR
Cc: LEE KATIE
Subject: RE: DHOM110169691900 / OD Claim - SLF5240S / DOA: 29.10.2019 / M11D08581911
Attachments: OD Template.zip

Dear Denise,

Please proceed with the repair authorisation at S\$42,000.00.
Excess :S\$800.00

Enclosed the discharge voucher for client due execution.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 4 November, 2019 9:19 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; LEW JENNY <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: DHOM110169691900 / OD Claim - SLF5240S / DOA: 29.10.2019

Dear Jenny,

Kindly advise on the authorization.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Friday, 1 November 2019 3:02 PM



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DHOM110169691900
Date: 31/10/2019

Our Ref: CS/UOI19019240/Etf3

The Motor Claims Department
United Overseas Insurance Ltd

Dear Sir/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLF 5240S

We thank you for the instruction on 31/10/2019

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 31/10/2019 at the premises of M/s Borneo Motor and have the following to report: -

| | |
|--------------------------|------------------|
| Workshop Estimate Amount | : S\$ 64,954.67 |
| Revised Estimate Amount | : S\$ 47,119.30 |
| "Check" Items Amount | : S\$ 9,587.10 |
| Total | : S\$ 56,706.40 |
| Market Value | : S\$ 121,000.00 |
| LTA Reimbursement Value | : S\$ 71,536.00 |
| Nett Value | : S\$ 49,464.00 |

Description of Damage:

The vehicle sustained at the front o/s and rear portion.



Comments/ Present Status:

Damages Consistent.

Pending repair cost from repairer

Yours faithfully
Steve Chen
Automotive Assessor

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 1 November 2019 2:34 PM
To: Admin-D (LKKAuto); 'LEW JENNY'; assignments; SUR
Cc: 'LEE KATIE'
Subject: RE: DHOM110169691900 / OD Claim - SLF5240S / DOA: 29.10.2019
Attachments: PRELI ADVISED OF SLF 5240S.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLF 5240S**
Number of days (estimated) : 12 days

Pending Repair cost from repairer

We have not authorise repair

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 31 October 2019 12:23 PM
To: 'LEW JENNY' <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'LEE KATIE' <katielee@uoi.com.sg>
Subject: RE: DHOM110169691900 / OD Claim - SLF5240S / DOA: 29.10.2019

Dear Jenny,

Thank you for the assignment.

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LEW JENNY [<mailto:jennylew@uoi.com.sg>]
Sent: Thursday, 31 October 2019 11:29 AM
To: wally.tan@borneomotors.com.sg; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: DHOM110169691900 / OD Claim - SLF5240S / DOA: 29.10.2019
Importance: High

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------------------|
| Date Of Report | 30/10/2019 15:45 |
| Date Of Accident | 29/10/2019 17:00 |
| Exact Location Of Accident | SLIP ROAD B11 JALAN AHMAD IBRAHIM |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|------------------------|
| Vehicle Registration Number | SLF5240S |
| Insured/Policyholder | |
| Name Of Registered Owner | CHIA ENG POH DENIS |
| NRIC No | S1260759H |
| Email Address | DEBEENCHIA@INBOX.SOM |
| Mobile Phone No | (FOREIGN) +65-64663922 |
| Alternative Phone No | OFFICE-64666678 |

Vehicle Particulars

| | |
|--|---------------|
| Manufacturer | LEXUS |
| Model | ES250-2.5 (A) |
| Exact Purpose for which vehicle was being used at time of accident | NORMAL USAGE |

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

| | |
|------------------|-------------|
| Vehicle Category | PRIVATE CAR |
|------------------|-------------|

Insurance Company

| | |
|---------------------------|-------------------------------|
| Name of Insurance Company | UNITED OVERSEAS INSURANCE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DH0M110169691900 |
| Cover Note Number | |

Driver

| | |
|----------------------|------------------------|
| Name of Driver | CHIA ENG POH DENIS |
| NRIC No | S1260759H |
| Date Of Birth | 09/11/1934 |
| Occupation | INDOOR |
| Date Of Driving Pass | 08/10/1970 |
| Driving Experience | 49 YEARS AND 0 MONTHS |
| Gender | MALE |
| Mobile Number | (FOREIGN) +65-64663922 |
| Fax Number | |
| Contact Number | OFFICE-64666678 |
| Email Address | DEBEENCHIA@INBOX.SOM |

| | |
|---|---------------------|
| Address | 24 KING ALBERT PARK |
| Postcode | 598307 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|-----------------|
| Type Of Accident | CHAIN COLLISION |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 6 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|---|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| Police Station Name | BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE |
| Police Station Address | ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE |
| Police Station Contact | TEL NO: 1800-4629999 - FAX NO: 64628933 |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | NO |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|-------------|
| Vehicle Registration Number | SLE6926X |
| Vehicle Make/Model/Colour | VOLVO |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | HENRY TAN |
| NRIC/Passport Number | S8008952Z |
| Contact Number | 90939730 |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

A-SLF 5240S

B-SLE 6926X




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

See police report attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NOTICE OF REPORTING

1 This is to confirm that Chia Eng Poh Denis, NRIC: S1260759H, 24 King Albert Park S(2159) had reported to the Police a non-injury traffic accident which occurred on 29/10/2019 along Jurong Pier Towards AYE at about 1700hrs.

a) Complainant vehicle:
SLF5240S

b) Other Party vehicle:
SLE6926X
Volvo
Henry Tan
S8008952Z
9093 9730

Briefly, I was traveling along the first lane of Jurong Pier and was entering the slip road to enter AYE when I noticed the car in front of me had started to brake. As I do not perceive it as a harsh brake, I lightly stepped on my brakes, only to realize afterwards that the vehicle in front had come to a complete stop.

{ Bill-Jabon
Advised to
Ibrahim

I then collided onto the vehicle in front. After stepping out of the vehicle, I then realize that there were 4 other cars in front of the vehicle I collided onto, all involved in the same nature of accident.

No one was injured, no traffic police attended, no government properties damaged, No riders involved in the accident and we exchanged our particulars.

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.



Rank/Name of Issuing Officer: Sgt(2) Lim Hong Ye
Date: 29/10/2019 Time: 2116 hrs
Police Post/Unit: Bukit Timah NPC



MEMBER OF THE UOB GROUP

United Overseas Insurance Limited
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909
Tel: (65) 6222 7733
Fax: (65) 6327 3849 / 6327 3870
Email: ContactUs@uoi.com.sg
uoi.com.sg
Co. Reg. No. 1973001528

Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

| | | | |
|-----------------------------|--------------------|----------------|--|
| CERTIFICATE NO. | DHOM110169691900 | Excess: | \$800/- NAMED DRIVERS \$1500/- OTHERS \$3000/- APPL TO <25 YRS & OR <3YRS EXP \$100/- WINDSCREEN DAMAGE CLAIM |
| Type of Cover | COMPREHENSIVE | | |
| Vehicle Number | SLF5240S | | |
| Name of Insured | CHIA ENG POH DENIS | | |
| Restricted Driver(s) | NOT APPLICABLE | | |

Period of Insurance 30 August 2019 to 29 August 2020

Engine# 2ARF234476
Chassis# JTHBJ1GGX02093658

PRIVATE CAR - INDIVIDUAL OWNERSHIP [MX 1]
AUTHORISED DRIVER

- (1) The Insured
- (2) Any other person who is driving on the Insured's order or with his permission
- (3) In the event of the death of the Insured
 - (a) any member of the Insured's family or a paid driver who has been driving the car during the lifetime of the Insured and permission to drive had not been withdrawn prior to the death of Insured and
 - (b) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the Insured

LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and for the Insured's business

THE POLICY DOES NOT COVER

Use for hire or reward or racing pace-making reliability trial or speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purposes in connection with the Motor Trade

The carriage of passengers pursuant to car pooling arrangements and payments or any of them made by the passengers thereunder towards the running expenses of any vehicle described in the Schedule shall not be deemed to constitute use for hire or reward

Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and part IV of the Road Transport Act, 1987 (Malaysia).

UNITED OVERSEAS INSURANCE LTD

FCABM Date : 06/08/2019

For the Company 

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|---------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 759H |
| Vehicle Details | |
| Vehicle No.: | SLF5240S |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 31 Oct 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | LEXUS ES250 A/T S/R |
| Primary Colour: | Black |
| Manufacturing Year: | 2016 |
| Engine No.: | 2ARF234476 |
| Chassis No.: | JTHBJ1GGX02093658 |
| Maximum Power Output: | 135.0 kW (181 bhp) |
| Open Market Value: | \$36,191.00 |
| Original Registration Date: | 30 Aug 2016 |
| First Registration Date: | 30 Aug 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$42,668.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 29 Aug 2026 |
| PARF Rebate Amount: | \$32,001.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 29 Aug 2026 |
| COE Category: | E - Open Category |
| COE Period(Years): | 10 |
| QP Paid: | \$58,201.00 |
| COE Rebate Amount: | \$39,535.00 |
| Total Rebate Amount: | \$71,536.00 |

The information contained herein is correct as at 31 Oct 2019

OK

Get More Cash for Your Car, Post an Ad Today.
Receive a higher selling price by selling your car yourself.
Advertise it for sale at just \$58, list till sold.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Honda Fit 08 1.3L



Head Turner, Well Maintained
And Low Mileage. Drive Around
\$400
Direct Owner



Post an Ad Advertiser Login Ways of Selling







Sort by Date Posted 20 results/page

Browse by Category

5 vehicles

Lexus ES250

Advanced Search

| Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status |
|--|-------|--------------|----------|---------|---------|----------|-----------|
| Lexus ES250 | Any | Any | 2016 | Any | Any | Any | Available |
|  Lexus ES250 | | | | | | | |
|  Lexus ES250 | | | | | | | |
|  Lexus ES250 | | | | | | | |
|  Lexus ES250 | | | | | | | |
|  Lexus ES250 | | | | | | | |
|  Lexus ES250 | | | | | | | |

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 120462
Tel no.: 6631 138866311506
98476178
Wally

| | | |
|---|-----------------|--|
| Account Detail | Account No | Customer Detail |
| United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept | S1000019/ICUOI1 | Mr Chia Eng Poh Denis 24 King Albert Park Singapore 598307 Work: 64663922 |
| | Document No | |
| | 0 | |
| | Document Date | |
| | 31/10/2019 | |

| Year | Make | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks |
|-------------------|------------|-------|------------------|------------|--------------|------------|--------------------------|
| 16 | BETGK | S3 | ASV60R | 30/08/2016 | SLF5240S | 34333 | 17865 40D/SLF5240S/29101 |
| Chassis No | Engine No | Terms | Lexus Consultant | Vehicle In | Collected On | | |
| JTHBJ1GGX02093658 | 2ARF234476 | 60 | Wally Tan G H | 30/10/2019 | 0.00 | --/--/---- | 0.00 |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|--|----|--|-----|------------|--------|----------|
| 1 | Z | BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS. | | | | |
| 2 | Z | BP-SUNDRY SUNDRIES POLICY NO.:DHOM110169691900 ACC DATE:29.10.19 TOW/DRIVE IN:29.10.19 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON: | | | | 50 80.00 |
| 3 | Z | BP-SUNDRY TOWING CHARGE. | | | | 208.00 ✓ |
| 4 | B | BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT) | | | | 216.50 ✓ |
| 5 | B | BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT) | | | | 216.50 ✓ |
| 6 | B | BP-MECH3 REMOVE/REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING AND FIT NEW PARTS. (NETT) | | | | 866.00 ✓ |
| Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply. | | | | | | |

| | | | |
|-------------------------------------|---------------------------------------|---|------------|
| For & on behalf of Borneo Motors | Customer's Signature | Change Summary | Total |
| | Please acknowledge receipt of vehicle | Parts Labour Materials Lubrication/Fluid Others | Less |
| | | | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 31/10/2019
TIME 08:15

VEHICLE NO SLP5240S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

| | | |
|---|-------------------------------|--|
| Account Detail | Account No S1000019/ICU011 | Customer Detail |
| United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept | Document No 0 | Mr Chia Eng Poh Denis 24 King Albert Park Singapore 598307 |
| | Document Date 31/10/2019 | Work: 64663922 |

| Year | Make | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks |
|------|-------|-------|----------|------------|------------|--------|--------------------------|
| 16 | BETGK | S3 | ASV60R | 30/08/2016 | SLF5240S | 34333 | 17865 40D/SLF5240S/29101 |

| Chassis No | Engine No | Terms | Lexus Consultant | Vehicle In | Collected On |
|-------------------|------------|-------|------------------|-----------------|-----------------|
| JTHBJ1GGX02093658 | 2ARF234476 | 60 | Wally Tan G H | 30/10/2019 0.00 | --/--/---- 0.00 |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|----|----|--|-------|------------|--------|----------|
| 7 | B | BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS, R/F AND L/F DOOR EDGES, CUT AND WELD PANEL AND FIT NEW PARTS. 866 x 6 742 x 7 | | | 5196 | 6062.00 |
| 8 | B | BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. 5194 | | | | 5565.00 |
| 9 | Z | BP-SLANT SUPPLY SEALANT (NETT) | | | | 200.00 ✓ |
| 10 | B | BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT) | | | | 216.50 ✓ |
| 11 | L | BP-LPO SUPPLY REGN PLATE (PO#) | | | | 96.00 ✓ |
| | | FRONT (NETT) | | | | |
| 12 | 1 | L53301-33160 HOOD SUB-ASSY ✓ | 1.00 | 2252.60 | | 2252.60 |
| 13 | 2 | L53341-33200 INSULATOR, HOOD ✓ | 1.00 | 349.70 | | 349.70 |
| 14 | 3 | T90467-09050 CLIP ✓ | 11.00 | 2.90 | | 31.90 |
| 15 | 4 | T88723-42070 LABEL, COOLER ✓ | 1.00 | 4.30 | | 4.30 |
| 16 | 5 | L53410-33290 HINGE ASSY, HOOD, RH ✓ | 1.00 | 83.60 | | 83.60 |
| 17 | 6 | L53420-33290 HINGE ASSY, HOOD, LH ✓ | 1.00 | 83.60 | | 83.60 |
| 18 | 7 | L53440-33100 SUPPORT ASSY, HOOD X ✓ | 1.00 | 349.70 | | 349.70 X |
| 19 | 8 | L53450-33090 SUPPORT ASSY, HOOD X ✓ | 1.00 | 349.70 | | 349.70 X |
| 20 | 9 | L53510-33410 LOCK ASSY, HOOD ✓ | 1.00 | 168.50 | | 168.50 |

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For & on behalf of Borneo Motors | Customer's Signature | Change Summary | Total |
|-------------------------------------|---------------------------------------|---|------------|
| | Please acknowledge receipt of vehicle | Parts Labour Materials Lubrication/Fluid Others | Less |
| | | | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 31/10/2019
TIME 08:15PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLP5240S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST R No : NP 850000-9www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

| Account Detail | Account No | Customer Detail |
|---|--------------------------|--|
| United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept | S1000019/ICU011 | Mr Chia Eng Poh Denis 24 King Albert Park Singapore 598307 Work: 64663922 |
| | Document No 0 | |
| | Document Date 31/10/2019 | |

| Year | Make | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks |
|------|-------|-------|------------|------------|------------|--------|--------------------|
| 16 | BETGR | S3 | 30/08/2016 | SLF5240S | 34333 | 17865 | 40D/SLF5240S/29101 |

| Chassis No | Engine No | Terms | Lexus Consultant | Vehicle In | Collected On |
|-------------------|------------|-------|------------------|-----------------|-----------------|
| JTHBJ1GGX02093658 | 2ARF234476 | 60 | Wally Tan G H | 30/10/2019 0.00 | --/--/---- 0.00 |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|----|----|---|-------|------------|--------|---------|
| 21 | 0 | L53630-33190 CABLE ASSY HOOD ? X NN | 1.00 | 68.50 | | 68.50 |
| 22 | 1 | T90959-01369 CLAMP X NN | 2.00 | 5.00 | | 10.00 |
| 23 | 2 | T90467-12009 CLIP X NN | 1.00 | 8.90 | | 8.90 |
| 24 | 3 | L53805-33040 SEAL SUB-ASSY, FR / | 1.00 | 132.30 | | 132.30 |
| 25 | 4 | L53806-33050 SEAL SUB-ASSY FR / | 1.00 | 132.30 | | 132.30 |
| 26 | 5 | L53811-33230 FENDER, FR RH / | 1.00 | 1339.60 | | 1339.60 |
| 27 | 6 | L53835-33100 BRACE, FR FENDER TO / | 1.00 | 71.20 | | 71.20 |
| 28 | 7 | L53827-33070 PROTECTOR, FR FENDER / | 1.00 | 100.70 | | 100.70 |
| 29 | 8 | L53812-33230 FENDER, FR LH / | 1.00 | 1339.60 | | 1339.60 |
| 30 | 9 | L53804-33040 BRACKET SUB-ASSY FR / | 1.00 | 73.10 | | 73.10 |
| 31 | 0 | L53828-33070 PROTECTOR, FR FENDER / | 1.00 | 100.70 | | 100.70 |
| 32 | 1 | L53837-33010 BRACKET, FR SIDE / | 2.00 | 20.50 | | 41.00 |
| 33 | 2 | T90467-07208 CLIP / | 8.00 | 2.70 | | 21.60 |
| 34 | 3 | T90467-07214 CLIP / | 12.00 | 2.60 | | 31.20 |
| 35 | 4 | L81105-33D00 HOUSING SUB-ASSY, HEADLAMP, RH / | 1.00 | 5322.90 | | 5322.90 |
| 36 | 5 | L81106-33B00 UNIT ASSY, HEADLAMP, LH / | 1.00 | 5322.90 | | 5322.90 |
| 37 | 6 | L90981-15021 BULB X NN | 2.00 | 6.80 | | 13.60 |
| 38 | 7 | L81125-33C80 CORD, HEADLAMP X NN | 2.00 | 53.30 | | 106.60 |
| 39 | 8 | L90981-13084 BULB HEADLAMP NO.1 X NN | 2.00 | 85.00 | | 170.00 |
| 40 | 9 | L81135-3A150 COVER, HEADLAMP / | 2.00 | 31.10 | | 62.20 |

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For & on behalf of Borneo Motors | Customer's Signature | Change Summary | Total |
|-------------------------------------|---------------------------------------|---|------------|
| | Please acknowledge receipt of vehicle | Parts Labour Materials Lubrication/Fluid Others | Less |
| | | | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 31/10/2019
TIME 08:15PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLP5240S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

| Account Detail | Account No | Customer Detail |
|---|-----------------------------|--|
| United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept | S1000019 / ICU011 | Mr Chia Eng Poh Denis 24 King Albert Park Singapore 598307 Work: 64663922 |
| | Document No 0 | |
| | Document Date 31/10/2019 | |

| Year | Make | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks |
|------|-------|-------|----------|------------|------------|--------|--------------------------|
| 16 | BETGK | S3 | ASV60R | 30/08/2016 | SLF5240S | 34333 | 17865 40D/SLF5240S/29101 |

| Chassis No | Engine No | Terms | Lexus Consultant | Vehicle In | Collected On |
|-------------------|------------|-------|------------------|------------|----------------------|
| JTHBJ1GGX02093658 | 2ARF234476 | 60 | Wally Tan G H | 30/10/2019 | 0.00 --/--/---- 0.00 |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|----|----|--|------|------------|--------|---------|
| 41 | 0 | L53111-33450 GRILLE, RADIATOR / DR | 1.00 | 1168.70 | | 1168.70 |
| 42 | 1 | L90975-02125 EMBLEM, SYMBOL / DR | 1.00 | 477.90 | | 477.90 |
| 43 | 2 | L53121-33080 MOULDING, RADIATOR / DR | 1.00 | 372.10 | | 372.10 |
| 44 | 3 | T53384-68010 CENTER HOOD CUSHION / MIS | 2.00 | 19.90 | | 39.80 |
| 45 | 4 | L52145-33070 STAY, FR BUMPER / DR | 1.00 | 57.40 | | 57.40 |
| 46 | 5 | L52146-33070 STAY, FR BUMPER / DR | 1.00 | 57.40 | | 57.40 |
| 47 | 6 | L52021-33210 REINFORCEMENT / DR | 1.00 | 498.80 | | 498.80 |
| 48 | 7 | L52611-33280 ABSORBER, FR BUMPER / DR | 1.00 | 154.30 | | 154.30 |
| 49 | 8 | L52125-33120 BRACKET, FOG LAMP / X NN | 1.00 | 168.50 | | 168.50 |
| 50 | 9 | L52126-33120 BRACKET, FOG LAMP / X NN | 1.00 | 168.50 | | 168.50 |
| 51 | 0 | L53155-33060 SEAL, RADIATOR / NPC | 1.00 | 100.70 | | 100.70 |
| 52 | 1 | L52119-3T910 COVER, FR BUMPER / DR | 1.00 | 960.30 | | 960.30 |
| 53 | 2 | L81481-33060 COVER, FOG LAMP, RH / DR | 1.00 | 141.60 | | 141.60 |
| 54 | 3 | L81482-33040 COVER, FOG LAMP, LH / DR | 1.00 | 141.60 | | 141.60 |
| 55 | 4 | L52128-33210 COVER, FR BUMPER / MIS | 1.00 | 86.60 | | 86.60 |
| 56 | 5 | L53127-33020 GRILLE, RADIATOR, (Comp. gov) / DR | 1.00 | 43.00 | | 43.00 |
| 57 | 6 | L53128-33020 GRILLE, RADIATOR, () / DR | 1.00 | 43.00 | | 43.00 |
| 58 | 7 | L53102-33080 GRILLE SUB-ASSY, () / DR (Comp. gov) | 1.00 | 879.60 | | 879.60 |
| 59 | 8 | L52114-33450 BRACKET, FR BUMPER / (Comp. gov) / DR | 1.00 | 141.70 | | 141.70 |
| 60 | 9 | L52197-30040 BUMPER BRACKET, ? / X NN | 2.00 | 7.70 | | 15.40 |

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For & on behalf of Borneo Motors | Customer's Signature | Change Summary | Total |
|-------------------------------------|---------------------------------------|---|------------|
| | Please acknowledge receipt of vehicle | Parts Labour Materials Lubrication/Fluid Others | Less |
| | | | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 31/10/2019
TIME 08:15

VEHICLE NO SLP5240S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1388**ESTIMATE**

| | | |
|---|-------------------|--|
| Account Detail | Account No | Customer Detail |
| United Overseas Insurance Ltd 3 Anson Road #29-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept | S1000019 / ICUOI1 | Mr Chia Eng Poh Denis 24 King Albert Park Singapore 598307 |
| | Document No | Work: 64663922 |
| | Document Date | |
| | 31/10/2019 | |

| Year | Make | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks |
|------|-------|-------|----------|------------|------------|--------|----------------------------|
| 16 | BETGK | S3 | ASV60R | 30/08/2016 | SLF5240S | 34333 | 17865 :40D/SLF5240S/29101! |

| Chassis No | Engine No | Terms | Lexus Consultant | Vehicle In | Collected On |
|-------------------|------------|-------|------------------|-----------------|-----------------|
| UTHB1JGGX02093658 | 2ARF234476 | 60 | Wally Tan G H | 30/10/2019 0.00 | --/--/---- 0.00 |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|----|----|--|------|------------|--------|----------|
| 61 | 0 | L47749-50090 CLIP / <i>PPC</i> | 2.00 | 1.80 | | 3.60 |
| 62 | 1 | L53879-30040 RETAINER, FR FENDER / <i>PPC</i> | 2.00 | 12.30 | | 24.60 |
| 63 | 2 | S52161-0K040 BUMPER CLIPS / <i>PPC</i> | 2.00 | 4.10 | | 8.20 |
| 64 | 3 | L89341-78010 C1 SENSOR, ULTRASONIC, / <i>DR (Sensor)</i> | 2.00 | 490.80 | | 981.60 |
| 65 | 4 | L89341-78010 C3 SENSOR, ULTRASONIC, X <i>NN</i> | 2.00 | 490.80 | | 981.60 X |
| 66 | 5 | L89348-76010 CLIP, ULTRASONIC / <i>PPC</i> | 2.00 | 12.10 | | 24.20 |
| 67 | 6 | L89348-78020 RETAINER, ULTRASONIC / <i>PPC</i> | 2.00 | 16.40 | | 32.80 |
| 68 | 7 | L89348-35030 CLIP, ULTRASONIC / <i>PPC</i> | 2.00 | 4.30 | | 8.60 |
| 69 | 8 | L81210-48051 LAMP ASSY, FOG RH X <i>NN</i> | 1.00 | 516.00 | | 516.00 |
| 70 | 9 | L81220-48051 LAMP ASSY, FOG, LH X <i>NN</i> | 1.00 | 516.00 | | 516.00 |
| 71 | 0 | L82114-33031 WIRE, ENGINE ROOM, / <i>TN</i> | 1.00 | 213.20 | | 213.20 |
| 72 | 1 | L51441-33200 COVER, ENGINE UNDER, X <i>NN</i> | 1.00 | 232.00 | | 232.00 |
| 73 | 2 | L51442-33200 COVER, ENGINE UNDER, X <i>NN</i> | 1.00 | 312.50 | | 312.50 |
| 74 | 3 | L53851-33050 PAD, FR WHEEL X <i>NN</i> | 1.00 | 60.50 | | 60.50 |
| 75 | 4 | L53852-33050 PAD, FR WHEEL X <i>NN</i> | 1.00 | 60.50 | | 60.50 |
| 76 | 5 | L57107-33032 PLATE SUB-ASSY, FR X <i>NN</i> | 1.00 | 134.60 | | 134.60 |
| 77 | 6 | L57027-33011 MEMBER SUB-ASSY, FR X <i>NN</i> | 1.00 | 983.50 | | 983.50 |
| 78 | 7 | L57108-33032 PLATE SUB-ASSY, FR X <i>NN</i> | 1.00 | 134.60 | | 134.60 |
| 79 | 8 | L57028-33060 MEMBER SUB-ASSY, FR X <i>NN</i> | 1.00 | 1156.00 | | 1156.00 |
| 80 | 9 | L53201-33191 SUPPORT, RADIATOR / <i>DO (R.M.)</i> | 1.00 | 1451.60 | | 1451.60 |

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| | | | |
|-------------------------------------|---------------------------------------|---|------------|
| For & on behalf of Borneo Motors | Customer's Signature | Change Summary | Total |
| | Please acknowledge receipt of vehicle | Parts Labour Materials Lubrication/Fluid Others | Less |
| | | | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 31/10/2019
TIME 08:15

VEHICLE NO SLF5240S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

| Account Detail | Account No | Customer Detail |
|---|-----------------------------|--|
| United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept | S1000019 / ICU011 | Mr Chia Eng Poh Denis 24 King Albert Park Singapore 598307 |
| | Document No 0 | Work: 64663922 |
| | Document Date 31/10/2019 | |

| Year | Make | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks |
|------|-------|-------|----------|------------|------------|--------|--------------------------|
| 16 | BETGK | S3 | ASV60R | 30/08/2016 | SLF5240S | 34333 | 17865 40D/SLF5240S/29101 |

| Chassis No | Engine No | Terms | Lexus Consultant | Vehicle In | Collected On |
|-------------------|------------|-------|------------------|-----------------|-----------------|
| JTHBJ1GGX02093658 | 2ARF234476 | 60 | Wally Tan G H | 30/10/2019 0.00 | --/--/---- 0.00 |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|-----|----|---------------------------------------|------|------------|--------|---------|
| 81 | 0 | L53208-33070 SUPPORT SUB-ASSY, ✓ DO | 1.00 | 152.20 | | 152.20 |
| 82 | 1 | L53736-33040 SEAL, R/FR FENDER ✓ DO | 1.00 | 100.40 | | 100.40 |
| 83 | 2 | L53737-33020 SEAL, FR FENDER ✓ DO | 1.00 | 72.40 | | 72.40 |
| 84 | 3 | L53293-33140 DEFLECTOR, RADIATOR ✓ DR | 1.00 | 158.10 | | 158.10 |
| 85 | 4 | L53294-33150 DEFLECTOR, RADIATOR ✓ DR | 1.00 | 149.20 | | 149.20 |
| 86 | 5 | L53295-33080 SEAL, COOL AIR ✓ MC | 1.00 | 302.70 | | 302.70 |
| 87 | 6 | L90541-15033 CUSHION ✓ MC | 2.00 | 12.80 | | 25.60 |
| 88 | 7 | T90467-07217 CLIP ✓ MC | 9.00 | 2.50 | | 22.50 |
| 89 | 8 | L86510-48050 HORN ASSY, HIGH ✓ DR | 1.00 | 174.40 | | 174.40 |
| 90 | 9 | L86520-48030 HORN ASSY LOW ✓ DR | 1.00 | 139.60 | | 139.60 |
| 91 | 0 | L88460-33180 CONDENSER ASSY ✓ DO | 1.00 | 2726.00 | | 2726.00 |
| 92 | 1 | L88710-33190 TUBE & ACCESSORY X NN | 1.00 | 860.10 | | 860.10 |
| 93 | 2 | L88711-33270 HOSE DISCHARGE X NN | 1.00 | 566.80 | | 566.80 |
| 94 | 3 | L88712-33300 HOSE, SUCTION X NN | 1.00 | 773.80 | | 773.80 |
| 95 | 4 | L88707-33050 TUBE SUB-ASSY X NN | 1.00 | 612.60 | | 612.60 |
| 96 | 5 | L16400-31770 RADIATOR ASSY ✓ DO | 1.00 | 3235.00 | | 3235.00 |
| 97 | 6 | L16561-36020 SEAL, RADIATOR TO ✓ MC | 1.00 | 29.50 | | 29.50 |
| 98 | 7 | L16563-36010 SEAL, RADIATOR TO ✓ MC | 2.00 | 10.20 | | 20.40 |
| 99 | 8 | L16562-36010 SEAL, RADIATOR TO ✓ MC | 1.00 | 23.70 | | 23.70 |
| 100 | 9 | L16523-20020 CUSHION RADIATOR X NN | 2.00 | 19.00 | | 38.00 |

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For & on behalf of Borneo Motors | Customer's Signature | Change Summary | Total |
|-------------------------------------|---------------------------------------|---|------------|
| | Please acknowledge receipt of vehicle | Parts Labour Materials Lubrication/Fluid Others | Less |
| | | | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 31/10/2019
TIME 08:15

VEHICLE NO SLF5240S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR 8500000-9www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388**ESTIMATE**

| Account Detail | Account No | Customer Detail |
|---|--------------------------|--|
| United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept | S1000019 / ICU011 | Mr Chia Eng Poh Denis 24 King Albert Park Singapore 598307 |
| | Document No 0 | Work: 64663922 |
| | Document Date 31/10/2019 | |

| Year | Make | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks |
|------|-------|-------|------------|------------|------------|--------|--------------------|
| 16 | BETGK | S3 | 30/08/2016 | SLF5240S | 34333 | 17865 | 40D/SLF5240S/29101 |

| Chassis No | Engine No | Terms | Lexus Consultant | Vehicle In | Collected On |
|-------------------|------------|-------|------------------|-----------------|-----------------|
| JTHBJ1GGX02093658 | 2ARF234476 | 60 | Wally Tan G H | 30/10/2019 0.00 | --/--/---- 0.00 |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|-----|----|---|------|------------|--------|---------|
| 101 | 0 | L16535-20010 SUPPORT, RADIATOR, <i>X NAI</i> | 2.00 | 19.70 | | 39.40 |
| 102 | 1 | L16711-36120 SHROUD, FAN <i>BR</i> | 1.00 | 371.00 | | 371.00 |
| 103 | 2 | L16361-36040 FAN <i>X NN</i> | 1.00 | 377.90 | | 377.90 |
| 104 | 3 | L16361-36030 FAN <i>X NN</i> | 1.00 | 302.00 | | 302.00 |
| 105 | 4 | L16363-36060 MOTOR, COOLING FAN <i>X NAI</i> | 1.00 | 768.70 | | 768.70 |
| 106 | 5 | L16363-23010 MOTOR, COOLING FAN <i>X NAI</i> | 1.00 | 616.40 | | 616.40 |
| 107 | 6 | L16470-36010 RESERVE TANK ASSY <i>BR</i> | 1.00 | 237.30 | | 237.30 |
| 108 | 7 | L16571-36100 HOSE, RADIATOR <i>X NN</i> | 1.00 | 64.40 | | 64.40 |
| 109 | 8 | L16572-36110 HOSE, RADIATOR, NO.2 <i>X NN</i> | 1.00 | 84.00 | | 84.00 |
| 110 | 9 | L17750-36021 INLET ASSY, AIR <i>BR</i> | 1.00 | 262.30 | | 262.30 |
| 111 | 0 | L17700-36230 CLEANER ASSY AIR <i>BR</i> | 1.00 | 1279.10 | | 1279.10 |
| 112 | 1 | L85315-33461 JAR, WASHER, A <i>X NN</i> | 1.00 | 273.50 | | 273.50 |
| 113 | 2 | L85319-33230 PACKING, <i>X NN</i> | 1.00 | 10.90 | | 10.90 |
| 114 | 3 | L85397-30400 SWITCH, LEVEL <i>X NN</i> | 1.00 | 121.70 | | 121.70 |
| 115 | 4 | L85330-47010 MOTOR & PUMP ASSY <i>X NAI</i> | 1.00 | 291.60 | | 291.60 |

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

| For & on behalf of Borneo Motors | Customer's Signature | Change Summary | Total |
|-------------------------------------|---------------------------------------|---|------------|
| | Please acknowledge receipt of vehicle | Parts Labour Materials Lubrication/Fluid Others | Less |
| | | | Amount Due |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 31/10/2019
TIME 08:15PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLF5240S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

**TAX INVOICE****Borneo Motors (Singapore) Pte Ltd**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1388**ESTIMATE**

| Account Detail | Account No | Customer Detail |
|---|-----------------------------|--|
| United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept | S1000019 / ICUOI1 | Mr Chia Eng Poh Denis 24 King Albert Park Singapore 598307 |
| | Document No 0 | Work: 64663922 |
| | Document Date 31/10/2019 | |

| Year | Make | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks |
|-------------------|------------|-------|------------------|------------|--------------|------------|--------------------------|
| 16 | BETGK | S3 | ASV60R | 30/08/2016 | SLF5240S | 34333 | 17865 40D/SLF5240S/29101 |
| Chassis No | Engine No | Terms | Lexus Consultant | Vehicle In | Collected On | | |
| JTHBJ1GGX02093658 | 2ARF234476 | 60 | Wally Tan G H | 30/10/2019 | 0.00 | --/--/---- | 0.00 |

| L | Cd | Job/Parts Description | Qty | Unit Price | Disc % | Amount |
|-----|----|--|-----|------------|--------|--------|
| 116 | T | BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE. | | | | |
| | | <p><i>Steve (LKK) 8322 8813</i> <i>Steve@lkkauto.com</i> <i>31/10/19, 1:00pm</i></p> <p><i>00 - Not Author (Repd)</i> <i>Excess - \$800</i> <i>12 days</i> <i>Ry be F sm</i> <i>P/P</i></p> | | | | |
| | | <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> | | | | |
| | | Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply. | | | | |

| For & on behalf of Borneo Motors | Customer's Signature | Change Summary | Total |
|-------------------------------------|---------------------------------------|------------------------|----------------------|
| | Please acknowledge receipt of vehicle | Parts 46,978.80 | 60,705.30 |
| | | Labour 13,630.50 | GST 7.00% 4,249.37 |
| | | Materials 96.00 | Less 0.00 |
| | | Lubrication/Fluid 0.00 | |
| | | Others 0.00 | Amount Due 64,954.67 |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 31/10/2019
TIME 08:15

VEHICLE NO SLF5240S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Inchcape



Attn: Steve
Final Bill

TAX INVOICE


Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

| | | | | | | | | | |
|--|----------|---|------------|------------------------|------------------|--|--------------------|------------|----------|
| Account Detail | | | | Account No | | Customer Detail | | | |
| United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept | | | | S1000019 / ICUOI1 | | Mr Chia Eng Poh Denim 24 King Albert Park Singapore 598307 Work: 64663922 | | | |
| | | | | Document No | | | | | |
| | | | | 0 | | | | | |
| | | | | Document Date | | | | | |
| | | | | 13/12/2019 | | | | | |
| Year | Make | Model | Reg Date | Veh Reg No | Kilometers | WIP No | Order No/Remarks | | |
| 16 | BETGK S3 | ASV60R | 30/08/2016 | SLF5240S | 34333 | 17865 | 40D/SLF5240S/29101 | | |
| Chassis No | | Engine No | | Terms | Lexus Consultant | Vehicle In | Collected On | | |
| JTHBJ1GGX02093658 | | 2ARF234476 | | 60 | Wally Tan G H | 30/10/2019 | 0.00 | 22/11/2019 | 18.00 |
| L | Cd | Job/Parts Description | | | | Qty | Unit Price | Disc% | Amount |
| 1 | Z | BP-SUNDRY SUNDRIES POLICY NO.:DHOM110169691900 ACC DATE:29.10.19 TOW/DRIVE IN:29.10.19 EXCESS:\$800/- DATE-IN: DATE SURVEY:31.10.19 NO OF REPAIR DAYS: BY:STEVE (LKK) AUTHORIZED ON:01.11.19 | | | | | | | |
| 2 | V | EXC Excess element of insurance repair to be 88 paidby the insured party | | | | | | | -800.00 |
| 3 | M | BP-REC GLOBAL SUM REPAIR | | | | | | | 42000.00 |
| <p>Offer 42K Finalize, 12 days</p> <p>Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.</p> | | | | | | | | | |
| For & on behalf of Borneo Motors | | Customer's Signature | | Change Summary | | Total 41,200.00 | | | |
|  | | Please acknowledge receipt of vehicle | | Parts 0.00 | | GST 7.00% 2,884.00 | | | |
| | | | | Labour 42,000.00 | | Less 0.00 | | | |
| | | | | Materials 0.00 | | | | | |
| | | | | Lubrication/Fluid 0.00 | | | | | |
| | | | | Others 0.00 | | Amount Due 44,084.00 | | | |

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 13/12/2019
TIME 14:32

VEHICLE NO SLF5240S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Steve Chen (LKK Auto)

From: Steve Chen (LKK Auto)
Sent: Friday, November 01, 2019 2:57 PM
To: Wally Tan PTCBC
Cc: Dion Wang; Ivan Ng PTCBC; Alvin Lee Yee Peng PTCBC; Denise Tay
Subject: SLF5240S

Dear Wally,

We agreed 42k global sum repair.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wally Tan PTCBC [<mailto:wally.tan@borneomotors.com.sg>]
Sent: Friday, November 01, 2019 10:25 AM
To: Steve Chen (LKK Auto)
Cc: Dion Wang; Ivan Ng PTCBC; Alvin Lee Yee Peng PTCBC
Subject: RE: SLF5240S

Hi Steve,

We needs \$42K for this repair.

Please reply.

Regards

Wally

From: Steve Chen (LKK Auto) [<mailto:SteveChen@lkkauto.com>]
Sent: Thursday, 31 October 2019 6:43 PM
To: Wally Tan PTCBC
Cc: Denise Tay (LKKAuto)
Subject: SLF5240S

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Dear Wally,




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|-----------------------------|---|
| UNITED OVERSEAS INSURANCE LTD | | | Ref : CS/UOI19019240/Etf3e2 | |
| 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909 | | | Date : 02-01-2020 |  |
| | | | Code : UOI2 | |
| 1. Policy Particulars :- OWN DAMAGE | | | | |
| Insured Veh. | | Veh. Inspected | | SLF 5240S |
| Policy No. | | Coverage (\$) | | 0.00 |
| Claim No. | DHOM110169691900 | Excess (\$) | | 800.00 |
| Assign From | JENNY LEW | Assign Date | | 31/10/2019 |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | LEXUS ES250 | c.c | 2494 | |
| Engine No. | HIDDEN | Year of Reg. | 2016 | |
| Chassis No. | JTHBJ1GGX02093658 | Colour | BLACK | |
| Odometer | 34333 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 215/55 R17 | YOKOHAMA | 5 mm | |
| L/H Front Tyre | 215/55 R17 | YOKOHAMA | 5 mm | |
| R/H Rear Tyre | 215/55 R17 | YOKOHAMA | 5 mm | |
| L/H Rear Tyre | 215/55 R17 | YOKOHAMA | 5 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. | | | | |
| DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 29/10/2019 | Inspection Date | 31/10/2019 | |
| Survey held at | BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462 | | | |
| 5a. Remarks | | | | |
| A) THE MARKET VALUE IS S\$121,000.00 (EST. AVERAGE) | | | | |
| B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 12 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5240S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------|---------------|---------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | SUNDRIES (SN) | NECESSARY | 80.00 | 50.00 |
| 1 | SEALANT (SN) | NECESSARY | 200.00 | 200.00 |
| 1 | HOOD SUB-ASSY (SN) | DENTED | 2,252.60 | 2,252.60 |
| 1 | INSULATOR, HOOD (SN) | CRUSHED | 349.70 | 349.70 |
| 11 | CLIP (SN) | NECESSARY | 31.90 | 31.90 |
| 1 | LABEL, COOLER (SN) | NECESSARY | 4.30 | 4.30 |
| 1 | HINGE ASSY, HOOD, RH (SN) | BENT | 83.60 | 83.60 |
| 1 | HINGE ASSY, HOOD, LH (SN) | BENT | 83.60 | 83.60 |
| 1 | SUPPORT ASSY, HOOD (SN) | NOT NECESSARY | 349.70 | - |
| 1 | SUPPORT ASSY, HOOD (SN) | NOT NECESSARY | 349.70 | - |
| 1 | LOCK ASSY, HOOD (SN) | BENT | 168.50 | 168.50 |
| 1 | CABLE ASSY HOOD (SN) | NOT NECESSARY | 68.50 | - |
| 2 | CLAMP (SN) | NOT NECESSARY | 10.00 | - |
| 1 | CLIP (SN) | NOT NECESSARY | 8.90 | - |
| 1 | SEAL SUB-ASSY, FR (SN) | CRUSHED | 132.30 | 132.30 |
| 1 | SEAL SUB-ASSY FR (SN) | CRUSHED | 132.30 | 132.30 |
| 1 | FENDER, FR RH (SN) | DENTED | 1,339.60 | 1,339.60 |
| 1 | BRACE, FR FENDER TO (SN) | DENTED | 71.20 | 71.20 |
| 1 | PROTECTOR, FR FENDER (SN) | DENTED | 100.70 | 100.70 |
| 1 | FENDER, FR LH (SN) | DENTED | 1,339.60 | 1,339.60 |
| 1 | BRACKET SUB-ASSY FR (SN) | DENTED | 73.10 | 73.10 |
| 1 | PROTECTOR, FR FENDER (SN) | DENTED | 100.70 | 100.70 |
| 2 | BRACKET, FR SIDE (SN) | DENTED | 41.00 | 41.00 |
| 8 | CLIP (SN) | NECESSARY | 21.60 | 21.60 |
| 12 | CLIP (SN) | NECESSARY | 31.20 | 31.20 |
| 1 | HOUSING SUB-ASSY, HEADLAMP, RH (SN) | BROKEN | 5,322.90 | 5,322.90 |
| 1 | UNIT ASSY, HEADLAMP, LH (SN) | BROKEN | 5,322.90 | 5,322.90 |
| 2 | BULB (SN) | NOT NECESSARY | 13.60 | - |
| 2 | CORD, HEADLAMP (SN) | NOT NECESSARY | 106.60 | - |
| 2 | BULB HEADLAMP NO.1 (SN) | NOT NECESSARY | 170.00 | - |
| 2 | COVER, HEADLAMP (SN) | BROKEN | 62.20 | 62.20 |
| 1 | GRILLE, RADIATOR (SN) | BROKEN | 1,168.70 | 1,168.70 |
| 1 | EMBLEM, SYMBOL (SN) | BROKEN | 477.90 | 477.90 |
| 1 | MOULDING, RADIATOR (SN) | BROKEN | 372.10 | 372.10 |

Report Ref No. CS/UOI19019240/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------|---------------|---------------------------|-------------------|
| 2 | CENTER HOOD CUSHION (SN) | MISSING | 39.80 | 39.80 |
| 1 | STAY, FR BUMPER (SN) | BROKEN | 57.40 | 57.40 |
| 1 | STAY, FR BUMPER (SN) | BROKEN | 57.40 | 57.40 |
| 1 | REINFORCEMENT (SN) | DENTED | 498.80 | 498.80 |
| 1 | ABSORBER, FR BUMPER (SN) | BROKEN | 154.30 | 154.30 |
| 1 | BRACKET, FOG LAMP (SN) | NOT NECESSARY | 168.50 | - |
| 1 | BRACKET, FOG LAMP (SN) | NOT NECESSARY | 168.50 | - |
| 1 | SEAL, RADIATOR (SN) | NECESSARY | 100.70 | 100.70 |
| 1 | COVER, FR BUMPER (SN) | BROKEN | 960.30 | 960.30 |
| 1 | COVER, FOG LAMP, RH (SN) | BROKEN | 141.60 | 141.60 |
| 1 | COVER, FOG LAMP, LH (SN) | BROKEN | 141.60 | 141.60 |
| 1 | COVER, FR BUMPER (SN) | MISSING | 86.60 | 86.60 |
| 1 | GRILLE, RADIATOR (SN) | BROKEN | 43.00 | 43.00 |
| 1 | GRILLE, RADIATOR (SN) | BROKEN | 43.00 | 43.00 |
| 1 | GRILLE SUB-ASSY (SN) | BROKEN | 879.60 | 879.60 |
| 1 | BRACKET-FR BUMPER (SN) | BROKEN | 141.70 | 141.70 |
| 2 | BUMPER BRACKET, (SN) | NOT NECESSARY | 15.40 | - |
| 2 | CLIP (SN) | NECESSARY | 3.60 | 3.60 |
| 2 | RETAINER, FR FENDER (SN) | NECESSARY | 24.60 | 24.60 |
| 2 | BUMPER CLIPS (SN) | NECESSARY | 8.20 | 8.20 |
| 2 | SENSOR, ULTRASONIC (SN) | BROKEN | 981.60 | 981.60 |
| 2 | SENSOR, ULTRASONIC (SN) | NOT NECESSARY | 981.60 | - |
| 2 | CLIP, ULTRASONIC (SN) | NECESSARY | 24.20 | 24.20 |
| 2 | RETAINER, ULTRASONIC (SN) | NECESSARY | 32.80 | 32.80 |
| 2 | CLIP, ULTRASONIC (SN) | NECESSARY | 8.60 | 8.60 |
| 1 | LAMP ASSY, FOG RH (SN) | NOT NECESSARY | 516.00 | - |
| 1 | LAMP ASSY, FOG, LH (SN) | NOT NECESSARY | 516.00 | - |
| 1 | WIRE, ENGINE ROOM, (SN) | TORN | 213.20 | 213.20 |
| 1 | COVER, ENGINE UNDER, (SN) | NOT NECESSARY | 232.00 | - |
| 1 | COVER, ENGINE UNDER, (SN) | NOT NECESSARY | 312.50 | - |
| 1 | PAD, FR WHEEL (SN) | NOT NECESSARY | 60.50 | - |
| 1 | PAD, FR WHEEL (SN) | NOT NECESSARY | 60.50 | - |
| 1 | PLATE SUB-ASSY, FR (SN) | NOT NECESSARY | 134.60 | - |
| 1 | MEMBER SUB-ASSY, FR (SN) | NOT NECESSARY | 983.50 | - |
| 1 | PLATE SUB-ASSY, FR (SN) | NOT NECESSARY | 134.60 | - |
| 1 | MEMBER SUB-ASSY, FR (SN) | NOT NECESSARY | 1,156.00 | - |

Report Ref No. CS/UOI19019240/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------|---------------|---------------------------|-------------------|
| 1 | SUPPORT, RADIATOR (SN) | DENTED | 1,451.60 | 1,451.60 |
| 1 | SUPPORT SUB-ASSY (SN) | DENTED | 152.20 | 152.20 |
| 1 | SEAL, R/FR FENDER (SN) | DENTED | 100.40 | 100.40 |
| 1 | SEAL, FR FENDER (SN) | DENTED | 72.40 | 72.40 |
| 1 | DEFLECTOR, RADIATOR (SN) | BROKEN | 158.10 | 158.10 |
| 1 | DEFLECTOR, RADIATOR (SN) | BROKEN | 149.20 | 149.20 |
| 1 | SEAL, COOL AIR (SN) | NECESSARY | 302.70 | 302.70 |
| 2 | CUSHION (SN) | NECESSARY | 25.60 | 25.60 |
| 9 | CLIP (SN) | NECESSARY | 22.50 | 22.50 |
| 1 | HORN ASSY, HIGH (SN) | BROKEN | 174.40 | 174.40 |
| 1 | HORN ASSY LOW (SN) | BROKEN | 139.60 | 139.60 |
| 1 | CONDENSER ASSY (SN) | DENTED | 2,726.00 | 2,726.00 |
| 1 | TUBE & ACCESSORY (SN) | NOT NECESSARY | 860.10 | - |
| 1 | HOSE DISCHARGE (SN) | NOT NECESSARY | 566.80 | - |
| 1 | HOSE, SUCTION (SN) | NOT NECESSARY | 773.80 | - |
| 1 | TUBE SUB-ASSY (SN) | NOT NECESSARY | 612.60 | - |
| 1 | RADIATOR ASSY (SN) | DENTED | 3,235.00 | 3,235.00 |
| 1 | SEAL, RADIATOR TO (SN) | NECESSARY | 29.50 | 29.50 |
| 2 | SEAL, RADIATOR TO (SN) | NECESSARY | 20.40 | 20.40 |
| 1 | SEAL, RADIATOR TO (SN) | NECESSARY | 23.70 | 23.70 |
| 2 | CUSHION RADIATOR (SN) | NOT NECESSARY | 38.00 | - |
| 2 | SUPPORT, RADIATOR (SN) | NOT NECESSARY | 39.40 | - |
| 1 | SHROUD FAN (SN) | BROKEN | 371.00 | 371.00 |
| 1 | FAN (SN) | NOT NECESSARY | 377.90 | - |
| 1 | FAN (SN) | NOT NECESSARY | 302.00 | - |
| 1 | MOTOR, COOLING FAN (SN) | NOT NECESSARY | 768.70 | - |
| 1 | MOTOR, COOLING FAN (SN) | NOT NECESSARY | 616.40 | - |
| 1 | RESERVE TANK ASSY (SN) | BROKEN | 237.30 | 237.30 |
| 1 | HOSE, RADIATOR (SN) | NOT NECESSARY | 64.40 | - |
| 1 | HOSE, RADIATOR, NO.2 (SN) | NOT NECESSARY | 84.00 | - |
| 1 | INLET ASSY, AIR (SN) | BROKEN | 262.30 | 262.30 |
| 1 | CLEANER ASSY AIR (SN) | BROKEN | 1,279.10 | 1,279.10 |
| 1 | JAR, WASHER, A (SN) | NOT NECESSARY | 273.50 | - |
| 1 | PACKING (SN) | NOT NECESSARY | 10.90 | - |
| 1 | SWITCH, LEVEL (SN) | NOT NECESSARY | 121.70 | - |

Report Ref No. CS/UOI19019240/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---------------------------------------|--|---------------|---------------------------|-------------------|
| 1 | MOTOR & PUMP ASSY (SN) | NOT NECESSARY | 291.60 | - |
| | | | 47,258.80 | 34,909.80 |
| | LABOUR | | | |
| | TOWING CHARGE | | 208.00 | 208.00 |
| | CHECK WIRING SYSTEM AND FOCUS HEADLAMP. | | 216.50 | 216.50 |
| | REMOVE / REFIX FRONT PARKING SENSORS. | | 216.50 | 216.50 |
| | REMOVE / REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING AND FIT NEW PARTS. | | 866.00 | 866.00 |
| | REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS, R/F AND L/F DOOR EDGES, CUT AND WELD PANEL AND FIT NEW PARTS. | | 6,062.00 | 5,196.00 |
| | SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. | | 5,565.00 | 5,194.00 |
| | TO RESET ECU & REPROGRAMME. | | 216.50 | 216.50 |
| | SUPPLY REGN PLATE (PO#) FRONT. | | 96.00 | 96.00 |
| | | | 13,446.50 | 12,209.50 |
| | GRAND TOTAL | | 60,705.30 | 47,119.30 |
| RECOMMENDED COST OF REPAIR SUM | | | | 42,000.00 |
| LESS EXCESS | | | | -800.00 |
| NETT LIABILITY | | | | 41,200.00 |

Report Ref No. CS/UOI19019240/Etf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.