

SPR00001

U.S. REC. DIV.

REF: CS/SPF19019242/RI+L307 Special Instruction:

Surveyor: RUSH

ASSIGNMENT (Office)

From (Person): Frankie Thuy of SPF Date/Time: 31/10/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / IVA / INV / MV / CS

To Inspect Vehicle No: SLN820J Insured: QX 234P

at Workshop n/s Trans Eurocare Tel: 81289802 Jess

of JFA Tanjung Penjuru

Policy No: _____ Claim No: AEMD/105/009/509/108

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. _____
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____


Date/Time: 31/10 Person Contacted: Jess Vehicle: (IN) OUT

Date/Time	Action/Instruction
	<u>Estimate ()</u>
	<u>SLN820J-X</u>
	<u>Pending Liability. Submit preli report.</u>

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLN 820J
 at Workshop m/s TRANSEUROKARS
 of 27A, Tanjong Pagar
 Insured: SAP
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLN 820J Yr Regt: 2017 / MPR
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MAZDA 3 1.5 AT c.c. 1496
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp Reading: 37310 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6BN22A8H015114X
 Gen. Cond: Good / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / Rim / STD A/Rim or _____
 Tyre Size: F: 205/50R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FRANKEN
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 27/10/19 D.O.I. 31/10/19
 Survey held at TRANSEUROKARS
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear o/s
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit 15K
RECEIVED 28 NOV 2019	

Date/Time, File Pass to? Prel. Report
 Final Report
 28/11/19 Typist

Days Of Repair: 27
 Resurvey No. of Trip: _____

- Add Fee:
- Site Insp (S)
 - Interview (S)
 - Tech. Insp (S)
 - (Make) Crs (S)

Survey Fee:	<u>220</u>
Transportation:	_____
S + PS	_____
Phone	_____
Other:	_____
TOTAL:	220

Report Format: TP
 Long Description: _____

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Thursday, 31 October 2019 9:45 AM
To: assignments; Veron Chen (LKKAuto)
Cc: Hafizul Farhan RAHMAT (SPF); Cui Fen ENG (SPF)
Subject: RE: PRE-REPAIR INSPECTION

Your reference: SLN 820J
Our reference: AEMD/105/009/2019/108

Veron,
Please conduct a Pre-Repair Inspection for the vehicle SJN820 J at the address listed below:

Trans Eurokars Pte Ltd
27 A Tanjong Penjuru
Singapore 609042
Contact person: Mr Jess Francis Carlos at 81289802

Thanks.

Frankie Thay (Mr)
1 Logistics Services Executive
Logistics Support & Services Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

Nivitha - Raveel

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Denise Tay (LKKAuto)

From: jess.francis@eurokars.com.sg
Sent: Tuesday, 26 November 2019 4:18 PM
To: Denise Tay (LKKAuto)
Subject: RE: SPF ref - QX234P / Our ref - SLN820J / DOA Oct 27, 2019 // REQUESTING FOR PRI

Hi Denise,

The owner opted to claim to his insurance policy first since up to now there is no answer from the SPF.

Regards.

Jess Francis Carlos
Insurance Claims Executive
Trans Eurokars Pte Ltd
27A Tanjong Penjuru
Singapore 609042
Tel no.: 8128 9802

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: 26 November 2019 3:38 PM
To: Jess Francis Amurao Carlos <jess.francis@eurokars.com.sg>
Subject: RE: SPF ref - QX234P / Our ref - SLN820J / DOA Oct 27, 2019 // REQUESTING FOR PRI

Dear Jess,

Can update the status of this case?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jess.francis@eurokars.com.sg <jess.francis@eurokars.com.sg>
Sent: Thursday, 7 November 2019 5:45 PM
To: Frankie_THAY@spf.gov.sg
Cc: Rosalyn_TAN@spf.gov.sg; ronald.yap@eurokars.com.sg; samuel.ng@eurokars.com.sg; Admin-D (LKKAuto) <admin-d@lkkauto.com>; [Hafizul Farhan_RAHMAT@spf.gov.sg](mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg); [ENG Cui Fen@spf.gov.sg](mailto:ENG_Cui_Fen@spf.gov.sg)
Subject: RE: SPF ref - QX234P / Our ref - SLN820J / DOA Oct 27, 2019 // REQUESTING FOR PRI

Sir,

May we have the liability for this case please.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2019 08:05
Date Of Accident	27/10/2019 21:50
Exact Location Of Accident	REPUBLIC BLVD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN820J
Insured/Policyholder	
Name Of Registered Owner	MR WONG WEI SHENG
NRIC No	S8711385Z
Email Address	WILSONKOG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83636106
Alternative Phone No	OFFICE-83636106
Vehicle Particulars	
Manufacturer	MAZDA
Model	3-1.5 STANDARD SKYACTIV (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA472641/1
Cover Note Number	
Driver	
Name of Driver	WONG HAN LIANG
NRIC No	S9228053E
Date Of Birth	13/08/1992
Occupation	INDOOR
Date Of Driving Pass	30/12/2011
Driving Experience	7 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92719371
Fax Number	
Contact Number	
Email Address	HLWONG_92@HOTMAIL.COM

Address	BLK 158 WOODLANDS STREET 13 #11-715
Postcode	730158
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHAN HONG YING GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO. - FAX NO.
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX234P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOBILE EQUIPMENT
Name of Driver	LIM ZHENG HONG
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name WONG HAN LIANG

Approximate Age

Injuries Sustain TBA

Injured person in which vehicle? SLN820J

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name CHAN HONG YING

Approximate Age

Injuries Sustain TBA

Injured person in which vehicle? SLN820J

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature:
Date & Time:

x 

Driver's Signature
(If driver is not the policyholder)
Date & Time:


JESS FRANCIS CARLOS
29-10-2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20191028/7013

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20191028/7013

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/10/2019 19:49	Video Report No.: A/20191027/0201	Station Diary No.:
--	--------------------------------------	--------------------

Informant's Particulars

Name of Informant: WONG WEI SHENG		Address: APT BLK 158 WOODLANDS STREET 13 #11-715 SINGAPORE 730158	
ID Type / ID No.: NRIC NO / S8711385Z		Contact No.: Home/Office: Mobile: 85000268	
Nationality: SINGAPORE CITIZEN		Email: wilsonkog@gmail.com	
Sex: Male	Age: 32	Date of Birth: 06/05/1987	Type of Informant: Vehicle Owner
Race: Chinese		Language: English	Institution / School Name:
Occupation: RSAF engineer		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 27/10/2019 22:00	Type of Location: T-Junction
Location: REPUBLIC BOULEVARD			
Weather: Raining	Road Surface: Wet	Road Speed Limit: 60 Km/h	
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLN820J (Not Accurate)	Car	MAZDA	Mazda 3	Grey	Seriously Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLN820J (Not Accurate)	AXA INSURANCE SINGAPORE PTE LTD	GA472641/1	07/06/2019	06/06/2020

Sketch Plan Pg. 4



SINGAPORE
POLICE FORCE



T201910287013

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4

Report No. T201910287013

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	WONG HAN LIANG	ID No.	S9228053E
Related Vehicle	SLN820J (Car)	Contact No.	92719371
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	CHAN HONG YING	ID No.	S9517843Z
Related Vehicle	SLN820J (Car)	Contact No.	84981618
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Vehicle Owner			
Name	WONG WEI SHENG	ID No.	S8711385Z
Related Vehicle	NIL	Contact No.	85000268
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

My brother, wong han liang, was driving our car mazda 3 grey sedan, SLN820J. Travelling along republic blvd to raffles ave. He stopped at the junction waiting for red light. When he saw a motorcycle rode pass him at his right side. Soon after, a police vehicle, QX234P, collided with our vehicle. Our vehicle was being pushed to the centre of the junction and was instructed to move the vehicle to the side by the police, in order not to obstruct the traffic. Police officer, Lim Zhang Hong ID:T160233 was the driver of the police vehicle. SCDF ambulance and Traffic police arrived to the scene. Traffic police, muhaimin accessed the situation and advised to lodge a accident report online via SPF Electronic Police Centre website. Tow service was required for our vehicle

Sketch Plan Pg. 5



**SINGAPORE
POLICE FORCE**



T/20191028/7013

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20191028/7013

CONTINUATION OF REPORT

Sketch Plan Pg. 6



**SINGAPORE
POLICE FORCE**



T/20191028/7013

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20191028/7013

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / TPIB / NOR FAIZAL BIN YAHYA Contact No.: 65476202

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 28/10/2019 19:49
Classification Of Case:

Authentication Stamp

NP168



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191030/7014

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	WONG HAN LIANG	ID No.	S9228053E
Related Vehicle	SLN820J (Car)	Contact No.	92719371
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	29/10/2019	Date Discharge	29/10/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Passenger			
Name	CHAN HONG YING	ID No.	S9517843Z
Related Vehicle	SLN820J (Car)	Contact No.	91871628
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	29/10/2019	Date Discharge	29/10/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Vehicle Owner			
Name	WONG WEI SHENG	ID No.	S8711385Z
Related Vehicle	NIL	Contact No.	85000268
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

i, Wong Han Liang (s9228053e) was driving Mazda 3 grey sedan, SLN820J. Travelling along republic blvd to raffles ave. As i was waiting for the red light, i saw a motorcycle rode pass by my right side. Soon after, a police vehicle, QX234P, collided with our vehicle. The Mazda was being forced to the centre of the junction and was instructed to move to the side by the police officer in order not to obstruct the traffic. Police offer Lim Zheng Hong ID:T160233 was the driver of the police vehicle. SCDF ambulance and Traffic police arrived to the scene. After checking, the traffic police have dismiss us and told to get the tow the vehicle to own workshop.



**SINGAPORE
POLICE FORCE**



T/20191030/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20191030/7014

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20191030/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No: T/20191030/7014

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
NOR FAIZAL BIN YAHYA
Contact No.: 65476202

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
30/10/2019 13:54

Classification Of Case:



redefining / insurance

AXA Insurance Pte Ltd
 1600 890 4688 (Within Singapore)
 (65) 6880 4998 (International)
 (65) 6880 4748
 customer.care@axa.com.sg
 www.axa.com.sg

Certificate of Insurance

account number
 15277

Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) Motor Vehicles (Third Party Risks and Compensation) Rules, 1987 (Road Transport Act, 1987 (Malaysia))
 Motor Vehicles (Third Party Risks) Rules, 1987 (Malaysia)

Policy details

Policyholder name	WONG WEI SHENG	Certificate number	GA472641 / 1
Cover	Comprehensive	Chassis number	JM68N22ABH0151144
Plan name	Essential+	Engine number	P520442409
NCD applicable	10%		
Vehicle registration number	SLN820J		
Period of Insurance	from 07/06/2019 to 06/06/2020 (both dates inclusive)		
Finance loan company	Maybank Singapore Limited		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, is in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations imposed hereunder by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	\$55,250.00
	Windscreen Excess	\$10,100.00

An Additional Excess is applicable as follows:

1. S\$500 for unlicensed Authorized Driver
2. S\$500 for declared Young and Inexperienced Driver
3. S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Additional Clause 1

Loss of use benefit is amended to:
 Daily transport allowance of \$50 for a maximum of ten (10) days

We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorized signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance with the Policy to the insurance company, if the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third Party Risks and Compensation) Act (Ch. 189).

The Premium Waiver Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd (199902512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3852
Vehicle Details	
Vehicle No.:	5LN820J
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520442409
Chassis No.:	JM6BN22A8H0151144
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,476.00
Original Registration Date:	21 Apr 2017
First Registration Date:	21 Apr 2017
Transfer Count:	1
Actual ARF Paid:	\$9,476.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Apr 2027
PARF Rebate Amount:	\$7,107.00
Intended COE Rebate Details	
COE Expiry Date:	20 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$37,436.00
Total Rebate Amount:	\$44,543.00

The information contained herein is correct as at 31 Oct 2019

OK

60,000
 44,543

 15,457
 (15K)



ESTIMATE COST OF REPAIRS

SPF ACCIDENT CLAIMS SECTION		NAME : Mr Wong Wei Sheng LTPI	WIP : 54793
AUTOMOTIVE ENGINEERING & MANAGEMENT		ADDRESS : Blk 158 Woodlands Street 13	EXCESS :
DIVISION POLICE LOGISTIC DEPARTMENT		#11-715	DATE: 30-Oct-19
1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY		Singapore 730158	
ATTN. :	MOTOR CLAIMS	TEL : 85000268	
FAX :			

VEH NO :	SLN820J	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BN22ABH0151144	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	21-Apr-17	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	FRONT BUMPER	1	MB63B-50-031BBB		866.80
2	RETAINER LHS	1	MBHN1-50-001E		19.70
3	CLIP, FRONT BUMPER	12	MC274-50-133		44.40
4	GROMMET, FRONT BUMPER	2	MGHP9-50-025		5.80
5	FASTENER, FRONT BUMPER	2	MB45A-56-146A		6.00
6	SEAL RUBBER, FRONT BUMPER	2	MB63B-50-2G2		4.80
7	RIVET, FRONT BUMPER	4	MS51S-51-833		16.00
8	RIVET, FRONT BUMPER	4	MTK21-50-355		36.80
9	FASTENER, FRONT BUMPER	8	MGD7A-50-EA1		25.60
10	FRONT FENDER RHS	1	MB45A-52-211B		350.60
11	STAY LHS, FENDER	1	MB45A-52-240		41.90
12	MUDGUARD LHS	1	MB45A-56-140H		101.90
13	FASTENER, MUDGUARD	15	MB45A-56-146A		45.00
14	HEADLAMP LHS	1	MBABK-51-0L0E		1,070.50
15	CORD SHORT, HEADLAMP	1	MBHN1-51-0K6A		150.80
16	RIVET, HEADLAMP	1	MB092-51-833		3.50
17	CLIP, HEADLAMP	2	MDR61-50-133		13.00
18	REAR BUMPER <i>TORN</i>	1	MBHN1-50-221ABB		1,128.60
19	RETAINER RHS <i>CR</i>	1	MBHN1-50-2H1A		38.00
20	BRACKET RHS <i>dis</i>	1	MBHN9-51-067B		47.90
21	BRACKET CENTER <i>na</i>	1	MKDS3-50-251		5.40
22	TOWING COVER RHS <i>MIS</i>	1	MBHN1-50-EK1 BB		17.10
23	REFLECTOR RHS <i>MIS</i>	1	MD350-51-5M0E		53.00
24	REAR REINFORCEMENT <i>bt</i>	1	MB45A-50-260		564.20
25	SHIELD SPLASH RHS <i>torn</i>	1	MBHN1-50-340B		74.70
26	GROMMET, REAR BUMPER <i>na</i>	4	MBHN1-50-021A		10.80
27	GROMMET, REAR BUMPER <i>na</i>	2	M9991-00-501		6.00
28	RIVET, REAR BUMPER <i>na</i>	4	MBRM4-50-355		18.00
29	FASTENER, REAR BUMPER <i>na</i>	4	MB45A-56-146A		12.00
30	REAR END PANEL <i>buc</i>	1	MB4YA-70-752		530.40
31	TAILLAMP PANEL RHS <i>buc</i>	1	MB4YA-70-44Y		396.70

Not consistent old damage

32	REAR FENDER RHS <i>grm /</i>	1	MB6YS-70-41X	1,233.00
33	PANEL LWR RHS <i>brn /</i>	1	MB4YA-70-40X	373.20
34	REAR WHEEL ARCH INNER RHS <i>repaired bt /</i>	1	MB4YA-70-11YA	700.10
35	PANEL SIDE RHS, FLOOR PANEL <i>brn /</i>	1	MB45A-53-731	66.00
36	TRIM, END PANEL <i>de /</i>	1	MBHN1-68-89XA	89.40
37	BEZEL LOCK ? <i>mis /</i>	1	MGHK1-68-894	11.40
38	TRIM RHS, BOOTSIDE <i>de /</i>	1	MBHN1-68-850A	247.40
39	FASTENER, TRIM <i>ne /</i>	10	MGJ21-68-885B02	30.00
40	SPONGE, FLOOR PANEL <i>de /</i>	1	MBHN1-68-8MXB	154.80
41	PLUG HOLE, PANEL RHS <i>ne /</i>	1	MB001-56-051	2.40
42	PLUG HOLE, PANEL RHS <i>ne /</i>	1	MBR70-51-264	2.40
43	JOINT DRAIN HOSE RHS, PANEL LOWER ?	1	MBHP2-69-926	6.70
44	EXTRACTOR VENT RHS <i>ca /</i>	1	MD350-51-920A	74.90
45	BOOTLID <i>bt /</i>	1	MBHY2-52-61XB	1,005.30
46	HINGE LHS, BOOTLID ?	1	MB61T-52-720	152.60
47	HINGE RHS, BOOTLID ?	1	MB61T-52-710	152.60
48	WEATHERSTRIP, BOOTLID <i>cut /</i>	1	MBHN1-56-951A	113.10
49	LOCK, BOOTLID ?	1	MGHK1-56-820A	160.70
50	STRIKER, BOOTLID <i>X SW</i>	1	MGG2A-56-840	35.10
51	ORNAMENT, MAZDA <i>ne /</i>	1	MBHN1-51-721	56.10
52	MASCOT, REAR <i>ne /</i>	1	MBHN1-51-730	78.20
53	ORNAMENT, SKYACTIVE <i>ne /</i>	1	MBHN1-51-771	66.80
54	FASTENER, BOOTLID <i>ne /</i>	2	MEG21-51-146	12.40
55	GROMMET, BOOTLID <i>ne /</i>	2	MGA7B-51-146	6.60
56	LAMP LHS, BOOTLID ?	1	MB45A-51-3G0	278.30
57	LAMP RHS, BOOTLID <i>sea /</i>	1	MB45A-51-3F0	278.30
58	TAILLAMP RHS <i>brn /</i>	1	MB45A-51-150B	534.90
59	FASTENER, TAILLAMP <i>ne /</i>	1	MKD53-51-146B	4.10
60	FASTENER, TAILLAMP <i>ne /</i>	1	MGJ6A-51-14Y	15.70
61	GASKET LHS, BOOTLID <i>ne /</i>	1	MB45A-51-3J8	22.00
62	GASKET RHS, BOOTLID <i>ne /</i>	1	MB45A-51-3H8	22.00
63	GASKET LHS, TAILLAMP <i>ne /</i>	1	MBHN1-51-163	22.00
64	GASKET RHS, TAILLAMP <i>ne /</i>	1	MBHN1-51-153	22.00
65	BRACKET SIDE RHS, BOOTLID LAMP <i>ne /</i>	1	MB45A-51-3HXA	28.40
66	LAMP LHS, LICENCE PLATE <i>X SW</i>	1	MB45A-51-2L0A	74.70
67	LAMP RHS, LICENCE PLATE ?	1	MB45A-51-270A	74.70
68	REAR WINDSCREEN MOULDING <i>ne /</i>	1	MBHN1-50-611C	77.00
69	SPACER, REAR WINDSCREEN <i>ne /</i>	1	MC001-50-897	4.70
70	GUARD STONE LHS <i>ne /</i>	1	MBHS2-50-4R2	17.40
71	GUARD STONE RHS <i>ne /</i>	1	MBHS2-50-4P2	18.20
72	REAR BEARING RHS ?	1	MB45A-26-15X	434.90
73	REAR KUNCKLE RHS ?	1	MBHR1-26-11XA	686.70
74	REAR DAMPER RHS ?	1	MSAHD-28-910A	322.40
75	REAR UPPER ARM RHS ?	1	MB45C-28-C10	190.90
76	REAR LOWER ARM RHS ?	1	MB45A-28-300C	262.80
77	REAR TRAILING ARM RHS ?	1	MB45A-28-200A	211.00
78	REAR LINK LATERAL RHS ?	1	MB63B-28-500	104.50
79	CROSSMEMBER REAR ?	1	MB63B-28-80X	869.20

80	BOLT	?	4	M9YA0-21-233		47.60
81	NUT	?	4	M9YB0-41-242		40.00
82	BOLT	?	4	M9YA0-2A-024		44.00
83	BOLT	?	4	M9YA0-21-451		44.00
84	SILENCER, EXHAUST	bt /	1	MP512-40-100C		1,129.60
85	HANGER, SILENCER	re /	2	MBP47-40-061A		70.00
86	GASKET, SILENCER	re /	1	MP549-40-305		15.40
87	CONVERTER, EXHAUST	bt /	1	MP535-20-55X		1,449.00
88	GASKET, CONVERTER	re /	1	MP549-40-305		15.40
89	REAR STABILIZER LINK ROD RHS	?	1	MKD31-28-170		87.80
90	REAR WHEEL RIM RHS	cut /	1	MD9965-D0-6560		1,156.80
TOTAL PARTS						19,213.50
TOTAL PARTS COST						19,213.50

Labour Description

1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		X	1,320.00
2	MZ-SP-SFRTO7	TO RESPRAY FRONT BUMPER AND FRONT FENDER LH		X	1,260.00
3		TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL SIDE RH, REAR FENDER RH, PANEL LOWER RH, TAILLAMP PANEL RH, REAR INNER WHEEL ARCH RH AND BOOTLID. TO REPAIR REAR CHASSIS RH, REAR FENDER LH, REAR DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT.		9900	10,500.00
4		TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL SIDE RH, REAR FENDER LH, REAR FENDER RH, PANEL LOWER RH, TAILLAMP PANEL RH, REAR CHASSIS RH, REAR INNER WHEEL ARCH RH, BOOTLID AND REAR DOOR RH.		4410	6,930.00
5	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		NETT	560.00
6	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		NETT	120.00
7	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		330	660.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		X	330.00
9	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		X	70.00
10		TO MOUNT VEHICLE IN CAR O LINER AND RE-ALIGN CAR BODY ACCORDING MAZDA SPECIFICATION. (photo)		NETT 1320	1,500.00
11	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.		660	990.00
12		TO SUPPLY 1 PC TIRE.	70%	partical	315 450.00
13	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.		660?	945.00

14	M2-BR-CROSS1	TO REPLACE CROSSMEMBER ASSY.	660?	1,320.00
15	M2-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	NETT 80	120.00
16	M2-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	560.00
17	M2-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	330	990.00
18	M2-BR-SEALER	TO SUPPLY SPRAY THEROSTAT SEALANT ON THE CUTTING	250	350.00
19	M2-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	250.00
20	M2-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	250.00
21	M2-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	350.00
22	M2-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	120.00
23	M2-BR-SUNDRI	SUNDRIES.	NETT 30	100.00

TOTAL LABOUR	\$ -	30,105.00
TOTAL PARTS	\$ -	19,213.50
TOTAL	\$ -	49,318.50
LESS EXCESS	\$ -	-
TOTAL AFTER EXCESS	\$ -	-
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
 THIS IS ONLY AN ESTIMATED COST VISUAL INSPECTION
 AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE
 PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE
 THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT
 SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS,
 A QUOTATION FEE OF \$400 WILL BE APPLIED
 ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR
 PARTS PRICE AS WELL AS LABOUR CHARGES.


 4/11/19

 Authorised Signature
 Rasul
 Hp 99010068
 24-27 days
 31/10/19 @ 1500 hrs
 Rekey before paint

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF19019242/R11f3e2

ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 06-12-2019



ATTN : FRANKIE THAY

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 234P	Veh. Inspected	SLN 820J
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/108	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	31/10/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 1.5 AT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0151144	Colour	BROWN
Odometer	37310	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	FALKEN	6 mm
L/H Front Tyre	205/50 R16	FALKEN	6 mm
R/H Rear Tyre	205/50 R16	FALKEN	6 mm
L/H Rear Tyre	205/50 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/10/2019	Inspection Date	31/10/2019
Survey held at	TRANS EUROKARS PTE LTD 27A TANJONG PENJURU SINGAPORE 609042		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	27 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 820J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	866.80	-
1	RETAINER LHS (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	19.70	-
12	CLIP, FRONT BUMPER (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	44.40	-
2	GROMMET, FRONT BUMPER (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	5.80	-
2	FASTENER, FRONT BUMPER (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	6.00	-
2	SEAL RUBBER, FRONT BUMPER (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	4.80	-
4	RIVET, FRONT BUMPER (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	16.00	-
4	RIVET, FRONT BUMPER (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	36.80	-
8	FASTENER, FRONT BUMPER (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	25.60	-
1	FRONT FENDER RHS (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	350.60	-
1	STAY LHS, FENDER (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	41.90	-
1	MUDGUARD LHS (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	101.90	-
15	FASTENER, MUDGUARD (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	45.00	-
1	HEADLAMP LHS (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	1,070.50	-
1	CORD SHORT, HEADLAMP (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	150.80	-
1	RIVET, HEADLAMP (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	3.50	-
2	CLIP, HEADLAMP (OLD DAMAGED) (SN)	NOT CONSISTENT WITH THE IMPACT	13.00	-
1	REAR BUMPER (SN)	TORN	1,128.60	1,128.60
1	RETAINER RHS (SN)	CRACKED	38.00	38.00
1	BRACKET RHS (SN)	DISTORTED	47.90	47.90

Report Ref No. CS/SPF19019242/R11f3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BRACKET CENTER (SN)	NECESSARY	5.40	5.40
1	TOWING COVER RHS (SN)	MISSING	17.10	17.10
1	REFLECTOR RHS (SN)	MISSING	53.00	53.00
1	REAR REINFORCEMENT (SN)	BENT	564.20	564.20
1	SHIELD SPLASH RHS (SN)	TORN	74.70	74.70
4	GROMMET, REAR BUMPER (SN)	NECESSARY	10.80	10.80
2	GROMMET, REAR BUMPER (SN)	NECESSARY	6.00	6.00
4	RIVET, REAR BUMPER (SN)	NECESSARY	18.00	18.00
4	FASTENER, REAR BUMPER (SN)	NECESSARY	12.00	12.00
1	REAR END PANEL (SN)	BUCKLED	530.40	530.40
1	TAILLAMP PANEL RHS (SN)	BUCKLED	396.70	396.70
1	REAR FENDER RHS (SN)	BUCKLED	1,233.00	1,233.00
1	PANEL LWR RHS (SN)	BUCKLED	373.20	373.20
1	REAR WHEEL ARCH INNER RHS (SN)	BENT	700.10	700.10
1	PANEL SIDE RHS, FLOOR PANEL (SN)	BUCKLED	66.00	66.00
1	TRIM, END PANEL (SN)	DEFORMED	89.40	89.40
1	BEZEL LOCK (SN)	MISSING	11.40	11.40
1	TRIM RHS, BOOTSIDE (SN)	DEFORMED	247.40	247.40
10	FASTENER, TRIM (SN)	NECESSARY	30.00	30.00
1	SPONGE, FLOOR PANEL (SN)	DEFORMED	154.80	154.80
1	PLUG HOLE, PANEL RHS (SN)	NECESSARY	2.40	2.40
1	PLUG HOSE, PANEL RHS (SN)	NECESSARY	2.40	2.40
1	JOINT DRAIN HOSE RHS, PANEL LOWER (SN)	* CHECK	6.70	-
1	EXTRACTOR VENT RHS (SN)	CRACKED	74.90	74.90
1	BOOTLID (SN)	BENT	1,005.30	1,005.30
1	HINGE LHS, BOOTLID (SN)	* CHECK	152.60	-
1	HINGE RHS, BOOTLID (SN)	* CHECK	152.60	-
1	WEATHERSTRIP, BOOTLID (SN)	CUT	113.10	113.10
1	LOCK, BOOTLID (SN)	* CHECK	160.70	-
1	STRIKER, BOOTLID (SN)	SERVICEABLE	35.10	-
1	ORNAMENT, MAZDA (SN)	NECESSARY	56.10	56.10
1	MASCOT, REAR (SN)	NECESSARY	78.20	78.20
1	ORNAMENT, SKYACTIVE (SN)	NECESSARYS	66.80	66.80

Report Ref No. CS/SPF19019242/R11f3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FASTENER, BOOTLID (SN)	NECESSARY	12.40	12.40
2	GROMMET, BOOTLID (SN)	NECESSARY	6.60	6.60
1	LAMP LHS, BOOTLID (SN)	* CHECK	278.30	-
1	LAMP RHS, BOOTLID (SN)	SCRATCHED	278.30	278.30
1	TAILLAMP RHS (SN)	BROKEN	534.90	534.90
1	FASTENER, TAILLAMP (SN)	NECESSARY	4.10	4.10
1	FASTENER, TAILLAMP (SN)	NECESSARY	15.70	15.70
1	GASKET LHS, BOOTLID (SN)	NECESSARY	22.00	22.00
1	GASKET RHS, BOOTLID (SN)	NECESSARY	22.00	22.00
1	GASKET LHS, TAILLAMP (SN)	NECESSARY	22.00	22.00
1	GASKET RHS, TAILLAMP (SN)	NECESSARY	22.00	22.00
1	BRACKET SIDE RHS, BOOTLID LAMP (SN)	NECESSARY	28.40	28.40
1	LAMP LHS, LICENCE PLATE (SN)	SERVICEABLE	74.70	-
1	LAMP RHS, LICENCE PLATE (SN)	* CHECK	74.70	-
1	REAR WINDSCREEN MOULDING (SN)	NECESSARY	77.00	77.00
1	SPACER, REAR WINDSCREEN (SN)	NECESSARY	4.70	4.70
1	GUARD STONE LHS (SN)	NECESSARY	17.40	17.40
1	GUARD STONE RHS (SN)	NECESSARY	18.20	18.20
1	REAR BEARING RHS (SN)	* CHECK	434.90	-
1	REAR KNUCKLE RHS (SN)	* CHECK	686.70	-
1	REAR DAMPER RHS (SN)	* CHECK	322.40	-
1	REAR UPPER ARM RHS (SN)	* CHECK	190.90	-
1	REAR LOWER ARM RHS (SN)	* CHECK	262.80	-
1	REAR TRAILING ARM RHS (SN)	* CHECK	211.00	-
1	REAR LINK LATERAL RHS (SN)	* CHECK	104.50	-
1	CROSSMEMBER REAR (SN)	* CHECK	869.20	-
4	BOLT (SN)	* CHECK	47.60	-
4	NUT (SN)	* CHECK	40.00	-
4	BOLT (SN)	* CHECK	44.00	-
4	BOLT (SN)	* CHECK	44.00	-
1	SILENCER, EXHAUST (SN)	BENT	1,129.60	1,129.60
2	HANGER, SILENCER (SN)	NECESSARY	70.00	70.00
1	GASKET, SILENCER (SN)	NECESSARY	15.40	15.40

Report Ref No. CS/SPF19019242/R1f3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CONVERTER, EXHAUST (SN)	BENT	1,449.00	1,449.00
1	GASKET, CONVERTER (SN)	NECESSARY	15.40	15.40
1	REAR STABILIZER LINK ROD RHS (SN)	* CHECK	87.80	-
1	REAR WHEEL RIM RHS (SN)	CUT	1,156.80	1,156.80
1	NUMBER PLATE (SN)	NOT NECESSARY	70.00	-
1	TIRE (70%) (SN)	PUNCTURE	450.00	315.00
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			19,833.50	12,474.20
LABOUR				
TO REPLACE FRONT BUMPER AND FRONT FENDER LH. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		NOT NECESSARY	1,320.00	-
TO RESPRAY FRONT BUMPER AND FRONT FENDER LH.		NOT NECESSARY	1,260.00	-
TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL SIDE RH, REAR FENDER RH, PANEL LOWER RH, TAILLAMP PANEL RH, REAR INNER WHEEL ARCH RH AND BOOTLID. TO REPAIR REAR CHASSIS RH, REAR FENDER LH, REAR DOOR RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			10,560.00	9,900.00
TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, PANEL SIDE RH, REAR FENDER LH, REAR FENDER RH, PANEL LOWER RH, TAILLAMP PANEL RH, REAR CHASSIS RH, REAR INNER WHEEL ARCH RH, BOOTLID AND REAR DOOR RH.			6,930.00	4,410.00
TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.			560.00	560.00
TO SUPPLY SEALER ON THE WINDSCREEN GLASS.			120.00	120.00
TO TRANSFER REVERSE SENSORS.			660.00	330.00
TO TRANSFER REVERSE CAMERA.		NOT NECESSARY	330.00	-
TO MOUNT VEHICLE IN CAR O LINER AND RE-ALIGN CAR BODY ACCORDING MAZDA SPECIFICATION.			1,500.00	1,320.00
TO REMOVE & INSTALL REAR EXHAUST ASSY.			990.00	660.00
TO REPLACE AXLE AND SUSPENSION MECHANISM.		* CHECK	945.00	-
TO REPLACE CROSSMEMBER ASSY.		* CHECK	1,320.00	-
TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.			120.00	80.00
TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.			560.00	560.00

Report Ref No. CS/SPF19019242/R1t3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		990.00	330.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.		350.00	250.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		120.00	120.00
			29,485.00	19,120.00
	GRAND TOTAL		49,318.50	31,594.20
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$6,436.40 NETT)			31,594.20

Report Ref No. CS/SPF19019242/R1f3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng.,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.