

ASS. REC. BY:

REF: CS/SMO19 019243 / Asf3/2 Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Thelma Choo of SMO Date/Time: 31/10/2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBB 5365 E Insured: GBF 4644 K

at Workshop m/s Yap Lee Motor Tel: 6844 1555

of 1 Kaki Bukit Ave 6 #01-26

Policy No: D19MTPCYE003440 Claim No: CMTD1905064

Sum Insured: Excess:

Make of Veh: D.O.A. 25.10.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 31/10 Person Contacted: Vehicle IN / OUT

Date/Time	Action/Instruction
	GBB 5365E - NA/IN (1009005/r) RSA - 10/04/2010
	GBF 4644K - X
04/11/19	@ 13:18 pm revert pending estimate from repairer to Thelma Choo via messenger.

ASS. REC. BY:

REF:

Adrian

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: G88836SE Yr Regn: 2009 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2982

Colour Red A/C: Insured / Std / NI / NA

Sp. Reading 385462 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFAT35780K200616

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C

R: 155 R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Condor

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 01/11/19

Survey held at Yap Lee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Smpo.

COE Expiry: 31/05/24

Adrian Confirmed US \$2,500/- @ 4 days with Adrian Bass  
( \$3,216.83 Red - 56% )

MV: 23K

PV: 12.7K

Nett: 10.3K.

RECEIVED 12 DEC 2019

Resurvey No. of Trip - 1

Date/Time, File Pass to?

Date/Time, File Return to?

1) 12/2/19

2) \_\_\_\_\_

3) Typist

4) \_\_\_\_\_

5) \_\_\_\_\_

6) \_\_\_\_\_

Prel. Report:

Final Report: \$2,500/- US

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

250

11

261

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2019		31 Oct 2019 09:06 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	THIRTYTHREE PRIVATE LIMITED, Co. Reg. No.: 200821941M		
Main Claimant:	TAN SOON HUAH GAS SUPPLY PTE LTD		
Vehicle Reg. No.:	GBB5365E	Date of Loss:	25/10/2019 20:00 - :59
Claim Type:	TP / CMTD1905064	Policy/Cover Note No.:	D19MTPCVE003440 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF4644K	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by <b>Thelma Choo</b> - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 11/11/2019]</b>		
Driver/Custodian (Insured):	TOH SWEE YONG (), NRIC: S7618910B, Tel: +6597611482 Email: -		
Adj Asg. Remarks:	Please assign to Mr Marcus Chua		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veh Out

**From:** Ruby Ong <ruby@htapartners.com.sg>  
**Sent:** Wednesday, 30 October, 2019 7:01 PM  
**To:** Ye, Yong Kang Melvin  
**Cc:** Yap Lee Motor; Henry, Irene James  
**Subject:** RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GBB 5365E [OUR REF. TCL.GCN.RO.50672.19.YLM] Our ref : CMTD1905064/THE

**Importance:** High

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear Sirs

We refer to your email of even date.

Our client is agreeable to appoint **Marcus Chua, LKK Auto Consultants** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no. **GBB 5365E**.

Please make the necessary arrangements with the contact person on the survey of our client's vehicle. The details are as follows :

**Venue :** **Yap Lee Motor**  
1 Kaki Bukit Avenue 6  
#01-26 Autobay@Kaki Bukit (417883)

**Contact Person :** **Mrs Chua / Shirley : 6844 1555**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,  
Ruby Ong  
Secretary  
M/s Hin Tat Augustine & Partners  
20 Upper Circular Road  
#02-10/12 The Riverwalk  
Singapore 058416  
**Tel : 6533 0212 ext 278**  
Fax : 6338 3536 / 6533 0313  
[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

---

**From:** Ye, Yong Kang Melvin <[melvin.ye@sompo.com.sg](mailto:melvin.ye@sompo.com.sg)>  
**Sent:** Wednesday, 30 October 2019 1:18 PM  
**To:** Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>  
**Cc:** Yap Lee Motor <[yap\\_lee\\_motor@singnet.com.sg](mailto:yap_lee_motor@singnet.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Subject:** RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GBB 5365E [OUR REF. TCL.GCN.RO.50672.19.YLM] Our ref : CMTD1905064/THE

Our Reference: CMTD1905064/THE  
Your Reference: TCL.GCN.ro.50672.19.ylm

**Without Prejudice**

Date: 29 October 2019

**Attention:**  
**HIN TAT AUGUSTINE & PARTNERS**

Dear Sir / Mdm,

**ACCIDENT INVOLVING GBB5365 & GBF4644K ON 25.10.2019**

We refer to your Notice of Accident dated 29/10/2019.

Please be informed that Ms Thelma Choo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert

Best Regards

**Melvin Ye**

Claims Division

signature banner


**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG**

App-store-badge

google-play-  
badge

Download now @

or

<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>

**Sent:** Tuesday, 29 October, 2019 4:07 PM

**To:** Claims - Motor Survey <[MotorSurvey@sompo.com.sg](mailto:MotorSurvey@sompo.com.sg)>

**Cc:** Yap Lee Motor <[yap\\_lee\\_motor@singnet.com.sg](mailto:yap_lee_motor@singnet.com.sg)>

**Subject:** REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GBB 5365E [OUR REF. TCL.GCN.RO.50672.19.YLM]

**Importance:** High

Your ref: GBF 4644K

**WITHOUT PREJUDICE**

Our ref : TCL.GCN.ro.50672.19.ylm

29 October 2019

**Sompo Insurance Pte Ltd**

**By Email Only**

Motor Claims Department

50 Raffles Place #05-01/06

Singapore Land Tower

Singapore 048623

**VERY URGENT**

Dear Sir,

**CLAIMANT: TAN SOON HUAH GAS SUPPLY PTE LTD**

**ACCIDENT INVOLVING GBB 5365E & GBF 4644K ALONG BUKIT TIMAH ROAD ON 25 OCTOBER 2019 @ 2000RS**

We are instructed by Tan Soon Huah Gas Supply Pte Ltd to notify you of a road traffic accident on 25 October 2019 at about 2000hrs along Bukit Timah Road involving our clients' vehicle registration number GBB 5365E and vehicle registration number GBF 4644K driven by your insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

**Tel : 6533 0212 ext 278**

**Fax : 6338 3536 / 6533 0313**

[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	144H
Vehicle Details	
Vehicle No.:	GBB5365E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	1KD1926586
Chassis No.:	JTFAT35Y80K200616
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	01 Jun 2009
First Registration Date:	01 Jun 2009
Transfer Count:	3
Actual ARF Paid:	\$1,249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,910.00
COE Rebate Amount:	\$12,720.00
Total Rebate Amount:	\$12,720.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 04 Nov 2019

OK





**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [i Ways of Selling](#)

**Saab Cabriolet**

Seats 4, Reliable, Fast, Fun  
Direct Owner StarAd



**VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND**

**HOTLINE: 6741 9997**

[View our cars](#)

Browse by Category

[Save Search](#)

[Print](#)

« Back ( 1 2 3 ) Next »

Sort by Date Posted

20 results/page

47 vehicles

**Search** dyna

[Advanced Search](#)

[Search](#)

[View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection dyna Any Any > 10 year(s) old Any Any Any Available



☐ Toyota Dyna 150 3.0M (COE  
till 04/2024)

\$22,800

\$5,110 /yr

21-Apr-2009

2,982 cc

-

Truck

Available

**Fuel Type:** Diesel

Full Loan Available! 1 Owner! Best Price In Town! Ready Condition! Serviced All Done! Low Fuel Consumption! New Paintwork! New Upholstery! Can Be Collect Immediately After You Paid! Call Us For Better Understanding!

Net Link Partners Pte Ltd

★ Posted: 25-Oct-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

[Premium Ad](#)



☐ Toyota Dyna 150 3.0M (COE  
till 05/2024)

\$27,800

\$6,120 /yr

19-May-2009

2,982 cc

-

Truck

Available

**Fuel Type:** Diesel

Class 3 Box Lorry! New 5-Years COE! Cheapest In The Market! No Need Repair! Fast Approval And Delivery! Don'T Wait Before Is Gone! Box Height (7 Feet)! Excellent Condition With 2 Sliding Door! Loan Available! Price Negotiable! Call Now For Viewing And Test Drive! Call...

Net Link Partners Pte Ltd

★ Posted: 02-Nov-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 150 3.0M (COE  
till 05/2029)

\$43,800

\$4,590 /yr

19-May-2009

2,982 cc

-

Truck

Available

**Fuel Type:** Diesel

Toyota Dyna With Box. Vehicle In Drive Away Condition And With New 10 Year COE. Loan Available Please Contact Us If Interested!

I-Deal Auto Trading Pte Ltd

★ Posted: 03-Oct-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 150 3.0M (COE  
till 05/2024)

\$24,800

\$5,460 /yr

20-May-2009

2,982 cc

-

Truck

Available

**Fuel Type:** Diesel

Hui Hua Credit Pte Ltd

★ Posted: 26-Oct-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

**GET YOUR  
COE  
RENEWAL  
LOAN**

**Is your COE expiring? Let us help you renew it!**

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ Toyota Dyna 150 3.0M (COE  
till 05/2024)

\$23,888

\$5,240 /yr

27-May-2009

2,982 cc

-

Truck

Available

**Fuel Type:** Diesel

100% Loan! 1 Owner! 3 Days Hand Over! Best Selling Lorry With Box! New Paintwork And Servicing Done! Ready For Immediate Delivery! High Loan! High Trade In! Call Now! Door Viewing Are Possible!

Net Link Partners Pte Ltd

★ Posted: 25-Oct-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

[Premium Ad](#)



☐ Toyota Dyna 150 3.0M (COE  
till 05/2029)

\$47,800

\$4,990 /yr

01-Jun-2009

2,982 cc

-

Truck

Available

**Fuel Type:** Diesel

Well Kept By One Careful Owner. Loan/Trade In Available. Call Now. Don't Miss.

★ Posted: 31-Oct-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

[SHORTLISTED](#) [HISTORY](#)

[Compare](#)

View Sent Message

This mail is associated with :

\*GBB5365E (CMTD1905064)  
[GBF4644K]

TP

TAN SOON HUAH GAS SUPPLY PTE LTD  
Oct 25 2019 8:00PM  
[THIRTYTHREE PRIVATE LIMITED]

Resend

View Recipients

Print Message

Delete Message

Forward

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 04/11/2019 13:18 PM.  
**To** thelma.choo@sompo.com.sg  
**CC** sur@lkkauto.com  
**Subject** GBB5365E (CMTD1905064) [GBF4644K] TP

Dear Thelma,

Please be informed that we have inspected the vehicle GBB 5365E on 01/11/2019.

We are pending estimate from repairer.

Thank you.  
Best Regards,  
Shirley Hiew | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/10/2019 14:43
Date Of Accident	25/10/2019 20:00
Exact Location Of Accident	BUKIT TIMAH RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB5365E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN SOON HUAH GAS SUPPLY PTE LTD
Co Reg No	200207114H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81265815
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	TOYOTA DYNA 150 MANUAL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110106007
Cover Note Number	
<b>Driver</b>	
Name of Driver	KUAN CHIN SONG
NRIC No	S1155178E
Date Of Birth	02/12/1955
Occupation	OUTDOOR
Date Of Driving Pass	04/02/1984
Driving Experience	35 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81265815
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 81 MACPHERSON LANE #12-51
Postcode	360081
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - EMPLOYEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF4644K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TOH SWEE YONG
NRIC/Passport Number	S7618910B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

- (a) my insurer, my broker and the General Insurance Association of Singapore ("GIA") may, are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in the accident and the Insurers' lawyers/law firms, may are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or a third party service providers or agents (including their lawyers/law firms, which may be situated outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information which will be collected and used to compile claims history for the purpose of fraud detection investigation and risk assessment, collected in all four states
- (e) the information is collected from, or otherwise received, by the:
- (i) self insured and/or any other third parties, has been evaluating, administering, controlling or arising from regulated law enforcement government agencies or government departments required for the purposes stated in

*[Signature]*  
 Date \_\_\_\_\_  
 Time \_\_\_\_\_

Sketch Plan #2

A - ABB 5365E

B - ABF 4644K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle is going straight suddenly car B  
hit onto my right rear portion.

DECLARATION

I hereby declare that the information provided is true and correct.

Driver's Signature  
Date: / /

Witness's Signature  
Date: / /

# YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883

Tel : 6844 1555 Fax. 6844 1311 Email : yap\_lee\_motor@singnet.com.sg

Date: 1st November 2019

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06

Singapore Land Tower

Singapore 048623

Your Reference: GBF 4644K

Shirley.

Owner Name: Tan Soon Huah Gas Supply Pte Ltd

Accident Date: 25th October 2019

## ESTIMATE COST OF REPAIRS FOR Toyota Dyna GBB 5365E

No.	Description	Unit	Unit Price	Amount
<b><u>Spare Parts - List Items</u></b>				
1	Rear tailgate <i>Dented</i>	1	\$ 1,265.60	\$ 1,265.60 ✓
2	Rear RH tailgate lock hinges <i>New</i>	1	\$ 290.00	\$ 290.00 +
3	Rear tailgate lower panel <i>Repair</i>	1	\$ 878.50	\$ 878.50 ✓
4	Rear RH tailgate lower stopper rubber <i>cut</i>	1	\$ 145.20	\$ 145.20 25
5	Rear RH tailgate lower stopper brackets <i>Bent</i>	1	\$ 213.00	\$ 213.00 -
6	Rear RH taillamp <i>cut</i>	1	\$ 659.30	\$ 659.30 225
7	Rear RH taillamp panel <i>Bent</i>	1	\$ 399.00	\$ 399.00 125
8	Rear number plate panel <i>Bent</i>	1	\$ 98.50	\$ 98.50 ✓
				\$ 3,949.10
			Less 25%	\$ 987.27
			Total	\$ 2,961.83
<b><u>Special Nett Items</u></b>				
1	Rear tailgate "70KM/H" sticker <i>New</i>	1	\$ 25.00	\$ 25.00 15
2	Rear tailgate "FLAMMABLE GAS" sticker <i>New</i>	1	\$ 80.00	\$ 80.00 30
3	Rear tailgate company sticker <i>New</i>	1	\$ 250.00	\$ 250.00 200
4	Rear step panel <i>New</i>	1	\$ 200.00	\$ 200.00 +
5	Rear number plate <i>Bent</i>	1	\$ 50.00	\$ 50.00 ✓
6	Rear reverse sensor (set) <i>Dump</i>	1	\$ 350.00	\$ 350.00 200
			Total	\$ 955.00

495

# YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883

Tel : 6844 1555 Fax. 6844 1311 Email : yap\_lee\_motor@singnet.com.sg

Date: 1st November 2019

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06

Singapore Land Tower

Singapore 048623

Owner Name: Tan Soon Huah Gas Supply Pte. Ltd.

Accident Date: 25th October 2019



## ESTIMATE COST OF REPAIRS FOR Toyota Dyna GBB 5365E

No.	Description	Unit Price	Amount
	<b><u>Labour</u></b>		
1	To remove, refit, replaced damaged lamps and check rear electrical wiring.	\$ 50.00	\$ 50.00
2	To remove and refit reverse sensor.	\$ 80.00	\$ 80.00
3	To remove, refit and replace exhaust silencer and mountings.	\$ 80.00	\$ 80.00
4	To apply undercoating on repaired and replaced panel	\$ 90.00	\$ 90.00
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$ 700.00	\$ 700.00
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 800.00	\$ 800.00
	<b>Total</b>		<b>\$ 1,800.00</b>
	<b>Spare Parts - List Items Total</b>		<b>\$ 2,961.83</b>
	<b>Special Nett Items Total</b>		<b>\$ 955.00</b>
	<b>Labour Total</b>		<b>\$ 1,800.00</b>
	<b>Grand Total</b>		<b>\$ 5,716.83</b>

total: 3111.57 Admin  
4/5 2.5K 4/5 01/11/19 04 Days



## ...CLAIM SUBFOLDER...(Pending for Survey Report)
































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2019		31 Oct 2019 09:06 <a href="#">Edit Adj Rpt</a>	<b>S\$2,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	THIRTYTHREE PRIVATE LIMITED, Co. Reg. No.: 200821941M								
Main Claimant:	TAN SOON HUAH GAS SUPPLY PTE LTD								
Vehicle Reg. No.:	GBB5365E	Date of Loss: 25/10/2019 20:00 - :59 [124 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / CMTD1905064	Policy/Cover Note No.: D19MTPCVE003440 (Comprehensive)							
Vehicle Reg. No. (Insured):	GBF4644K	Policy No. (Claimant):							
		Excess:							
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/11/2019]								
Driver/Custodian (Insured):	TOH SWEE YONG (), NRIC: S7618910B, Tel: +6597611482 Email:								
Adj Asg. Remarks:	Please assign to Mr Marcus Chua								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBB5365E (CMTD1905064)  
[GBF4644K]  
TP  
TAN SOON HUAH GAS SUPPLY PTE LTD  
Oct 25 2019 8:00PM  
[THIRTYTHREE PRIVATE LIMITED]  
Yap Lee Motor

Upload Documents   Upload Photos   Compose New Letter			View <span>View in Browser</span>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
2	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
3	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
4	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
5	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
6	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
7	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
8	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
9	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
10	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
12	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
13	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
14	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/12/19 15:00	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/12/19 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	06/12/19 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	06/12/19 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	06/12/19 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	06/12/19 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	06/12/19 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	06/12/19 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	06/12/19 15:00	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	30/10/19 13:18	PRI - ACK	 Load HTM	
2	31/10/19 09:04	PRI - LKK	 Load HTM	
3	13/11/19 09:18	Third Party Singapore Accident Statement	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19019243/ASF3E2

Date: 20/12/2019

## REFERENCE

Handling Insurer: Somp Insurance Singapore Pte. Ltd. Policy No: D19MTPCVE003440

Claimant Vehicle No : GBB5365E Insured Vehicle No : GBF4644K

Date of Loss: 25/10/2019 Nature of Claim: TP Claim No: CMTD1905064

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBB5365E

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD1926586

Reg. Date: 01/06/2009 (Man. Year: 2009) Chassis No: JTFAT35Y80K200616

Colour: Red Odometer: 385462 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C

Front Left Side: Condor 6 mm Rear Left Side: Condor 6 mm

Front Right Side: Condor 6 mm Rear Right Side: Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,916.82	1,959.07	1,957.75	49.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,180.00	620.00	34.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,716.82</b>	<b>3,139.07</b>	<b>2,577.75</b>	<b>45.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,716.82</b>	<b>2,500.00</b>	<b>3,216.82</b>	<b>56.27</b>

## INSPECTION

Date of Assignment: 31/10/2019

Date Inspected: 01/11/2019 Inspected At: Yap Lee Motor (HQ)  
1 Kaki Bukit Avenue 6, #01-26  
Autobay @ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 20 Dec 2019)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBB5365E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE	Dented	1,265.60 FL	*1,265.60 FL
2	1	*REAR RH TAILGATE LOCK HINGES	Not Necessary	290.00 FL	*- FL
3	1	*REAR TAILGATE LOWER PANEL	Repair	878.50 FL	*- FL
4	1	*REAR RH TAILGATE LOWER STOPPER RUBBER	Cut	145.20 FL	*25.00 FL
5	1	*REAR RH TAILGATE LOWER STOPPER BRACKETS	Bent	213.00 FL	*213.00 FL
6	1	*REAR RH TAILLAMP	Cut	659.30 FL	*225.00 FL
7	1	*REAR RH TAILLAMP PANEL	Bent	399.00 FL	*125.00 FL
8	1	*REAR NUMBER PLATE PANEL	Bent	98.50 FL	*98.50 FL
9	1	*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
10	1	*REAR TAILGATE FLAMMABLE GAS STICKER	Necessary	80.00 FS	*30.00 FS
11	1	*REAR TAILGATE COMPANY STICKER	Necessary	250.00 FS	*200.00 FS
12	1	*REAR STEP PANEL	Not Necessary	200.00 FS	*- FS
13	1	*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
14	1	*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,904.10</b>	<b>2,447.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>987.28</b>	<b>488.03</b>
<b>Total Parts (\$\$)</b>	<b>3,916.82</b>	<b>1,959.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK REAR ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
3	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	80.00	0.00
4	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	90.00	50.00
5	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	550.00
6	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	800.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,800.00</b>	<b>1,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >