

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

31st OCT 2019

ONG KON LAI
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

Accident date: 29th OCT 2019

Estimated repair cost for vehicle no: SJP863Z NISSAN SYLPHY 1.5A '2018

S/n	Qty	Items	U/price	Amount
				\$685.00
1	1	Front Bumper		\$50.00
2	1	Front bumper number plate		\$120.00
3	1	Front Bumper fog lamp cover -RH		\$561.90
4	1	Front bumper reinforcement		\$222.40
5	1	Front bumper inner sponge		\$336.80
6	2	Front Bumper bracket	\$168.40	\$669.60
7	1	Front support panel		\$307.00
8	1	Front support panel top garnish		\$56.10
9	1	Front bumper towing cover		\$134.40
10	2	Front Bumper Side Bracket	\$67.20	\$215.00
11	1	Front Bumper center lower garnish		\$40.00
12	8	Front bumper clips	\$5.00	\$28.00
13	8	Front bumper clips	\$3.50	\$315.00
14	1	front grille		\$325.00
15	1	Front grille centre garnish		\$50.00
16	1	Front Grille emble logo		\$40.00
17	8	front grille clips	\$5.00	\$855.00
18	1	Front headlamp -RH		\$585.20
19	1	Front fender RH		\$115.20
20	1	Front R/H fender cowling		\$35.00
21	10	Front RH fender cowling clips	\$3.50	\$88.20
22	1	Front R/H fender inner side cover		\$30.00
23	6	Front L/H fender inner side cover clips	\$5.00	\$58.00
24	1	Front R/H fender signal lamp		\$980.00
25	1	Front door -RH		\$458.20
26	1	Front door side mirror-RH		\$367.90
27	1	Front knuckle arm-RH		\$293.80
28	1	Front wheel bearing-rh		\$877.70
29	1	Front driveshaft-rh		\$1,552.70
30	1	Front steering rack-RH		\$385.00
31	1	Front shock absorber-RH		\$450.00
32	1	Front rim -RH		\$350.00
33	1	Front tyre -RH		\$325.20
34	1	Rear fender inner trim board		\$50.00
35	6	Rear fender inner trim board clips		\$957.50
36	2	Rear fender -RH		\$784.40
37	1	Rear Bumper		\$170.00
38	2	Rear Bumper Side Bracket	\$85.00	\$300.00
39	1	Rear Bumper reverse sensor		\$388.20
40	1	Rear tail lamp-RH		\$350.00
41	1	Rear tyre -RH		\$400.00
42	1	rear rim -RH		\$325.00
43	1	rear shock absorber-RH		\$185.20
44	1	rear wheel bearing -RH		
Subtotal :-				\$15,873.60

<u>Labour charges</u>	\$100.00
Remove and refix rear reverse sensor	
	\$400.00
Remove and refix Front & rear RH undercarriage	
	\$100.00
Towing Fee	
	\$120.00
Wheel alignment (computer)	
	\$80.00
To Check Wiring System	
	\$120.00
to Remove & Refix rear cushion	
	\$120.00
Tuff kote	
	\$1,200.00
Panel beating	
	\$1,200.00
Spray painting	
Subtotal :-	<u>\$3,440.00</u>
Total:-	<u>\$19,313.60</u>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	057J
Vehicle Details	
Vehicle No.:	SJP863Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Oct 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	HR16937222C
Chassis No.:	MNTBBAB17Z0033851
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,509.00
Original Registration Date:	17 Dec 2018
First Registration Date:	17 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$16,509.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Dec 2028
PARF Rebate Amount:	\$12,381.00
Intended COE Rebate Details	
COE Expiry Date:	16 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$23,568.00
COE Rebate Amount:	\$18,854.00
Total Rebate Amount:	\$31,235.00

The information contained herein is correct as at 30 Oct 2019

OK