

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9796L**AAD1910-224***Not Authorized
L/Snp & 1800h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

30 OCT 2019

SHD 9796L

VF1ABL15AUC277285

RENAULT

LATITUDE

25.10.19

AIG

14/4/2014

PART			LIST		
1	1	BUMPER COVER REAR	\$	<i>cm</i> 561.70	—
2	1	BUMPER LOWER REAR	\$	<i>nd/167</i> 411.90	—
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10	X
5	1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80	X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 16.60	X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 80.80	X
8	1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 54.20	X
9	1	BUMPER REFLECTOR LH	\$	<i>cm</i> 16.60	—
10	1	BUMPER BEAM REAR	\$	<i>R</i> 547.80	—
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50	} X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 100.90	
13	1	BUMPER BLOCK LH REAR	\$	<i>SL</i> 75.70	
14	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 745.80	
15	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>SL</i> 404.56	
16	1	TAILLAMP RH	\$	<i>SL</i> 313.10	
17	1	TAILLAMP PANEL RH	\$	<i>R</i> 401.40	
18	1	TAILLAMP LH	\$	<i>SL</i> 401.40	
19	1	TAILLAMP PANEL LH	\$	<i>R</i> 401.40	
20	1	BOOT REAR	\$	<i>R</i> 1,677.20	
21	1	BOOT FINISHER	\$	<i>SL</i> 344.70	
22	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 178.20	
23	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 277.70	
24	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 277.70	
25	1	BOOT BADGE 'RENAULT'	\$	<i>nn</i> 82.40	
26	1	BOOT BADGE	\$	<i>nn</i> 95.80	

Trans-cab Auto Services Pte Ltd**AAD1910-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9796L

27	1	BOOT STRUT LH	\$	SL	145.10	}	X	
28	1	BOOT STRUT RH	\$	SL	145.10			
29	1	BOOT HINGE LH	\$	N	254.20			
30	1	BOOT HINGE RH	\$	N	253.80			
31	2	BOOT RUBBER PLUG	\$	SL	139.90			
32	2	BOOT BUFFER	\$	SL	26.80			
33	1	BOOT LOCK LINKAGE	\$	SL	20.60			
34	1	BOOT LOCK LINKAGE HOLDER	\$	SL	99.50			
35	1	BOOT INNER TRIM BOARD	\$	SL	611.00			
36	1	BOOT SWITCH	\$	SL	113.00			
37	1	BOOT LOCK	\$	N	246.60	}	X	
38	1	BOOT LOCK CATCH	\$	N	41.70			
39	1	EXHAUST CAP REAR	\$	N	125.40			
TOTAL			\$		10,044.76			
10%			\$		1,004.48			
			\$		9,040.28			

Special Nett

1	1SET	PARKING AID	\$	SL	700.00	X	
2	1SET	REAR BUMPER CLIP	\$	N	66.00		
3	1SET	BUMPER BRACKET CTR CLIP	\$	N	33.00		
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	N	10.00	X	
5	1SET	BUMPER RETAINER RH CLIP RR	\$	N	20.00	X	
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	N	10.00	X	
7	1SET	BUMPER RETAINER CLIP LH RR	\$	N	20.00	X	
8	1SET	BUMPER LOWER REAR RIVET	\$	N	22.00	X	
9	1SET	BUMPER LOWER REAR CLIP	\$	N	66.00		
10	1	BOOT STICKER "Trans-cab"	\$	N	30.00		}
11	1	BOOT STICKER "6555-3333"	\$	N	30.00		
12	2	REAR WINDSCREEN SEALANT	\$	N	80.00		
13	1	WINDSCREEN MOULDING	\$	N	100.00		
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	N	100.00		
15	1	BOOT INNER TRIM CLIP	\$	N	45.00		
16	1SET	BOOT FINISHER CLIP	\$	N	24.20		}
17	1	TAILLAMP CLIP LH	\$	N	5.00		

Trans-cab Auto Services Pte Ltd**AAD1910-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9796L

18	1	TAILLAMP CLIP RH	\$	nn	5.00	}	X
19	1	Rear Bumper Protector	\$	nn	100.00		
20	1	EXHAUST MOUNTING REAR	\$	nn	16.00		
21	1	REAR LEFT TYRE	\$	sn	300.00		
22	1	REAR LEFT TYRE RIM	\$	sn	380.00		
TOTAL			\$		2,162.20		
TOTAL PARTS			\$		11,202.48		

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	2001
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	151
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9796L

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	6,000.00 <i>2200</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00 <i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>4</i> 170.00 <i>X</i>
Towing Fees	\$	<i>4</i> 170.00 <i>X</i>
TOTAL	\$	14,680.00
Over All Total	\$	25,882.48

LUMP SUM (REPAIR DAY)**20 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: