

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9386L**AAD1910-202***Not Notified**Resurvey B&Paint**1076.75*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9386L

JTDKB3FUX03079660

TOYOTA

PRIUS

26.10.19

AIG

29/3/2019

30 OCT 2019

		PART			LIST
1	1	REAR BUMPER	\$	<i>12</i>	442.60 X
2	1	REAR BUMPER RE-INFORCEMENT	\$	<i>12</i>	332.70 <i>2</i>
3	1	REAR BUMPER TOWING COVER	\$	<i>12</i>	15.40 X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>12</i>	576.30 <i>—</i>
5	1	REAR BUMPER SIDE RETAINER LH	\$	<i>12</i>	116.50 X
6	1	REAR BUMPER SIDE RETAINER RH	\$	<i>12</i>	117.70 X
7	1	ANTENNA, ELECTRICAL KEY	\$	<i>12</i>	72.00 X
8	1	REAR TAILGATE	\$	<i>12</i>	1,147.80
9	1	REAR TAILGATE OUTER GARNISH	\$	<i>12</i>	925.60
10	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>12</i>	64.50
11	1	COVER, REAR COMBINATION LAMP, LH	\$	<i>12</i>	64.50
12	1	GARNISH, BACK DOOR SIDE, LH	\$	<i>12</i>	95.60
13	1	GARNISH, BACK DOOR SIDE, RH	\$	<i>12</i>	95.60
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>12</i>	56.50
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>12</i>	56.50
16	1	BOARD ASSY, BACK DOOR TRIM	\$	<i>12</i>	259.20
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>12</i>	52.10
18	1	REAR TAILGATE WEATHERSTRIP	\$	<i>12</i>	372.30
19	1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>12</i>	650.30
20	1	TAILLAMP LOWER RH	\$	<i>12</i>	502.00
21	1	TAILLAMP UPPER RH	\$	<i>12</i>	451.80
22	1	REAR BUMPER SIDE RH	\$	<i>12</i>	123.70
23	1	REAR BUMPER SIDE LH	\$	<i>12</i>	123.70
24	1	TAILLAMP LOWER LH	\$	<i>12</i>	502.00
25	1	TAILLAMP UPPER LH	\$	<i>12</i>	443.30
26	1	BOARD, BACK DOOR TRIM	\$	<i>12</i>	225.20
27	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>12</i>	355.90
28	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>12</i>	355.90

Trans-cab Auto Services Pte Ltd**AAD1910-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9386L

29	1	COVER, DECK TRIM, REAR	\$	Sh	126.70 X
30	1	COVER, FLOOR UNDER, NO 1	\$	Sh	175.10 X
31	1	COVER, FLOOR UNDER, NO 2	\$	Sh	241.90 X
32	1	COVER, REAR FLOOR	\$	Sh	229.90 X

TOTAL	\$	9,370.80
25%	\$	2,342.70
	\$	7,028.10

Special Nett

1	1SET	PARKING AID	\$	Sh	700.00 X
2	1SET	REAR BUMPER CLIP	\$	nn	55.00
3	2	REAR WINDSCREEN SEALANT	\$	nn	80.00
4	1	WINDSCREEN MOULDING	\$	nn	100.00
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00
6	1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00
10	1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00
11	1	REAR BUMPER PROTECTOR	\$	nn	100.00
12	1	REAR WHEEL RIM	\$	Sh	1,570.55
13	1	REAR TYRE 195/65/15	\$	Sh	350.00
14	1	REAR WHEEL RIM COVER	\$	Sh	175.80

TOTAL	\$	3,544.75
--------------	-----------	-----------------

TOTAL PARTS	\$	10,572.85
--------------------	-----------	------------------

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ nn 170.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 220f

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1910-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9386L

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i> 170.00 <i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 <i>X</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 <i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<i>1201</i> 4,500.00
TOTAL	\$	11,340.00
Over All Total	\$	21,912.85

(PART-BY-PART) Repair Days**15 Days***1 1/2 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: