



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIG Insured's Veh No : SMD606C

Date of Accident : 25 October 2019

Messrs Sunled Co Pte Ltd

Date : 25 October 2019

Estimate To Repair SJT9687K - Toyota Vios E Auto

Chassis No : MR053HY9305135665

LKK - Mr LIM
25/10/19 @ 1520h

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid	\$ 536.00
02	1 pc	bootlid Vios badge	\$ 48.00
03	1 pc	bootlid TRD badge	\$ 30.00 50.00
04	1 pc	bootlid centre logo badge	\$ 55.00
05	1 pc	bootlid lock - top	\$ 100.00
06	1 pc	bootlid lock latch bottom	\$ 28.00
07	1 pc	bootlid weatherstrip	\$ 175.00
08	2 ps	bootlid rubber stopper @ \$17.80	\$ 35.60
09	3 ps	bootlid lock cable clip @ \$4.30	\$ 12.90
10	3 ps	bootlid wire harness clip @ \$4.30	\$ 12.90
11	2 ps	bootlid hinge @ \$60.00	\$ 120.00
12	1 pc	rear end panel	\$ 539.13 605.00
13	1 pc	rear end panel inner trim	\$ 80.70
14	3 ps	rear end panel inner trim clip @ \$3.80	\$ 11.40
15	2 ps	rear lamp @ \$390.00 249.40	\$ 498.80 780.00
16	4 ps	rear lamp clip holder @ \$17.80	\$ 50.00 71.20
17	1 pc	rear bumper	\$ 419.60 435.00
18	2 ps	rear bumper side retainer @ \$100.00	\$ 164.00 200.00
19	2 ps	rear bumper side holder @ \$35.00	\$ 70.00
20	2 ps	rear bumper reflector @ \$90.00 LH @ 80.00	\$ 80.00 180.00
21	8 ps	rear bumper fastener clip @ \$4.30	\$ 30.00 34.40
22	2 ps	rear bumper splashshield cover @ \$50.00 30.00	\$ 60.00 100.00
23	1 pc	rear luggage floor cardboard	\$ 115.50
24	2 ps	rear luggage side foam @ \$214.00	\$ 428.00
25	1 pc	rear exhaust box	\$ 635.00
26	1 pc	rear exhaust box chrome cuttler	\$ 43.30
27	1 pc	rear exhaust heat shield	\$ 39.90
		2983.23	\$ 5,002.80
		745.81	\$ 1,250.70
		2237.42	\$ 3,752.10
<u>SPECIAL NETT ITEMS</u>			
28	1 set	rear bumper parking sensor	\$ 280.00 280.00
29	1 pc	rear luggage floor insulator	\$ 180.00
		280.00	\$ 460.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 60.00
02		To rust-proofing of the affected areas.	\$ 60 120.00

BT ✓
NECV ✓
DD ✓
NDX ✓
TN ✓
NDX ✓
DD ✓
DLV ✓
NECV ✓
BR ✓
NECV ✓
BR ✓
NECV ✓
TN ✓
NDX ✓
NDX ✓
NDX ✓

NDX

✓



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIG Insured's Veh No : SMD606C

Date of Accident : 25 October 2019

Messrs Sunled Co Pte Ltd

Date : 25 October 2019

Estimate To Repair SJT9687K - Toyota Vios E Auto

Chassis No : MR053HY9305135665

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
03		To check electrical lighting concerned.	\$ 120.00 ✓
04		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 60.00 120.00
05		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 60.00 100.00
06		To drop rear exhaust box and renew the same.	\$ 80.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00 800.00
08		Putty and spray painting of the affected portion.	\$ 600.00 800.00
			\$ 2,120.00
			1380.00
		Total	\$ 6,332.10
		<i>Lump sum repair</i> <i>Repair days 4</i>	
		LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	
		<i>TL Lim</i> <i>25/10/13</i> <i>1600 km</i>	
		<i>Parts</i>	2237.42
		<i>SN</i>	200.00
		<i>Labour</i>	1380.00
			3817.42
		<i>@ 20%</i>	763.48
			3053.936
		<i>4/5 3050/2</i>	
		<i>TL Lim</i> <i>29/10/13</i>	