

Surveyor:

KENNETH

DOI:

ASSIGNMENT
31/10/2019

Date / Time: 31.10.2019

Registered in Merimen: 31.10.2019

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBH 1809L

Claim No.:

Name of Insured:

PACIFIC PACKAGING PTE LTD

Policy No.:

1900005873

Insured Tel No.:

HP:

Make / Model:

TOYOTA DYNA 150 1.7 TON (LORRY)

Excess Sec II :SS

D.O.A.:

16/10/2019 11:20

Place of Accident:

ALONG BLK 6 EVERTON PARK NEAR CARPARK EXIT

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age: CHAN KIM HIN (ZENG JINXING)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : +65-81853919

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SMM 7384Z

INSRS:
WSP:
Tel:
Liability:
RMKS:ESTEEM
PERFORMANCEINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	SMM 7384Z - x	GBH 1809L - x	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	EMAIL 31-11-19
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	☐
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☐
			LTA / GIA:	☒
			Medical Bill:	☐
			PIR:	☐
			Mandate/Reject Instruction:	☒
			LOD:	☐
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐

N3 - W, now indicate work loc.

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	P/P	SS1,934.00	(4 days) Reduction: 44 %
FINAL SETTLEMENT		Date/Time: 01/03/20	Confirm with: CAEMEN
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	26
Repair Cost:	2/167	SS1,965.38	OD REAR DOOR OPEN + 17 TP.
Loss of Rental (LOR):	SS 498.00	(6 days) x 723	
Loss of Use (LOU):	SS -	(5 x days)	
Loss of Income (LOI):	SS -	(5 x days)	
LOR only ☒	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐
[Tick only one]			
GIA/LTA Search:	SS1-95		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost:	SS -		
Total:	SS2,467.83	Global Sum SS:	
FINAL PAYMENT		Date/Time: 02-03-20	Confirm with: CAEMEN
Payee 1:	SS2,467.83	Name 1:	ESTEEM PERFORMANCE PIR CO.
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
4/3/2020

ASSIGNMENT

From

Date

30/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMM 7384Z

at Workshop n/s

Esteem Performance.

of

385 Sin Ming Drive

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

1-B.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMM 7384Z

Regn:

07 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

Wogan

C.C.

1496

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp Reading

31242

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GB7

1079111

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

3

mm

L/Bal.

4

mm

L/Bal.

3

mm

D.O.A.

16/10/19

D.O.I.

30/10/19

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP: 1.834 (SED: 1.144 44%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

☐

: Wash and (\$

Report Format:

Lump Sum / LB is:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

3 + PS 3

Photos

Others

TOTAL



ESTEEM PERFORMANCE PTE LTD

Bk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMM 7384 Z

Finellred

Not Authorise

Resurvey 86 paint

Parts (a) Cost / List Price Items

Plus/Less 20%

Total of Cost / List

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

Total Parts Cost

Labour

Total

1105.00 2247.50

221.00 444.50

884.00 1792.00

\$ 450.00 1,450.00

\$ 1234.00 3242.00
1,450.00

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Kenneth

CKIC

31/10/18

at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Le

Date: 31/10/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SMM 7384 Z
Make & Model : HONDA FREED
Chassis No : GB71079111

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :
Cost / List

i/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door	1	1105.00		✓
2	LH rear door hinge top	1	85.00		✓
3	LH rear door hinge bottom	1	270.00		✓
4	LH rear door lock	1	425.00		✓
5	LH rear door catch	1	27.00		✓
6	LH rear door checker sensor	1	325.00		✓
7	LH rear door weatherstrip	1			✓
8					
9					
10					
11					
12					
13	P: +1105				
14	- 20%				
15	+884				
16	L: +950				
17	T: +1,834.00				
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

1105.00



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMM 7384 Z

*Not Authorized
Resurvey B4paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To insurey follow-up surveying
- To supply damaged parts during survey
- Parts shall not subject to condition
- Third party is not a "Valid Repairer" here
- No signature is allowed
- Surveys must be reviewed and it subject to the approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Parts	(a) Cost / List Price Items	_____
	Plus/Less 20%	_____
	Total of Cost / List	=====
	(b) Nett Price Items	_____
	Less	_____
	Total of Nett Item	=====
	(c) Special Nett Items	_____
Total Parts Cost		=====
Labour	\$	1,450.00
Total	\$	1,450.00

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	<u>Kenneth</u>
Company	:	<u>CKIC</u>
Survey conducted on	:	<u>31/10/18</u> at _____
Remarks By Surveyor		
(a)	The repair of this vehicle is authorized / is not authorized until further notice.	
(b)	Recommended Days of Repair	: <u>04</u> day(s)
(c)	Resurvey	: Required / Not Required <u>Not Required</u>
(d)	Excess	:\$ _____
(e)	Signature of surveyor	: <u>Le</u> Date: <u>31/10/18</u>



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SMM 7384 Z
Make & Model : HONDA FREED
Chassis No : GB71079111

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door <i>As</i>	1			✓
2	LH rear door hinge top <i>As</i>	1			✓
3	LH rear door hinge bottom <i>As</i>	1			✓
4	LH rear door lock <i>As</i>	1			✓
5	LH rear door catch <i>As</i>	1			✓
6	LH rear door checker <i>As</i>	1			✓
7	LH rear door weatherstrip <i>As</i>	1			✓
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

PRE-REPAIR INSPECTION REQUEST – SMM7384Z vs GBH1809L (OI) on D.O.A.: 16/10/2019

From: Hor, Yinnui
To: "assignments@lkkauto.com", Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariessa, Azlan, Syazairidina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashri
Sent: 10/29/2019 9:35:55 AM
Attachments: image001.png; SMM7384Z_16102019.pdf

107261 (203)

Hi,

Please refer to the enclosed request from Esteem Performance Pte Ltd.

Claim no : 6150393921SG003
Case Owner : Loh Chee Heng

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinnui.Hor@aig.com | www.aig.sg

From: serence ctc [mailto:serence@esteemperf.com.sg]
Sent: Saturday, October 26, 2019 3:55 PM
To: AIG SGP, Claims-Survey
Cc: Carmen Lim; jenny chong
Subject: [EXTERNAL] REQUEST FOR PRI SURVEY SMM7384Z

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for PHV Leasing Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no SMM 7384 Z

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : 385 SIN MING DRIVE (S) 575718

Tel : 8799 0066
Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

We are prefer **LKK Auto Consultants Pte Ltd- KENNETH** to survey the car.

Freundliche Grüße / Best Regards

Serence Chee

Claims Assistant | Operation Division
Esteem Performance Pte Ltd

P: 6566 2112
E: serence@esteemperf.com.sg
5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)
385 Sin Ming Drive Vicom Inspection Centre
(Showroom)
www.esteemperformance.com

Veh lu - 30/10/19



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 11 November 2019 11:56 AM
To: Carmen Lim; serence ctc
Subject: ACCIDENT INVOLVING SMM 7384Z & GBH 1809L ON 16/10/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

ACCIDENT INVOLVING SMM 7384Z & GBH 1809L ON 16/10/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
 Attn : Loh, Chee-Heng

Your Ref : 6150393921SG
 Our Ref : CC4/AIG19019261/KEA3
 Date : 21 Feb 2020

"WITHOUT PREJUDICE"**ACCIDENT INVOLVING GBH1809L & SMM7384Z ON 16/10/2019**

Refer to the above accident.

The accident occurred when insured rear door open hit third party. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. GBH1809L) and third party claimant (vehicle no. SMM7384Z).

Summary of offer made to workshop Esteem Performance Pte Ltd - Sin Ming is as follows :

	Claimed	Revised
Cost of Repairs	\$ 3,248.00	\$ 1,962.38
Loss of Use / Rental (6days)		\$ 300~ 600.00 (6days x \$50 - \$100)
GIA / LTA Search Fee		\$ 2.00 ~ 7.45
Amount of claim at Liability 100%		\$ 2,264.38 - 2,569.83

Our surveyor recommended 4days repair.

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
 Asher Sng Rong Yi
 LKK Auto Consultants Pte Ltd

Print Received Message

This mail is associated with :

***SMM7384Z (6150393921SG)**
[GBH1809L]

TP

PHV LEASING PTE. LTD.

Oct 16 2019 11:00AM

[PACIFIC PACKAGING PTE LTD]

Esteem Performance Pte Ltd - Sin Ming

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 24/02/2020 08:22 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2569.83) - SMM7384Z - Claim Handler: Loh, Chee-Heng

Approved:2569.83.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2019 Edit Reg		31 Oct 2019 00:00 Edit Adj Rpt	S\$1,834.00 Edit Estimates	S\$1,834.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	PACIFIC PACKAGING PTE LTD, Co. Reg. No.: 201718419G								
Main Claimant:	PHV LEASING PTE. LTD., Co. Reg. No.: 201918386R								
Vehicle Reg. No.:	SMM7384Z	Date of Loss:	16/10/2019 11:00 - :59 [3 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6150393921SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	GBH1809L	Policy No. (Claimant):	S110578772(CLASSIC)						
		Excess:							
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (24/02/2020): Alert - Adj Mandate Approved (S\$2569.83) - SMM7384Z - Claim Handler: Loh, Chee-H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMM7384Z (6150393921SG)
[GBH1809L]
TP
PHV LEASING PTE. LTD.
Oct 16 2019 11:00AM
[PACIFIC PACKAGING PTE LTD]
Esteem Performance Pte Ltd - Sin Ming

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Assessment Reports										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	21/02/20 15:06	Adjuster Immediate Advice							Load HTM		
Photos/Images										3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	21/02/20 15:00	General View							Load JPG	☒	
2	21/02/20 15:00	General View							Load JPG	☒	
3	21/02/20 15:00	General View							Load JPG	☒	
4	21/02/20 15:00	General View							Load JPG	☒	
5	21/02/20 15:00	General View							Load JPG	☒	
6	21/02/20 15:00	General View							Load JPG	☒	
7	21/02/20 15:00	General View							Load JPG	☒	
8	21/02/20 15:00	General View							Load JPG	☒	
9	21/02/20 15:00	Chassis Number							Load JPG	☒	
10	21/02/20 15:00	Odometer Reading							Load JPG	☒	
11	21/02/20 15:02	Reinspection Photo							Load JPG	☒	
12	21/02/20 15:02	Reinspection Photo							Load JPG	☒	
13	21/02/20 15:02	Reinspection Photo							Load JPG	☒	
Documentation										1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	31/10/19 14:51	ACKNOWLEDGEMENT EMAIL TO AIG DD 29.10.19							Load PDF		
2	31/10/19 14:51	EMAIL FROM AIG DD 29.10.19							Load PDF		
3	31/10/19 14:51	TP GIA REPORT							Load PDF		
4	06/11/19 12:09	TP ESTIMATE - MARKED							Load PDF		
5	11/11/19 11:57	LETTER TO OI							Load PDF		
6	21/02/20 14:59	TP ESTIMATED - MARKED (FINAL)							Load PDF		
7	06/03/20 09:23	WORKSHOP INVOICE							Load PDF		
8	06/03/20 09:23	AUTHORISATION TO ACT FORM							Load PDF		
9	06/03/20 09:23	Release Voucher							Load PDF		
10	06/03/20 09:23	RENTAL RECEIPT							Load PDF		
11	06/03/20 09:23	LTA SEARCH							Load PDF		
12	06/03/20 09:23	LOD							Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	01/11/19 11:00	OI GIA REPORT							Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBH1809L (Insd veh)	Model:	HONDA FREED HYBRID 1.5
	SMM7384Z (TP veh)		G (A)
Date of Accident:	16/10/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	3,475.36
Final Repair Cost	:	\$	1,962.38
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	498.00 6 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,467.83

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Esteem Performance Pte Ltd	:	\$ 2,467.83
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

06 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019261/KEA3Q2

Date: 06/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SMM7384Z

Insured Vehicle No : GBH1809L

Date of Loss: 16/10/2019

Nature of Claim: TP

Claim No: 6150393921SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM7384Z

Make & Model: HONDA FREED HYBRID, 1.5 G (A)

Engine No: LEB5615176

Reg. Date: 11/07/2019 (Man. Year: 2018)

Chassis No: GB71079111

Colour: Metallic Blue

Odometer: 31242 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size:

185/65 R15

Front Left Side: Yokohama 4 mm

Rear Left Side:

Yokohama 3 mm

Front Right Side: Yokohama 4 mm

Rear Right Side:

Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,798.00	884.00	914.00	50.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	950.00	500.00	34.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,248.00	1,834.00	1,414.00	43.53
+ GST 7.00/7.00% (S\$)	227.36	128.38	98.98	43.53
Nett Amount (S\$)	3,475.36	1,962.38	1,512.98	43.53
+ Car Rental (6.0 x S\$83.00/day) (S\$)		498.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,467.83		

INSPECTION

Date of Assignment: 31/10/2019

Date Inspected: 31/10/2019 Inspected At:

Esteem Performance Pte Ltd - Sin
Ming (HQ)
385 Sin Ming Drive
Singapore 575718

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR DOOR	Bent	1,105.00 FL	*1,105.00 FL
2	1		*LH REAR DOOR HINGE TOP	Repair	85.00 FL	*- FL
3	1		*LH REAR DOOR HINGE BOTTOM	Repair	220.00 FL	*- FL
4	1		*LH REAR DOOR LOCK	Repair	425.00 FL	*- FL
5	1		*LH REAR DOOR CATCH	Repair	27.50 FL	*- FL
6	1		*LH REAR DOOR SENSOR }	Serviceable	385.00 FL	*- FL
7	1		*LH REAR DOOR WEATHERSTRIP }	Serviceable	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc

Sub Total (\$\$)	2,247.50	1,105.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	449.50	221.00
Total Parts (\$\$)	1,798.00	884.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (RHR DOOR ,RHR FENDER)	New	600.00	400.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (RHR DOOR ,RHR FENDER)	New	600.00	440.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR ,DOOR LOCK TO ASSIST WORK LOAD	New	150.00	60.00
5	TO TUFF COAT	New	50.00	30.00
Gross Labour Cost (S\$)			1,450.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >