



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 4408
Date Estimated : 30/10/2019
Prepared By : Andy Ooi Lee Keong

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -

Lai Tat Seng
50 Hume Avenue
#04-12

Singapore 596229

- ACCOUNT - 35

India Int'l Insurance Pte Ltd
64 Cecil Street #04/05
IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD7394D	VF30EBH2TFS320074	28/06/2016	5008 1.6 BlueHdi	0

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM-INDIA INS AGAINST-GBE226R. DOA.26/10/19	0.00
SUNDRIES	✓ 30. 150.00
LABOUR TO REMOVE, REPLACE, REPAIR, REALIGN REAR BUMPER, REVERSE SENSOR, REAR BUMPER REINFORCEMENT AND ALL AFFECTED AREA. 600	✓ 600. 1,200.00
LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAILGATE PANEL AND ALL AFFECTED AREA. 600	✓ 1200. 1,200.00
TO CONDUCT ECU PROGRAMMING & CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULE.(NETT)	✓ ✓ 600.00

Total Labour 1: 3,150.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
7416R8	BRACKET SET	1	98.00	10.00	88.20
7416R9	BUMPER BRACKET	1	120.00	10.00	108.00
7410KR	REAR BUMPER	1	750.00	10.00	675.00
9677782980	RR OBSTACLE DETECTION SENSOR centre - photo.	24	180.00	10.00	648.00

Total Parts : 1,519.20

SUPPLEMENTARY

BLUE H02 - acc ✓

5008 Emblem - acc ✓

Taufik 97495749 6/11/19 WTS
WP Repairing before paint.
taufik@ihants.com. 03days-04days

Customer Name & Signature / Company Stamp

Date

Labour 1	:	3,150.00
Parts	:	1,519.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	326.84
Grand Total	:	4,996.04

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SLD7394D

RO Number: BP115232

Date: 06/11/2019

No.	Supplementary / Check Items Parts	Part Number	Qty	U / Price	Disc %	Ext Price
1	BADGE - BLUE HDI	98097076DX	1	\$40.00	10%	\$36.00
2	BADGE - 5008	00008666S2	1	\$30.00	10%	\$27.00
3						
Parts Total:						\$63.00

No.	Supplementary Labour Charges	Price
Total Labour:		\$0.00
Total Parts & Labour:		\$63.00
GST @ 7%:		\$4.41
Grand Total:		\$67.41

Raised By Technician	Approved By CSA SIMON KOH	Acknowledge By Parts Assistant	BO Parts: Yes / No ETA: _____
-------------------------	-------------------------------------	-----------------------------------	--------------------------------------

AUTOFRANCE

(A Division of Vantage Automotive Limited)
Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942
Service Booking: 6477 7377
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300

FINALIZATION REPORT**SERVICE TAX INVOICE**

RE-PRINT



REPAIR ORDER NO. bp 115232	Date IN 18/11/2019 Payment Term 30 Days From Invoice Customer Service Advisor Simon Koh Eng Aun	Invoice Number Invoice Date Invoice By Simon Koh Eng Aun	Page No. 1 of 1
--------------------------------------	---	--	------------------------

CUSTOMER INFORMATION	INVOICE TO 35
Lai Tat Seng 50 Hume Avenue #04-12 Singapore 596229	India Int'l Insurance Pte Ltd 64 Cecil Street #04/05 IOB Building Singapore 049711

REGISTRATION No. SLD7394D	CHASSIS No. VF30EBHZTFS320074	STOCK No. 209108	REGISTRATION DATE 28/06/2016	MODEL 5008 1.6 BlueHDI	MILEAGE 28516
-------------------------------------	---	----------------------------	--	----------------------------------	-------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM-INDIA INS AGAINST-GBE226R. DOA.26/10/19	0	0.00	0.00
	SUNDRIES	1	0.00	30.00
	LABOUR TO REMOVE, REPLACE, REPAIR, REALIGN REAR BUMPER, REVERSE SENSOR, REAR BUMPER REINFORCEMENT AND ALL AFFECTED AREA.	1	0.00	600.00
	LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAILGATE PANEL AND ALL AFFECTED AREA.	1	0.00	1,200.00
	TO CONDUCT ECU PROGRAMMING & CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULE.(NETT)	2	0.00	600.00
Sub-Total :				2,430.00

CODE	DESCRIPTION	UNITS	DISC %	NETT
00008666S2	BADGE - 5008	1	10.00	27.00
00007410KR	REAR BUMPER W/SENSOR MARKING HOLE	1	10.00	675.00
9677782980	RR OBSTACLE DETECTION SENSOR	2	10.00	324.00
98097076DX	BADGE - BLUE HDI	1	10.00	36.00
Sub-Total :				1,062.00

Attending CSO : Simon Koh

Should you require further explanation, please reach me at

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	3,492.00 ✕
Labour Charges	2,430.00	Less Insurance Excess	S\$	0.00
Parts Charges	1,062.00	GST @ 7%	S\$	244.44
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	3,736.44
		Less Deposit/Voucher	S\$	0.00

Computer generated invoice. No signature is required.

Amount Payable

S\$

3,736.44

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.