

Our Job Ref No : 305344896
Date : 04/11/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHC2983P

Date of Accident : 29-Oct-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING — SME7487C

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$1,039.⁵⁰~~40~~

(b) Labour Charges

\$770.00

Total for Part-By-Part Repair Cost

\$1,809.⁵⁰~~40~~

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : KALVIN

Date : 5/11/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

VEHICLE	:	<u>SHC2983P</u>	TYPE OF CLAIM	:	<u>TP</u>
MODEL	:	<u>PRIUS</u>	SURVEY BY	:	<u>KALVIN</u>
JOB NO	:	<u>305344896</u>	DATE	:	<u>10/29/19</u>

[illegible]

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305344896
 REGN NO : SHC2983P
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 29.05.2019
 DATE/TIME IN : 29.10.2019 10:55
 ACCIDENT DATE : 29.10.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2270-G	BOOTLID (HYBRID S)	1	52.90	25.00	39.67
0002	04-01-0302-2271-G	BOOTLID (PRIUS)	1	52.90	25.00	39.67
0003	04-01-0302-2269-G	BOOTLID (TOYOTA STAR)	1	47.00	25.00	35.25
0004	04-01-0302-2282-G	REAR BUMPER	1	458.60	25.00	343.95
0005	04-01-0302-2267-G	REAR BUMPER CLIPS	10	22.00	25.00	16.50
0006	04-01-0302-2287-G	REAR BUMPER UNDER COVER*	1	552.60	25.00	414.45
0007	04-01-0302-1150-A	REAR BUMPER MAT	1	50.00		50.00
0008	28-01-0302-0006-A	BOOTLID (65521111)	1	30.00		30.00
0009	28-01-9999-2025-A	BOOTLID (APPS)	1	40.00		40.00
0010	28-01-0302-2015-A	BOOTLID (COMFORTDELGRO)	1	30.00		30.00

SUB-TOTAL : 1,039.49

JOB NATURE

0000	PB	PANEL BEATING	320.00
------	----	---------------	--------

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305344896
REGN NO : SHC2983P
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 29.05.2019
DATE/TIME IN : 29.10.2019 10:55
ACCIDENT DATE : 29.10.2019

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 SP	SPRAYPAINT CHARGE			400.00		
0002 17-01	CHECK ALL LIGHTING			20.00		
0003 L	R/I REVERSE SENSOR			30.00		

SUB-TOTAL : 770.00

TOTAL : 1,809.49


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : AUTHORIZED : YES / NO

REPAIR ESTIMATE

VEHICLE NO: SHC 2983P

MAKE :

MODEL : TOYOTA PRIUS

China Taiping CP/P)

30/10/2019

LKK - Calvin.

TS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR TRUNK LID LOGO(PRIUS) — <i>me</i>			\$ 52.90	
REAR TRUNK LID LOGO(HYBRID) — <i>me</i>			\$ 52.90	
REAR TRUNK LID LOGO(TOYOTA STAR) — <i>me</i>			\$ 47.00	
REAR BUMPER — <i>should</i>			\$ 458.60	
REAR BUMPER CLIPS — <i>me</i>			\$ 22.00	
<i>for Bumper under cover — should</i>		552.60		
SUB TOTAL			\$ 633.40	
LESS 25%			\$ 158.35	
DISCOUNTED TOTAL			\$ 475.05	
REAR TRUNK LID APPS STICKER — <i>me</i>			\$ 40.00	NETT
REAR TRUNK LID COMFORT & TEL NO. STICKER — <i>me</i>			\$ 60.00	NETT
REAR BUMPER REVERSE SENSOR X <i>me</i>			\$ 135.70	NETT
REAR BUMPER RUBBER MAT — <i>me</i>			\$ 50.00	NETT
			\$ 285.70	
LABOUR CHARGE				
Panel Beating			\$ 350.00 320	
Spray Painting Charge			\$ 500.00 400	
Wiring Charge			\$ 50.00 20	
Remove/Refix Reverse Sensor			\$ 80.00 30	
TOTAL LABOUR			\$ 980.00	
ESTIMATE TOTAL			\$ 1,740.75	

Kalin LKK

M

30/10/19 10554

30/10/19

VP

Before Paint photo

TOTAL LABOUR

ESTIMATE TOTAL

is subject to: ...

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.