

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

30-Oct-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1189 S

1 pc	Front bumper	✓	ca	\$	811.11
1 pc	Front bumper sponge	✓	midly	\$	218.03
1 pc	Front bumper reinforcement	✓	su	\$	636.40
1 pc	Front bumper tow cap	✓	su	\$	60.10
2 pcs	Front n/s & o/s headlamp @ \$1531.57	✓	o/s - 1/5 x su	\$	3,063.14
1 pc	Bonnet grille	✓	su	\$	566.46
1 pc	Front bumper emblem	✓	"	\$	27.80
1 pc	Front bumper o/s fog lamp cover	✓	su	\$	25.00
2 pcs	Front n/s & o/s side bracket @ \$32.51	✓	o/s - 1/5 x su	\$	65.02
1 pc	Front o/s fender	✓	Reble	\$	514.02
1 pc	Front o/s fender inner shield	✓	su	\$	176.72
1 pc	Front o/s rim	✓	su	\$	246.00

Less 20% Key	\$	1,281.96
Total	\$	5,127.84
Labour	\$	48.00
Signature: [Signature]	\$	30.00
Date: 30/10/19		

S/NETT

1 set	Front bumper clips	✓	acc	\$	48.00
1 pc	Front o/s fender sticker	✓	acc	\$	30.00
	Sundry			\$	50.00
	Towing Fee			\$	50.00
	To check for front o/s wheel alignment			\$	80.00
	To check wiring and focus on front n/s & o/s headlamp			\$	80.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.			\$	650.00
	To putty and spray painting on front bumper, front o/s fender			\$	400.00
	To apply rustproofing on the repaired and replaced panels.			\$	120.00
				\$	6,635.84

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

4/11/19
whd PIP \$3463.79/3Rp