

ASS. REC. BY:

REF: CS/FCI 19019271 / AY f3 172

Special Instruction:

SUNAJOR: Adnan

ASSIGNMENT (Office)

From (Person): Karint of FCI Date/Time: 31.10.19 3:16 p.m.

Estimated Cost: Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 4137B Insured: SHA F886P

at Workshop m/s N-51 Automohire Tel: 68420051

of 2 kati Bukit Nuri 2 #01-13

Policy No: Claim No: D19006907 MP54

Sum Insured: Excess:

Make of Veh: D.O.A. 30.10.19
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 31.10.19 3:40 p.m. Person Contacted: Zi Ting Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 4137B - X
	SHA F886P - CS/FCI 16016379/ 09/03/2016 p.u.d. - 26/08/2016
08/11/19	Pending Estimate sent email
5/3/20	Sent Preli by Merimen
5/3/20	L/S \$1400/- (Red \$1046-08, 42%)

287



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006907MFSH

Date: 05 March 2020

Our Ref: CS/FCI1901927/Ayf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLR4137B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/11/2019 at the premises of M/s N51 AUTOMOTIVE PTE LTD. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,446.08</u> .
Revised Estimate Amount (LumpSum)	: S\$ <u>1,400.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the rear o/s portion



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	31-10-2019	Our Ref No. D19006907MFSH
Accident Date	30-10-2019	Claim Type. Third Party
Insured Vehicle	SHA7886P	Third Party Vehicle. SLR4137B
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	ZI TING	
Contact No.	68420051/ 0	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Thursday, March 05, 2020 7:25 PM
To: 'CWS Motor Claims'
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D19006907MFSH/1
Attachments: SLR4137B DOA 30102019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SLR4137B
Date of survey : 06/11/2019
Number of days : 3 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne Wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yvonne Wong (LKK Auto)
Sent: Friday, November 08, 2019 4:45 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006907MFSH/1

Dear Sir,

Please be informed that we have inspected the vehicle SLR4137B on 06/11/2019.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne Wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, November 08, 2019 4:45 PM
To: 'CWS Motor Claims'
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D19006907MFSH/1

Dear Sir,

Please be informed that we have inspected the vehicle SLR4137B on 06/11/2019.

We are still pending estimate from repairer.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Thursday, 31 October, 2019 3:16 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006907MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SLR4137B
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Gold
Manufacturing Year:	2017
Engine No.:	LEB5953361
Chassis No.:	RU31253343
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,661.00
Original Registration Date:	15 Aug 2017
First Registration Date:	15 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$36,072.00
Total Rebate Amount:	\$39,822.00

The information contained herein is correct as at 10 Jan 2020

OK



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

(LKC - Mr Adrian)

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

TP 1st Gp
 Yvonne

ESTIMATE

Repair Code : CLM15735

Date in : 30/10/2019

Vehicle Num. : SLR4137B

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31253343/LEB5953361

Contact : 66550005-GRAB 91997404

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>ut</i>	1	762.70	762.70 ✓
REAR BUMPER SIDE RETAINER L/R <i>ren</i>	1198.70 ²	23.00	46.00 ✓
REAR RH AIR VENT <i>ren</i>	1	30.30	30.30 ✗
REAR RH BUMPER REFLECTOR <i>ren</i>	858.56 ¹	141.10	141.10 ✗
REAR RH BUMPER SIDE <i>dehomed</i>	1	195.00	195.00 ✓
REAR RH FENDER ARCH GARNISH <i>ut</i>	1	195.00	195.00 ✓
Subtotal before discount			1,370.10
Percentage discount 20%			274.02
Sub-total 1			1,096.08
REAR BUMPER CLIPS - SET <i>ren</i>	50	50.00	50.00 30
REAR RH FENDER ARCH GARNISH CLIPS - SET <i>ren</i>	1	30.00	30.00 20
Subtotal before discount			80.00
Percentage discount 0%			0.00
Sub-total 2			80.00
Parts-total			1,176.08

LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

50.00 ✓
 100.00 ✗
 600.00
 350

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 91997404

ESTIMATE

Repair Code : CLM15735

Date in : 30/10/2019

Vehicle Num. : SLR4137B

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31253343/LEB5953361

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,270.00
Parts & Labour Total	2,446.08

750

480.00 350

40.00 X

*** This is a computer-generated document which requires no signature.***

page 2

total: 1758.96

h/s: 14K.

03 Days.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FC119019271/Ayf3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-03-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7886P	Veh. Inspected	SLR 4137B
Policy No.		Coverage (\$)	0.00
Claim No.	D19006907MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	31/10/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31253343	Colour	BRONZE
Odometer	230305	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	HABILEAD	6 mm
L/H Front Tyre	215/60 R16	HABILEAD	6 mm
R/H Rear Tyre	215/60 R16	HABILEAD	6 mm
L/H Rear Tyre	215/60 R16	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/10/2019	Inspection Date	06/11/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 4137B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CUT	762.70	762.70
2	REAR BUMPER SIDE RETAINER L/R @\$23.00	NECESSARY	46.00	46.00
1	REAR RH AIR VENT	NOT NECESSARY	30.30	-
1	REAR RH BUMPER REFLECTOR	NOT NECESSARY	141.10	-
1	REAR RH BUMPER SIDE	DEFORMED	195.00	195.00
1	REAR RH FENDER ARCH GARNISH	CUT	195.00	195.00
	LESS 20% DISCOUNT		-274.02	-239.74
			1,096.08	958.96
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR RH FENDER ARCH GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
			80.00	50.00
LABOUR				
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		50.00	50.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).	NOT NECESSARY	100.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		600.00	350.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		480.00	350.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	40.00	-
			1,270.00	750.00
GRAND TOTAL			2,446.08	1,758.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/FCI19019271/Ayf3n2



Report Ref No. CS/FCI19019271/Ayf3n2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.