

ASS. REC. BY:

REP: CS/SMO19019279/UYF312

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Thelma choo of SMO Date/Time: 31.10.19 15:57pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 5064H Insured: SK U 414J

at Workshop n/s Fastach Tel: 67465405

of 1 Kaki Bukit Ave 6 #01-46

Policy No: D19MTP601001029 Claim No: CMFD 1905085

Sum Insured: Excess:

Make of Veh: D.O.A. 30/10/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 31.10.19 4:59pm Person Contacted: Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 5064H - X
	SKU 414J - X
1/11/19	Informed Thelma pending workshop est via merimen
7/11/19	Sent Prel: advise in Merimen

photo a.k

ASS. REC. BY:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c.

Colour:

A/C:

Insured / Std / NI / NA

Sp Reading:

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond:

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

not 20800

LTA 44440 7 yrs. 2nd. rep. 800

5/11/19 2/3 @ 12.500 confirmed with Alar. (Red \$52022-91, 80%)

RECEIVED 07 NOV 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

7/11/19 Typist

Request Form:

Kenny Pina 12/11/19

\$12500

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Misc. (\$

Survey Fee:

Transportation:

Photos

Other:

Total:

450

11

461

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 07 Nov 2019

Preliminary Advice

Insured Vehicle No	: SKU4141J	Accident Date	: 30/10/2019
TP Vehicle No	: SLK5064H	Assignment Date	: 31/10/2019
Make	:	Est. Duration of Repair	: 8.00
Date of Inspection	: 31/10/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	64,522.51
Revised Amount	:S\$	12,500.00 (Lump Sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	12,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a without "prejudice" basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2019		31 Oct 2019 15:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		GOH ZI YANG ERIC, ID: S7837381D							
Main Claimant:		UNKNOWN5085							
Vehicle Reg. No.:		SLK5064H	Date of Loss:	30/10/2019 00:00 - :59					
Claim Type:		TP / CMTD1905085	Policy/Cover Note No.:	D19MTPV01001029 (Comprehensive)					
Vehicle Reg. No. (Insured):		SKU4141J	Policy No. (Claimant):						
Repairer:		Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405							
Handling Insurer:		Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/11/2019]							
Adj Asg. Remarks:		Please assign to Mr Marcus Chua							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SLK5064H (CMTD1905085)
[SKU4141J]**

TP
UNKNOWN5085
Oct 30 2019 12:00AM
[GOH ZI YANG ERIC]
Fastech Auto Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **01/11/2019 12:11 PM**.
To ThelmaChoo
Subject TP SURVEY SLK 5064H

Dear Thelma,

Please be informed that we have inspected the vehicle SLK 5064H on 31/10/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Free Car Valuation

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges & no obligations!

vezelPrice Range▼Depreciation▼2017▼Vehicle Type▼SubmitAdvanced Search

Home > Used Cars > Prime Motor & Leasing > Honda Vezel 1.5A X

Honda Vezel 1.5A X

OverviewFinancialInsuranceAccessoriesSimilarResearchPhotosMap



(ICHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SUTTON CREDIT & HIRE/LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Price	\$67,500		
Depreciation	\$8,620 /yr <small>View models with similar depre</small>	Reg Date	25-Jan-2017 (7yrs 2mths 24days COE left)
Mileage	N.A.	Manufactured	2016
Road Tax	\$682 /yr	Transmission	Auto
Dereg Value	\$44,485 as of today <small>(change)</small>	OMV	\$20,142
COE	\$50,889	ARF	\$10,199
Engine Cap	1,496 cc	Power	96.0 kW (128 bhp)
Curb Weight	1,190 kg	No. of Owners	1
Type of Vehicle	SUV		

Features

Airbags, ABS, Reliable 1.5L 4 Cylinder DOHC I-Vtec Engine, CVT Auto Transmission, Keyless Start/Stop. View specs of the Honda Vezel (2014)

Accessories

Leather Seats, Sports Rims, Audio System, Reverse Camera.

Description

Elegant Silver SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Category

PARF Car

Status

Available


Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Seller Information

Company	Prime Motor & Leasing <ul style="list-style-type: none">dealer's pricelist76 vehs sold 131 vehs available	
Address	5 Benoi Place <small>Search cars nearby this location</small>	
Office No	68723113	
Contact Person(s)	Jack Ng Eliz Larry	91096509 88680011 96861029

vezel

Price Range

Depreciation

2017

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Prime Motor & Leasing > Honda Vezel 1.5A X

Honda Vezel 1.5A X

OverviewFinancialInsuranceAccessoriesSimilarResearchPhotosMap



ICHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Price	\$67,500		
Depreciation	\$8,620 /yr <small>View models with similar depre</small>	Reg Date	25-Jan-2017 (7yrs 2mths 24days COE left)
Mileage	N.A.	Manufactured	2016
Road Tax	\$682 /yr	Transmission	Auto
Dereg Value	\$44,485 as of today (change)	OMV	\$20,142
COE	\$50,889	ARF	\$10,199
Engine Cap	1,496 cc	Power	96.0 kW (128 bhp)
Curb Weight	1,190 kg	No. of Owners	1
Type of Vehicle	SUV		

Features

Airbags, ABS, Reliable 1.5L 4 Cylinder DOHC I-VTEC Engine, CVT Auto Transmission, Keyless Start/Stop. View specs of the Honda Vezel (2014)

Accessories

Leather Seats, Sports Rims, Audio System.

Description

Elegant Silver SUV, One Owner Only, Low Maintenance Cost, Comes With Warranty, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)




Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



Price Chart

Summary



ShortlistCompareAdd note

Report ErrorMore Actions

Seller Information

Company	Prime Motor & Leasing <ul style="list-style-type: none">• dealer's pricelist• 76 vels sold 131 vels available	
Address	31 West Coast Highway #01-19/20 Search cars nearby this location	
Location	West Coast Car Mart	
Office No	67782233	
Contact Person(s)	Danny Bobby	83661373 86863300

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 092C

Vehicle Details

Vehicle No.: SLK5064H
Vehicle to be Exported: No
Intended Deregistration Date: 31 Oct 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: L15B4410631
Chassis No.: RU11210671
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$20,184.00
Original Registration Date: 18 Jan 2017
First Registration Date: 18 Jan 2017
Transfer Count: 0
Actual ARF Paid: \$10,258.00 *5,29*

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Jan 2027
PARF Rebate Amount: \$7,693.00

Intended COE Rebate Details

COE Expiry Date: 17 Jan 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,951.00
COE Rebate Amount: \$36,747.00
Total Rebate Amount: \$44,440.00

The information contained herein is correct as at 31 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2019 13:14
Date Of Accident	30/10/2019 17:30
Exact Location Of Accident	OPP PASIR LABA CAMP BUS STOP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK5064H
Insured/Policyholder	
Name Of Registered Owner	CHEW POH KWEE
NRIC No	S6942092C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93670093
Alternative Phone No	OTHERS-93670093

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087538604-02
Cover Note Number	

Driver

Name of Driver	CHEW POH KWEE
NRIC No	S6942092C
Date Of Birth	30/11/1969
Occupation	INDOOR
Date Of Driving Pass	22/09/1997
Driving Experience	22 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93670093
Fax Number	
Contact Number	OTHERS-93670093
Email Address	NOEMAIL

Address	BLK 768 #04-27 CHOA CHU KANG STREET 54
Postcode	680768
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN ATTACHED:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU4141J
Vehicle Make/Model/Colour	MITSUBISHI / OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLR9110U
-----------------------------	----------

Vehicle Make/Model/Colour	B.M.W. / 216D ACTIVE TOURER D/AB LED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHEW POH KWEE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLK5064H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 768 #04-27 CHOA CHU KANG STREET 54
Postcode	680768

Date of Accident : 30.10.2019 Accident Time: 17.30 (24-HR-Format)
Accident Place : Opp Pasir Laba Camp bus stop
Vehicle No. (Car Plate No.) : SLK 5064 H Make/Model: Honda Vezel
Insurance Company : MTUC Policy No: 5087538604-02
Owner or Company Name /IC No. : Chew Poh Kwee (S6942092C)
Owner or Company Contact No. : 9367 0093 Owner's Hp - Company Tel
DRIVER'S Name / IC No. : as above
DRIVER'S Date Of Birth : 30.11.1969 DRIVER'S License Pass Date 22.09.1997
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Owner
DRIVER'S Address : Bkt 768 Choa Chu Kong Street 54 #04-27 (S) 680768
DRIVER'S Contact No./ Alt No. : 1) - 2) -
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : -
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): Driver Only
Was there any video Captured by car camera: YES (NO)
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): NO

Other Party Driver's Particular (if any)

Vehicle No: SLK 4141 J
Vehicle Make/Model: _____
Name Driver: _____
IC No. Driver/Contact: _____

Vehicle No: SLR 9110V
Vehicle Make/Model: _____
Name Driver: _____
IC No. Driver/Contact: _____

*** NEW - Passenger's name & gender:**



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30.10.2019 at about 17.30, I was travelling along Opp Basir
Laba Comp Bus Stop. I was stationary due to front traffic. Suddenly
I felt an impact from my rear. The impact caused my vehicle to hit the
front vehicle. I was involved in a 3 vehicle chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

Not Authorized
Date
1/5/2019
3/10/19
Signature

VEHICLE NO: SLK506411

QTY	PARTICULAR			
1 PCS	BONNET		1	\$915.00 X
2 PCS	BONNET HINGES @\$78.10		11	\$170.00 X
1 PCS	BONNET INSULATOR		11	\$211.30 X
1 SET	BONNET INSULATOR CLIPS		11	\$35.00 X
1 PCS	BONNET LOCK		Two	\$135.50 ✓
2 PCS	BONNET RUBBERS @\$32.00		11	\$64.00 X
1 PCS	FRONT BUMPER	801.70	20/30m	\$950.00 ✓
1 PCS	FRONT BUMPER REINFORCEMENT	321.00	Set	\$480.00 ✓
2 PCS	FRONT BUMPER SIDE RETAINERS@ \$65.00	60.30 X 2 = 120.60	Set	\$130.00 ✓
2 PCS	FRONT BUMPER BRACKETS @\$115.00		11	\$230.00 X
1 PCS	FRONT BUMPER CENTRE GRILLE	145.30	20/30m	\$285.00 ✓
1 PCS	FRONT BUMPER LOWER SPOILER		11	\$525.00 X
1 PCS	FRONT BUMPER UNDER COVER		11	\$480.00 X
1 SET	FRONT BUMPER UNDER COVER CLIPS		11	\$35.00 X
1 PCS	FRONT BUMPER TOW COVER		11	\$45.00 X
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$180.00		11	\$360.00 X
2 PCS	FRONT BUMPER FOG LAMPS @\$445.00		11	\$890.00 X
1 SET	FRONT BUMPER CLIPS		me	\$40.00 ✓
1 PCS	FRONT GRILLE	295.00	one	\$525.00 ✓
1 PCS	FRONT GRILLE OUTER GARNISH	288.00	one	\$548.00 ✓
1 PCS	FRONT GRILLE 'H' LOGO		me	\$38.80 ✓
2 PCS	HEADLAMPS @\$2250	1759.10 X 2 = 3518.20	one	\$4,500.00 ✓
2 PCS	HEADLAMP LOWER BRACKETS @\$85.00		one	\$170.00 ✓
1 PCS	FRONT SUPPORT PANEL		1	\$745.11 X
1 PCS	FRONT SUPPORT PANEL TOP GARNISH	184.20	Two	\$322.30 ✓
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS		11	\$50.00 X
2 PCS	FRONT FENDERS @\$688.00		1	\$1,376.00 X
2 PCS	FRONT FENDER INNERSHIELDS @\$166.50		11	\$333.00 X
2 PCS	FRONT FENDER OUTER PROTECTORS @\$295.00		20/30m	\$590.00 ✓
1 PCS	AIR CON CONDENSER		11	\$1,568.00 X
2 PCS	AIR CON CONDENSER SIDE GARNISH @\$148.00		11	\$296.00 X
1 PCS	RADIATOR		11	\$1,817.50 X
1 PCS	RADIATOR FAN COWLING		11	\$288.30 X
1 PCS	RADIATOR FAN MOTOR		11	\$488.20 X
1 PCS	RADIATOR FAN BLADE		11	\$101.50 X
1 PCS	FRONT FENDER INNER PANEL N/S		1	\$525.30 X
1 PCS	FRONT WHEEL HOUSING PANEL N/S		11	\$988.20 X
1 PCS	FRONT LOCK CENTRE BRACKET		one	\$115.00 ✓
1 PCS	AIR DUCT		11	\$215.00 X

6763.30

1 PCS	AIR CLEANER BOX	
1 PCS	FRONT WIPER PANEL GARNISH	
1 PCS	RESONATOR BOX	
2 PCS	FRONT GRILLE CHROME MOULDING @\$98.50	
1 PCS	BATTERY TRAY	
1 PCS	WASHER TANK	
1 PCS	FRONT WINDSCREEN	
1 PCS	TAILGATE	953.00
1 PCS	TAILGATE 'H' LOGO	
1 PCS	TAILGATE 'VEZEL' EMBLEM	
1 PCS	TAILGATE OUTER HANDLE GARNISH	
2 PCS	TAILGATE REFLECTORS @\$460.50	280.00 x 2 = 560
1 PCS	TAILGATE INNER LOCK	
1 PCS	TAILGATE INNER TRIM BOARD	
1 SET	TAILGATE INNER TRIM BOARD CLIPS	
2 PCS	TAILGATE DAMPERS @\$299.10	
1 PCS	TAILGATE WEATHERSTRIP	
1 PCS	TAILGATE REAR WIPER ARM	
1 PCS	TAILGATE REAR WIPER MOTOR	
1 PCS	TAILGATE KEYLESS SENSOR	
1 PCS	REAR WINDSCREEN	
1 PCS	REAR WINDSCREEN MOULDING	
1 PCS	TAILGATE TOP SPOILER	
1 PCS	REAR BUMPER	
2 PCS	REAR BUMPER SIDES @\$285.10	
2 PCS	REAR BUMPER SIDE REATAINERS @\$35.20	
2 PCS	REAR BUMPER REFLECTORS @\$85.00	
1 PCS	REAR BUMPER DIFFUSER	
1 SET	REAR BUMPER DIFFUSER CLIPS	
2 PCS	REAR BUMPER MUDFLAPS @\$145.00	
2 PCS	TAILLAMPS @\$485.20	
2 PCS	TAILGATE HOUSING PANELS @\$195.00	
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNISH	
1 PCS	REAR FLOOR PANEL	316.50
1 PCS	REAR FLOOR PANEL TOP BOARD	495.50
1 PCS	REAR FLOOR PANEL TOOLS SPONGE	
1 PCS	REAR FLOOR PANEL SIDE PANEL N/S	
1 PCS	REAR FLOOR PANEL SIDE TOP PANEL N/S	
2 PCS	REAR FENDERS @\$885.10	
2 PCS	REAR FENDER OUTER PROTECTORS @\$264.00	
2 PCS	REAR FENDER INNER TRIM BOARD @\$845.30	389.10
1 PCS	REAR EXHAUST	
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00	
2 PCS	REAR SHOCK ABSORBERS @\$305.00	
2 PCS	REAR WHEELHUB BEARINGS @\$450.00	
1 PCS	REAR AXLE ARM	
1 PCS	REAR EXHAUST HEAT SHIELD	

11	\$788.00	X
11	\$344.20	X
11	\$385.20	X
nu	\$197.00	/
11	\$180.20	X
11	\$305.20	X
11	\$1,488.20	X
Body 11	\$1,100.90	/
nu	\$35.80	/
nu	\$56.20	/
CNO	\$399.20	/
CNO	\$921.00	/
twi	\$198.50	/
de/cno	\$321.70	/
nu	\$45.00	/
11	\$598.20	X
twi	\$135.70	/
11	\$188.20	X
11	\$695.00	X
CNO	\$180.00	/
11	\$1,566.20	X
nu	\$181.00	/
11	\$950.00	X
11	\$762.70	/
N/S de	\$570.20	IPC
N/S de	\$70.40	IPC
N/S CNO	\$170.00	IPC
twi	\$348.20	/
nu	\$50.00	/
11	\$290.00	X
CNO	\$970.40	/
11	\$390.00	X
Body 11	\$514.00	/
twi	\$184.00	/
11	\$912.00	X
worped/ Top	\$499.20	/
de/Top	\$685.00	/
11	\$399.20	X
11	\$299.20	X
11	\$1,770.20	X
de/Top	\$528.00	X Svc
N/S Top	\$1,290.60	IPC
11	\$899.20	X
11	\$90.00	X
11	\$610.00	X
11	\$900.00	X
11	\$1,885.00	X
11	\$199.00	X

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19019279/UYF3N2

Date: 12/11/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01001029
Claimant Vehicle No :	SLK5064H	Insured Vehicle No :	SKU4141J
Date of Loss:	30/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1905085

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK5064H	Engine No:	L15B4410631
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11210671
Reg. Date:	18/01/2017 (Man. Year: 2016)	Odometer:	63080 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	53,912.51	12,297.28	41,615.23	77.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,610.00	3,370.00	7,240.00	68.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	64,522.51	15,667.28	48,855.23	75.72
Approved Total (Overridden) (\$\$)		12,500.00		
(\$\$)	64,522.51	12,500.00	52,022.51	80.63
+ GST 7.00/7.00% (\$\$)	4,516.58	875.00	3,641.58	80.63
Nett Amount (\$\$)	69,039.09	13,375.00	55,664.09	80.63

INSPECTION

Date of Assignment:	31/10/2019	
Date Inspected:	31/10/2019	Inspected At:
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK5064H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	915.00 F	*- FL
2	2		*BONNET HINGES	Not Necessary	170.00 F	*- FL
3	1		*BONNET INSULATOR	Not Necessary	211.30 F	*- FL
4	1		*SET BONNET INSULATOR CLIPS	Not Necessary	35.00 F	*- FL
5	1		*BONNET LOCK	Twisted	135.50 F	*135.50 FL
6	2		*BONNET RUBBERS	Not Necessary	64.00 F	*- FL
7	1		*FRONT BUMPER	Dented/Torn	950.00 F	*801.70 FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	480.00 F	*321.00 FL
9	2		*FRONT BUMPER SIDE RETAINERS	Bent	130.00 F	*120.60 FL
10	2		*FRONT BUMPER BRACKETS	Not Necessary	230.00 F	*- FL
11	1		*FRONT BUMPER CENTRE GRILLE	Deformed/Torn	285.00 F	*145.30 FL
12	1		*FRONT BUMPER LOWER SPOILER	Not Necessary	525.00 F	*- FL
13	1		*FRONT BUMPER UNDER COVER	Not Necessary	480.00 F	*- FL
14	1		*SET FRONT BUMPER UNDER COVER CLIPS	Not Necessary	35.00 F	*- FL
15	1		*FRONT BUMPER TOW COVER	Not Necessary	45.00 F	*- FL
16	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	360.00 F	*- FL
17	2		*FRONT BUMPER FOG LAMPS	Not Necessary	890.00 F	*- FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
19	1		*FRONT GRILLE	Cracked	525.00 F	*295.00 FL
20	1		*FRONT GRILLE OUTER GARNISH	Cracked	548.00 F	*288.00 FL
21	1		*FRONT GRILLE H LOGO	Necessary	38.80 F	*38.80 FL
22	2		*HEADLAMPS	Cracked	4,500.00 F	*3,518.20 FL
23	2		*HEADLAMP LOWER BRACKETS	Cracked	170.00 F	*170.00 FL
24	1		*FRONT SUPPORT PANEL	Repair	745.11 F	*- FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Twisted	322.30 F	*184.20 FL
26	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 F	*- FL
27	2		*FRONT FENDERS	Repair	1,376.00 F	*- FL
28	2		*FRONT FENDER INNERSHIELDS	Not Necessary	333.00 F	*- FL
29	2		*FRONT FENDER OUTER PROTECTORS	Deformed/Torn	590.00 F	*590.00 FL
30	1		*AIR CON CONDENSER	Not Necessary	1,568.00 F	*- FL
31	2		*AIR CON CONDENSER SIDE GARNISH	Not Necessary	296.00 F	*- FL
32	1		*RADIATOR	Not Necessary	1,817.50 F	*- FL
33	1		*RADIATOR FAN COWLING	Not Necessary	288.30 F	*- FL
34	1		*RADIATOR FAN MOTOR	Not Necessary	488.20 F	*- FL
35	1		*FRONT FENDER INNER PANEL N/S	Repair	525.30 F	*- FL
36	1		*FRONT WHEEL HOUSING PANEL N/S	Not Necessary	988.20 F	*- FL
37	1		*FRONT LOCK CENTRE BRACKET	Cracked	115.00 F	*115.00 FL
38	1		*AIR DUCT	Not Necessary	215.00 F	*- FL
39	1		*AIR CLEANER BOX	Not Necessary	788.00 F	*- FL
40	1		*FRONT WIPER PANEL GARNISH	Not Necessary	344.20 F	*- FL
41	1		*RESONATOR BOX	Not Necessary	385.20 F	*- FL
42	2		*FRONT GRILLE CHROME MOULDING	Necessary	197.00 F	*197.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*BATTERY TRAY	Not Necessary	180.20 F	*- FL
44	1		*WASHER TANK	Not Necessary	305.20 F	*- FL
45	1		*FRONT WINDSCREEN	Not Necessary	1,488.20 F	*- FL
46	1		*TAILGATE	Badly Dented	1,100.90 F	*953.00 FL
47	1		*TAILGATE H LOGO	Necessary	35.80 F	*35.80 FL
48	1		*TAILGATE VEZEL EMBLEM	Necessary	56.20 F	*56.20 FL
49	1		*TAILGATE OUTER HANDLE GARNISH	Cracked	399.20 F	*399.20 FL
50	2		*TAILGATE REFLECTORS	Cracked	921.00 F	*560.00 FL
51	1		*TAILGATE INNER LOCK	Twisted	198.50 F	*198.50 FL
52	1		*TAILGATE INNER TRIM BOARD	Deformed/Cracked	321.70 F	*321.70 FL
53	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	45.00 F	*45.00 FL
54	2		*TAILGATE DAMPERS	Not Necessary	598.20 F	*- FL
55	1		*TAILGATE WEATHERSTRIP	Twisted	135.70 F	*135.70 FL
56	1		*TAILGATE REAR WIPER ARM	Not Necessary	188.20 F	*- FL
57	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	695.00 F	*- FL
58	1		*TAILGATE KEYLESS SENSOR	Cracked	180.00 F	*180.00 FL
59	1		*REAR WINDSCREEN	Not Necessary	1,566.20 F	*- FL
60	1		*REAR WINDSCREEN MOULDING	Necessary	181.00 F	*181.00 FL
61	1		*TAILGATE TOP SPOILER	Not Necessary	950.00 F	*- FL
62	1		*REAR BUMPER	Distorted	762.70 F	*762.70 FL
63	1		*REAR BUMPER SIDES	N/s Deformed	570.20 F	*285.10 FL
64	1		*REAR BUMPER SIDE REATAINERS	N/s Bent	70.40 F	*35.20 FL
65	1		*REAR BUMPER REFLECTORS	N/s Cracked	170.00 F	*85.00 FL
66	1		*REAR BUMPER DIFFUSER	Twisted	348.20 F	*348.20 FL
67	1		*SET REAR BUMPER DIFFUSER CLIPS	Necessary	50.00 F	*50.00 FL
68	2		*REAR BUMPER MUDFLAPS	Not Necessary	290.00 F	*- FL
69	2		*TAILLAMPS	Cracked	970.40 F	*970.40 FL
70	2		*TAILGATE HOUSING PANELS	Repair	390.00 F	*- FL
71	1		*REAR END PANEL	Badly Dented	514.00 F	*514.00 FL
72	1		*REAR END PANEL TOP GARNISH	Twisted	184.00 F	*184.00 FL
73	1		*REAR FLOOR PANEL	Repair	912.00 F	*- FL
74	1		*REAR FLOOR PANEL TOP BOARD	Warped/Torn	499.20 F	*316.50 FL
75	1		*REAR FLOOR PANEL TOOLS SPONGE	Deformed/Torn	685.00 F	*495.50 FL
76	1		*REAR FLOOR PANEL SIDE PANEL N/S	Repair	399.20 F	*- FL
77	1		*REAR FLOOR PANEL SIDE TOP PANEL N/S	Repair	299.20 F	*- FL
78	2		*REAR FENDERS	Repair	1,770.20 F	*- FL
79	2		*REAR FENDER OUTER PROTECTORS	Serviceable	528.00 F	*- FL
80	1		*REAR FENDER INNER TRIM BOARD	N/s Torn	1,290.60 F	*385.10 FL
81	1		*REAR EXHAUST	Not Necessary	899.20 F	*- FL
82	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
83	2		*REAR SHOCK ABSORBERS	Not Necessary	610.00 F	*- FL
84	2		*REAR WHEELHUB BEARINGS	Not Necessary	900.00 F	*- FL
85	1		*REAR AXLE ARM	Not Necessary	1,885.00 F	*- FL
86	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	199.00 F	*- FL
87	1		*REAR WHEEL HOUSING PANELS N/S	Not Necessary	1,150.00 F	*- FL
88	1		*REAR END LOCK SENSOR	Cracked	288.50 F	*288.50 FL
89	1		*REAR FENDER UNDER TRIM N/S	Not Necessary	299.30 F	*- FL
90	1		*REAR CHASSIS MEMBER N/S	Repair	699.20 F	*- FL
91	2		*REAR DOOR	Not Necessary	1,996.40 F	*- FL
92	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
93	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	250.00 FS	*- FS
94	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
95	1		*SET REAR REVERSE CAMERA	Shorted	380.00 FS	*300.00 FS
96	1		*REAR LICENCE PLATE W/HOLDER	Scratched	50.00 FS	*40.00 FS
97	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
98	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS
99	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
100	1		*BATTERY	Not Necessary	220.00 FS	*- FS
101	1		*BOT RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS
102	1		*RADIATOR FAN BLADE	Not Necessary	101.50 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	53,912.51	15,246.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	2,949.32
Total Parts (\$\$)	53,912.51	12,297.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	150.00	0.00
2	TO CHECK WIRING	New	100.00	30.00
3	TO DISMANTLE & REPLACING REVERSE SENSOR	New	100.00	50.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REPLACING REAR WINDSCREEN	New	150.00	120.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	80.00
8	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
9	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	380.00	0.00
10	TO SPRAY RUST PROOFING	New	200.00	80.00
11	TO REFILL AIR CON GAS	New	150.00	0.00
12	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
13	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
14	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	150.00	0.00
15	LABOUR FOR PANEL BRATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS	New	4,500.00	1,450.00
16	TO PUTTY & SPRAY PAINTING	New	3,800.00	1,500.00
Gross Labour Cost (S\$)			10,610.00	3,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >