

ASS. REC. BY:

REF: CS/SMO1909285/ETf3

72

Special Instruction:

Surveyor

Steve

ASSIGNMENT (Office)

From (Person):

Gneph Pau Lung

of

SMO

Date/Time:

31.10.19 16.02pm

Estimated Cost:

Bill to:

OD / TP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 210 L

Insured:

FBA 4184m

at Workshop m/s

Wah Hong

Tel:

67737377

of

36 Tbh Guan Road East #01-57

Policy No:

D19MTM61008129

Claim No:

CMTD 1905086

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

30.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

31.10.19 4.50pm

Person Contacted:

Chris

Vehicle

H.O.D. Endorsement:

(IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 210 L - X

FBA 4184m - X

11/4-

Revised via preli advise. menimen

Lump Sum \$3250. confirm (Red. 3120, 48%)

ASS. REC. BY:

Steve

REF: SMO

ASSIGNMENT

From:

Date:

1.11.2019

Estimated Cost:

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLF 210 L

at Workshop m/s

Wah Hong

of 38 Toh Guan Road East #01-57

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

mup"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLF210L

Yr Regn:

23/8/16

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C.

1597

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

56729

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC5650GT000063

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/42R18

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankok

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

30/10/19

D.O.A.

1/11/19

Survey held at

Wah Hong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Mv - 74K

Date/Time, File Pass to?



Prel. Report

11/23/12 Typst



Final Report

Date/Time, File Return to?

2

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Meal and (\$)

Survey Fee:

Transportation:

S + RS \$1

Photos

Others

TOTAL

Rep. Form 1

Lump Sum / TRC: TP

3250/-

250

11

261

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 04 Nov 2019

Preliminary Advice

Insured Vehicle No	: FBQ4184M	Accident Date	: 30/10/2019
TP Vehicle No	: SLF210L	Assignment Date	: 31/10/2019
Make	:	Est. Duration of Repair	: 5.00
Date of Inspection	: 01/11/2019		
Inspection At	: WAH HONG MOTORS & CREDIT PTE LTD (HQ) 38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB SINGAPORE 608581		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,370.00
Revised Amount	:S\$	4,140.00
Check Items (Estimated)	:S\$	189.00
Total	:S\$	4,329.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2019		31 Oct 2019 16:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

MUHAMMAD RUZAINI BIN ROSLI, ID: S9425738G

Main Claimant:

ELVIN CHUA CHEE PENG, ID: S7528903J

Vehicle Reg. No.:

SLF210L

Date of Loss:

30/10/2019 18:00 - :59

Claim Type:

TP / CMTD1905086

Policy/Cover Note No.:

D19MTMC01008129 (TP, Fire & Theft)

Vehicle Reg. No. (Insured):

FBQ4184M

Policy No. (Claimant):

Excess:

Repairer:

Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub, 608581 Jurong East - Tel: +65 6773 7377

Handling Insurer:

Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/11/2019]

Adj Asg. Remarks:

Please survey on a without prejudice basis

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Wahhong motors & credit pte ltd <motor@wahhong.sg>
Sent: Monday, 23 December 2019 3:22 PM
To: Denise Tay (LKKAuto)
Subject: Re: SLF 210L / TP / DOA:30/10/2019 SOMPO

Dear Denise,

Finalized lump sum \$3250/-, 5days confirmed.

LOD sent to who?

On 2019-12-23 14:57, Denise Tay (LKKAuto) wrote:

> Dear Melvin,
>
> Offer finalized lump sum \$3250/-, 5days
>
> Please check and revert back
>
> Best Regards,
>
> DENISE TAY | Case Handler
>
> LKK AUTO CONSULTANTS PTE LTD
>
> Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
>
> Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
>
> FROM: Denise Tay (LKKAuto)
> SENT: Monday, 9 December 2019 3:23 PM
> TO: Melvin Wee <motor@wahhong.sg>
> SUBJECT: SLF 210L / TP / DOA:30/10/2019 SOMPO
>
> Dear Melvin,
>
> Help me check on this case if repair is done and can finalized
>
> Best Regards,
>
> DENISE TAY | Case Handler
>
> LKK AUTO CONSULTANTS PTE LTD
>
> Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
>
> Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

—
Thank You and Best Regards,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 903J

Vehicle Details

Vehicle No.: SLF210L
Vehicle to be Exported: No
Intended Deregistration Date: 31 Oct 2019
Vehicle Make: HONDA
Vehicle Model: CIVIC 1.6 VTI CVT
Primary Colour: Grey
Manufacturing Year: 2016
Engine No.: R16B21600164
Chassis No.: MRHFC5650GT000063
Maximum Power Output: 92.0 kW (123 bhp)
Open Market Value: \$19,561.00
Original Registration Date: 23 Aug 2016
First Registration Date: 23 Aug 2016
Transfer Count: 0
Actual ARF Paid: \$19,561.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Aug 2026
PARF Rebate Amount: \$14,670.00

Intended COE Rebate Details

COE Expiry Date: 22 Aug 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$52,301.00
COE Rebate Amount: \$35,612.00
Total Rebate Amount: \$50,282.00

The information contained herein is correct as at 31 Oct 2019

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	903J
Vehicle Details	
Vehicle No.:	SLF210L
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTi CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	R16B21600164
Chassis No.:	MRHFC5650GT000063
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,561.00
Original Registration Date:	23 Aug 2016
First Registration Date:	23 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$19,561.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Aug 2026
PARF Rebate Amount:	\$14,670.00
Intended COE Rebate Details	
COE Expiry Date:	22 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$35,598.00
Total Rebate Amount:	\$50,268.00

The information contained herein is correct as at 01 Nov 2019

OK



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SLF210L HONDA CIVIC 1.6A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear bumper / 00		575.00	/
1	Rear reinforcement beam / 00		330.00	/
1	Rear bumper undercover / CR4		175.00	/
1	Bootlid / 00		590.00	/
1	Bootlid center garnish / ? / DR		210.00	/
1	Rear HONDA logo badge / NR		125.00	/
1	Rear i-VTEC logo / NR		95.00	/
1	Rear CIVIC logo / NR		105.00	/
1	Bootlid lamp LH/RH@ \$175.00 X ANI		350.00	X
1	End panel / 00		360.00	/
1	End panel top cover / CR4		95.00	/
1	Rear bumper reflector LH/RH@ \$35.00 X ANI		70.00	X
1	Rear bumper reflector cover LH/RH@ \$40.00 X NN		80.00	X
1	Rear exhaust tip X NN		190.00	X
			3350.00	
Less			10%	10%
			335.00	
			3015.00	
SPECIAL NETT ITEMS				
1	Reverse sensor / SL1		200 220.00	
1	Rear bumper clips / NR		30 40.00	
1	End panel top cover clips / NR		20 30.00	
1	Rear bumper undercover clips / NR		20 30.00	
1	Rear license plate with holder / CR4		35 55.00	
			3390.00	

[Handwritten signature]

Steve (LKK)
8322 8813

wr ml 11/11/19, 2.0pm
5 dy
L/S
By AL SM

305



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. SLF210L HONDA CIVIC 1.6A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1400.00 800	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00 700	
3	To remove, refix wiring system at accident damaged areas and check for proper function	120.00 30	
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	120.00 50	
9	To perform anti-rust treatment on affected areas	140.00 30	
	Labour Total :	2980.00	1610
	TOTAL (PARTS & LABOUR):	6370.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2128
N- 305
L- 1610
4 043
L/S- 3234.40
= 3250

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19019285/ETF3N2
Date: 26/12/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTMC01008129
Claimant Vehicle No : SLF210L **Insured Vehicle No :** FBQ4184M
 Date of Loss: 30/10/2019 Nature of Claim: TP Claim No: CMTD1905086

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF210L**
 Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B21600164
 Reg. Date: 23/08/2016 (Man. Year: 2016) Chassis No: MRHFC5650GT000063
 Colour: Grey Odometer: 56729 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18
 Front Left Side: Hankook 5 mm Rear Left Side: Hankook 5 mm
 Front Right Side: Hankook 5 mm Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,390.00	2,433.00	957.00	28.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,610.00	1,370.00	45.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,370.00	4,043.00	2,327.00	36.53
Approved Total (Overridden) (S\$)		3,250.00		
(S\$)	6,370.00	3,250.00	3,120.00	48.98
+ GST 7.00/7.00% (S\$)	445.90	227.50	218.40	48.98
Nett Amount (S\$)	6,815.90	3,477.50	3,338.40	48.98

INSPECTION

Date of Assignment: 31/10/2019
 Date Inspected: 01/11/2019 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)
 38 Toh Guan Road East, #01-57, Enterprise Hub
 Singapore 608581
 Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Dec 2019)

Parts: 143 HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLF210L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	575.00 FL	*575.00 FL
2	1		*REAR REINFORCEMENT BEAM	Dented	330.00 FL	*330.00 FL
3	1		*REAR BUMPER UNDERCOVER	Crushed	175.00 FL	*175.00 FL
4	1		*BOOTLID	Dented	590.00 FL	*590.00 FL
5	1		*BOOTLID CENTER GARNISH	Broken	210.00 FL	*210.00 FL
6	1		*REAR HONDA LOGO BADGE	Necessary	125.00 FL	*125.00 FL
7	1		*REAR I-VTEC LOGO	Necessary	95.00 FL	*95.00 FL
8	1		*REAR CIVIC LOGO	Necessary	105.00 FL	*105.00 FL
9	2		*BOOTLID LAMP LH/RH	Not Necessary	350.00 FL	*- FL
10	1		*END PANEL	Dented	360.00 FL	*360.00 FL
11	1		*END PANEL TOP COVER	Crushed	95.00 FL	*95.00 FL
12	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	70.00 FL	*- FL
13	2		*REAR BUMPER REFLECTOR COVER LH/RH	Not Necessary	80.00 FL	*- FL
14	1		*REAR EXHAUST TIP	Not Necessary	190.00 FL	*- FL
15	1		*REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
16	1		*REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
17	1		*END PANEL TOP COVER CLIPS	Necessary	30.00 FS	*20.00 FS
18	1		*REAR BUMPER UNDERCOVER CLIPS	Necessary	30.00 FS	*20.00 FS
19	1		*REAR LICENSE PLATE WITH HOLDER	Cut	55.00 FS	*35.00 FS

F=Franchise part, S=SpchNett, L=ListItemDisc.

Sub Total (S\$)	3,725.00	2,965.00
- List Item Discount on L Items 10.00/20.00% (S\$)	335.00	532.00
Total Parts (S\$)	3,390.00	2,433.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	800.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	700.00
3	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	120.00	30.00
4	TO REMOVE/REFIX INNER TRIMS,FITTINGS,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	120.00	50.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	140.00	30.00
Gross Labour Cost (S\$)			2,980.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >