

EROFIA MOTOR TRADING PTE LTD

A169

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Lim Khoon Him

Accident Date : 14-Jun-19

Vehicle No : FBJ 5748 S

Vehicle Model : Sym Joyride 200

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Top cowling	\$ One 75.00 —
1	Front fairing	\$ One 450.00 —
1	Front fairing inner panel	\$ One 265.00 —
1	Front lower fairing	\$ One 210.00 —
1	Headlamp	\$ One 225.00 —
2	Front signals	\$ 055ea 210.00 —
1	Front mudguard	\$ One 155.00 —
1	Front fork assy	\$ but/tu 850.00 2
1	Fork under bracket	\$ tu 220.00 2
1	Front rim	\$ n 310.00 X
1	Front brake disc	\$ n 165.00 X
1	Lower belly panel	\$ One 285.00 —
1	Front rim shaft	\$ n 45.00 X
1	Centre inner cowling	\$ One 175.00 —
1	Centre inner cowling top cover	\$ One 110.00 —
1	Windshield	\$ sec 165.00 X
1	Side mirror - R/H	\$ One 80.00 —
1	Handle bar	\$ but 125.00 ?
1	Handle bar end	\$ sin 25.00 —
1	Brake lever	\$ sec 32.00 —
1	Handle bar top cover	\$ One 100.00 2
1	Handle bar lower cover	\$ n 68.00 X
1	Rear fairing - R/H	\$ n 355.00 X
1	Footstep panel	\$ One 105.00 —
1	Exhaust assy	\$ 20/24 550.00 —
1	Exhaust protector	\$ tu 55.00 —
1	Main stand	\$ n 120.00 X
1	Rear footrest - R/H	\$ One 65.00 —
1	Rear taillamp	\$ n 320.00 X
1	Rear mudguard	\$ n 165.00 X
		\$ 6,080.00
	Less 10%	\$ 608.00
		\$ 5,472.00

not admit
dew
n/s #4000/
31/10/19
S.L.J.
Wheate 11/11/19

4367

c/f: \$ 5,472.00

							<i>S. Next</i>
		\$	<i>11</i>	28.00		<i>X</i>	
1	Number plate (1 set)	\$	<i>11</i>	30.00		<i>X</i>	
2	Fork oils	\$	<i>11</i>	56.00		<i>X</i>	
2	Fork oil seals	\$	<i>11</i>	85.00		<i>X</i>	
1	Steering cone (1 set)	\$	<i>11</i>	250.00		<i>✓</i>	
1	Rear box	\$	<i>11</i>	100.00		<i>✓</i>	
1	Rear box bracket	\$	<i>11</i>	55.00		<i>✓</i>	
1	" Joyride 200 " emble	\$		604.00		<i>✓</i>	

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service.	\$	<i>35</i>	45.00
2	To provide labour.	\$	<i>300</i>	380.00
3	To respray painting	\$	<i>400</i>	600.00
4	To straighten body frame to the original position	\$	<i>RA</i>	400.00 <i>X</i>
5	To check wiring and reset headlamp focusing	\$	<i>11X</i>	80.00
		\$		1,505.00

Grand Total \$ 7,581.00

MS. J

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed ~~and~~ is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____