

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1910-132

DATE : 30-Oct-2019

POLICY NO. : AVIVA 10801675

VEHICLE REG. NO. : SLK2434T

VEHICLE MAKE : TOYOTA ALTIS 1.6L A

TO Motor Claim Department

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

Tel: 1800-880-4741

Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / <i>OP</i>	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clip / <i>MC</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Upper Retainer RH / <i>OR</i>	1	\$ 80.00	\$ 80.00
4	Rear Bumper Upper Retainer LH / <i>BR</i>	1	\$ 80.00	\$ 80.00
5	Rear Bumper Side Retainer RH	1	\$ 120.00	\$ 120.00
6	Rear Bumper Side Retainer LH	1	\$ 120.00	\$ 120.00
7	Rear Bumper Reflector RH <i>x</i>	1	\$ 60.00	\$ 60.00
8	Rear Bumper Reflector LH <i>x</i>	1	\$ 60.00	\$ 60.00
9	Rear Reinforcement <i>?</i>	1	\$ 400.00	\$ 400.00
10	Rear Reinforcement Arm RH <i>x</i>	1	\$ 70.00	\$ 70.00
11	Rear Reinforcement Arm LH <i>x</i>	1	\$ 70.00	\$ 70.00
12	Rear Antenna <i>?</i>	1	\$ 180.00	\$ 180.00
13	Rear Reverse Sensor / <i>BR</i>	<i>2</i>	\$ 220.00	\$ 440.00
14	End Panel <i>x R</i>	1	\$ 600.00	\$ 600.00
15	End Panel Top Garnish / <i>CRU</i>	1	\$ 240.00	\$ 240.00
Total Spare Parts				\$ 3,250.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
16	Respray Rear Bumper, Rear Bootlip and Inner Panel	1	\$ 500.00	\$ 500.00
17	Repair, Replace and Refill Affected Accident Area Inc. End Panel	1	\$ 500.00	\$ 500.00
18	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
19	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
20	Check and Rectify Electrical Wiring	1	\$ 20.00	\$ 20.00
Total Labour				\$ 1,200.00
Amount Before Excess				\$ 4,450.00
Add GST @ 7%				311.50
Total Amount Payable				\$ 4,761.50

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasional worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

- LKK Auto Consultants** hereby certify the Repair estimate as follows:
- To resurvey damaged part(s) during resurvey
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer