

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1910-132
DATE : 30-Oct-2019
POLICY NO. : AVIVA 10801675
VEHICLE REG. NO. : SLK2434T
VEHICLE MAKE : TOYOTA ALTIS 1.6L A

TO Motor Claim Department
AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
Tel: 1800-880-4741
Fax: 6880 4740

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / <i>OP</i>	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clip / <i>MC</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Upper Retainer RH / <i>OR</i>	1	\$ 80.00	\$ 80.00
4	Rear Bumper Upper Retainer LH / <i>BR</i>	1	\$ 80.00	\$ 80.00
5	Rear Bumper Side Retainer RH / <i>X NAI</i>	1	\$ 120.00	\$ 120.00
6	Rear Bumper Side Retainer LH / <i>X NAI</i>	1	\$ 120.00	\$ 120.00
7	Rear Bumper Reflector RH / <i>X NAI</i>	1	\$ 60.00	\$ 60.00
8	Rear Bumper Reflector LH / <i>X NAI</i>	1	\$ 60.00	\$ 60.00
9	Rear Reinforcement / <i>OP</i>	1	\$ 400.00	\$ 400.00
10	Rear Reinforcement Arm RH / <i>X</i>	1	\$ 70.00	\$ 70.00
11	Rear Reinforcement Arm LH / <i>X</i>	1	\$ 70.00	\$ 70.00
12	Rear Antenna / <i>X NAI</i>	1	\$ 180.00	\$ 180.00
13	Rear Reverse Sensor / <i>BR</i>	2	\$ 220.00	\$ 440.00
14	End Panel / <i>X R</i>	1	\$ 600.00	\$ 600.00
15	End Panel Top Garnish / <i>X NAI</i>	1	\$ 240.00	\$ 240.00
Total Spare Parts				\$ 3,250.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
16	Respray Rear Bumper, Rear Bootlip and Inner Panel	1	\$ 500.00	\$ 500.00
17	Repair, Replace and Refill Affected Accident Area Inc. End Panel	1	\$ 500.00	\$ 500.00
18	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
19	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
20	Check and Rectify Electrical Wiring	1	\$ 20.00	\$ 20.00
Total Labour				\$ 1,200.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 1,200.00
Amount Before Excess	\$ 4,450.00
Add GST @ 7%	311.50
Total Amount Payable	\$ 4,761.50

Steve Chen (LKK Auto)

From: raymond@automotiverepaircentre.com.sg
Sent: Tuesday, November 12, 2019 5:27 PM
To: Steve Chen (LKK Auto)
Cc: shujuan@automotiverepaircentre.com.sg
Subject: RE: Your Ref : SLK2434T Our Ref : S9M025D2MC/CL *** LKK REF: CC4/ASM19019299/pa3

Dear Steve,

Please confirmed P/P repair @ \$1,833.75. (4 Repair days)

Thank you.

Best Regards,
Raymond Tan
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: +65 64688834
Fax: +65 64622278

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Tuesday, 12 November 2019 5:15 PM
To: raymond@automotiverepaircentre.com.sg
Cc: shujuan@automotiverepaircentre.com.sg
Subject: Your Ref : SLK2434T Our Ref : S9M025D2MC/CL *** LKK REF: CC4/ASM19019299/pa3

Dear Raymond,

Kindly refer our finalize \$1833.75 (P/P, before GST). 4 repair days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)