

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 17031**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/1288/2019/KK  
**Date** : 26-Oct-19

**Vehicle NOT IN workshop. Please arrange for survey**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Ms Chang Min Chia  
**Address** : 42 East Coast Road  
#17-01  
Singapore 428762  
**Telephone** : HP +65 82236625  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 2100456670-03  
**Vehicle No** : **SLB 2167 L**  
**Model Code** : Audi Q3 1.4 TFSI S TRONIC  
**Model / Year** : Mar-16  
**Engine No** : CZD 224116  
**Chassis No** : WAUZZZ8U7GR061809  
**Mileage** :  
**Date In** :  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 23-Oct-19  
**Place of Accident** : AYE Towards Tuas Along Road 1

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
 Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLB 2167 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature and headlight washer assy. S/N	\$ 360.00	/
2	To dismantle and renew front bumper assy. Re-organise front crash management crash components. Reinstall all parts removed.	\$ <del>1,200.00</del>	500.
3	To respray front bumper, lower spoiler, wheel arch trims and bonnet. ✓ X ✓ / ✓	\$ <del>3,000.00</del>	1600. Wheel Arch 250 x 2 = 500
4	To carry out diagnostic check. S/N	\$ 192.00	/ 2 x 550 = 1100
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 4,752.00</b>	<b>1600</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLB 2167 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER <i>deformed.</i>	\$ 1,788.00	✓
2	FRONT BUMPER FIXING PARTS <i>Me n</i>	\$ 99.00	X
3	FRONT BUMPER SPOILER ?	\$ 527.00	?
4	FRONT BUMPER UNDERRUN BAR ?	\$ 891.00	?
5	RADIATOR GRILLE - CENTER <i>could</i>	\$ 197.00	✓
6	RADIATOR GRILLE <i>could</i>	\$ 1,053.00	✓
7	RADIATOR GRILLE BRACKET - LH ?	\$ 111.00	?
8	FRONT BUMPER AIR GUIDE DRILLE - LH <i>Me n</i>	\$ 139.00	X.
9	FRONT BUMPER REINFORCEMENT ?	\$ 770.00	?
10	FOAM FILLER PIECE ?	\$ 93.00	?
11	FRONT BUMPER REINFORCEMENT COVER ?	\$ 59.00	?
12	FRONT BUMPER TOP COVER <i>Me n</i>	\$ 112.00	X
13	SIGN 'CAUTION' <i>next to</i>	\$ 13.00	X
14	FRONT WHEEL COVER - LH/RH <i>Me</i>	\$ 964.00	✓
15	HEADLIGHT MOUTING - LH ?	\$ 107.00	?
16	HEADLIGHT MOUTING SUPPORT - LH ?	\$ 23.00	?
17	LIFT CYLINDER - LH ?	\$ 192.00	?
18	FRONT NO PLATE <i>Dented</i>	S/N \$ 40.00	✓
19	SUNDRIES ?	\$ 300.00	?
<b>TOTAL SPARE PARTS</b>		<b>\$ 7,478.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 4,752.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 12,230.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lim  
Surveyed Date : 01/11/19  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

### Estimate No.

PA/OD/1288/2019/KK

### Date

1-Nov-19

### Service Advisor

Glory Tan

### Pages

1 of 1

### Regn No

SLB 2167 L

### Model No

Audi Q3 1.4 TFSI S TRONIC

Quantity	Description	Unit Price	Amount
<b>Parts</b>			
1	Headlight LHS	\$ 7,087.00	✓ CRA
		<u>\$ 7,087.00</u>	
<b>Labours</b>			
1	To remove and renew headlight LHS.	\$ 800.00	✓ 250
Labour total		\$ 800.00	
Part total		<u>\$ 7,087.00</u>	
<b>GRAND TOTAL</b>		<u><b>\$ 7,887.00</b></u>	

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorised Signature