

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Nov 2019 16:08		01 Nov 2019 14:48 Edit Adj Rpt	S\$4,929.28 Edit Estimates	S\$4,929.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: JOSEPH CHAN WAI MENG , ID: S7046562J, Tel: +6581800028, Email: JOSEPH.WM.CHAN@GMAIL.COM									
Vehicle Reg. No.: SJC1000J		Date of Loss: 01/11/2019 07:00 - :59 [92 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 4876959806SG		Policy/Cover Note No.: (Comprehensive)							
		Excess: S\$1,000.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/11/2019]									
Driver/Custodian: JOSEPH CHAN WAI MENG (48 / Male) , NRIC: S7046562J, Tel: +6581800028 Email: JOSEPH.WM.CHAN@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (03/04/2020): Alert - Adj Mandate Approved (S\$4929.28) - SJC1000J - Claim Handler: Nadaraja, D... - AIG_SG (04/11/2019): Alert - Adj Mandate Approved (S\$4952.00) - SJC1000J - Claim Handler: Nadaraja, D... - AIG_SG (04/11/2019): SJC1000J / OD / 01/11/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJC1000J (4876959806SG)**
OD
Nov 1 2019 7:00AM
[JOSEPH CHAN WAI MENG]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio				View View in Browser ▼	
Video					
				1 per page ▼	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	01/11/19 10:34	Video - Accident [Linked Accident Report Documents]		Load MP4	
Assessment Reports					
				1 per page ▼	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/11/19 16:35	Adjuster Immediate Advice		Load HTM	
Photos/Images					
				3 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/11/19 15:31	General View		Load JPG	☒
2	01/11/19 15:31	General View		Load JPG	☒
3	01/11/19 15:31	General View		Load JPG	☒
4	01/11/19 15:31	General View		Load JPG	☒
5	01/11/19 15:31	General View		Load JPG	☒
6	01/11/19 15:31	General View		Load JPG	☒
7	01/11/19 15:31	General View		Load JPG	☒
8	01/11/19 15:31	General View		Load JPG	☒
9	01/11/19 15:31	General View		Load JPG	☒
10	01/11/19 15:31	General View		Load JPG	☒
11	01/11/19 15:31	General View		Load JPG	☒
12	01/11/19 15:31	General View		Load JPG	☒
13	01/11/19 15:31	General View		Load JPG	☒
14	01/11/19 15:31	General View		Load JPG	☒
15	01/11/19 15:31	General View		Load JPG	☒
16	01/11/19 15:31	General View		Load JPG	☒
17	01/11/19 15:31	General View		Load JPG	☒
18	01/11/19 15:31	General View		Load JPG	☒
19	19/03/20 10:23	Reinspection Photo		Load JPG	☒
20	19/03/20 10:23	Reinspection Photo		Load JPG	☒
21	19/03/20 10:23	Reinspection Photo		Load JPG	☒
22	19/03/20 10:23	Reinspection Photo		Load JPG	☒
23	19/03/20 10:23	Reinspection Photo		Load JPG	☒
24	19/03/20 10:23	Reinspection Photo		Load JPG	☒
25	19/03/20 10:23	Reinspection Photo		Load JPG	☒
26	19/03/20 10:23	Reinspection Photo		Load JPG	☒
Documentation					
				1 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/11/19 15:30	Singapore Accident Statement		Load PDF	
2	01/11/19 15:30	Certificate of Insurance		Load PDF	
3	01/11/19 15:30	DRIVING LICENSE		Load PDF	
4	01/11/19 16:00	ESTIMATE		Load PDF	
5	02/04/20 12:04	ESTIMATE		Load PDF	
6	28/05/20 09:30	WORKSHOP INVOICE		Load PDF	
7	28/05/20 09:30	DISCHARGE VOUCHER		Load PDF	

Linked Accident Report Documents

View

View in Browser

Video

1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	01/11/19 10:34	Video - Accident		Load MP4	

Assessment Reports

1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	06/12/19 19:18	Accident Statement		Load HTM	
2	06/12/19 19:19	Accident Statement		Load HTM	
3	06/12/19 19:20	Accident Statement		Load HTM	
4	06/12/19 19:27	Accident Statement		Load HTM	

Photos/Images

3 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	01/11/19 10:33	Accident Photo		Load JPG	☒
2	01/11/19 10:33	Accident Photo		Load JPG	☒
3	01/11/19 10:33	Accident Photo		Load JPG	☒
4	01/11/19 10:33	Accident Photo		Load JPG	☒
5	01/11/19 10:33	Accident Photo		Load JPG	☒
6	01/11/19 10:33	Accident Photo		Load JPG	☒
7	01/11/19 10:33	Accident Photo		Load JPG	☒
8	01/11/19 10:33	Accident Photo		Load JPG	☒
9	01/11/19 10:33	Accident Photo		Load JPG	☒
10	01/11/19 10:33	Accident Photo		Load JPG	☒
11	01/11/19 10:33	Accident Photo		Load JPG	☒
12	01/11/19 10:33	Accident Photo		Load JPG	☒
13	01/11/19 10:33	Accident Photo		Load JPG	☒
14	01/11/19 10:33	Accident Photo		Load JPG	☒
15	01/11/19 10:33	Accident Photo		Load JPG	☒
16	01/11/19 10:33	Accident Photo		Load JPG	☒
17	01/11/19 10:33	Accident Photo		Load JPG	☒

Documentation

1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	01/11/19 10:35	Sketch Plan		Load JPG	☒
2	01/11/19 10:35	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19019332/ATF3S2**Date:** 28/05/2020**REFERENCE**

Insured/Claimant: JOSEPH CHAN WAI MENG
Date of Loss: 01/11/2019

Policy No:
Nature of Claim: OD Claim No: 4876959806SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC1000J**
Make & Model: AUDI S5, 3.0 TFSI QUATTRO (A) Engine No: CAK021464
Reg. Date: 14/02/2012 (Man. Year: 2011) Chassis No: WAUZZZ8T5BA110441
Colour: Grey Odometer: 85750 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$75,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,243.00	3,207.28	16,035.72	83.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,072.00	1,722.00	7,350.00	81.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,315.00	4,929.28	23,385.72	82.59
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	27,315.00	3,929.28	23,385.72	85.61
+ GST 7.00/7.00% (S\$)	1,912.05	275.05	1,637.00	85.61
Nett Amount (S\$)	29,227.05	4,204.33	25,022.72	85.61

INSPECTION

Date of Assignment: 01/11/2019

Date Inspected: 01/11/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,907.00 FS	*1,525.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	234.00 FS	*- FS
3	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	802.00 FS	*- FS
4	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	414.00 FS	*- FS
5	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	52.00 FS	*- FS
6	2		*FRONT BUMPER GUIDE PIECE - LH / RH	Not Necessary	80.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	216.00 FS	*- FS
8	3		*FRONT BUMPER PULL STRAP - LOWER	Not Necessary	140.00 FS	*- FS
9	1		*FRONT BUMPER TRIM - LOWER	Not Necessary	527.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	116.00 FS	*- FS
11	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	418.00 FS	*- FS
12	1		*FRONT BUMPER COVER	Cracked	89.00 FS	*70.88 FS
13	2		*FOG LAMP TRIM - LH / RH	Not Necessary	128.00 FS	*- FS
14	2		*HEADLIGHT MOUNTING - LH / RH	Not Necessary	228.00 FS	*- FS
15	2		*CORNERING LIGHT HEADLIGHT - LH / RH	Not Necessary	4,934.00 FS	*- FS
16	2		*HEADLIGHT BRACKET - LH / RH	Not Necessary	146.00 FS	*- FS
17	2		*LIFT CYLINDER - LH / RH	Not Necessary	502.00 FS	*- FS
18	5		*HEADLIGHT HOSE	Not Necessary	179.00 FS	*- FS
19	1		*LOCK CARRIER	Not Necessary	928.00 FS	*- FS
20	1		*A/C CONDENSER	Not Necessary	677.00 FS	*- FS
21	1		*PRESSURE RELIEF VALVE	Not Necessary	48.00 FS	*- FS
22	1		*PRESSURE SENDER	Not Necessary	175.00 FS	*- FS
23	2		*COOLANT REGULATOR SUPPORT	Not Necessary	69.00 FS	*- FS
24	1		*RADIATOR	Not Necessary	1,485.00 FS	*- FS
25	2		*RADIATOR RUBBER BUSH - UPPER	Not Necessary	12.00 FS	*- FS
26	4		*READY MIX COOLANT	Not Necessary	84.00 FS	*- FS
27	1		*ADDITIONAL RADIATOR	Not Necessary	749.00 FS	*- FS
28	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	134.00 FS	*- FS
29	2		*RADIATOR SEALING STRIP - LOWER / UPPER	Not Necessary	42.00 FS	*- FS
30	1		*RADIATOR GRILLE	Cracked	1,851.00 FS	*1,480.80 FS
31	1		*SS INSCRIPTION	Necessary	113.00 FS	*90.00 FS
32	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
33	1		*AIRCON STICKER	Not Necessary	18.00 FS	*- FS
34	1		*FRONT BUMPER COVER	Not Necessary	116.00 FS	*- FS
35	1		*SIGNAL HORN - RH LOW TONE	Not Necessary	184.00 FS	*- FS
36	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	184.00 FS	*- FS
37	1		*SPRING SHACKLE - RH LOW TONE	Not Necessary	23.00 FS	*- FS
38	1		*SPRING SHACKLE - LH HIGH TONE	Not Necessary	23.00 FS	*- FS
39	2		*FRONT PARKING AID SENSOR	Not Necessary	419.00 FS	*- FS
40	1		*BONNET LID LOCK	Not Necessary	196.00 FS	*- FS
41	1		*BONNET CATCH HOOK	Not Necessary	127.00 FS	*- FS
42	1		*BONNET LOCK COVER	Not Necessary	21.00 FS	*- FS
43	1		*FRONT NO PLATE	Necessary	40.00 FS	*40.00 FS
44	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,243.00 3,207.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	4,800.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	New	2,200.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			9,072.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >