

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 17489

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1299/2019/NS
Date	:	31-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Chong Lee Fong
Address	:	8 Bee San Avenue Singapore 589963
Telephone	:	(HP) +65 97876383
Type of Claim	:	Own Damage Claims
Policy No.	:	1800080001-01
Vehicle No	:	SJT 9963 M
Model Code	:	Audi A4 SEDAN 2.0 TFSI
Model / Year	:	20/7/2018
Engine No	:	CVK 064081
Chassis No	:	WAUZZZF49JN015027
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	30-Oct-19
Place of Accident	:	Clementi Ulu Pandan Road Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJT 9963 M

S/n	Nature of Jobs		Estimated Charges	Surveyor's Reccomendations
1	To remove , check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	✓
2	To dismantle and renew front bumper, lhs front fender, and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$	2,450.00 1000	
3	To respray front bumper and lhs front fender.	\$	2,000.00 1100	
4	To renew lhs front rim and carry out wheel alignment.	S/N \$	280.00	✓
5	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 5,402.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SIT 9963 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Repair</i>	\$ 1,999.00	+
2	FRONT BUMPER FIXING PARTS	\$ 258.00	+
3	FRONT BUMPER AIR GUIDE - LH	\$ 56.00	+
4	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 123.00	+
5	FRONT BUMPER GUIDE SECTION - LH	\$ 33.00	+
6	FRONT FENDER - LH <i>Dented</i>	\$ 700.00	✓ 559.60
7	FRONT FENDER ATTACHMENT PARTS <i>Not Rec</i>	\$ 183.00	? X
8	FRONT FENDER CLOSING ELEMENT - LH <i>Rec</i>	\$ 45.00	+
9	FRONT FENDER BRACKET - LH <i>Not Rec</i>	\$ 32.00	? X
10	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH <i>Rec</i>	\$ 45.00	+
11	FRONT FENDER BRACKET - LH <i>Not Rec</i>	\$ 29.00	? X
12	FRONT FENDER BRACE - LH FRONT <i>Not Rec</i>	\$ 107.00	? X
13	FRONT WHEEL HOUSING LINER - LH <i>Rec</i>	\$ 223.00	+
14	WHEEL HOUSING LINER ATTACH, EMT PARTS <i>Rec</i>	\$ 82.00	+
15	WHEEL SPOILER <i>Rec</i>	\$ 66.00	+
16	WHEEL SPOILER TRIM - LH <i>Rec</i>	\$ 32.00	+
17	STONE CHIP GUARD - LH <i>Rec</i>	\$ 46.00	✓ 36.64
18	FENDER LEDGE COVER - LH <i>Not Rec</i>	\$ 28.00	? X
19	FENDER TOP LEDGE COVER - LH <i>Not Rec</i>	\$ 21.00	? X
20	FRONT PARKING AID SENSOR - INNER / OUTER <i>Rec</i>	\$ 231.00	+

SUB TOTAL SPARE PARTS

: \$ 4,339.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJT 9963 M

S/N	Parts Description			Damaged Parts & Prices	
				S/Nett	Remarks
21	PARKING AID SEAL RING	4	\$	12.00	✓
22	LED HEADLIGHT - LH		\$	7,087.00	✓
23	FRONT ALUMINIUM RIM - LH		\$	651.00	✓ 520.80
24	ALUMINIUM RIM RUBBER VALVE	4	\$	13.00	✓
25	SUNDRIES		\$	400.00	✓

TOTAL SPARE PARTS

: \$ 12,502.00

TOTAL LABOUR CHARGES

\$ 5,402.00

GRAND TOTAL

\$ 17,904.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name
Surveyed Date
Authorised Date
Excess Cost
Liability
Remarks

: Adrian King
: 01/11/12

:
: Not Authorised, 05 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant