

**CAS GARAGE PTE LTD**

REG NO. 11000000000000000000

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: NO 78, SHENTON WAY, #07-16
S(079120)

Vic

Telephone: 64193000

Fax: 68357416

Email aigsgp_claimssurvey@aig.com

Make/ Model : VOLKSWAGEN TOURAN

Date: 30.10.2019

Chassis No : WVGZZZITZFW009980

Vehicle No: SKQ6591B

Date/Time of Accide 17.10.2019/08 10

Date of Reg: 17.12.2014

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	FRONT DOOR LH <i>Rep</i>	1	\$ 1,470.30		\$ X 1,470.30
2	FRONT DOOR PROTECTOR LH <i>Ren</i>	1	\$ 158.60		\$ + 158.60
3	REAR DOOR LH <i>Dented</i>	1	\$ 1,456.80		\$ ✓ 1,456.80
4	REAR DOOR PROTECTOR LH <i>Lt</i>	1	\$ 158.90		\$ ✓ 158.90
5	REAR DOOR OUTER HANDLE LH <i>Ren</i>	1	\$ 225.30		\$ + 225.30
6	REAR DOOR INNER TRIM LH <i>Ren</i>	1	\$ 659.30		\$ + 659.30
7	SIDE ROCKER PANEL LH <i>Rep</i>	1	\$ 956.80		\$ + 956.80
8	REAR FENDER LH <i>Dented</i>	1	\$ 1,278.90		\$ ✓ 1,278.90
9	REAR RIM LH <i>Lt</i>	1	\$ 785.60		\$ ✓ 785.60
Total List Price Cost					\$ 7,150.50

3680.70

3312.18

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR BUMPER CLIPS <i>Ren</i>	1 SET	\$ 30.00		\$ X 30.00
2	REAR DOOR INNER TRIM CLIPS <i>Ren</i>	1 SET	\$ 30.00		\$ + 30.00
3	REAR TAILGATE INNER TRIM CLIPS <i>Ren</i>	4 SET	\$ 120.00		\$ + 120.00
4	REAR FENDER GLASS SEALANTS <i>Ren</i>	2	\$ 80.00		\$ 60.00
Total Special Nett Items					\$ 260.00

60.

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE ALL PARTS	\$ 1,600.00
	800.
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,600.00
	600.
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 60 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 80 180.00
TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS	\$ 60 200.00
TO CONDUCT WATER LEAKAGE TEST	\$ x 150.00
TO REMOVE/REFIT REVERSE SENSORS AND DISTANCE SETTLING	\$ x 180.00
TO REMOVE/ REFIT REAR FENDER GLASS	\$ 60 180.00
Total Others Cost	\$ 1,070.00
GRAND TOTAL	
	\$ 11,680.50

1660

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allangoh.cas@gmail.com
Fax: +65 6509 9501

Adrian L
L/s 31/10/19.

06 Days

Total: 5032.08.

L/s: 4K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: