

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Oct 2019 Edit Reg		31 Oct 2019 00:00 Edit Adj Rpt	S\$1,650.00 Edit Estimates	S\$1,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD267G	Date of Loss:	29/10/2019 16:00 - :59 [47 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3366219722SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKS8969Y	Policy No. (Claimant):	VFX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (13/04/2020): Alert - Adj Mandate Approved (S\$2070.38) - SHD267G - Claim Handler: MdNoor, Nors...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD267G (3366219722SG)**
[SKS8969Y]

TP

TRANS-CAB SERVICES PTE LTD

Oct 29 2019 4:00PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences				
1 per page ▼			☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Assessment Reports				
1 per page ▼			☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/20 11:12	Adjuster Immediate Advice	Load HTM	
Photos/Images				
3 per page ▼			☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/20 10:57	General View	Load JPG	☒
2	24/01/20 10:57	General View	Load JPG	☒
3	24/01/20 10:57	General View	Load JPG	☒
4	24/01/20 10:57	General View	Load JPG	☒
5	24/01/20 10:57	General View	Load JPG	☒
6	24/01/20 10:57	General View	Load JPG	☒
7	24/01/20 10:57	General View	Load JPG	☒
8	24/01/20 10:57	General View	Load JPG	☒
9	24/01/20 10:57	General View	Load JPG	☒
10	24/01/20 10:57	Odometer Reading	Load JPG	☒
11	24/01/20 10:57	Chassis Number	Load JPG	☒
Documentation				
1 per page ▼			☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/19 16:45	TP ESTIMATE- MARKED	Load PDF	
2	01/11/19 16:45	TP GIA REPORT	Load PDF	
3	24/01/20 11:01	LOD	Load PDF	
4	24/01/20 11:01	RENTAL RECEIPT	Load PDF	
5	24/01/20 11:01	LTA SEARCH FEE	Load PDF	
6	28/04/20 10:28	Authorisation to Act	Load PDF	
7	28/04/20 10:28	LETTER TO OI	Load PDF	
8	28/04/20 10:28	Release Voucher	Load PDF	
9	28/04/20 10:28	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/11/19 13:44	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.		

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKS8969Y (Insd veh)	Model:	RENAULT LATITUDE 2.0 D DCI
	SHD267G (TP veh)		(A)
Date of Accident:	29/10/2019		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				26,711.85
Final Repair Cost	:	\$				1,765.50
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				297.39 3 days
LTA / GIA Search Fee	:	\$				7.49
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				2,070.38

Is Third Party Workshop GIA Registered?				[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:				Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ 0 _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	: \$	2,070.38
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

28 Apr
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19019337/KDS3S2**Date:** 28/04/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHD267G**Insured Vehicle No :** SKS8969Y

Date of Loss: 29/10/2019

Nature of Claim: TP

Claim No: 3366219722SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD267G**

Make & Model: RENAULT LATITUDE, 2.0 D dCi (A)

Engine No: M9R8839C002921

Reg. Date: 20/11/2015 (Man. Year: 2015)

Chassis No: VF1ABL15AUC282311

Colour: Metallic White/Red

Odometer: 658381 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Sailun 9 mm

Rear Left Side: Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,454.35	1,574.26	8,880.09	84.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,510.00	495.00	14,015.00	96.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,964.35	2,069.26	22,895.09	91.71
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	24,964.35	1,650.00	23,314.35	93.39
+ GST 7.00/7.00% (S\$)	1,747.50	115.50	1,632.00	93.39
Nett Amount (S\$)	26,711.85	1,765.50	24,946.35	93.39
+ Car Rental (3.0 x S\$99.13/day) (S\$)		297.39		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,070.38		

INSPECTION

Date of Assignment: 31/10/2019

Date Inspected: 31/10/2019 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented / Distorted	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
7	1		*BUMPER BRACKET SIDE REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	313.10 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
19	1		*BOOT REAR	Repair	1,677.20 FL	*- FL
20	1		*BOOT FINISHER	Scratched	344.70 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	95.80 FL	*- FL
26	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
28	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
29	1		*BOOT HINGE RH	Repair	253.80 FL	*- FL
30	2		*BOOT RUBBER PLUG	Serviceable	139.90 FL	*- FL
31	2		*BOOT BUFFER	Serviceable	26.80 FL	*- FL
32	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*- FL
33	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
34	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*- FL
35	1		*BOOT SWITCH	Serviceable	113.00 FL	*- FL
36	1		*BOOT LOCK	Repair	246.60 FL	*- FL
37	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
38	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL
39	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
40	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
41	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
42	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
43	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
44	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
45	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
46	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
47	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
48	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
49	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
50	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
51	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
52	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
53	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
54	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
55	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
57	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS
58	1		*EXHAUST MOUNTING REAR	Serviceable	16.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					11,451.26	1,726.40
- List Item Discount on L Items 10.00/10.00% (\$\$)					996.91	152.14
Total Parts (\$\$)					10,454.35	1,574.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REAIR.	New	380.00	0.00
3	TO RUST=PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	15.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
7	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAAME.	New	6,000.00	200.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
11	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	220.00
14	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
Gross Labour Cost (\$\$)			14,510.00	495.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >