

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 267G**AAD1910-230***Not Authorised*
L1 Imp @ 1650/-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

31 OCT 2019

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 267G

VF1ABL15AUC282311

RENAULT

LATITUDE

29.10.19

AIG

20/11/2015

		PART	LIST
1	1	BUMPER COVER REAR	\$ Bu 561.70 ✓
2	1	BUMPER LOWER REAR	\$ Nd1011 411.90 ✓
3	1	BUMPER BRACKET CTR REAR	\$ SL 98.10 X
4	1	BUMPER BRACKET SIDE RH REAR	\$ SL 82.10 X
5	1	BUMPER RETAINER RH REAR	\$ SL 59.80 X
6	1	BUMPER REFLECTOR RH	\$ SL 16.60 X
7	1	BUMPER BRACKET SIDE LH REAR	\$ SL 80.80 X
8	1	BUMPER RETAINER LH REAR	\$ SL 54.20 X
9	1	BUMPER REFLECTOR LH	\$ SL 16.60 X
10	1	BUMPER BEAM REAR	\$ B 547.80 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$ H 114.50
12	1	BUMPER BEAM BRACKET RH REAR	\$ H 100.90
13	1	OUTER PANEL REAR (End Panel)	\$ H 745.80
14	1	OUTER PANEL REAR (End Panel) TRIM	\$ SL 404.56
15	1	TAILLAMP RH	\$ SL 313.10
16	1	TAILLAMP PANEL RH	\$ H 401.40
17	1	TAILLAMP LH	\$ SL 401.40
18	1	TAILLAMP PANEL LH	\$ H 401.40
19	1	BOOT REAR	\$ H 1,677.20
20	1	BOOT FINISHER	\$ SL 344.70
21	1	BOOT WHEATERSTRIP	\$ SL 178.20
22	1	BOOT REFLECTOR LAMP LH	\$ SL 277.70
23	1	BOOT REFLECTOR LAMP RH	\$ SL 277.70
24	1	BOOT BADGE 'RENAULT'	\$ nn 82.40
25	1	BOOT BADGE	\$ nn 95.80
26	1	BOOT STRUT LH	\$ SL 145.10
27	1	BOOT STRUT RH	\$ SL 145.10

Trans-cab Auto Services Pte Ltd**AAD1910-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 267G

28	1	BOOT HINGE LH	\$	254.20	}
29	1	BOOT HINGE RH	\$	253.80	
30	2	BOOT RUBBER PLUG	\$	139.90	
31	2	BOOT BUFFER	\$	26.80	
32	1	BOOT LOCK LINKAGE	\$	20.60	
33	1	BOOT LOCK LINKAGE HOLDER	\$	99.50	
34	1	BOOT INNER TRIM BOARD	\$	611.00	
35	1	BOOT SWITCH	\$	113.00	
36	1	BOOT LOCK	\$	246.60	
37	1	BOOT LOCK CATCH	\$	41.70	
38	1	EXHAUST CAP REAR	\$	125.40	
TOTAL			\$	9,969.06	
10%			\$	996.91	
			\$	8,972.15	

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	—
10	1	BOOT STICKER "Trans-cab"	\$	30.00	}
11	1	BOOT STICKER "6555-3333"	\$	30.00	
12	2	REAR WINDSCREEN SEALANT	\$	80.00	
13	1	WINDSCREEN MOULDING	\$	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
15	1	BOOT INNER TRIM CLIP	\$	45.00	
16	1SET	BOOT FINISHER CLIP	\$	24.20	}
17	1	TAILLAMP CLIP LH	\$	5.00	
18	1	TAILLAMP CLIP RH	\$	5.00	
19	1	Rear Bumper Protector	\$	100.00	405m
20	1	EXHAUST MOUNTING REAR	\$	16.00	X

Trans-cab Auto Services Pte Ltd**AAD1910-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 267G**TOTAL \$ 1,482.20****TOTAL PARTS \$ 10,454.35****LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>15/</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>2001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>4</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1910-230**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 267G

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *nn* 380.00 *X*

Putty and spray painting of the affected portion.

\$ 6,000.00 *22cl*

To repair and realign rear exhaust pipe.

\$ *nn* 170.00 *X*

TOTAL \$ 14,510.00

Over All Total \$ 24,964.35

LUMP SUM (REPAIR DAY)

~~20~~ DAYS

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: