

ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg
TO : AXA Insurance Singapore Pte Ltd
ATTN : Motor Claim Department
TEL. NO. : 1800-8804-741
EMAIL : motor.survey@axa.com.sg
CC : TBC Transportation & Trading P/L
ATTN : Mr. David

DATE : 31.10.2019
VEHICLE NO. : XE 3828 Z
MODEL NO. : SCANIA P400LA4X2MSZ
CHASSIS NO. : YS2P4X20005485835
ENGINE NO. : DC13113L017042893
LTA REG DATE : 22/12/2017
CLAIM TYPE : Third Party - XD 6065 T
D.O.A : 24.10.2019
CLAIM REF NO. : asm/AC19098/JL

Quotation for Accident Repair


S/N	SPARE PARTS	QUANTITY	UNIT PRICE	AMOUNT
1	Front windscreen	1	\$ 888.00	\$ 888.00
2	Wiper arm, LH	1	\$ 355.00	\$ 355.00
3	Wiper blade, LH	1	\$ 71.00	\$ 71.00
4	Member panel, LH	1	\$ 149.33	\$ 149.33
5	Member panel, center	1	\$ 108.00	\$ 108.00
6	Front panel	1	\$ 2,578.60	\$ 2,578.60
7	Gas spring, LH	1	\$ 178.00	\$ 178.00
8	Space frame	1	\$ 2,155.00	\$ 2,155.00
9	Cab corner, LH - outer	1	\$ 1,004.00	\$ 1,004.00
10	Cab corner, LH - inner	1	\$ 94.00	\$ 94.00
11	Front lower panel	1	\$ 2,341.50	\$ 2,341.50
12	Headlamp seal, LH	1	\$ 223.30	\$ 223.30
13	Headlamp, LH	1	\$ 658.30	\$ 658.30
14	Front signal lamp, LH	1	\$ 102.00	\$ 102.00
15	Headlamp inner housing, LH	1	\$ 501.50	\$ 501.50
16	Bumper corner, LH	1	\$ 1,151.60	\$ 1,151.60
17	Bumper end piece, LH	1	\$ 95.30	\$ 95.30
18	Step cover, LH - upper	1	\$ 210.10	\$ 210.10
19	Front wheel mudguard, LH - 1st	1	\$ 699.00	\$ 699.00
20	Front wheel mudguard seal, LH - 1st	1	\$ 216.00	\$ 216.00
21	Front wheel mudguard, LH - 2nd	1	\$ 699.00	\$ 699.00
22	Front wheel mudguard seal, LH - 2nd	1	\$ 216.00	\$ 216.00

SUB-TOTAL :	\$ 14,694.53
LESS 10% :	\$ 1,469.45
BALANCE :	\$ 13,225.08

S/N	SPARE PARTS (SPECIAL NETT ITEMS)	QUANTITY	UNIT PRICE	AMOUNT
1	Sealant for front windscreen	2	\$ 20.00	\$ 40.00
2	Fifth wheel assy	1	\$ 1,200.00	\$ 1,200.00

40FT TRAILER : TRD4148Y

1	I/beam (5x8x8ftx21lb)	1	\$ 580.00	\$ 580.00
2	Twistlock	4	\$ 75.00	\$ 300.00



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
 Main Line: 6265 0980 Fax: 6265 6068
 Email: enquiry@asmauto.com.sg
 Co. / GST Reg. No.: 201203813C




3	Twistlock housing	3	\$ 75.00	\$ 225.00
4	Housing bolts & locknut	4	\$ 3.00	\$ 12.00
5	I/beam side support angle bar (3x3x33x6mm)	2	\$ 60.00	\$ 120.00
6	Tailamp set (canter)	2	\$ 45.00	\$ 90.00
7	Tailamp housing	2	\$ 30.00	\$ 60.00
8	Red reflector	2	\$ 4.00	\$ 8.00
9	Number plate lamp	2	\$ 15.00	\$ 30.00
10	Reverse buzzer	1	\$ 22.50	\$ 22.50
11	Number plate (TRD4148Y)	1	\$ 15.00	\$ 15.00
12	Number plate support flat bar	2	\$ 15.00	\$ 30.00
13	New reflective markings (3M original)	2	\$ 10.00	\$ 20.00
14	New rear bumper (4x4x8ftx4.5mm)	1	\$ 230.00	\$ 230.00
15	Bumper top support bracket	2	\$ 90.00	\$ 180.00
16	Step board support angle bar (2x2x30x9mm)	1	\$ 30.00	\$ 30.00
17	Step board checkered plate (4x30x6mm)	1	\$ 75.00	\$ 75.00
18	New axle set	1	\$ 2,900.00	\$ 2,900.00
19	Hanger set	2	\$ 340.00	\$ 680.00
20	C-channel hanger support (2x4x33 1/2)	1	\$ 68.00	\$ 68.00
21	Brake hose (6ft x 2 = 12ft)	12	\$ 4.50	\$ 54.00
22	Brake hose clip	4	\$ 2.00	\$ 8.00
23	Brake chamber set	2	\$ 150.00	\$ 300.00
24	Spring u/bolts & locknut	4	\$ 98.00	\$ 392.00
25	Spring seat	2	\$ 90.00	\$ 180.00
26	Spring centre bolts & locknut	2	\$ 45.00	\$ 90.00
27	Torque arm bushes	8	\$ 30.00	\$ 240.00
28	Torque arm bolts & locknut	4	\$ 30.00	\$ 120.00
29	Equaliser busher	4	\$ 72.00	\$ 288.00
30	Equaliser bolts & locknuts	2	\$ 30.00	\$ 60.00

DAMAGED CONTAINER : PCIU1601794

1	Container door with h/ware, RH - DX3N	1	\$ 1,200.00	\$ 1,200.00
2	Section dent rail assy - DG3N 60cm	1	\$ 180.00	\$ 180.00
3	Rem/cam keeper - DG3N	1	\$ 18.00	\$ 18.00
4	Gasket assy - DX3N	1	\$ 98.00	\$ 98.00
5	Cut single digit decal - DT3N 11pcs	1	\$ 24.00	\$ 24.00
6	Country code digit decal - DT3N 4pcs	1	\$ 12.00	\$ 12.00
7	Mass decals - DX3N full set	1	\$ 52.00	\$ 52.00
8	Hinge assy - DB4N	1	\$ 96.00	\$ 96.00
9	Hinge assy - DX4N 3pcs	1	\$ 50.00	\$ 50.00
10	Cut slam plate - DX3N	1	\$ 25.00	\$ 25.00
11	Floorboard remove thick mud - BXXX	1	\$ 80.00	\$ 80.00
12	Floorboard washing	1	\$ 60.00	\$ 60.00

S/N ITEMS TOTAL : \$ 10,542.50

TOTAL PARTS : \$ 23,767.58



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



LABOUR CHARGES

1 Body repair : To remove and replace damaged parts include front windscreen, cab corner, front panel, lamp, fifth wheel etc. (\$350 x 4 days)	\$	1,400.00
2 Trailer repair : Jacking, straightening and welding of chassis main body frame. Patching and welding of trailer undercarriage crossmember, replace all the damaged parts.	\$	2,500.00
3 Spray painting on the new parts, including LHS door and trailer.	\$	1,200.00
4 Logo writing on LHS door	\$	150.00
5 Towing fee	\$	120.00
TOTAL LABOUR :	\$	5,370.00
GRAND TOTAL :	\$	29,137.58