

ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : AXA Insurance Singapore Pte Ltd
ATTN : Motor Claim Department
TEL. NO. : 1800-8804-741
EMAIL : motor.survey@axa.com.sg

CC : TBC Transportation & Trading P/L
ATTN : Mr. David

DATE : 31.10.2019

VEHICLE NO. : XE 3828 Z
MODEL NO. : SCANIA P400LA4X2MSZ
CHASSIS NO. : YS2P4X20005485835
ENGINE NO. : DC13113L017042893
LTA REG DATE : 22/12/2017

CLAIM TYPE : Third Party - XD 6065 T
D.O.A : 24.10.2019
CLAIM REF NO. : asm/AC19098/JL


Quotation for Accident Repair

S/N	(A) SPARE PARTS	QUANTITY	UNIT PRICE	AMOUNT	
1	Front windscreen	1	\$ 888.00	\$ 888.00	crs
2	Wiper arm, LH	1	\$ 355.00	\$ 355.00	bt
3	Wiper blade, LH	1	\$ 71.00	\$ 71.00	at
4	Member panel, LH	1	\$ 149.33	\$ 149.33	crs
5	Member panel, center	1	\$ 108.00	\$ 108.00	ant
6	Front panel	1	\$ 2,578.60	\$ 2,578.60	crs
7	Gas spring, LH	1	\$ 178.00	\$ 178.00	?
8	Space frame	1	\$ 2,155.00	\$ 2,155.00	?
9	Cab corner, LH - outer	1	\$ 1,004.00	\$ 1,004.00	crs
10	Cab corner, LH - inner	1	\$ 94.00	\$ 94.00	crs
11	Front lower panel	1	\$ 2,341.50	\$ 2,341.50	crs
12	Headlamp seal, LH	1	\$ 223.30	\$ 223.30	Rx
13	Headlamp, LH	1	\$ 658.30	\$ 658.30	?
14	Front signal lamp, LH	1	\$ 102.00	\$ 102.00	crs
15	Headlamp inner housing, LH	1	\$ 501.50	\$ 501.50	?
16	Bumper corner, LH	1	\$ 1,151.60	\$ 1,151.60	bt
17	Bumper end piece, LH	1	\$ 95.30	\$ 95.30	dis
18	Step cover, LH - upper	1	\$ 210.10	\$ 210.10	de
19	Front wheel mudguard, LH - 1st	1	\$ 699.00	\$ 699.00	Rx
20	Front wheel mudguard seal, LH - 1st	1	\$ 216.00	\$ 216.00	Rx
21	Front wheel mudguard, LH - 2nd	1	\$ 699.00	\$ 699.00	de
22	Front wheel mudguard seal, LH - 2nd	1	\$ 216.00	\$ 216.00	mis
SUB-TOTAL :				\$ 14,694.53	
LESS 10% :				\$ 1,469.45	
BALANCE :				\$ 13,225.08	

S/N	(A) SPARE PARTS (SPECIAL NETT ITEMS)	QUANTITY	UNIT PRICE	AMOUNT	
1	Sealant for front windscreen	2	\$ 20.00	\$ 40.00	all
2	Fifth wheel assy	1	\$ 1,200.00	\$ 1,200.00	?

(B) 40FT TRAILER : TRD4148Y

1	I/beam (5x8x8ftx21lb)	1	\$ 580.00	\$ 580.00	bt
2	Twistlock	4	\$ 75.00	\$ 300.00	bt



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



3 Twistlock housing	3	\$ 75.00	\$ 225.00	bt ✓
4 Housing bolts & locknut	4	\$ 3.00	\$ 12.00	rec ✓
5 I/beam side support angle bar (3x3x33x6mm)	2	\$ 60.00	\$ 120.00	bt ✓
6 Tailamp set (canter)	2	\$ 45.00	\$ 44-x 90.00	RH-cub ✓
7 Tailamp housing	2	\$ 30.00	\$ 44-x 60.00	RH-bt ✓
8 Red reflector	2	\$ 4.00	\$ 44-x 8.00	CR ✓ RH
9 Number plate lamp	2	\$ 15.00	\$ x 30.00	
10 Reverse buzzer	1	\$ 22.50	\$ x 22.50	
11 Number plate (TRD4148Y)	1	\$ 15.00	\$ x 15.00	
12 Number plate support flat bar	2	\$ 15.00	\$ x 30.00	
13 New reflective markings (3M original)	2	\$ 10.00	\$ 20.00	rec ✓
14 New rear bumper (4x4x8ftx4.5mm)	1	\$ 230.00	\$ 230.00	bt ✓
15 Bumper top support bracket	2	\$ 90.00	\$ 180.00	bt ✓
16 Step board support angle bar (2x2x30x9mm)	1	\$ 30.00	\$ 30.00	mis ✓
17 Step board checkered plate (4x30x6mm)	1	\$ 75.00	\$ 75.00	ms ✓
18 New axle set	1	\$ 2,900.00	\$ x 2,900.00	bt ✓
19 Hanger set	2	\$ 340.00	\$ x 680.00	bt ✓
20 C-channel hanger support (2x4x33 1/2)	1	\$ 68.00	\$ x 68.00	bt ✓
21 Brake hose (6ft x 2 = 12ft)	12	\$ 4.50	\$ x 54.00	x
22 Brake hose clip	4	\$ 2.00	\$ x 8.00	x
23 Brake chamber set	2	\$ 150.00	\$ x 300.00	?
24 Spring u/bolts & locknut	4	\$ 98.00	\$ x 392.00	rec ✓
25 Spring seat	2	\$ 90.00	\$ x 180.00	rec ✓
26 Spring centre bolts & locknut	2	\$ 45.00	\$ x 90.00	rec ✓
27 Torque arm bushes	8	\$ 30.00	\$ x 240.00	?
28 Torque arm bolts & locknut	4	\$ 30.00	\$ x 120.00	rec ✓
29 Equaliser busher	4	\$ 72.00	\$ x 288.00	rec ✓
30 Equaliser bolts & locknuts	2	\$ 30.00	\$ x 60.00	rec ✓

DAMAGED CONTAINER : PCIU1601794


1 Container door with h/ware, RH - DX3N	1	\$ 1,200.00	\$ 1,200.00	bt ✓
2 Section dent rail assy - DG3N 60cm	1	\$ 180.00	\$ 180.00	bt ✓
3 Rem/cam keeper - DG3N	1	\$ 18.00	\$ 18.00	bt ✓
4 Gasket assy - DX3N	1	\$ 98.00	\$ 98.00	rec ✓
5 Cut single digit decal - DT3N 11pcs	1	\$ 24.00	\$ 24.00	rec ✓
6 Country code digit decal - DT3N 4pcs	1	\$ 12.00	\$ 12.00	rec ✓
7 Mass decals - DX3N full set	1	\$ 52.00	\$ 52.00	rec ✓
8 Hinge assy - DB4N	1	\$ 96.00	\$ 96.00	bt ✓
9 Hinge assy - DX4N 3pcs	1	\$ 50.00	\$ 50.00	bt ✓
10 Cut slam plate - DX3N	1	\$ 25.00	\$ 25.00	bt ✓
11 Floorboard remove thick mud - BXXX	1	\$ 80.00	\$ 80.00	✓
12 Floorboard washing	1	\$ 60.00	\$ 60.00	✓

S/N ITEMS TOTAL :

\$ 10,542.50

TOTAL PARTS :

\$ 23,767.58



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424

Main Line: 6265 0980 Fax: 6265 6068

Email: enquiry@asmauto.com.sg

Co. / GST Reg. No.: 201203813C



LABOUR CHARGES

1 Body repair : To remove and replace damaged parts include front windscreen, cab corner, front panel, lamp, fifth wheel etc. (\$350 x 4 days)	\$ 1,400.00	1050-
2 Trailer repair : Jacking, straightening and welding of chassis main body frame. Patching and welding of trailer undercarriage crossmember, replace all the damaged parts.	\$ 2,500.00	1500
3 Spray painting on the new parts, including LHS door and trailer.	\$ 1,200.00	800-
4 Logo writing on LHS door	\$ 150.00	100-
5 Towing fee	\$ 120.00	100-
TOTAL LABOUR :	\$ 5,370.00	

GRAND TOTAL : \$ 29,137.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 9749 5746
01/11/19 @ 3pm

* Resurvey new parts
* Resurvey after repair

10 days

tanjiah@lkkauto.com